

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19014254/T1GA3Q2

Date: 23/09/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00005669
Claimant
Vehicle No : SKJ8411L **Insured Vehicle No :** SLB6249H
Date of Loss: 14/08/2019 **Nature of Claim:** TP **Claim No:** 1201900023732

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKJ8411L**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZRX250885
 Reg. Date: 17/05/2013 (Man. Year: 2013) Chassis No: MR053REE104155383
 Colour: Black Odometer: 179782 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,038.20	4,162.80	6,875.40	62.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	1,760.00	2,070.00	54.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,868.20	5,922.80	8,945.40	60.16
Approved Total (Overridden) (\$\$)		4,700.00		
Nett Amount (\$\$)	14,868.20	4,700.00	10,168.20	68.39
+ Loss of Use (7.0 x S\$50.00/day) (\$\$)		350.00		
Nett Liability (\$\$)		5,050.00		
Global Sum Settlement (\$\$)		5,000.00		

INSPECTION

Date of Assignment: 15/08/2019
 Date Inspected: 16/08/2019 Inspected At: Ama Autocare Pte Ltd (HQ)
 42 Toh Guan Road East, #01-79
 Singapore 608583
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ8411L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	1,478.00 FL	*855.10 FL
2	1		*REAR BOOTLID CENTRE CHROME MOULDING	Not Necessary	254.00 FL	*- FL
3	1		*REAR BOOTLID WEATHERSTRIP	Cut	214.00 FL	*214.00 FL
4	1		*REAR BOOTLID COROLLA EMBLEM	Necessary	108.00 FL	*108.00 FL
5	1		*REAR BOOTLID ALTIS EMBLEM	Necessary	82.00 FL	*82.00 FL
6	1		*REAR BOOTLID 1.6 E EMBLEM	Necessary	58.00 FL	*58.00 FL
7	1		*REAR BOOTLID VVT-I EMBLEM	Necessary	70.00 FL	*70.00 FL
8	1		*REAR BOOTLID COROLLA BADGE	Necessary	88.00 FL	*88.00 FL
9	1		*REAR BOOTLID DUAL BADGE	Necessary	58.00 FL	*58.00 FL
10	1		*REAR BOOTLID ELEGANCE BADGE	Necessary	82.00 FL	*82.00 FL
11	1		*REAR BOOTLID LOCK ASSY	Bent	480.00 FL	*285.20 FL
12	1		*REAR BOOTLID REFLECTOR	N/S Not Necessary / O/S Cut	1,144.80 FL	*314.00 FL
13	1		*REAR TAILLAMP	N/S Not Necessary / O/S Cut	1,560.00 FL	*594.60 FL
14	2		*TAILLAMP LOWER PANEL	Repair	429.00 FL	*- FL
15	1		*REAR END PANEL	Bent	982.00 FL	*586.60 FL
16	1		*REAR END PANEL TOP GARNISH	Deformed	216.00 FL	*216.00 FL
17	1		*REAR BUMPER	Deformed	1,250.00 FL	*596.50 FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	672.00 FL	*392.60 FL
19	1		*REAR BUMPER FOAM	Cracked	310.00 FL	*163.80 FL
20	1		*SET REAR BUMPER SIDE RETAINER	N/S Not Necessary/O/SDistorted	196.00 FL	*98.00 FL
21	2		*RHS & LHS REAR FENDER	Repair	1,565.00 FL	*- FL
22	2		*RHS & LHS REAR FENDER INNER TRIM	Not Necessary	544.80 FL	*- FL
23	1		*REAR SPARE TYRE PANEL	Repair	980.00 FL	*- FL
24	1		*REAR SPARE TYRE TOP COVER	Cracked	288.00 FL	*288.00 FL
25	1		*REAR EXHAUST SILENCER ASSEMBLY	Repair	670.00 FL	*- FL
26	1		*REAR EXHAUST SILENCER ASSEMBLY MOUNTINGS	Not Necessary	98.00 FL	*- FL
27	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
28	1		*SET INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
29	1		*SET TAILLAMP CLIPS	Necessary	70.00 FS	*30.00 FS
30	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	220.00 FS	*200.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
32	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,507.60	5,450.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,469.40	1,287.60
Total Parts (\$\$)	11,038.20	4,162.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS	New	1,400.00	800.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,400.00	800.00
3	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	200.00	30.00
4	TO REMOVE AND REFIX /REPLACE REAR ITEMS GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR COMPARTMENT	New	250.00	60.00
5	TO REMOVE AND REPLACE REVERSE SENSORS	New	150.00	30.00
6	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	180.00	40.00
7	TO REMOVE AND REPLACE REAR EXHAUST SILENCER ASSY	New	250.00	0.00
Gross Labour Cost (\$\$)			3,830.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >