

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

KMH D841cmku879543.

LEE ENG HWA
BLK 622 ANG MO KIO AVE 9
#03-40
S 560622

TPA16.
Ashes.

Date :21.08.2019
Vehicle No :SMN 5454 M
Make/Model :HYUNDAI AVANTE
Accident date :13.08.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front bonnet <i>Dented.</i>	1	\$ 2101.9 1910.
2	Front bonnet hinges @ \$ 54.00 <i>Bent.</i>	2	\$ 108 ✓
3	Front bonnet lock <i>Face new</i>	1	\$ 175.5 ✓
4	Front bonnet lock bracket	1	\$ 53.9 ✓
5	Front bonnet insulation <i>new</i>	1	\$ 244 ✓
6	Front susport panel <i>Buckled.</i>	1	\$ 996.4 ✓
7	Front susport panel top garnish <i>new</i>	1	\$ 237.2 ✓
8	Front susport panel top cover <i>Dented</i>	1	\$ 81.5 ✓
9	Front susport panel top cover clips @ \$ 9.40 <i>on</i>	6	\$ 56.4 20.
10	Front susport panel rubber <i>new</i>	1	\$ 155 ✓
11	Front head lamp @ \$ 1,977.60 <i>LH cracked</i>	2	\$ 3955.2 1678.
12	Front grille <i>cracked</i>	1	\$ 572 ✓
13	Front grille emblem <i>new</i>	1	\$ 33 ✓
14	Front bumper <i>Distorted</i>	1	\$ 564.1 ✓
15	Front bumper side holder @ \$ 49.50 <i>LH Daged</i>	2	\$ 99 49.50.
16	Front bumper lower lip <i>delaminated.</i>	1	\$ 90.9 ✓
17	Front bumper LH fod lamp <i>cracked.</i>	1	\$ 264 ✓
18	Front bumper LH fod lamp garnish <i>cut</i>	1	\$ 46.2 ✓
19	Front bumper LH fod lamp lower garnish <i>delaminated</i>	1	\$ 57.2 ✓
20	Front bumper reinforcement <i>Bent.</i>	1	\$ 765.4 ✓
21	Front bumper sponge <i>cracked.</i>	1	\$ 132.7 ✓
22	Front bumper bracket @ \$ 83.40 <i>new</i>	2	\$ 166.8 ✓
23	Front bumper clips (1 set) <i>new</i>	1	\$ 66 30.
24	Front LH fender <i>Buckled.</i>	1	\$ 574 ✓
25	Front LH fender inner shield <i>torn</i>	1	\$ 130.5 ✓
26	Front LH fender inner shield clips (1 set) <i>new</i>	1	\$ 66 30
27	Front engine lower cover <i>torn</i>	1	\$ 90.9 ✓
28	Front LH wheel housing <i>Repair</i>	1	\$ 579.5 ✓
29	Fuel box assy <i>cracked.</i>	1	\$ 908.2 ✓
30	Air cleanner assy <i>cracked.</i>	1	\$ 341 ✓

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

LEE ENG HWA
BLK 622 ANG MO KIO AVE 9
#03-40
S 560622

Date :21.08.2019
Vehicle No :SMN 5454 M
Make/Model :HYUNDAI AVANTE
Accident date :13.08.2019

No	DESCRIPTION	Qty	Amount (\$)
31	Air cleanner house <i>Not new</i>	1	\$ 83.4 x
32	Resornator <i>Delid</i>	1	\$ 242.7 ✓
33	Resornator house Air Duct <i>Delid</i>	1	\$ 60.5 ✓
34	Electric fan assy <i>Not new</i>	1	\$ 624.6 x
35	Radiator <i>Best</i>	1	\$ 561.9 ✓
36	Air condenser <i>Bent</i>	1	\$ 819.6 ✓
37	Air condenser side garnish <i>cracked</i>	1	\$ 30.8 ✓
38	Front Bumper Cover Beam <i>195</i>		\$ 16135.9
		Less 20% Disc	\$ 3227.2
		Total	\$ 12908.7

Special Nett Items

1	Front LH sport rim <i>cut</i>	1	\$ 780 <i>650</i>
2	Front LH tyre	1	\$ 380 <i>250</i>
		Total	\$ 1160

Labour Cost

1	To check wiring	\$ 100 <i>30</i>
2	To check wheel alignment	\$ 100 <i>80</i>
3	To reset	\$ 100 x
4	Remove & reinstall air con fill in gas	\$ 150 <i>120</i>
5	Remove ,replace & repair consistent to the accident	\$ 2000 <i>1200</i>
6	Respray painting	\$ 1800 <i>1000</i>
7	Tuff kote	\$ 150 x
	Total	\$ 4400

Grand Total \$ 18468.7

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 11871.84
L/S 9.5K
08 Days.

9.5K