



Your Ref : S9M01WS8

Date: 11th November 2019

Our Ref : CC4/ASM19014262/Epa3s2

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01

AXA Tower

Singapore 068811

(The Motor Claims Department)

Attn: Richard Ang

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBE 958L
ACCIDENT ON 11/08/2019 INSURED VEHICLE NO. SKE 7130E**

Instruction was received to inspect the vehicle Reg. No. FBE 958L. The inspection was conducted on 16/08/2019 at the premises of M/s SG 98 Motor Pte Ltd, Blk 4001 Ang Mo Kio Industrial Park 1 #01-21 Singapore 569622.

The following vehicle information was recorded:

Registration Number	: FBE 958L
Make/Model	: Piaggio Fly
Year of Registration	: 2009
Body Colour	: Blue
Chassis Number	: LBMM5720000003617
Engine Capacity	: 151 cc
Speedometer Reading	: 055367 km

The vehicle sustained damages at the front portion and o/s body. (Details see photographs enclosed).


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“uneconomical Total Loss”**.

Market Value	S\$	500.00
Less: LTA Reimbursement Value (RV)	(S\$	23.00)
Nett Liability	S\$	477.00

Vehicle Inspected By:



CHEN TSUE YEE
Automotive Assessor



K.K. LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.