

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG19014270/KBA3Q2  
**Date:** 16/02/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
<b>Claimant Vehicle No :</b>	SHC5601Y	<b>Insured Vehicle No :</b>	SMN3770M
Date of Loss:	10/08/2019	Nature of Claim:	TP
		Claim No:	1570352959SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC5601Y</b>	Engine No:	M9R8839C001927
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC279405
Reg. Date:	30/09/2014 (Man. Year: 2014)	Odometer:	601363 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Giti 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,773.36	4,735.70	24,037.66	83.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,940.00	1,520.00	14,420.00	90.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>44,713.36</b>	<b>6,255.70</b>	<b>38,457.66</b>	<b>86.01</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
(S\$)	44,713.36	5,000.00	39,713.36	88.82
<b>+ GST 7.00/7.00% (S\$)</b>	3,129.94	350.00	2,779.94	88.82
<b>Nett Amount (S\$)</b>	<b>47,843.30</b>	<b>5,350.00</b>	<b>42,493.30</b>	<b>88.82</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$96.99/day) (S\$)</b>		290.97		
(S\$)		5,790.97		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>2,895.49</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>2,902.98</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,900.00</b>		

### INSPECTION

Date of Assignment: 15/08/2019

2/16/2021

Adjuster Report

Date Inspected: 15/08/2019 Inspected At:  
Estimated Period of Repair: 3.0 days

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)  
2, Ang Mo Kio Street 63  
Singapore 569111

---

**Adjuster:** KENNETH KONG

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Repair	1,259.42 FL	*- FL
2	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT LH	Serviceable	151.41 FL	*- FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
7	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
8	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
9	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
10	1		*HEADLAMP LH	Serviceable	1,184.43 FL	*- FL
11	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
12	1		*FENDER PANEL FRT LH	Bent	783.83 FL	*783.83 FL
13	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
14	1		*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*- FL
15	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
16	1		*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
17	1		*RADIATOR GRILLE	Serviceable	1,707.78 FL	*- FL
18	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
19	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
20	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
21	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
22	1		*BONNET	Repair	1,941.63 FL	*- FL
23	1		*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
24	1		*BONNET STRUT LH	Serviceable	88.61 FL	*- FL
25	1		*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
26	1		*BONNET HINGE LH	Repair	348.31 FL	*- FL
27	1		*BONNET HINGE RH	Repair	348.31 FL	*- FL
28	1		*BONNET LOCK	Repair	305.48 FL	*- FL
29	1		*BONNET CABLE	Repair	119.19 FL	*- FL
30	1		*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
31	1		*BONNET SEAL OUTER	Serviceable	92.36 FL	*- FL
32	1		*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
33	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
34	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
35	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
36	1		*DOOR PANEL FRT LH	Bent	2,844.66 FL	*2,844.66 FL
37	1		*DOOR HANDLE OUTER FRT LH	Serviceable	477.76 FL	*- FL
38	1		*DOOR HANDLE COVER FRT LH	Serviceable	13.22 FL	*- FL
39	1		*DOOR HANDLE MODULE FRT LH	Serviceable	133.60 FL	*- FL
40	1		*DOOR MIRROR ASSY LH	Dented / Cracked	1,483.40 FL	*1,483.40 FL
41	1		*DOOR HARNESS WIRE LH	Serviceable	2,670.00 FL	*- FL
42	1		*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*- FL
43	1		*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*- FL
44	1		*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	*- FL
45	1		*ROCKER PANEL CENTER LH	Repair	990.25 FL	*- FL
46	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
47	1		*BUMPER CLIP FRT	Not Necessary	66.00 FS	*- FS
48	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
49	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
50	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
51	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
53	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
54	1		*WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
55	1		*FRONT LEFT TYRE	Serviceable	300.00 FS	*- FS
56	1		*FRONT LEFT TYRE RIM	Serviceable	380.00 FS	*- FS
57	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS
58	1		*WINDSCREEN SEALANT	Not Necessary	253.80 FS	*- FS
59	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	*- FS
60	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
61	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	*- FS
62	2		*BONNET STRUT L70Y	Serviceable	88.61 FS	*- FS
63	2		*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	*- FS
64	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	*- FS
65	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS
66	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
67	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
68	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS
69	1		*REAR DOOR STICKER 6555-3333	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>31,752.30</b>	<b>5,246.89</b>
- List Item Discount on L Items 10.00/10.00% (\$)	2,978.94	511.19
<b>Total Parts (\$)</b>	<b>28,773.36</b>	<b>4,735.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	6,000.00	500.00
2	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
3	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
4	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
10	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	880.00
11	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	60.00
12	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
13	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
14	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
15	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>15,940.00</b>	<b>1,520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >