

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19014272/R1TF3E2

Date: 25/10/2019

REFERENCE

Insured/Claimant:	LIU JUNCHEN	Policy No:	1800116814
Date of Loss:	27/06/2019	Nature of Claim:	OD
		Claim No:	4863151747SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME6660A	Engine No:	CVK064186
Make & Model:	AUDI A4, 2.0 (A)	Chassis No:	WAUZZZF47JN015074
Reg. Date:	29/09/2018 (Man. Year: 2018)	Odometer:	11662 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$139,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,217.00	1,627.92	1,589.08	49.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,752.00	2,402.00	1,350.00	35.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,969.00	4,029.92	2,939.08	42.17
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	5,369.00	2,429.92	2,939.08	54.74
+ GST 7.00/7.00% (S\$)	375.83	170.09	205.74	54.74
Nett Amount (S\$)	5,744.83	2,600.01	3,144.82	54.74

INSPECTION

Date of Assignment: 16/08/2019

Date Inspected: 15/08/2019 Inspected At:

281 Alexandra Road
Repairer : Premium Automobiles Pte Ltd (UBI)

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	2,015.00 FS	*1,612.00 FS	
2	1		*REAR BUMPER FIXING PARTS	Serviceable	66.00 FS	*- FS	
3	1		*REAR BUMPER SECURING STRIP	Serviceable	203.00 FS	*- FS	
4	1		*REAR BUMPER SPOILER	Serviceable	227.00 FS	*- FS	
5	1		*REAR LIGHT REFLECTOR - LH	Serviceable	38.00 FS	*- FS	
6	1		*REAR BUMPER GUIDE SECTION - LH	Serviceable	40.00 FS	*- FS	
7	1		*REAR BUMPER GUIDE SECTION BRACKET - LH	Serviceable	20.00 FS	*- FS	
8	1		*PIN	Not Necessary	3.00 FS	*- FS	
9	1		*FRONT WHEEL HOUSING LINER - LH	Serviceable	223.00 FS	*- FS	
10	1		*WHEEL HOUSING ATTACHMENT PARTS	Serviceable	82.00 FS	*- FS	
11	1		*SUNDRIES	Necessary	300.00 FS	*15.92 FS	
					Total Parts (S\$)	3,217.00	1,627.92

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR LHS REAR FENDER. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,400.00	750.00
3	TO RESPRAY REAR BUMPER AND LHS REAR FENDER	New	1,800.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			3,752.00	2,402.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >