

22/03/2012

ASS. REC. BY:

REF: CS/CT1 19014312/ k19f3n2

Special Instruction:

Surveyor: RasulASSIGNMENT (Office)From (Person): Chong Boon Sen

of

CTIDate/Time: 16/8/19 @ 10:16am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJL 8682Y

Insured:

GBD 8539R

at Workshop in/s

ASM Automotive

Tel:

9236 8218

of

No. 13 - Pioneer Seletor 1

Policy No:

DMCVSN 304 78919044

Claim No:

SNM19D203550002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:49am 16/8/19

Person Contacted:

JoylynVehicle ☒ IN / OUT

| Date/Time | Action/Instruction                                     |
|-----------|--------------------------------------------------------|
|           | Johny ✓                                                |
|           | SJL 8682Y - CCB/A1G/16008480/ uha 2/2 DON - 25/04/2016 |
|           | GBD 8539R - 4                                          |
| 29/8/19 @ | 1.05am Rasul finalised US \$ 1600, 5 days.             |
|           | (Red \$ 2322, 59.1%)                                   |

ASS. REC'D BY: JP

REF:

## ASSIGNMENT

506K  
CBE XPIRY: 2028/06

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJL 86824at Workshop m/s: ASM AUTOMOTIVEof 13, Pioneer Sector 1Insured: CTI

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SJL 86824 Yr Regn: 2008 / 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA MTIS 1.6A c.c. 1598Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 243115 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MROS3 ZEE 106124 765

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 27/07/19D.O.I. 16/08/19

Survey held at

ASM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 09 SEP 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 03/9/19 Final☐

Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weat and (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Other

TOTAL

Report Format: MER-TPLump Sum / Fee: 1600

220

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Friday, 16 August 2019 10:16 AM  
**To:** ASM Jaclyn  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D203550-GBD8539R-CBS- FW: Third party claim: SJL8682Y and GBD8539R (your insured); DOA: 27.07.19

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** ASM Jaclyn [mailto:jaclynlai@asmauto.com.sg]

**Sent:** Friday, 16 August, 2019 9:53 AM

**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

**Subject:** RE: OUR REF: SNM19D203550-GBD8539R-CBS- FW: Third party claim: SJL8682Y and GBD8539R (your insured); DOA: 27.07.19

Dear Boon Sen,

We would like to choose Kenneth Kong

Thank you

Best Regards,

*Jaclyn Lai*

Assistant Manager  
Claims & Operation

## ASM Automotive Services Pte Ltd

No. 13, Pioneer Sector 1, Singapore 628424.

Hp: 9236 8218 | DID: 6265 0026 | Fax: 6265 6068

Web: [www.asmauto.com.sg](http://www.asmauto.com.sg)



**From:** Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

**Sent:** Friday, 16 August 2019 9:46 AM

**To:** ASM Jaclyn

**Subject:** RE: OUR REF: SNM19D203550-GBD8539R-CBS- FW: Third party claim: SJL8682Y and GBD8539R (your insured); DOA: 27.07.19

### WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

|                         |
|-------------------------|
| ADRIAN LING             |
| Kelvin Ang              |
| SEE CHEW SENG           |
| MOHD FADHILAH BIN OSMAN |
| XING QUO QIANG          |
| KENNETH KONG            |
| SIMON HO                |
| CHUA WEIJIE             |
| MARCUS CHUA             |
| HENRY NG                |

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

### Chong Boon Sen

Claims Executive  
Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** ASM Jaclyn [<mailto:jaclynlai@asmauto.com.sg>]

**Sent:** Friday, 16 August, 2019 9:42 AM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>  
**Subject:** RE: OUR REF: SNM19D203550-GBD8539R-CBS- FW: Third party claim: SJL8682Y and GBD8539R (your insured); DOA: 27.07.19

Dear Boon Sen,

Would appreciate you can arrange survey on today.

Thank you

Best Regards,  
*Jaclyn Lai*

Assistant Manager  
Claims & Operation

**ASM Automotive Services Pte Ltd**

No. 13, Pioneer Sector 1, Singapore 628424.  
Hp: 9236 8218 | DID: 6265 0026 | Fax: 6265 6068  
Web: [www.asmauto.com.sg](http://www.asmauto.com.sg)



---

**From:** Claims Dept of CTI [<mailto:claimsdept@sg.cntaiping.com>]  
**Sent:** Thursday, 15 August 2019 6:24 PM  
**To:** Chong Boon Sen; Alfred Toh; Chee So Chow; ASM Jaclyn  
**Subject:** OUR REF: SNM19D203550-GBD8539R-CBS- FW: Third party claim: SJL8682Y and GBD8539R (your insured); DOA: 27.07.19

Dear Boon Sen,

Please conduct PRS for SJL8682Y.

Note: officer in charge – Boon Sen 63896171.

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
T: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** ASM Jaclyn [<mailto:jaclynlai@asmauto.com.sg>]  
**Sent:** Thursday, 15 August, 2019 11:26 AM

To: Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

Subject: Third party claim: SJL8682Y and GBD8539R (your insured); DOA: 27.07.19

Dear Sir / Madam,

Our client, the owner of SJL 8682Y wishes to file claim for the damages sustained from the above-stated accident, against your insured, GBD 8539R.

We hereby append a copy of our estimate and SAS for your kind perusal.

Kindly advise on liability and arrange for survey. Thank you.

Best Regards,

*Jaclyn Lai*

Assistant Manager

Claims & Operation

**ASM Automotive Services Pte Ltd**

No. 13, Pioneer Sector 1, Singapore 628424.

Hp: 9236 8218 | DID: 6265 0026 | Fax: 6265 6068

Web: [www.asmauto.com.sg](http://www.asmauto.com.sg)



---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## Shiau Chan (LKKAuto)

---

**From:** ASM Jaclyn <jaclynlai@asmauto.com.sg>  
**Sent:** Thursday, 29 August 2019 11:55 AM  
**To:** Rasul (LKKAuto)  
**Cc:** ASM Yandy  
**Subject:** RE: TP claim (China Taiping) -- SJL8682Y \_ finalization

Dear Rasul,

Noted with thanks.

Best Regards,

*Jaclyn Lai*

Assistant Manager

Claims & Operation

**ASM Automotive Services Pte Ltd**

No. 13, Pioneer Sector 1, Singapore 628424.

Hp: 9236 8218 | DID: 6265 0026 | Fax: 6265 6068

Web: [www.asmauto.com.sg](http://www.asmauto.com.sg)



---

**From:** Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]  
**Sent:** Thursday, 29 August 2019 11:05 AM  
**To:** ASM Jaclyn  
**Subject:** RE: TP claim (China Taiping) -- SJL8682Y \_ finalization

Hi Jacklyn,

Finalised amount confirmed


Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** ASM Jaclyn [mailto:jaclynlai@asmauto.com.sg]  
**Sent:** Wednesday, 28 August, 2019 11:21 AM  
**To:** Rasul (LKKAuto)  
**Subject:** TP claim (China Taiping) -- SJL8682Y \_ finalization

Dear Rasul

Please find attached after repaired photos for your reference. LHS bumper side support had missing, you may refer back the photos that taken while survey.

COR @ lump-sum \$1,600/- and 5 days. Please confirm.

Thank you

Best Regards,

*Jackyn Lai*

Assistant Manager

Claims & Operation

**ASM Automotive Services Pte Ltd**

No. 13, Pioneer Sector 1, Singapore 628424.

Hp: 9236 8218 | DID: 6265 0026 | Fax: 6265 6068

Web: [www.asmauto.com.sg](http://www.asmauto.com.sg)







# ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424  
Main Line: 6265 0980 Fax: 6265 6068  
Email: enquiry@asmauto.com.sg  
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai  
TEL. NO. : 6265-0026 / 9236-8218  
EMAIL : jaclynlai@asmauto.com.sg

DATE : 15/8/2019

TO : China Taiping Insurance (Sg) P/L  
ATTN : Motor Claim Department  
TEL. NO. : 6389-6111 (main)  
EMAIL : claimsdept@sg.cntaiping.com

VEHICLE NO. : SJL 8682 Y  
MODEL NO. : TOYOTA COROLLA ALTIS 1.6 A  
CHASSIS NO. : MR053ZEE106124765  
ENGINE NO. : 3ZZ4815768  
LTA REG DATE : 15/12/2008 - 14/12/2028

CC : BT News Agency  
ATTN : Mr. Chow

CLAIM TYPE : Third Party - GBD 8539 R  
D.O.A : 27/7/2019  
CLAIM REF NO. : asm/AC19069/JL

## Quotation for Accident Repair

| S/N         | SPARE PARTS                    | QUANTITY | UNIT PRICE | AMOUNT      |
|-------------|--------------------------------|----------|------------|-------------|
| 1           | Radiator grille X sue          | 1        | \$ 250.00  | \$ 250.00   |
| 2           | Headlamp, LH sue               | 1        | \$ 340.00  | \$ 340.00   |
| 3           | Side fender, LH front bt       | 1        | \$ 405.00  | \$ 405.00   |
| 4           | Headlamp, RH X sue             | 1        | \$ 340.00  | \$ 340.00   |
| 5           | Front bumper cm                | 1        | \$ 375.00  | \$ 375.00   |
| 6           | Bumper grille, center X sue    | 1        | \$ 110.00  | \$ 110.00   |
| 7           | Bumper side support, LH 7. mis | 1        | \$ 68.00   | \$ 68.00    |
| 8           | Bumper side support, RH X sue  | 1        | \$ 68.00   | \$ 68.00    |
| 9           | Engine under cover X sue       | 1        | \$ 160.00  | \$ 160.00   |
| SUB-TOTAL : |                                |          |            | \$ 2,116.00 |
| LESS 25% :  |                                |          |            | \$ 529.00   |
| BALANCE :   |                                |          |            | \$ 1,587.00 |

| S/N               | SPARE PARTS (SPECIAL NETT ITEMS) | QUANTITY | UNIT PRICE | AMOUNT   |
|-------------------|----------------------------------|----------|------------|----------|
| 1                 | Front emboss number plate X sue  | 1        | \$ 35.00   | \$ 35.00 |
| S/N ITEMS TOTAL : |                                  |          |            | \$ 35.00 |

TOTAL PARTS : \$ 1,622.00

## LABOUR CHARGES

1 To remove and replace damaged parts, realignment & check lamp wiring etc.

2 Spray painting

LKK Auto Consultant's hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL LABOUR : \$ 2,300.00

GRAND TOTAL : \$ 3,922.00

Acknowledged by Repairer

Signature:

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119014312/R1QF3N2

Date: 06/09/2019

### REFERENCE

|                       |                                               |                      |                   |                           |
|-----------------------|-----------------------------------------------|----------------------|-------------------|---------------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMCVSN30478919044 |                           |
| Claimant Vehicle No : | SJL8682Y                                      | Insured Vehicle No : | GBD8539R          |                           |
| Date of Loss:         | 27/07/2019                                    | Nature of Claim:     | TP                | Claim No: SNM19D203550C02 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | SJL8682Y                          | Engine No:  | 3ZZ4815768        |
| Make & Model:               | TOYOTA COROLLA ALTIS, 1.6 CVT (A) | Chassis No: | MR053ZEE106124765 |
| Reg. Date:                  | 15/12/2008 (Man. Year: 2008)      | Odometer:   | 243115 km         |
| Colour:                     | Black                             |             |                   |
| Engine Capacity:            | 1598 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | Market Value/New Car Price        |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 195/65R15        | Rear Tyre Size:  | 195/65R15        |
| Front Left Side:  | Continental 6 mm | Rear Left Side:  | Continental 6 mm |
| Front Right Side: | Continental 6 mm | Rear Right Side: | Continental 6 mm |

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

|                                           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                     | 1,622.00        | 891.00          | 731.00          | 45.07        |
| Miscellaneous Items                       | 0.00            | 0.00            | 0.00            |              |
| Labour                                    | 2,300.00        | 1,100.00        | 1,200.00        | 52.17        |
| Paintwork Labour                          | 0.00            | 0.00            | 0.00            |              |
| Towing                                    | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (\$\$)</b>      | <b>3,922.00</b> | <b>1,991.00</b> | <b>1,931.00</b> | <b>49.24</b> |
| <b>Approved Total (Overridden) (\$\$)</b> |                 | <b>1,600.00</b> |                 |              |
| <b>(\$\$)</b>                             | 3,922.00        | 1,600.00        | 2,322.00        | 59.20        |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 274.54          | 112.00          | 162.54          | 59.20        |
| <b>Nett Amount (\$\$)</b>                 | <b>4,196.54</b> | <b>1,712.00</b> | <b>2,484.54</b> | <b>59.20</b> |

### INSPECTION

|                             |            |                                                                                                  |
|-----------------------------|------------|--------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 03/09/2019 |                                                                                                  |
| Date Inspected:             | 16/08/2019 | Inspected At: ASM Automotive Services Pte Ltd (HQ)<br>No.13 Pioneer Sector 1<br>Singapore 628424 |
| Estimated Period of Repair: | 5.0 days   |                                                                                                  |

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                    |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 06 Sep 2019)                      |
| <b>Parts:</b>        | 143                                                                                                                                                                          | TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SJL8682Y)                                                                                                                                    |                                                                    |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                    |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                    |

### Recommended Parts

| No. | Qty | Part No. | Particulars                | Condition   | Repairer's | Amount     |
|-----|-----|----------|----------------------------|-------------|------------|------------|
| 1   | 1   |          | *RADIATOR GRILLE           | Serviceable | 250.00 FL  | *- FL      |
| 2   | 1   |          | *HEADLAMP,LH               | Scratched   | 340.00 FL  | *340.00 FL |
| 3   | 1   |          | *SIDE FENDER,LH FRONT      | Bent        | 405.00 FL  | *405.00 FL |
| 4   | 1   |          | *HEADLAMP,RH               | Serviceable | 340.00 FL  | *- FL      |
| 5   | 1   |          | *FRONT BUMPER              | Cracked     | 375.00 FL  | *375.00 FL |
| 6   | 1   |          | *BUMPER GRILLE,CENTER      | Serviceable | 110.00 FL  | *- FL      |
| 7   | 1   |          | *BUMPER SIDE SUPPORT,LH    | Missing     | 68.00 FL   | *68.00 FL  |
| 8   | 1   |          | *BUMPER SIDE SUPPORT,RH    | Serviceable | 68.00 FL   | *- FL      |
| 9   | 1   |          | *ENGINE UNDER COVER        | Serviceable | 160.00 FL  | *- FL      |
| 10  | 1   |          | *FRONT EMBOSS NUMBER PLATE | Serviceable | 35.00 FS   | *- FS      |

F=Franchise part. S=SpcNett, L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>2,151.00</b> | <b>1,188.00</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>529.00</b>   | <b>297.00</b>   |
| <b>Total Parts (\$\$)</b>                                  | <b>1,622.00</b> | <b>891.00</b>   |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                             | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                         |          |                 |                 |
| 1                               | TO REMOVE AND REPLACE DAMAGED PARTS,REALIGNMENT & CHECK LAMP WIRING ETC | New      | 1,500.00        | 500.00          |
| 2                               | SPRAY PAINTING                                                          | New      | 800.00          | 600.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                         |          | <b>2,300.00</b> | <b>1,100.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >