

INS. CASE OWNER:

NG Stacey

CC4/ASM19014320/ G pa3

LKK: 131848
IDAC:

Surveyor:

XGQ

DOI:


ASSIGNMENT

19/8/19

Date / Time : 16/08/2019

Registered in Merimen: _____

Pre-assign / CCU / FTE



Insured Vehicle No. : XE 1606K Claim No. : S9M01X6X
 Name of Insured : T B C TRANSPORTATION & TRADING PTE LTD Policy No. : _____
 Insured Tel No. : _____ HP: 6567 4755 Make / Model : _____
 Excess Sec II :S\$ _____ D.O.A : 13/08/2019 Place of Accident : _____
 Is driver the owner? (YES NO) Nature of Accident : _____
 If NO, Driver Name / Age : _____ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Driver Tel No. : _____ (V/L: YES / NO) Insured Liability : % Final ? Yes / No

GBJ 5178L



INSRS:
WSP: YONG SING
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	GBJ 5178L - X	XE 1606K - X	STAGE	DATE / PIC
16/08/2019	OINR. To send out first letter. File pass to Su Li.		Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
			After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
			Authorisation To Act:	<input type="checkbox"/> <input type="checkbox"/>
			Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>
			Final Repair Bill:	<input type="checkbox"/> <input type="checkbox"/>
			Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
			Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
			LTA / GIA :	<input type="checkbox"/> <input type="checkbox"/>
			Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
			PIR:	<input type="checkbox"/> <input type="checkbox"/>
			Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
			LOD	<input type="checkbox"/> <input type="checkbox"/>
			Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
			Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
			Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
 Repair Cost: S\$ _____ (_____ days) Reduction: % _____ Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with _____ Email Call

Final Liability: % _____ (Agreed / Assessed) BOLA S/N No. : _____ If NO or B 28, Ass. Lia : _____
 Repair Cost: S\$ _____
 Loss of Rental (LOR): S\$ _____ (_____ days)
 Loss of Use (LOU): S\$ _____ (\$ x _____ days)
 Loss of Income (LOI): S\$ _____ (\$ x _____ days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
 GIA/LTA Search S\$ _____
 Medical: S\$ _____
 Disbursement: S\$ _____ (e.g. Tow/ Independent)
 Legal Cost S\$ _____
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format:
 3) Survey fee:

Total: S\$ _____ **Global Sum S\$:** _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: S\$ _____ Name 1: _____
 Payee 2: (Strike if N.A.) S\$ _____ Name 2: _____
 Payee 3: (Strike if N.A.) S\$ _____ Name 3: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	386K
Vehicle No.:	GBJ5178L
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 MANUAL
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	1KD2851350
Chassis No.:	KDY2318038154
Maximum Power Output:	-
Open Market Value:	\$33,209.00
Original Registration Date:	09 May 2019
First Registration Date:	09 May 2019
Transfer Count:	0
Actual ARF Paid:	\$1,661.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	08 May 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$27,264.00
COE Rebate Amount:	\$26,497.00
Total Rebate Amount:	\$26,497.00

The information contained herein is correct as at 19 Aug 2019

OK


Yong Sing Estimate Repair

Section A - To be completed by Claims Advisor

Vehicle Registration Number : GBJ5178L
 Make / Model : DYNA 3.0 MANUAL
 Chassis No : KDY2318038154
 Year of Manufacture : 2019
 Registration Date : 9-May-19
 Type of Repair (TP/OD/WS) : TP
 Date/Time of Accident : 13/8/2019 13:00
 Rental Vehicle : Yes No
 Remark : TP

Case Ref. : YS/19/0071
 No. _____

The damages on the vehicle are as indicated in the following diagram :



	Yong Sing estimate breakdown cost	Adjusted by Surveyor, if applicable
Total Labour Cost	\$ 4,000.00	\$ -
Total Spray Painting Cost	\$ 5,800.00	\$ -
Total Spare Parts Cost	\$ 45,698.78	\$ -
Other Charges	\$ 3,580.00	\$ -
TOTAL	\$ 59,078.78	\$ -

Lump Sum Repair, if any : _____

No. of Repair Days : [18] days [] days

SURVEYOR'S Remark

3 Pans.
 Lump sum repair.
 After repair photos.
 Gino Qianp - 82880282
 19/8/19.

L&L Asia Carwash have notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Part 1 - Labour & Panel Beating Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO REMOVE & INSTALL ALL REPLACE ITEM, TO REPAIR REAR PORTION	\$4,000.00	200 ?
Total Labour Cost	\$4,000.00	\$0.00

Part 2 - Spray Painting Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO RESPRAY RAIL, FRAME SIDE, REAR LH	\$600.00	X
TO RESPRAY RAIL, FRAME SIDE, REAR RH	\$600.00	X
TO RESPRAY GATE ASSY, REAR BODY TAIL	\$800.00	X
TO RESPRAY PANEL ASSY, REAR BODY SIDE, RH	\$800.00	0 200
TO RESPRAY PANEL ASSY, REAR BODY SIDE, LH	\$800.00	X
TO REPSRAY CROSSMEMBER, FRAME, REAR	\$600.00	X
TO RESPRAY CROSSMEMBER SUB-ASSY, FRAME, NO.6	\$600.00	X
TO RESPRAY GUARD ASSY, REAR BODY	\$1,000.00	X
Total Spray Painting Cost	\$5,800.00	\$0.00

Part 3 - Other Costs - Accident Repair Related Expenses

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO TEST, REMOVE AND REFIT REVERSE SENSOR SYSTEM	\$200.00	X
TO REMOVE AND REFIT REAR DECK CHECKER AND CANOPY	\$1,000.00	X
TO PROVIDE ANTI RUST COATING	\$400.00	X
TO CONDUCT WIRE CHECKING	\$250.00	X
TO VACCUMM AND CLEAN ON INTERIOR	\$80.00	X
TO CHECK WATER LEAKAGE ON INSTALLED PARTS	\$200.00	X
TO REMOVE AND REFIT EXHUAST TAIL PIPE	\$400.00	X
TO DO 4 WHEEL ALIGNMENT TYRE BALANCING	\$250.00	X
TO REMOVE AND REFIT REAR SPARE TYRE	\$300.00	X
TO REMOVE AND REFIT UNDERCARRIAGE COMPARTMENT	\$500.00	X
Total Other Costs	\$3,580.00	\$0.00

Part 4 - Spare Parts / Material Usage

Item	Part Name	Part No	Qty	List Price (\$)	Discount (25%)	Final Price (\$)	Repair @ Replace (/) (Yong Sing Request)	Repair @ Replace (/) (Surveyor Recommend)
1	GATE ASSY, REAR BODY TAIL X	6570025051	1	\$ 2,000.00	25%	\$ 1,500.00	Replace	
2	HANDLE, TAIL GATE LATCH, RH X	6626437010	1	\$ 322.00	25%	\$ 241.50	Replace	
3	HANDLE, TAIL GATE LATCH, LH X	6626537010	1	\$ 322.00	25%	\$ 241.50	Replace	
4	HINGE ASSY, TAIL GATE X	6611037010	2	\$ 700.00	25%	\$ 525.00	Replace	
5	CAP, GATE LATCH HANDLE X	6616587402	2	\$ 211.00	25%	\$ 158.25	Replace	
6	PLUG, HOLE(FOR TAIL GATE) X	9095001430	2	\$ 255.00	25%	\$ 191.25	Replace	
7	CHAIN ASSY, TAIL GATE X	6628037030	2	\$ 155.00	25%	\$ 116.25	Replace	
8	SUPPORT SUB-ASSY, CORNER, RH X	6550737040	1	\$ 355.00	25%	\$ 266.25	Replace	
9	SUPPORT SUB-ASSY, CORNER, LH X	6550837040	1	\$ 355.00	25%	\$ 266.25	Replace	
10	PANEL ASSY, REAR BODY SIDE, RH X	6550025250	1	\$ 2,100.00	25%	\$ 1,575.00	Replace	
11	PANEL ASSY, REAR BODY SIDE, LH X	6560025250	1	\$ 2,100.00	25%	\$ 1,575.00	Replace	
12	PANEL ASSY REAR BODY SIDE HANDRAIL LH X		1	\$ 1,200.00	25%	\$ 900.00	Replace	
13	PANEL ASSY REAR BODY SIDE HANDRAIL RH X		1	\$ 1,200.00	25%	\$ 900.00	Replace	
14	REAR DECK CANOPY BT			\$ 3,500.00 ?	25%	\$ 2,625.00	Replace	
15	HINGE ASSY, SIDE GATE, NO.1 RH X	6501037040	1	\$ 322.20	25%	\$ 241.65	Replace	
16	HINGE ASSY, SIDE GATE, NO.2 RH X	6505037080	1	\$ 322.20	25%	\$ 241.65	Replace	
17	HINGE ASSY, SIDE GATE, NO.1 LH X	6501037042	1	\$ 310.30	25%	\$ 232.73	Replace	
18	HINGE ASSY, SIDE GATE, NO.2 LH X	6505037080	1	\$ 310.30	25%	\$ 232.73	Replace	
19	SEAL, SIDE GATE X	6567937010	2	\$ 443.20	25%	\$ 332.40	Replace	
20	LATCH, SIDE GATE FEMALE, RH NO. 1 X	6615192703	1	\$ 342.22	25%	\$ 256.67	Replace	
21	LATCH, SIDE GATE FEMALE, LH NO. 1 X	6615292703	1	\$ 342.22	25%	\$ 256.67	Replace	
22	LATCH, TAIL GATE FEMALE, RH NO. 2 X	6615337010	1	\$ 342.22	25%	\$ 256.67	Replace	
23	LATCH, TAIL GATE FEMALE, LH NO. 2 X	6615437010	1	\$ 342.22	25%	\$ 256.67	Replace	
24	HANDLE, SIDE GATE LATCH, CENTER NO.2 X	6618737011	2	\$ 672.90	25%	\$ 504.68	Replace	
25	GUARD ASSY, REAR BODY X	6540025691	1	\$ 2,500.00	25%	\$ 1,875.00	Replace	
26	STOP, GUARD FRAME LOAD SLIDE, LH X	6549225020	1	\$ 420.20	25%	\$ 315.15	Replace	
27	STOP, GUARD FRAME LOAD SLIDE, RH X	6549137010	1	\$ 420.20	25%	\$ 315.15	Replace	
28	HANDLE ASSY, SIDE GATE LATCH X	6508092701	2	\$ 772.00	25%	\$ 579.00	Replace	
29	PLATE, BAFFLE DUST REAR BODY X	6545737060	1	\$ 720.00	25%	\$ 540.00	Replace	
30	PLATE, FLOOR BOARD, FRONT X	6532537020	1	\$ 544.00	25%	\$ 408.00	Replace	
31	FLOOR ASSY, REAR BODY X	651002E07 1	1	\$ 2,122.00	25%	\$ 1,591.50	Replace	
32	FRAME SUB-ASSY, FLOOR SIDE, RH X	6530325420	1	\$ 1,000.00	25%	\$ 750.00	Replace	
33	FRAME SUB-ASSY, FLOOR SIDE, LH X	6530425361	1	\$ 1,000.00	25%	\$ 750.00	Replace	
34	PLATE, REAR FENDER, UPPER X	6620325010	1	\$ 677.00	25%	\$ 507.75	Replace	
35	FRAME SUB-ASSY, FLOOR, REAR X	6530725120	1	\$ 740.00	25%	\$ 555.00	Replace	
36	REAR DECK FLOOR CHECKER PLATE X		1	\$ 1,500.00	25%	\$ 1,125.00	Replace	
37	STICKER 70KM/H X		1	\$ 50.00	25%	\$ 37.50	Replace	
38	REFLECTOR ASSY, REFLEX, REAR X	8191025041	2	\$ 700.00	25%	\$ 525.00	Replace	
39	REFLECTOR ASSY, REFLEX, RH X	8191095A01	1	\$ 300.00	25%	\$ 225.00	Replace	
40	REFLECTOR ASSY, REFLEX, LH X	8191095A01	1	\$ 300.00	25%	\$ 225.00	Replace	
41	LAMP ASSY, REAR COMBINATION, RH X	8155025110	1	\$ 655.00	25%	\$ 491.25	Replace	
42	LAMP ASSY, REAR COMBINATION, LH X	8156025100	1	\$ 655.00	25%	\$ 491.25	Replace	
43	LAMP ASSY, LICENSE PLATE X	8127025030	2	\$ 344.00	25%	\$ 258.00	Replace	
44	NUMBER PLATE W/ FRAME X		1	\$ 50.00	0%	\$ 50.00	Replace	

45	SENSOR REVERSE X		1	\$ 500.00	25%	\$ 375.00	Replace
46	CROSSMEMBER, FRAME, REAR X	5129125030		\$ 906.20	25%	\$ 679.65	Replace
47	CROSSMEMBER SUB-ASSY, FRAME, NO.6 X	5120625150		\$ 977.80	25%	\$ 733.35	Replace
48	RAIL, FRAME SIDE, REAR LH X	5111625040		\$ 1,800.00	25%	\$ 1,350.00	Replace
49	RAIL, FRAME SIDE, REAR RH / BT X	5111525100		\$ 1,800.00 ?	25%	\$ 1,350.00	Replace
50	STICKER (SKYLINK AUTO PTE LTD) X		1	\$ 1,000.00	25%	\$ 750.00	Replace
51	STICKER (DYNA) X		1	\$ 100.00	25%	\$ 75.00	Replace
52	STICKER (1500KG) X		1	\$ 100.00	25%	\$ 75.00	Replace
53	PIPE ASSY, EXHAUST, TAIL X	1743030120	1	\$ 2,122.00	25%	\$ 1,591.50	Replace
54	TOOLBOX W/LOCKER LH X		1	\$ 1,500.00	25%	\$ 1,125.00	Replace
55	CARRIER ASSY, SPARE WHEEL X	5190025110	1	\$ 521.40	25%	\$ 391.05	Replace
56	PLATE, SPARE WHEEL CARRIER BASE X	5193125070	1	\$ 377.00	25%	\$ 282.75	Replace
				TOTAL MATERIALS \$ 45,698.78		\$ 34,286.59	

Survey record

Workshop: <u>YONG SING MOTOR WORKS</u>	
Vehicle No. <u>G15 5178L</u>	Date of accident:

Name of TP insurer company _____
Surveyor's firm and name UKF - GMA Org.
Contact no. 8288 0282

<u>1st PRS conducted</u>	
Date <u>19/8/19</u>	Time
Name <u>GMA Org</u>	Signature <u>[Signature]</u>
Require of Resurvey Hidden/Check items	<input checked="" type="radio"/> Yes / No

Inform surveyor: Date/Time	<u>2nd PRS conducted - Hidden/Check damages items</u>	
	Date	Time
	Name	Signature
	Require of Resurvey after repair : Yes / No	

Inform surveyor: Date/Time	<u>3rd PRS conducted - After repairs</u>	
	Date	Time
	Name	Signature