

45	SENSOR REVERSE	X		1	\$ 500.00	25%	\$ 375.00	Replace	
46	CROSSMEMBER, FRAME, REAR	X	5129125030		\$ 906.20	25%	\$ 679.65	Replace	
47	CROSSMEMBER SUB-ASSY, FRAME, NO.6	X	5120625150		\$ 977.80	25%	\$ 733.35	Replace	
48	RAIL, FRAME SIDE, REAR LH	X	5111525040		\$ 1,800.00	25%	\$ 1,350.00	Replace	
49	RAIL, FRAME SIDE, REAR RH	X BT	5111525100		\$ 1,800.00	25%	\$ 1,350.00	Replace	250 (SN)
50	STICKER (SKYLINK AUTO PTE LTD)	X		1	\$ 1,000.00	25%	\$ 750.00	Replace	
51	STICKER (DYNA)	X nn		1	\$ 100.00	25%	\$ 75.00	Replace	
52	STICKER (1500KG)	X nn		1	\$ 100.00	25%	\$ 75.00	Replace	
53	PIPE ASSY, EXHAUST, TAIL	X	1743030120		\$ 2,122.00	25%	\$ 1,591.50	Replace	
54	TOOLBOX W/LOCKER LH	X		1	\$ 1,500.00	25%	\$ 1,125.00	Replace	
55	CARRIER ASSY, SPARE WHEEL	X	5190025110		\$ 521.40	25%	\$ 391.05	Replace	
56	PLATE, SPARE WHEEL CARRIER BASE	X	5193125070		\$ 377.00	25%	\$ 282.75	Replace	
TOTAL MATERIALS					\$ 45,698.78		\$ 34,286.59		

47,654.08#

B95
 25% : 1046.25
 SN : 860
 900
 2806.25
 6 Days.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: