

ASS. REC. BY:

REF: CF/MSG19014367/cqf3

Special Instruction:

Surveyor: smm

ASSIGNMENT (Office)

minimum

From (Person): Jasmin lot King King of MS29

Date/Time: 13.8.19 18.46pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GB C 3178 L

Insured: YP 61442

at Workshop m/s Ryder Auto

Tel: 90 908277

of 2 Kaki Bukit Ave 2 #02-19

Policy No: 29119268 MKC

Claim No: 597369

Sum Insured:

Excess:

Make of Veh:

D.O.A. 24.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14.8.19

Person Contacted: Orson

Vehicle IN/OUT

Date/Time	Action/Instruction
	() Estimate
	GB C 3178 L - CC3/TM1 15008073 City 363 RPA - 26/05/2015
	YP 61442 - CS1 MSG 190166 4010743 RPA - 27/07/2019
	cancel ll Ryder feedback to MSG don't want us to finalise. Cancel 20/9/19.

**MSIG**

MSIG Insurance (Singapore Pte. Ltd)

(Co. Reg. No 200412212G)

4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

www.msig.com.sg*Ryder*Executive
Claims Services**Inspection Report****Type of Survey:**

OD - Excess	
TP Without Prejudice	☒

Vehicle Details:

Vehicle Reg No
Make
Model
Passenger capacity
Paint colour & code
Paint type

ABC 3178L
Urvan Nissan
Urvan 3.0 MT
02
Grey

Vehicle Extras:

In-built camera
Modification

Yes / No
Yes / ☒ No

Vehicle Data:

Odometer reading
Engine No
VIN No
Engine capacity
Engine modification

253136 km

Vehicle Condition:

Seviceable Yes / No

Handbrake
Footbrake
Steering
Body
Paint

Tyre Condition:

Front right
Front left
Rear left
Rear right

Tread mm	Size	Condition
5	Yokohama 195 / R 15	
5	u	
4	u	
4	u	

General Data:

Date of accident
Date of inspection
Date of assignment
Inspection location

24-06-19
25-06-19
24-06-19
Ryder.

Painting Process:

Prepare off vehicle
Painting off vehicle
Neither (default)

Cost Details:

Parts
Supplementary
Miscellaneous
Body Labour
Paint labour
Paint material
TOTAL
Towing
Excess
Total less excess
Estimated days for repair

Repairer	Adjuster

Body Panel Repair:

Panel repair calculator used
Yes / No

--

Remarks:

Lump / Global Sum

--

Reason(s)

Margin Repair / Fast-line

Others:

Repair Authorised
Date:

--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jun 2019		13 Aug 2019 18:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MAC-NELS (KD) TERMINAL PTE LTD, Co. Reg. No.: 198901670D								
Main Claimant:	BPH TRADING & TRANSPORTATION SERVICES, Co. Reg. No.: 53045226W								
Vehicle Reg. No.:	GBC3178L	Date of Loss:	24/06/2019 00:00 - :59 [90 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 597369	Policy/Cover Note No.:	29119268MKC Coverage: 15/03/2019 - 06/04/2020						
Vehicle Reg. No. (Insured):	YP6144Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, 417921 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/08/2019]								
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. (manual assigned) Liab: dispute (OI NR). Contact: Mr Orson @ 90908277 / Mr Chan @ 97924673.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



MSIG

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

www.msig.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____

Date : _____

Policy No : _____

Claim No : _____

Insured Vehicle No : YP 6144Z Date of Accident : 24-06-19

TP Vehicle No : GBC 3178L Place of Survey : Ryder

Make & Model : Hissan Urvan Date of Survey : 25-06-19

Point of Impact / Damages :


Rear and Front

Recommended Reserve :

Repairer's Estimate : \$ 24617.83

Interim Adjustment : \$ 16074.50

Check Items : \$ -



Proposed : Part by Part / Lump Sum Repair \$12859.60 Excess : \$ -

Estimate Repair Period : 12 days

Pre-accident Market Value (for total loss consideration) : \$ 20800.00

COE / PARF to owner : \$ 7288.00

Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☐ OD Claim
Excess : \$ _____
(Authorised / Revert)

☒ TP Claim
(Without Prejudice)

Vehicle No. GBC 3178L

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos.

Number of Repair Days 12 days.

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 25-06-19

Victor Seng @ sg.msig-asia.com

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

GBC3178L Pg 1/2

Veh # : GBC3178L Model : NISSAN URVAN (29/11/2011)

Date Of Accident : 24/6/19 3P : YP6144Z (MSIG)

Location : KJE TOWARD PIE BEFORE LAM SAM FLYOVER

S/Nos.	Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
		List Items				
1	1 pc	Rear bumper / Deformed			796.20	
2	2 pcs	Rear bumper o/s & n/s corner clips / necc			100.145.40	
3	1 pc	Rear tail-gate / Deformed			2,986.20	?
4	1 pc	Rear tail-gate lower panel / Deformed			1,076.20	
5	1 pc	Rear o/s tail-lamp panel (Outer) X			986.20	
6	1 pc	Rear o/s tail-lamp panel (Inner) X Deformed			897.20	
7	1 pc	Rear o/s fuel tank cover / Deformed			202.60	
8	1 pc	Front bumper / Deformed			858.60	
9	1 pc	Front bumper o/s fog lamp bracket / Deformed X			73.55	
10	1 pc	Front panel X			872.20	
		Sub-Total			8,894.35	
		After -30%			6,226.05	
		Special Nett Items				
1	1 pc	Rear reg. no. plate / Deformed			45.00	
2	1 pc	Rear reg. no. plate bracket / Deformed			29.00	
3	1 set	Rear reverse sensor / short / Deformed			280.00	200
4	1 pc	Rear windscreen sealant / necc			80.00	
5	1 pc	Rear windscreen inner seal / Deformed			60.00	
6	1 pc	Front reg. no. plate / Deformed			45.00	
7	1 pc	Front windscreen sealant X			80.00	
8	1 pc	Front windscreen inner seal X			60.00	
9	1 pc	Rear tail-gate 70 kmph emblem / necc			25.00	
10	1 pc	Rear tail-gate 6 PAX emblem / necc			25.00	
		5382.68 Sub-Total			729.00	
		Nett Items				
1	1 pc	Rear bumper enforcement X Deformed			407.40	
2	10 pcs	Rear bumper clips / necc			30.00	
3	1 pc	Rear bumper step fabric / Deformed			396.20	
4	1 pc	Rear tail-gate weatherstrip / Deformed			421.60	
5	2 pcs	Rear tail-gate o/s & n/s stopper (Male) X			242.00	
6	2 pcs	Rear tail-gate o/s & n/s stopper (Female) X			264.00	
7	2 pcs	Rear tail-gate o/s & n/s hinges X			388.20	
8	1 pc	Rear tail-gate garnish (Outer) / Deformed			228.60	
9	1 pc	Rear tail-gate lock (Upper) / Deformed			246.20	
10	1 pc	Rear tail-gate lock (Lower) / Deformed			106.10	
11	1 pc	Rear tail-gate inner board / Cracked			206.20	
12	10 pcs	Rear tail-gate inner board clips / necc			30.00	
13	1 pc	Rear tail-gate wiper arm / Deformed			196.20	

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

GBC3178L Pg 2/2

S/Nos.	Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
14	1 pc	Rear tail-gate wiper blade <i>/ Deformed</i>			21.20	
15	1 pc	Rear tail-gate wiper motor <i>X</i>			496.20	
16	2 pcs	Rear o/s & n/s tail-lamp <i>/ Cracked</i>			797.20	
17	2 pcs	Rear o/s & n/s tail-lamp sealant <i>X</i>			797.20	
18	4 pcs	Rear o/s & n/s tail-lamp clips <i>/ necc</i>			12.00	
19	1 pc	Rear o/s body panel <i>/ Deformed</i>			2,697.40	? Price
20	1 pc	Rear o/s fuel tank pipe <i>X</i>			196.20	
21	1 pc	Rear o/s fuel tank hose <i>X</i>			106.20	
22	1 pc	Rear windscreen <i>/ shattered</i>			2,196.10	? Price
23	10 pcs	Front bumper clips <i>/ necc</i>			30.00	
24	1 pc	Front bumper enforcement <i>/ Deformed</i>			429.60	
25	1 pc	Front bumper o/s retainer <i>/ cracked</i>			101.30	
26	1 pc	Front bumper o/s corner clips <i>/ necc</i>			110.85	
27	1 pc	Front bumper o/s fog lamp <i>/ cracked</i>			324.80	
28	1 pc	Front bumper o/s fog lamp garnish <i>/ cracked</i>			96.20	
29	1 pc	Front grille <i>/ cracked</i>			494.10	
30	1 pc	Front grille emblem <i>/ missing</i>			96.00	
31	4 pcs	Front grille clips <i>/ necc</i>			12.00	
32	1 pc	Front o/s head-lamp <i>/ cracked</i>			952.20	?
33	2 pcs	Front o/s head-lamp clips <i>/ necc</i>			6.00	
34	1 pc	Front o/s lamp <i>/ cracked</i>			423.20	
		Sub-Total			13,558.65	
		After -10%			12,202.79	
		Labour				
1		To dismantle damaged parts, straighten and welding.	2100	1400	2400.00	
2		To spray painting.	1500	1400	1600.00	
3		To re-align rear chassis frame.			150 280.00	
4		To remove and replace rear windscreen.			100 180.00	
5		To remove and replace rear reverse sensor.			80 120.00	
6		To remove and refit front instrument and front windscreen.			120 500.00	
7		To check wiring.			60 120.00	
8		To re-seal anti-rust.			120 260.00	
		Sub-Total			5,460.00	
		Total			24,617.83	
		After -20%			19,694.26	

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

BOK SENG
(heavy vehicles, marine vessels)

Authorised Workshop
Authorised Reporting Centre

8778 1999
24 hr accident call

Mobil 1 *bigSAFE*

12 days
25/06/19 @ 1300hrs.
Victor - Seng @ sg.msig-asia.com
87747011
w/o prejudice
L/S After paint.

14574.56