

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CF/MSG19014369/DQF3E2
Date: 17/01/2020**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant Vehicle No :	SKH406R	Insured Vehicle No :	SLM806G
Date of Loss:	22/07/2019	Nature of Claim:	TP
		Claim No:	600790

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH406R	Engine No:	ZYB10777
Make & Model:	MAZDA 2, 1.5 (A)	Chassis No:	JM6DE10Y2C0231770
Reg. Date:	30/10/2012 (Man. Year: 2012)	Odometer:	41514 km
Colour:	White		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,598.56	1,960.40	5,638.16	74.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	1,590.00	3,210.00	66.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,398.56	3,550.40	8,848.16	71.36
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	12,398.56	2,800.00	9,598.56	77.42
+ GST 7.00/7.00% (S\$)	867.90	196.00	671.90	77.42
Nett Amount (S\$)	13,266.46	2,996.00	10,270.46	77.42

INSPECTION

Date of Assignment:	13/08/2019	
Date Inspected:	24/07/2019 Inspected At:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Jan 2020)
Parts: 143	MAZDA 2 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: LKK Auto Consultants Pte Ltd/SKH406R/17/01/2020 17:11	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Deformed	975.10 FL	*975.10 FL
2	2		*REAR DOOR HINGE RH	Not Necessary	79.80 FL	*- FL
3	1		*REAR DOOR WEATHER STRIP RH	Necessary	141.00 FL	*141.00 FL
4	1		*REAR DOOR INNER LOCK RH	Not Necessary	276.80 FL	*- FL
5	1		*REAR DOOR GLASS REGULATOR GEAR MOTOR RH	Not Necessary	545.60 FL	*- FL
6	1		*REAR DOOR OUTER MOULDING RH	Necessary	52.80 FL	*52.80 FL
7	1		*REAR DOOR GLASS CHANNEL RH	Not Necessary	144.90 FL	*- FL
8	1		*REAR DOOR INNER TRIM BOARD RH	Not Necessary	764.80 FL	*- FL
9	1		*SIDE SKIRT RH	Cracked	694.10 FL	*694.10 FL
10	1		*REAR ABS SENSOR RH	Not Necessary	279.40 FL	*- FL
11	1		*REAR AXLE	Not Necessary	2,496.70 FL	*- FL
12	1		*REAR WHEEL HUP C/W BEARING RH	Not Necessary	595.40 FL	*- FL
13	1		*REAR SHOCK ABSORBER RH	Not Necessary	376.80 FL	*- FL
14	1		*REAR DOOR SEALANT RH	Necessary	150.00 FS	*50.00 FS
15	1		*SET REAR DOOR INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
16	1		*SET SIDE SKIRT CLIP RH	Necessary	50.00 FS	*40.00 FS
17	1		*REAR WHEEL TYRE RH	Not Necessary	480.00 FS	*- FS
18	1		*REAR WHEEL RIM RH	Grazed	850.00 FS	*350.00 FS
19	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
20	1		*BRAKE OIL	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,083.20	2,333.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,484.64	372.60
Total Parts (S\$)	7,598.56	1,960.40

LKK Auto Consultants Pte Ltd/SKH406R/17/01/2020 17:11. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	New	1,200.00	700.00
2	TO SPRAY PAINT	New	1,200.00	700.00
3	TUFF COAT	New	250.00	50.00
4	WIRING, BULB CHECKING	New	180.00	30.00
5	REMOVE & REFIX CUSHION SEAT / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	0.00
6	REMOVE & REFIX AUDIO SPEAKER	New	120.00	0.00
7	TRANSFER REAR DOOR MECHANISM	New	80.00	50.00
8	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
9	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	60.00
11	REMOVE AND REFIX REAR WINDOW GLASS	New	100.00	0.00
12	RESET ABS LIGHT	New	350.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
			Gross Labour Cost (\$)	4,800.00
				1,590.00

LKK Auto Consultants Pte Ltd/SKH406R/17/01/2020 17:11. Not valid without Reference section.

< END OF ESTIMATES >