

ASS. REC. BY:

REF: CF/MSG 190143731/D 9/30/19

Special Instructions:

Survey: smon

ASSIGNMENT (Office)

reimburse

From (Person): Enghwey Ni of MSIG Date/Time: 14/1/19 @ 4:34pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDW10506 Insured: SLH 665Y

at Workshop m/s Vision Autoworks Tel: 98564815.

of Bkeksi Bukit Ave #08-09

Policy No: 29114756 Claim No: 601359

Sum Insured: Excess:

Make of Veh: D.O.A. 26/7/19
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: Person Contacted: Michelle Vehicle: IN/OUT

| Date/Time | Action/Instruction | Signature |
|-----------|--|------------------|
| | SDW 10506 - VAL T.M2 19013241/13 | Don - 26/07/2019 |
| | SLH 665Y - VAL T.M2 19013241/13 | REA - 26/07/2019 |
| 17/1/200 | 4:34pm confirmed with Michelle LG to 11200, 8 days by email. clad to 12531.04, 537.7) | |

RECEIVED 20 JAN 2020

190
10
160



MSIG Insurance (Singapore Pte. Ltd) [Co. Reg. No 200412212G]
 4 Shenton Way. #27-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
 www.msig.com.sg

Executive
Claims Services

Inspection Report

Type of Survey:

| | |
|----------------------|-------------------------------------|
| OD - Excess | <input type="checkbox"/> |
| TP Without Prejudice | <input checked="" type="checkbox"/> |

Vehicle Data:

| | |
|---------------------|----------|
| Odometer reading | 17671 km |
| Engine No | |
| VIN No | |
| Engine capacity | |
| Engine modification | |

Vehicle Details:

| | |
|---------------------|-----------|
| Vehicle Reg No | SDW 1050E |
| Make | Honda |
| Model | Jazz |
| Passenger capacity | 05 |
| Paint colour & code | Silver |
| Paint type | |

Vehicle Condition:

| Seviceable | Yes / No |
|--------------------------|----------|
| <input type="checkbox"/> | |

Vehicle Extras:

In-built camera Yes / No
 Modification Yes / No

| Tyre Condition: | Tread mm | Size | Condition |
|-----------------|----------|----------------------|-----------|
| Front right | 5 | Dunlop 185 / 55 / 16 | |
| Front left | 5 | " | |
| Rear left | 4 | " | |
| Rear right | 4 | " | |

General Data:

| | |
|---------------------|----------|
| Date of accident | 26-01-19 |
| Date of inspection | 30-07-19 |
| Date of assignment | 29-07-19 |
| Inspection location | Vision |

Painting Process:

| | |
|----------------------|--------------------------|
| Prepare off vehicle | <input type="checkbox"/> |
| Painting off vehicle | <input type="checkbox"/> |
| Neither (default) | <input type="checkbox"/> |

Cost Details:

| | Repairer | Adjuster |
|---------------------------|----------|----------|
| Parts | | |
| Supplementary | | |
| Miscellaneous | | |
| Body Labour | | |
| Paint labour | | |
| Paint material | | |
| TOTAL | | |
| Towing | | |
| Excess | | |
| Total less excess | | |
| Estimated days for repair | | |

Body Panel Repair:

Panel repair calculator used
 Yes / No

Remarks:

Lump / Global Sum

Reason(s) Margin Repair / Fast-line

Others:

| |
|--|
| |
| |
| |

Repair Authorised Date:

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|---------|---------------|------------|---|
| Main | 27 Jul 2019 | | 14 Aug 2019 16:34 Assign | | | | New Assignment Cancel Case |

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

| | | | |
|-----------------------------|--|------------------------|--|
| Insured: | GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G | | |
| Main Claimant: | MS THIA GEOK HAR, ID: S1778419F | | |
| Vehicle Reg. No.: | SDW1050E | Date of Loss: | 26/07/2019 18:00 - :59 [31 Months and 13 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / 601359 | Policy/Cover Note No.: | 29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020 |
| Vehicle Reg. No. (Insured): | SLH665Y | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789 | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eng Huey NI - 6643 1314] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019] | | |
| Driver/Custodian (Insured): | NG JUI MENG (52 / Male) , NRIC: S1803608H Email: | | |
| Adj Asg. Remarks: | As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. OI: Grab. Liab: 100%, TP req for IHS. Contact : Michelle @ 9856 4815 | | |

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Shiau Chan (LKKAuto)

From: Vision Autowork <visionautowork@gmail.com>
Sent: Friday, 17 January 2020 4:34 PM
To: Shiau Chan (LKKAuto)
Subject: Re: SDW1050E (Dismantle photo)--3

Dear Shiau Chan,

Lump Sum 11,200.00 before GST and 8 repair days--OFFER ACCEPT

--

Thank You.

Yours Sincerely,

Michelle
HP : 9856 4815

8 Kaki Bukit Avenue 4
#08-09Premier @ Kaki Bukit
Singapore (415875)
Tel : 6341 6789
Fax : 6341 6778

On Fri, Jan 17, 2020 at 3:59 PM Shiau Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

Dear Michelle,

WITHOUT PREJUDICE

Re-offer Lump Sum 11,200.00 before GST and 8 repair days.

Kindly check.

Please note that the finalisation subject to insurer's approval.



PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____ Policy No : _____
 Date : _____ Claim No : _____


Insured Vehicle No : SLH 6657 Date of Accident : 26-07-19
 TP Vehicle No : SPW 1050E Place of Survey : Vision
 Make & Model : Honda Jazz Date of Survey : 30-07-19

Point of Impact / Damages :

Front

Recommended Reserve :

Repairer's Estimate : \$ 23731.04
 Interim Adjustment : \$ 17782.90
 Check Items : \$ -



Proposed : Part by Part / Lump Sum Repair \$142001- Excess : \$ -

Estimate Repair Period : 10 days

Pre-accident Market Value (for total loss consideration) : \$ 62000.00

COE / PARF to owner : \$ 46981.00

Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

OD Claim
Excess: \$ _____
(Authorised / Revert)

TP Claim
(Without Prejudice)

Vehicle No. SDW 1050E

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 10 days

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 30-07-19

Victor_Seng @ sg.msig-asia.com

Shiau Chan (LKKAuto)

From: Vision Autowork <visionautowork@gmail.com>
Sent: Friday, 11 October 2019 1:40 PM
To: Shiau Chan (LKKAuto)
Cc: Admin A; Jason_Sim@sg.msig-asia.com; Eng Huey Ni; Claims
Subject: Re: SDW1050E (Finalise)

Dear Shiau Chan,

We refer to the above matter.

We are unable to accept the COR that you offered on 10/10/2019, as there was a huge difference between the amount that recommended by the **MSIG-In House Surveyor** based on the markings on estimate (when he physically conducted the survey on the vehicle) and what you offered.

According to NIMA protocol, the appointed **MSIG-In House Surveyor** is agreed between the insurers (MSIG) and us (the workshop) to conduct the pre repair survey (SJE). Thus, there shouldn't be any dispute on the items that were recommended by the **MSIG In-House Surveyor** and marked with ticks. Furthermore the labour section also had been adjusted by the MSIG In-House Surveyor prior to confirmation.

Please re-adjust the cost of repair fair and reasonably; and note the photos of those items with question marking (clearly shown the damages) we sent to you on 05/09/2019.

We shall looking ahead for your reply soon.

Thank You

Yours faithfully,

Michelle
Hp: 9856 4815

8 Kaki Bukit Avenue 4,
#08-09, Premier @ Kaki Bukit,
Singapore 415875
Tel: 6341 6789
Fax: 6341 6778

On Thu, Oct 10, 2019 at 12:15 PM Shiau Chan (LKKAuto) <sjewsc@lkkauto.com> wrote:

Dear Michelle,

As spoken with you.

Shiau Chan (LKKAuto)

From: Vision Autowork <visionautowork@gmail.com>
Sent: Thursday, 22 August 2019 1:23 PM
To: Shiau Chan (LKKAuto)
Subject: SDW1050E (Finalise) DOA:26.07.19
Attachments: Picture2.jpg; Picture3.jpg; Picture1.jpg; 13082019142524.pdf

Dear Shiau Chan,

Please refer to attach document and after repair photos.

Can we close the case at **\$14,200.00 (8 days)**?

Thank You

Yours faithfully,

Michelle
Hp: 9856 4815

8 Kaki Bukit Avenue 4,
#08-09, Premier @ Kaki Bukit,
Singapore 415875
Tel: 6341 6789
Fax: 6341 6778

On Thu, Aug 22, 2019 at 11:56 AM Shiau Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

Dear Sir/Madam,

Kindly advise the status of below vehicles:

- | | |
|------------------------|-----------------|
| 1. SDW 1050E (MSIG-TP) | DOA: 26/07/2019 |
| 2. SKH 406R (MSIG-TP) | DOA: 22/07/2019 |

If done of repair, kindly send us the before or after paint photos and final bill for finalise.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd



MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
 www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: Eng Huey Ni

Date: 31 Jul 2019

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|--------------|
| Insured Vehicle No | : SLH665Y | Accident Date | : 26/07/2019 |
| TP Vehicle No | : SDW1050E | Assignment Date | : 29/07/2019 |
| Make | : HONDA JAZZ | Est. Duration of Repair | : 10.00 |
| Date of Inspection | : 30/07/2019 | | |
| Inspection At | : VISION AUTOWORK PTE LTD (HQ) 8 KAKI BUKIT AVE 4., #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front portion.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 23,731.04 |
| Revised Amount | :S\$ | 17,782.90 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | |

| | | |
|-----------------|------|--------|
| Lump Sum Repair | :S\$ | 14,200 |
|-----------------|------|--------|

Total Loss Consideration

| | | |
|--------------------|------|--------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 62,000 |
| COE / PARF Rebate | :S\$ | 46,981 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | |

Remarks

- (X) The vehicle is economical/~~not economical~~ for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------------|--------------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 419F |
| Vehicle Details | |
| Vehicle No.: | SDW1050E |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 05 Sep 2019 |
| Vehicle Make: | HONDA |
| Vehicle Model: | JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD |
| Primary Colour: | Silver |
| Manufacturing Year: | 2016 |
| Engine No.: | L15B31190537 |
| Chassis No.: | JHMGK5850HX200790 |
| Maximum Power Output: | 96.0 kW (128 bhp) |
| Open Market Value: | \$17,528.00 |
| Original Registration Date: | 13 Dec 2016 |
| First Registration Date: | 13 Dec 2016 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$12,528.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 12 Dec 2026 |
| PARF Rebate Amount: | \$9,396.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 12 Dec 2026 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$50,951.00 |
| COE Rebate Amount: | \$37,035.00 |
| Total Rebate Amount: | \$46,431.00 |

The information contained herein is correct as at 05 Sep 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

| Vehicle Details | | | |
|--|--------------------------------------|---------------------|---------------------------|
| Vehicle No.: | SDW1050E | | |
| Vehicle Type: | P10 - Passenger Motor Car | | |
| Vehicle Attachment 1: | No Attachment | | |
| Vehicle Scheme: | Normal | | |
| Vehicle Make: | HONDA | | |
| Vehicle Model: | JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD | | |
| Chassis No.: | JHMGK5850HX200790 | | |
| Propellant: | Petrol | | |
| Engine No.: | L15B31190537 | | |
| Engine Capacity: | 1498 cc | | |
| Maximum Power Output: | 96.0 kW (128 bhp) | | |
| Maximum Laden Weight: | 1490 kg | | |
| Unladen Weight: | 1046 kg | | |
| Year Of Manufacture: | 2016 | | |
| Original Registration Date: | 13 Dec 2016 | | |
| Lifespan Expiry Date: | - | | |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) | | |
| Quota Premium: | \$50,951.00 | | |
| COE Expiry Date: | 12 Dec 2026 | | |
| Road Tax Expiry Date: | 12 Dec 2019 | | |
| PARF Eligibility Expiry Date: | 12 Dec 2026 | | |
| Inspection Due Date: | 12 Dec 2019 | | |
| Intended Transfer Date: | 05 Sep 2019 | | |
| CO2 Emission: | 127.00 (g/km) | | |
| CEV/VES Rebate Utilised Amount: | \$5,000.00 | | |
| CO Emission: | - | | |
| HC Emission: | - | | |
| NOx Emission: | - | | |
| PM Emission: | - | | |
| Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable. | | | |
| Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred. | | | |
| Amount Payable | | | |
| | Amount Before GST (S\$) | GST Amount (S\$) | Amount After GST (S\$) |
| Transfer Fee: | 25.00 | - | 25.00 |
| Total Amount Payable: | | | 25.00 |

You may print this page for reference.

OK

Print

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 27.07.19

TO : **MSIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SDW1050E**
 MODEL : **HONDA JAZZ** 12/2016
 DATE OF ACCIDENT : 26.07.19
 TIME OF ACCIDENT : 18:40HRS

JHMRK58

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

| S/N | DESCRIPTION | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|--|-----|-----------------|------------------|
| 1 | FRONT BUMPER / cracked | 1 | \$ 801.20 | \$ 801.20 |
| 2 | FRONT BUMPER LOWER LIP X | 1 | \$ 80.40 | \$ 80.40 |
| 3 | FRONT BUMPER SIDE LAMP RH / cracked | 1 | \$ 217.40 | \$ 217.40 |
| 4 | FRONT BUMPER FOGLAMP COVER GRANISH / ^{RH} cracked | 2 | \$ 68.30 | \$ 136.60 |
| 5 | FRONT BUMPER FOGLAMP RH / cracked | 1 | \$ 291.60 | \$ 291.60 |
| 6 | FRONT BUMPER LOWER GRILLE / | 1 | \$ 180.40 | \$ 180.40 |
| 7 | FRONT BUMPER NUMBER PLATE HOLDER / Deformed | 1 | \$ 98.30 | \$ 98.30 |
| 8 | FRONT BUMPER TOW COVER / Cracked | 1 | \$ 40.10 | \$ 40.10 |
| 9 | FRONT BUMPER REINFORCEMENT / Deformed | 1 | \$ 326.30 | \$ 326.30 |
| 10 | FRONT BUMPER SIDE RETAINER / ^{RH} Cracked | 2 | \$ 18.40 | \$ 36.80 |
| 11 | ENGINE UNDER COVER X | 1 | \$ 306.30 | \$ 306.30 |
| 12 | ENGINE SIDE COVER GARNISH X | 2 | \$ 157.10 | \$ 314.20 |
| 13 | HEADLAMP (HID) / cracked RH-CNT | 1 | \$ 1,600.20 | \$ 1,600.20 |
| 14 | HEADLAMP LOWER BRACKET / cracked | 2 | \$ 38.20 | \$ 76.40 |
| 15 | FRONT GRILLE / cracked | 1 | \$ 352.20 | \$ 352.20 |
| 16 | FRONT GRILLE LOGO / none | 1 | \$ 29.40 | \$ 29.40 |
| 17 | FRONT GRILLE COVER GARNISH / cracked | 1 | \$ 176.20 | \$ 176.20 |
| 18 | FRONT GRILLE CENTER CHROME / cracked | 1 | \$ 148.90 | \$ 148.90 |
| 19 | FRONT GRILLE CENTER BRACKET / cracked | 1 | \$ 37.40 | \$ 37.40 |
| 20 | FRONT GRILLE INNER GARNISH | 1 | \$ 122.40 | \$ 122.40 |
| 21 | BONNET / Dented | 1 | \$ 650.20 | \$ 650.20 |
| 22 | BONNET TOP SIDE GARNISH / ^{RH} Cracked | 2 | \$ 124.80 | \$ 249.60 |
| 23 | BONNET INSULATOR X | 1 | \$ 179.20 | \$ 179.20 |
| 24 | BONNET LOCK / Dented | 1 | \$ 97.70 | \$ 97.70 |
| 25 | BONNET STOPPER X | 2 | \$ 17.20 | \$ 34.40 |
| 26 | BONNET HINGE X | 2 | \$ 83.20 | \$ 166.40 |
| 27 | BONNET INNER RUBBER / ^{RH} Torn | 1 | \$ 59.20 | \$ 59.20 |
| 28 | FRONT WIPER PANEL GARNISH X | 1 | \$ 287.50 | \$ 287.50 |
| 29 | FRONT SUPPORT PANEL / Deformed | 1 | \$ 590.40 | \$ 590.40 |

504.60

X NN

29.60

225.40

cap

X NN

X NN

X 1,140

✓ Δ

289

✓

X NS

X NN

X NN

X NN

BT

X NN

X NN

X SVC 59.20 ✓

X NN

BVC

TO : MSIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SDW1050E
 MODEL : HONDA JAZZ
 DATE OF ACCIDENT : 26.07.19
 TIME OF ACCIDENT : 18:40HRS

| | | | | | |
|----|------------------------------------|---|-------------|-------------|---------|
| 30 | FRONT SUPPORT LOWER APRON PANEL ? | 1 | \$ 196.50 | \$ 196.50 | X R |
| 31 | FRONT WASHER TANK / cracked | 1 | \$ 75.20 | \$ 75.20 | |
| 32 | AIR DUCT / cracked | 1 | \$ 79.40 | \$ 79.40 | |
| 33 | HORN / Dented | 2 | \$ 89.60 | \$ 179.20 | X NN |
| 34 | AIR CON CONDENSER / DD | 1 | \$ 850.80 | \$ 850.80 | 790 |
| 35 | AIR CON CONDENSER SWITCH X | 1 | \$ 65.30 | \$ 65.30 | X NN |
| 36 | AIR CON CONDENSER PIPE OR / Dented | 1 | \$ 398.10 | \$ 398.10 | |
| 37 | AIR CON CONDENSER SIDE GARNISH X | 2 | \$ 27.40 | \$ 54.80 | X NN |
| 38 | AIR CON COMPRESSOR / Dented | 1 | \$ 1,870.20 | \$ 1,870.20 | ? / |
| 39 | AIR CON PRESSURE HOSE R / Cracked | 1 | \$ 489.10 | \$ 489.10 | X NN |
| 40 | AIR CON SUCTION HOSE R / Cracked | 1 | \$ 398.70 | \$ 398.70 | X NN |
| 41 | AIR CON FAN COWLING / cracked | 1 | \$ 289.10 | \$ 289.10 | |
| 42 | AIR CON FAN MOTOR X | 1 | \$ 360.40 | \$ 360.40 | X NN |
| 43 | AIR CON BELT / missing | 1 | \$ 145.60 | \$ 145.60 | |
| 44 | RADIATOR / Dented | 1 | \$ 1,540.80 | \$ 1,540.80 | ? X SIC |
| 45 | RADIATOR RUBBER MOUNTING X | 4 | \$ 39.40 | \$ 157.60 | X NN |
| 46 | RADIATOR FAN MOTOR X | 1 | \$ 439.20 | \$ 439.20 | X NN |
| 47 | RADIATOR FAN COWLING / cracked | 1 | \$ 299.10 | \$ 299.10 | |
| 48 | RADIATOR FAN BLADE X | 1 | \$ 165.40 | \$ 165.40 | X |
| 49 | RADIATOR SPARE TANK X | 1 | \$ 76.90 | \$ 76.90 | X NN |
| 50 | RADIATOR HOSE (LOWER) X | 1 | \$ 68.20 | \$ 68.20 | X |
| 51 | WATER PUMP X | 1 | \$ 349.30 | \$ 349.30 | X |
| 52 | THERMOSTAT HOUSING X | 1 | \$ 395.50 | \$ 395.50 | X |
| 53 | RESORNATOR BOX / cracked | 1 | \$ 170.70 | \$ 170.70 | X NN |
| 54 | ALTERNATOR / cracked | 1 | \$ 1,894.70 | \$ 1,894.70 | |
| 55 | FRONT WIRE HARNESS HOLDER X | 1 | \$ 134.50 | \$ 134.50 | X NN |
| 56 | FRONT FENDER / Deformed | 2 | \$ 535.20 | \$ 1,070.40 | X NN |
| 57 | FRONT FENDER COLWING / Torn | 2 | \$ 171.60 | \$ 343.20 | X NN |

TOTAL PRICE \$ 21,963.80
 LESS 20% \$ 4,392.76
 SUB TOTAL PRICE \$ 17,571.04

| S/N | DESCRIPTION | QTY | UNIT S/NETT | TOTAL S/NETT | |
|-----|--------------------------------------|-----|-------------|--------------|-----|
| 1 | FRONT NUMBER PLATE | 1 | \$ 50.00 | \$ 50.00 | 120 |
| 2 | FRONT BUMPER CLIP (SET) | 1 | \$ 80.00 | \$ 80.00 | 30 |
| 3 | ENGINE UNDER COVER CLIP (SET) | 1 | \$ 30.00 | \$ 30.00 | 20 |
| 4 | ENGINE SIDE COVER GARNISH CLIP (SET) | 1 | \$ 30.00 | \$ 30.00 | 20 |
| 5 | BONNET SEALANT | 1 | \$ 150.00 | \$ 150.00 | X |

TO : MSIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SDW1050E
 MODEL : HONDA JAZZ
 DATE OF ACCIDENT : 26.07.19
 TIME OF ACCIDENT : 18:40HRS

| | | | | | |
|----|---|---|-----------|-----------|--------|
| 6 | BONNET INSULATOR CLIP (SET) | 1 | \$ 30.00 | \$ 30.00 | 15 |
| 7 | BONNET INNER RUBBER CLIP (SET) | 1 | \$ 40.00 | \$ 40.00 | 15X NN |
| 8 | BONNET TOP SIDE GARNISH CLIP (SET) | 1 | \$ 40.00 | \$ 40.00 | 15X NN |
| 9 | CENTER GRILLE CLIP (SET) | 1 | \$ 30.00 | \$ 30.00 | 20 |
| 10 | CENTER GRILLE COVER GARNISH CLIP (SET) | 1 | \$ 50.00 | \$ 50.00 | 20X NN |
| 11 | CENTER GRILLE INNER GARNISH CLIP (SET) | 1 | \$ 50.00 | \$ 50.00 | 20X NN |
| 12 | FRONT WIPER PANEL GARNISH CLIP (SET) | 1 | \$ 50.00 | \$ 50.00 | X NN |
| 13 | FRONT SUPPORT PANEL SEALANT | 1 | \$ 150.00 | \$ 150.00 | 60X |
| 14 | FRONT SUPPORT LOWER APRON PANEL SEALANT | 1 | \$ 120.00 | \$ 120.00 | X NN |
| 15 | AIR CON CONDENSER SIDE GARNISH CLIP (SE | 1 | \$ 40.00 | \$ 40.00 | 20 |
| 16 | FRONT FENDER COLWING CLIP (SET) | 1 | \$ 80.00 | \$ 80.00 | 40 |
| 17 | BETTERY | 1 | \$ 380.00 | \$ 380.00 | X NN |
| 18 | COOLANT | 1 | \$ 80.00 | \$ 80.00 | 40 NEC |

TOTAL \$ 1,480.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

| S/N | JOB DESCRIPTION | PRICE | ADJUSTED COST |
|-----|--|-------------|---------------|
| 1 | PANEL BEATING, REMOVING AND REPLACING PARTS | \$ 1,800.00 | 1200 700 |
| 2 | SPRAY PAINTING TO AFFECTED AREA | \$ 1,800.00 | 1000 |
| 3 | WIRING CHECK | \$ 180.00 | 80 30 |
| 4 | REMOVE AND REFIX AIRCON CONDENSOR AND AIR CON COMPRESSOR AND REFILL AIRCON GAS | \$ 120.00 | 60 |
| 5 | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST | \$ 80.00 | 60 |
| 6 | REMOVE AND REFIX ALTERNATOR | \$ 180.00 | 100 50 |
| 7 | REMOVE AND REFIX WATER PUMP | \$ 280.00 | 120 X |
| 8 | REFOCUS HEADLAMP BEAM | \$ 60.00 | 30 X |
| 9 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 180.00 | 80 X |

TOTAL \$ 4,680.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 19,051.04
 TOTAL LABOUR COST : \$ 4,680.00
 TOTAL REPAIR COST : \$ 23,731.04

8 days

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)
 8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Tel : 6341 6789 Fax: 6341 6778
 E-mail: visionautowork@gmail.com

** Request 8 days*

DATE : 27.07.19

TO : MSIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SDW1050E
 MODEL : HONDA JAZZ 12/2016
 DATE OF ACCIDENT : 26.07.19
 TIME OF ACCIDENT : 18:40HRS

FOR 10 days
\$ 14200.00

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.
 CLAIM DETAIL : PARTS

| S/N | DESCRIPTION | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|---|-----|-----------------|------------------|
| 1 | FRONT BUMPER / <i>cracked</i> | 1 | \$ 801.20 | \$ 801.20 |
| 2 | FRONT BUMPER LOWER LIP X | 1 | \$ 80.40 | \$ 80.40 |
| 3 | FRONT BUMPER SIDE LAMP RH / <i>cracked</i> | 1 | \$ 217.40 | \$ 217.40 |
| 4 | FRONT BUMPER FOGLAMP COVER GRANISH <i>cracked</i> | 1 | \$ 126.60 | \$ 126.60 |
| 5 | FRONT BUMPER FOGLAMP RH / <i>cracked</i> | 1 | \$ 291.60 | \$ 291.60 |
| 6 | FRONT BUMPER LOWER GRILLE / | 1 | \$ 180.40 | \$ 180.40 |
| 7 | FRONT BUMPER NUMBER PLATE HOLDER <i>delivered</i> | 1 | \$ 98.30 | \$ 98.30 |
| 8 | FRONT BUMPER TOW COVER / <i>delivered</i> | 1 | \$ 40.10 | \$ 40.10 |
| 9 | FRONT BUMPER REINFORCEMENT <i>delivered</i> | 1 | \$ 326.30 | \$ 326.30 |
| 10 | FRONT BUMPER SIDE RETAINER <i>2 LH Cracked</i> | 2 | \$ 16.40 | \$ 32.80 |
| 11 | ENGINE UNDER COVER X | 1 | \$ 306.30 | \$ 306.30 |
| 12 | ENGINE SIDE COVER GARNISH X | 2 | \$ 157.10 | \$ 314.20 |
| 13 | HEADLAMP (HID) / <i>cracked</i> | 2 | \$ 1,600.20 | \$ 3,200.40 |
| 14 | HEADLAMP LOWER BRACKET / <i>cracked</i> | 2 | \$ 38.20 | \$ 76.40 |
| 15 | FRONT GRILLE / <i>cracked</i> | 1 | \$ 352.20 | \$ 352.20 |
| 16 | FRONT GRILLE LOGO / <i>wacc</i> | 1 | \$ 29.40 | \$ 29.40 |
| 17 | FRONT GRILLE COVER GARNISH / <i>cracked</i> | 1 | \$ 176.20 | \$ 176.20 |
| 18 | FRONT GRILLE CENTER CHROME / <i>cracked</i> | 1 | \$ 148.90 | \$ 148.90 |
| 19 | FRONT GRILLE CENTER BRACKET / <i>cracked</i> | 1 | \$ 37.40 | \$ 37.40 |
| 20 | FRONT GRILLE INNER GARNISH | 1 | \$ 122.40 | \$ 122.40 |
| 21 | BONNET / <i>Painted</i> | 1 | \$ 650.20 | \$ 650.20 |
| 22 | BONNET TOP SIDE GARNISH <i>2 / delivered</i> | 2 | \$ 124.50 | \$ 249.00 |
| 23 | BONNET INSULATOR X | 1 | \$ 179.20 | \$ 179.20 |
| 24 | BONNET LOCK / <i>Painted</i> | 1 | \$ 97.70 | \$ 97.70 |
| 25 | BONNET STOPPER X | 2 | \$ 17.20 | \$ 34.40 |
| 26 | BONNET HINGE X | 2 | \$ 83.20 | \$ 166.40 |
| 27 | BONNET INNER RUBBER <i>2 / delivered</i> | 2 | \$ 89.20 | \$ 178.40 |
| 28 | FRONT WIPER PANEL GARNISH X | 1 | \$ 297.50 | \$ 297.50 |
| 29 | FRONT SUPPORT PANEL / <i>delivered</i> | 1 | \$ 590.40 | \$ 590.40 |

5971.90

TO : MSIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SDW1050E
 MODEL : HONDA JAZZ
 DATE OF ACCIDENT : 26.07.19
 TIME OF ACCIDENT : 18.40HRS

| | | | | |
|----|--|---|-------------|-------------|
| 30 | FRONT SUPPORT LOWER APRON PANEL ? | 1 | \$ 196.50 | \$ 196.50 |
| 31 | FRONT WASHER TANK / cracked | 1 | \$ 75.20 | \$ 75.20 |
| 32 | AIR DUCT / cracked | 1 | \$ 79.40 | \$ 79.40 |
| 33 | HORN / Dented | 2 | \$ 89.00 | \$ 179.20 |
| 34 | AIR CON CONDENSER / | 1 | \$ 850.80 | \$ 850.80 |
| 35 | AIR CON CONDENSER SWITCH X | 1 | \$ 65.30 | \$ 65.30 |
| 36 | AIR CON CONDENSER PIPE ¹⁰ / Dented | 1 | \$ 398.10 | \$ 398.10 |
| 37 | AIR CON CONDENSER SIDE GARNISH X | 2 | \$ 27.40 | \$ 54.80 |
| 38 | AIR CON COMPRESSOR / Dented | 1 | \$ 1,870.20 | \$ 1,870.20 |
| 39 | AIR CON PRESSURE HOSE ¹² / Corroded | 1 | \$ 489.10 | \$ 489.10 |
| 40 | AIR CON SUCTION HOSE ¹⁴ / Corroded | 1 | \$ 398.70 | \$ 398.70 |
| 41 | AIR CON FAN COWLING / cracked | 1 | \$ 289.10 | \$ 289.10 |
| 42 | AIR CON FAN MOTOR X | 1 | \$ 360.40 | \$ 360.40 |
| 43 | AIR CON BELT / missing | 1 | \$ 145.60 | \$ 145.60 |
| 44 | RADIATOR ¹⁵ / Dented | 1 | \$ 1,540.80 | \$ 1,540.80 |
| 45 | RADIATOR RUBBER MOUNTING X | 4 | \$ 39.40 | \$ 157.60 |
| 46 | RADIATOR FAN MOTOR X | 1 | \$ 439.20 | \$ 439.20 |
| 47 | RADIATOR FAN COWLING / cracked | 1 | \$ 299.10 | \$ 299.10 |
| 48 | RADIATOR FAN BLADE X | 1 | \$ 165.40 | \$ 165.40 |
| 49 | RADIATOR SPARE TANK X | 1 | \$ 76.90 | \$ 76.90 |
| 50 | RADIATOR HOSE (LOWER) X | 1 | \$ 68.20 | \$ 68.20 |
| 51 | WATER PUMP X | 1 | \$ 349.30 | \$ 349.30 |
| 52 | THERMOSTAT HOUSING X | 1 | \$ 395.60 | \$ 395.60 |
| 53 | RESONATOR BOX / cracked | 1 | \$ 170.70 | \$ 170.70 |
| 54 | ALTERNATOR / cracked ¹⁶ | 1 | \$ 1,894.70 | \$ 1,894.70 |
| 55 | FRONT WIRE HARNESS HOLDER X | 1 | \$ 134.50 | \$ 134.50 |
| 56 | FRONT FENDER / Deformed | 2 | \$ 535.20 | \$ 1,070.40 |
| 57 | FRONT FENDER COWLING ¹⁷ | 2 | \$ 171.60 | \$ 343.20 |

13504.90

2500.98

10973.92

TOTAL PRICE \$ 21,903.80
 LESS 20% \$ 4,392.76
 SUB TOTAL PRICE \$ 17,571.04

| S/N | DESCRIPTION | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|--------------------------------------|-----|-------------|--------------|
| 1 | FRONT NUMBER PLATE | 1 | \$ 50.00 | \$ 50.00 |
| 2 | FRONT BUMPER CLIP (SET) | 1 | \$ 80.00 | \$ 80.00 |
| 3 | ENGINE UNDER COVER CLIP (SET) | 1 | \$ 30.00 | \$ 30.00 |
| 4 | ENGINE SIDE COVER GARNISH CLIP (SET) | 1 | \$ 30.00 | \$ 30.00 |
| 5 | BONNET SEALANT | 1 | \$ 150.00 | \$ 150.00 |

Check with MSIG photo

6527

10273.00

15000.00

TO : MSIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SDW1050E
 MODEL : HONDA JAZZ
 DATE OF ACCIDENT : 26.07.19
 TIME OF ACCIDENT : 18:40HRS

| | | | | | |
|----|---|---|-----------|-----------|------|
| 6 | BONNET INSULATOR CLIP (SET) | 1 | \$ 30.00 | \$ 30.00 | 15 |
| 7 | BONNET INNER RUBBER CLIP (SET) | 1 | \$ 40.00 | \$ 40.00 | 15 X |
| 8 | BONNET TOP SIDE GARNISH CLIP (SET) | 1 | \$ 40.00 | \$ 40.00 | 15 X |
| 9 | CENTER GRILLE CLIP (SET) | 1 | \$ 30.00 | \$ 30.00 | 20 |
| 10 | CENTER GRILLE COVER GARNISH CLIP (SET) | 1 | \$ 50.00 | \$ 50.00 | 20 X |
| 11 | CENTER GRILLE INNER GARNISH CLIP (SET) | 1 | \$ 50.00 | \$ 50.00 | 20 X |
| 12 | FRONT WIPER PANEL GARNISH CLIP (SET) | 1 | \$ 50.00 | \$ 50.00 | X |
| 13 | FRONT SUPPORT PANEL SEALANT | 1 | \$ 150.00 | \$ 150.00 | 60 X |
| 14 | FRONT SUPPORT LOWER APRON PANEL SEALANT | 1 | \$ 120.00 | \$ 120.00 | X |
| 15 | AIR CON CONDENSER SIDE GARNISH CLIP (SET) | 1 | \$ 40.00 | \$ 40.00 | 20 |
| 16 | FRONT FENDER COLWING CLIP (SET) | 1 | \$ 80.00 | \$ 80.00 | 40 |
| 17 | BATTERY | 1 | \$ 380.00 | \$ 380.00 | X |
| 18 | COOLANT | 1 | \$ 80.00 | \$ 80.00 | 40 |

245

TOTAL \$ 1,480.00

385

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

| S/N | JOB DESCRIPTION | PRICE | ADJUSTED COST |
|-----|--|-------------|---------------|
| 1 | PANEL BEATING, REMOVING AND REPLACING PARTS | \$ 1,800.00 | 1200 (700) -? |
| 2 | SPRAY PAINTING TO AFFECTED AREA | \$ 1,500.00 | 1000 |
| 3 | WIRING CHECK | \$ 180.00 | 80 (100) -? |
| 4 | REMOVE AND REFIX AIRCON CONDENSOR AND AIR CON COMPRESSOR AND REFILL AIRCON GAS | \$ 120.00 | 60 |
| 5 | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST | \$ 80.00 | 60 |
| 6 | REMOVE AND REFIX ALTERNATOR | \$ 180.00 | 100 (100) -? |
| 7 | REMOVE AND REFIX WATER PUMP | \$ 380.00 | 120 X |
| 8 | REFOCUS HEADLAMP BEAM | \$ 50.00 | 30 X |
| 9 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 150.00 | 80 X |

TOTAL \$ 4,680.00

2730

ESTIMATE REPORT

TOTAL PARTS COST : \$ 19,051.04
 TOTAL LABOUR COST : \$ 4,680.00
 TOTAL REPAIR COST : \$ 23,731.04

19/3

TO : MSIG MOTOR CLAIMS DEPTS
VEHICLE NO : SDW1050E
MODEL : HONDA JAZZ
DATE OF ACCIDENT : 26.07.19
TIME OF ACCIDENT : 18:40HRS

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY (HP: 9856 4815)

10003.92
245
1910

12158.92
2431.78

9727.14

14593.28
385
2730

17708.28
3541.66

14166.62

TO : MSIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SDW1050E
 MODEL : HONDA JAZZ
 DATE OF ACCIDENT : 26.07.19
 TIME OF ACCIDENT : 18:40HRS

| | | | | | |
|----|------------------------------------|---|-------------|-------------|---------------|
| 30 | FRONT SUPPORT LOWER APRON PANEL ? | 1 | \$ 196.50 | \$ 196.50 | DM |
| 31 | FRONT WASHER TANK / cracked | 1 | \$ 75.20 | \$ 75.20 | |
| 32 | AIR DUCT / cracked | 1 | \$ 79.40 | \$ 79.40 | |
| 33 | HORN / Dented | 2 | \$ 89.60 | \$ 179.20 | |
| 34 | AIR CON CONDENSER | 1 | \$ 850.80 | \$ 850.80 | DM |
| 35 | AIR CON CONDENSER SWITCH X | 1 | \$ 65.30 | \$ 65.30 | X NN |
| 36 | AIR CON CONDENSER PIPE OR / Dented | 1 | \$ 398.10 | \$ 398.10 | |
| 37 | AIR CON CONDENSER SIDE GARNISH X | 2 | \$ 27.40 | \$ 54.80 | X X NN |
| 38 | AIR CON COMPRESSOR / Dented | 1 | \$ 1,870.20 | \$ 1,870.20 | ? / |
| 39 | AIR CON PRESSURE HOSE OR / Cracked | 1 | \$ 489.10 | \$ 489.10 | |
| 40 | AIR CON SUCTION HOSE OR / Cracked | 1 | \$ 398.70 | \$ 398.70 | X NN |
| 41 | AIR CON FAN COWLING / cracked | 1 | \$ 289.10 | \$ 289.10 | |
| 42 | AIR CON FAN MOTOR X | 1 | \$ 360.40 | \$ 360.40 | X X NN |
| 43 | AIR CON BELT / missing | 1 | \$ 145.60 | \$ 145.60 | |
| 44 | RADIATOR / Dented | 1 | \$ 1,540.80 | \$ 1,540.80 | ? 1187 |
| 45 | RADIATOR RUBBER MOUNTING X | 4 | \$ 39.40 | \$ 157.60 | X X NN |
| 46 | RADIATOR FAN MOTOR X | 1 | \$ 439.20 | \$ 439.20 | X X NN |
| 47 | RADIATOR FAN COWLING / cracked | 1 | \$ 299.10 | \$ 299.10 | |
| 48 | RADIATOR FAN BLADE X | 1 | \$ 165.40 | \$ 165.40 | X X NN |
| 49 | RADIATOR SPARE TANK X | 1 | \$ 76.90 | \$ 76.90 | X X NN |
| 50 | RADIATOR HOSE (LOWER) X | 1 | \$ 68.20 | \$ 68.20 | X NN 10290.50 |
| 51 | WATER PUMP X | 1 | \$ 349.30 | \$ 349.30 | X X NN |
| 52 | THERMOSTAT HOUSING X | 1 | \$ 395.50 | \$ 395.50 | X NN |
| 53 | RESONATOR BOX / cracked | 1 | \$ 170.70 | \$ 170.70 | X NN |
| 54 | ALTERNATOR / cracked | 1 | \$ 1,894.70 | \$ 1,894.70 | |
| 55 | FRONT WIRE HARNESS HOLDER X | 1 | \$ 134.50 | \$ 134.50 | X X NN |
| 56 | FRONT FENDER / Deformed | 2 | \$ 535.20 | \$ 1,070.40 | X NN |
| 57 | FRONT FENDER COLWING / Torn | 2 | \$ 171.60 | \$ 343.20 | X NN |

TOTAL PRICE \$ 21,963.80
 LESS 20% \$ 4,392.76
 SUB TOTAL PRICE \$ 17,571.04

1824160
 3648.32
 14593.20

| S/N | DESCRIPTION | QTY | UNIT S/NETT | TOTAL S/NETT | |
|-----|--------------------------------------|-----|-------------|--------------|--------|
| 1 | FRONT NUMBER PLATE | 1 | \$ 50.00 | \$ 50.00 | 40 DM |
| 2 | FRONT BUMPER CLIP (SET) | 1 | \$ 80.00 | \$ 80.00 | 30 REC |
| 3 | ENGINE UNDER COVER CLIP (SET) | 1 | \$ 30.00 | \$ 30.00 | 20 REC |
| 4 | ENGINE SIDE COVER GARNISH CLIP (SET) | 1 | \$ 30.00 | \$ 30.00 | 20 REC |
| 5 | BONNET SEALANT | 1 | \$ 150.00 | \$ 150.00 | X NN |

TO : MSIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SDW1050E
 MODEL : HONDA JAZZ
 DATE OF ACCIDENT : 26.07.19
 TIME OF ACCIDENT : 18:40HRS

| | | | | | |
|--------------|---|---|-----------|--------------------|------------|
| 6 | BONNET INSULATOR CLIP (SET) | 1 | \$ 30.00 | \$ 30.00 | 15 REC |
| 7 | BONNET INNER RUBBER CLIP (SET) | 1 | \$ 40.00 | \$ 40.00 | 15 X NN |
| 8 | BONNET TOP SIDE GARNISH CLIP (SET) | 1 | \$ 40.00 | \$ 40.00 | 15 X NN |
| 9 | CENTER GRILLE CLIP (SET) | 1 | \$ 30.00 | \$ 30.00 | 20 REC |
| 10 | CENTER GRILLE COVER GARNISH CLIP (SET) | 1 | \$ 50.00 | \$ 50.00 | 20 X NN |
| 11 | CENTER GRILLE INNER GARNISH CLIP (SET) | 1 | \$ 50.00 | \$ 50.00 | 20 X NN |
| 12 | FRONT WIPER PANEL GARNISH CLIP (SET) | 1 | \$ 50.00 | \$ 50.00 | X NN |
| 13 | FRONT SUPPORT PANEL SEALANT | 1 | \$ 150.00 | \$ 150.00 | 60 X NN |
| 14 | FRONT SUPPORT LOWER APRON PANEL SEALANT | 1 | \$ 120.00 | \$ 120.00 | X NN |
| 15 | AIR CON CONDENSER SIDE GARNISH CLIP (SET) | 1 | \$ 40.00 | \$ 40.00 | 20 REC |
| 16 | FRONT FENDER COLWING CLIP (SET) | 1 | \$ 80.00 | \$ 80.00 | 40 REC |
| 17 | BATTERY | 1 | \$ 380.00 | \$ 380.00 | X NN |
| 18 | COOLANT | 1 | \$ 80.00 | \$ 80.00 | 40 REC |
| TOTAL | | | | \$ 1,480.00 | 385 |

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

| S/N | JOB DESCRIPTION | PRICE | ADJUSTED COST |
|--------------|--|--------------------|------------------|
| 1 | PANEL BEATING, REMOVING AND REPLACING PARTS | \$ 1,800.00 | 1200 1200 700 |
| 2 | SPRAY PAINTING TO AFFECTED AREA | \$ 1,800.00 | 1000. |
| 3 | WIRING CHECK | \$ 180.00 | 80 80 20 |
| 4 | REMOVE AND REFIX AIRCON CONDENSOR AND AIR CON COMPRESSOR AND REFILL AIRCON GAS | \$ 120.00 | 60 |
| 5 | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST | \$ 80.00 | 60 |
| 6 | REMOVE AND REFIX ALTERNATOR | \$ 180.00 | 100 100 60 |
| 7 | REMOVE AND REFIX WATER PUMP | \$ 280.00 | 120 X |
| 8 | REFOCUS HEADLAMP BEAM | \$ 60.00 | 30 X |
| 9 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 180.00 | 80 X |
| TOTAL | | \$ 4,680.00 | 2730 |

ESTIMATE REPORT

TOTAL PARTS COST : \$ 19,051.04
 TOTAL LABOUR COST : \$ 4,680.00
 TOTAL REPAIR COST : \$ 23,731.04

TO : MSIG MOTOR CLAIMS DEPTS
VEHICLE NO : SDW1050E
MODEL : HONDA JAZZ
DATE OF ACCIDENT : 26.07.19
TIME OF ACCIDENT : 18:40HRS

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY (HP: 9856 4815)

14593.28

385

2730

17708.28

3541.66

14166.62

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---|---|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 27 Jul 2019 | | 14 Aug 2019 16:34 Edit Adj Rpt | S\$11,200.00 Edit Estimates | S\$11,200.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|--|----------------|----------------|--------------------|---------------------|-------------------|--------------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G | | | | | | | | |
| Main Claimant: | MS THIA GEOK HAR , ID: S1778419F | | | | | | | | |
| Vehicle Reg. No.: | SDW1050E | Date of Loss: | 26/07/2019 18:00 - :59 [31 Months and 13 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 601359 | Policy/Cover Note No.: | 29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020 | | | | | | |
| Vehicle Reg. No. (Insured): | SLH665Y | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789 | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by SIMON HO LEONG CHUAN] ... [Imm.Advice due 15/08/2019] | | | | | | | | |
| Driver/Custodian (Insured): | NG JUI MENG (52 / Male), NRIC: S1803608H Email: | | | | | | | | |
| Adj Asg. Remarks: | As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. OI: Grab. Liab: 100%. TP req for IHS. Contact : Michelle @ 9856 4815 | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

***SDW1050E (601359)**
[SLH665Y]
TP
MS THIA GEOK HAR
Jul 26 2019 6:00PM
[GRAB RENTALS PTE LTD]
Vision Autowork Pte Ltd

| Upload Documents Upload Photos Compose New Letter | | | View | View in Browser |
|---|----------------|--|--|-------------------------------------|
| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) | Thumbnail | Print |
| 1 | 31/07/19 14:28 | Adjuster Immediate Advice |  Load HTM | <input type="checkbox"/> |
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) | Thumbnail | Print |
| 1 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 30/07/19 19:36 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|--|-------------------------------------|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) | Thumbnail | Print |
| | | | | <input checked="" type="checkbox"/> |
| 35 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 30/07/19 19:37 | SURVEY PHOTO |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|------------|-------------------------------------|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) | Thumbnail | Print |
| 84 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 85 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 86 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 87 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 88 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 89 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 90 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 91 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 92 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 93 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 94 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 95 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 96 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 97 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 98 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 99 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 100 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 101 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 102 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |
| 103 | 30/07/19 19:37 | SURVEY PHOTO | | <input checked="" type="checkbox"/> |

| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|---|------------|-------------------------------------|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 29/07/19 11:21 | PRI | | <input type="checkbox"/> |
| 2 | 29/07/19 11:21 | OI Accident Report | | <input type="checkbox"/> |
| 3 | 29/07/19 11:21 | TP SDW1050E E-REPORT | | <input type="checkbox"/> |
| 4 | 29/07/19 12:38 | Acknowledge PRI | | <input type="checkbox"/> |

| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor) | Thumbnail | Print |
|----|----------------|--|-----------|--------------------------|
| 1 | 31/07/19 15:56 | Preliminary Loss Advise | | <input type="checkbox"/> |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | | | |
| <div style="border: 1px solid black; width: 100%; height: 100%;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014373/DQF3E2

Date: 31/01/2020

REFERENCE

| | | |
|--|----------------------|---------------------|
| Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | 29114756 |
| Claimant Vehicle No : SDW1050E | Insured Vehicle No : | SLH665Y |
| Date of Loss: 26/07/2019 | Nature of Claim: | TP Claim No: 601359 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | |
|--|-------------------------------|
| Reg No: SDW1050E | Engine No: L15B31190537 |
| Make & Model: HONDA JAZZ, 1.3 (A) | Chassis No: JHMGK5850HX200790 |
| Reg. Date: 13/12/2016 (Man. Year: 2016) | Odometer: 17671 km |
| Colour: Silver | |
| Engine Capacity: 1498 cc | |
| Market Value/New Car Price: N/A | |
| Sum Insured (S\$): Market Value/New Car Price | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | |
|-------------------------------|------------------------------|
| Front Tyre Size: 185/55 R16 | Rear Tyre Size: 185/55 R16 |
| Front Left Side: Dunlop 5 mm | Rear Left Side: Dunlop 4 mm |
| Front Right Side: Dunlop 5 mm | Rear Right Side: Dunlop 4 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|------------------|------------------|--------------|
| Parts | 19,051.04 | 11,525.40 | 7,525.64 | 39.50 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,680.00 | 2,500.00 | 2,180.00 | 46.58 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 23,731.04 | 14,025.40 | 9,705.64 | 40.90 |
| Approved Total (Overridden) (S\$) | | 11,200.00 | | |
| (S\$) | 23,731.04 | 11,200.00 | 12,531.04 | 52.80 |
| + GST 7.00/7.00% (S\$) | 1,661.17 | 784.00 | 877.17 | 52.80 |
| Nett Amount (S\$) | 25,392.21 | 11,984.00 | 13,408.21 | 52.80 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 14/08/2019 | |
| Date Inspected: | 30/07/2019 Inspected At: | Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4., #08-09 PREMIER @ KAKI BUKIT Singapore 415875 |
| Estimated Period of Repair: | 8.0 days | |

Adjuster: SIMON HO LEONG CHUAN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| Reference | |
|---|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 31 Jan 2020) |
| Parts: 144 | HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SDW1050E) | |
| Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Cracked | 801.20 FL | *594.70 FL |
| 2 | 1 | | *FRONT BUMPER LOWER LIP | Not Necessary | 80.40 FL | *- FL |
| 3 | 1 | | *FRONT BUMPER SIDE LAMP RH | Cracked | 217.40 FL | *217.40 FL |
| 4 | 1 | | *FRONT BUMPER FOGLAMP COVER GARNISH | O/S Cracked | 136.60 FL | *68.30 FL |
| 5 | 1 | | *FRONT BUMPER FOGLAMP RH | Cracked | 291.60 FL | *291.60 FL |
| 6 | 1 | | *FRONT BUMPER LOWER GRILLE | Damaged | 180.40 FL | *180.40 FL |
| 7 | 1 | | *FRONT BUMPER NUMBER PLATE HOLDER | Deformed | 98.30 FL | *98.30 FL |
| 8 | 1 | | *FRONT BUMPER TOW COVER | Grazed | 40.10 FL | *40.10 FL |
| 9 | 1 | | *FRONT BUMPER REINFORCEMENT | Deformed | 326.30 FL | *326.30 FL |
| 10 | 1 | | *FRONT BUMPER SIDE RETAINER | N/S Cracked | 36.80 FL | *18.40 FL |
| 11 | 1 | | *ENGINE UNDER COVER | Not Necessary | 306.30 FL | *- FL |
| 12 | 2 | | *ENGINE SIDE COVER GARNISH | Not Necessary | 314.20 FL | *- FL |
| 13 | 2 | | *HEADLAMP (HID) | Cracked | 3,200.40 FL | *2,280.00 FL |
| 14 | 1 | | *HEADLAMP LOWER BRACKET | Cracked | 76.40 FL | *38.20 FL |
| 15 | 1 | | *FRONT GRILLE | Cracked | 352.20 FL | *352.20 FL |
| 16 | 1 | | *FRONT GRILLE LOGO | Necessary | 29.40 FL | *29.40 FL |
| 17 | 1 | | *FRONT GRILLE COVER GARNISH | Cracked | 176.20 FL | *176.20 FL |
| 18 | 1 | | *FRONT GRILLE CENTER CHROME | Cracked | 148.90 FL | *148.90 FL |
| 19 | 1 | | *FRONT GRILLE CENTER BRACKET | Cracked | 37.40 FL | *37.40 FL |
| 20 | 1 | | *FRONT GRILLE INNER GARNISH | Not Necessary | 122.40 FL | *- FL |
| 21 | 1 | | *BONNET | Dented | 650.20 FL | *650.20 FL |
| 22 | 2 | | *BONNET TOP SIDE GARNISH | Not Necessary | 249.60 FL | *- FL |
| 23 | 1 | | *BONNET INSULATOR | Not Necessary | 179.20 FL | *- FL |
| 24 | 1 | | *BONNET LOCK | Dented | 97.70 FL | *97.70 FL |
| 25 | 2 | | *BONNET STOPPER | Not Necessary | 34.40 FL | *- FL |
| 26 | 2 | | *BONNET HINGE | Not Necessary | 166.40 FL | *- FL |
| 27 | 3 | | *BONNET INNER RUBBER | Not Necessary | 177.60 FL | *- FL |
| 28 | 1 | | *FRONT WIPER PANEL GARNISH | Not Necessary | 287.50 FL | *- FL |
| 29 | 1 | | *FRONT SUPPORT PANEL | Deformed | 590.40 FL | *590.40 FL |
| 30 | 1 | | *FRONT SUPPORT LOWER APRON PANEL | Damaged | 196.50 FL | *196.50 FL |
| 31 | 1 | | *FRONT WASHER TANK | Cracked | 75.20 FL | *75.20 FL |
| 32 | 1 | | *AIR DUCT | Cracked | 79.40 FL | *79.40 FL |
| 33 | 1 | | *HORN | Dented | 179.20 FL | *89.60 FL |
| 34 | 1 | | *AIR CON CONDENSER | Damaged | 850.80 FL | *850.80 FL |
| 35 | 1 | | *AIR CON CONDENSER SWITCH | Not Necessary | 65.30 FL | *- FL |
| 36 | 1 | | *AIR CON CONDENSER PIPE | Dented | 398.10 FL | *398.10 FL |
| 37 | 2 | | *AIR CON CONDENSER SIDE GARNISH | Not Necessary | 54.80 FL | *- FL |
| 38 | 1 | | *AIR CON COMPRESSOR | Dented | 1,870.20 FL | *1,870.20 FL |
| 39 | 1 | | *AIR CON PRESSURE HOSE | Grazed | 489.10 FL | *489.10 FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|--------------|
| 40 | 1 | | *AIR CON SUCTION HOSE | Not Necessary | 398.70 FL | *- FL |
| 41 | 1 | | *AIR CON FAN COWLING | Cracked | 289.10 FL | *289.10 FL |
| 42 | 1 | | *AIR CON FAN MOTOR | Not Necessary | 360.40 FL | *- FL |
| 43 | 1 | | *AIR CON BELT | Missing | 145.60 FL | *145.60 FL |
| 44 | 1 | | *RADIATOR | Dented | 1,540.80 FL | *1,187.00 FL |
| 45 | 4 | | *RADIATOR RUBBER MOUNTING | Not Necessary | 157.60 FL | *- FL |
| 46 | 1 | | *RADIATOR FAN MOTOR | Not Necessary | 439.20 FL | *- FL |
| 47 | 1 | | *RADIATOR FAN COWLING | Cracked | 299.10 FL | *299.10 FL |
| 48 | 1 | | *RADIATOR FAN BLADE | Not Necessary | 165.40 FL | *- FL |
| 49 | 1 | | *RADIATOR SPARE TANK | Not Necessary | 76.90 FL | *- FL |
| 50 | 1 | | *RADIATOR HOSE (LOWER) | Not Necessary | 68.20 FL | *- FL |
| 51 | 1 | | *WATER PUMP | Not Necessary | 349.30 FL | *- FL |
| 52 | 1 | | *THERMOSTAT HOUSING | Not Necessary | 395.50 FL | *- FL |
| 53 | 1 | | *RESONATOR BOX | Not Necessary | 170.70 FL | *- FL |
| 54 | 1 | | *ALTERNATOR | Cracked | 1,894.70 FL | *1,894.70 FL |
| 55 | 1 | | *FRONT WIRE HATNESS HOLDER | Not Necessary | 134.50 FL | *- FL |
| 56 | 2 | | *FRONT FENDER | Not Necessary | 1,070.40 FL | *- FL |
| 57 | 2 | | *FRONT FENDER COWLING | Not Necessary | 343.20 FL | *- FL |
| 58 | 1 | | *FRONT NUMBER PLATE | Damaged | 50.00 FS | *40.00 FS |
| 59 | 1 | | *SET FRONT BUMPER CLIP | Necessary | 80.00 FS | *30.00 FS |
| 60 | 1 | | *SET ENGINE UNDER COVER CLIP | Necessary | 30.00 FS | *20.00 FS |
| 61 | 1 | | *SET ENGINE SIDE COVER GARNISH CLIP | Necessary | 30.00 FS | *20.00 FS |
| 62 | 1 | | *BONNET SEALANT | Not Necessary | 150.00 FS | *- FS |
| 63 | 1 | | *SET BONNET INSULATOR CLIP | Necessary | 30.00 FS | *15.00 FS |
| 64 | 1 | | *SET BONNET INNER RUBBER CLIP | Not Necessary | 40.00 FS | *- FS |
| 65 | 1 | | *SET BONNET TOP SIDE GARNISH CLIP | Not Necessary | 40.00 FS | *- FS |
| 66 | 1 | | *SET CENTER GRILLE CLIP | Necessary | 30.00 FS | *20.00 FS |
| 67 | 1 | | *SET CENTER GRILLE COVER GARNISH CLIP | Not Necessary | 50.00 FS | *- FS |
| 68 | 1 | | *SET CENTER GRILLE INNER GARNISH CLIP | Not Necessary | 50.00 FS | *- FS |
| 69 | 1 | | *SET FRONT WIPER PANEL GARNISH CLIP | Not Necessary | 50.00 FS | *- FS |
| 70 | 1 | | *FRONT SUPPORT PANEL SEALANT | Not Necessary | 150.00 FS | *- FS |
| 71 | 1 | | *FRONT SUPPORT LOWER APRON PANEL SEALANT | Not Necessary | 120.00 FS | *- FS |
| 72 | 1 | | *SET AIR CON CONDENSER SIDE GARNISH CLIP | Necessary | 40.00 FS | *20.00 FS |
| 73 | 1 | | *SET FRONT FENDER COWLING CLIP | Necessary | 80.00 FS | *40.00 FS |
| 74 | 1 | | *BATTERY | Not Necessary | 380.00 FS | *- FS |
| 75 | 1 | | *COOLANT | Necessary | 80.00 FS | *40.00 FS |

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$) **23,443.80** **14,345.50**
 - List Item Discount on L Items 20.00/20.00% (S\$) **4,392.76** **2,820.10**

Total Parts (S\$) 19,051.04 11,525.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | PANEL BEATING, REMOVING AND REPLACING PARTS | New | 1,800.00 | 1,200.00 |
| 2 | SPRAY PAINTING TO AFFECTED AREA | New | 1,800.00 | 1,000.00 |
| 3 | WIRING CHECK | New | 180.00 | 80.00 |
| 4 | REMOVE AND REFIX AIRCON CONDENSOR AND AIR CON COMPRESSOR AND REFILL AIRCON GAS | New | 120.00 | 60.00 |
| 5 | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST | New | 80.00 | 60.00 |
| 6 | REMOVE AND REFIX ALTERNATOR | New | 180.00 | 100.00 |
| 7 | REMOVE AND REFIX WATER PUMP | New | 280.00 | 0.00 |
| 8 | REFOCUS HEADLAMP BEAM | New | 60.00 | 0.00 |
| 9 | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC | New | 180.00 | 0.00 |
| Gross Labour Cost (S\$) | | | 4,680.00 | 2,500.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >