

ASS. REC. BY:

REF: CP/MSG 190143751 09/302

Special Instruction:

Surveyor: Simo

ASSIGNMENT (Office)

From (Person): Meymen Vimmala

of M81A

Date/Time: 14/8/19 @ 4:55pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBE 63772

Insured:

at Workshop m/s: FM Solution

Tel: 91018302

of 160 Sin Ming Drive #03-19

Policy No: A29068691 MKC

Claim No: 601592

Sum Insured:

Excess: \$600.00

Make of Veh:

D.O.A. 30/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted: Bernard

Vehicle IN OUT

Date/Time

Action/Instruction

Estimate /

GBE 63772 - X

24/9/19

3:11pm confirmed with Bernard US \$5750, 5 days.
(led \$773.65, 56%)

JN IMC 2E



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)
 4 Shenton Way. #27-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
 www.msig.com.sg

Executive
Claims Services

Inspection Report

Type of Survey:

OD - Excess	<input checked="" type="checkbox"/>	600
TP Without Prejudice		

Vehicle Data:

Odometer reading	72043 km
Engine No	
VIN No	
Engine capacity	
Engine modification	

Vehicle Details:

Vehicle Reg No	GBE 6377Z
Make	Nissan
Model	NV 350
Passenger capacity	02
Paint colour & code	White
Paint type	

Vehicle Condition:

	Seviceable	Yes / No
Handbrake	<input type="checkbox"/>	
Footbrake	<input type="checkbox"/>	
Steering	<input type="checkbox"/>	
Body	<input type="checkbox"/>	
Paint	<input type="checkbox"/>	

Vehicle Extras:

In-built camera	<input checked="" type="checkbox"/> Yes / No
Modification	<input checked="" type="checkbox"/> Yes / No

Tyre Condition:	Tread mm	Size	Condition
Front right	4	OHTSU 195 / 15	
Front left	4	"	
Rear left	4	"	
Rear right	4	"	

General Data:

Date of accident	30-07-19
Date of inspection	02-08-19
Date of assignment	01-08-19
Inspection location	EM solution

Painting Process:

Prepare off vehicle	<input type="checkbox"/>
Painting off vehicle	<input type="checkbox"/>
Neither (default)	<input type="checkbox"/>

Cost Details:	Repairer	Adjuster
Parts		
Supplementary		
Miscellaneous		
Body Labour		
Paint labour		
Paint material		
TOTAL		
Towing		
Excess		
Total less excess		
Estimated days for repair		

Body Panel Repair:

Panel repair calculator used	
Yes / No	<input type="checkbox"/>

Remarks:

Lump / Global Sum	
Reason(s)	Margin Repair / Fast-line

Others:

Repair Authorised Date:

--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Aug 2019		14 Aug 2019 16:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	ROTARY SWITCHGEAR & TESTING PTE LTD, Co. Reg. No.: 198202150R								
Vehicle Reg. No.:	GBE6377Z	Date of Loss:	30/07/2019 20:00 - :59 [42 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 601592	Policy/Cover Note No.:	A29068091MKC (Comprehensive) Coverage: 29/01/2019 - 28/01/2020						
		Excess:	S\$600.00						
Repairer:	Em Solution Pte Ltd (160 Sin Ming) (HQ) 160 Sin Ming Drive, #03-19 Sin Ming Autocity, 575722 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]								
Driver/Custodian:	LAN TECK HUA (55 / Male) , NRIC: S2606276D, Tel: +6598511619 Email: NOEMAIL								
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. Please revert first. Please arrange for the survey. Vehicle is presently at EM Solution 160 Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722. To call Bernard HP: 91018302 to arrange for survey. Surveyor to check on the market vlaue & rebate.								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: EM Auto <emautosolution@singnet.com.sg>
Sent: Tuesday, 24 September 2019 3:11 PM
To: Shiau Chan (LKKAuto)
Subject: RE: KINDLY ADVISE THE STATUS OF GBE 6377Z (DOA: 30/07/2019)

Hi Shiau Chan,

Since your insist I cannot resist.

Thanks & regards,

Bernard

HP: 91018302

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Tuesday, 24 September, 2019 3:06 PM
To: EM Auto <emautosolution@singnet.com.sg>
Subject: RE: KINDLY ADVISE THE STATUS OF GBE 6377Z (DOA: 30/07/2019)

Dear Bernard,

WITHOUT PREJUDICE

After review the photos as your provided, offer Lump Sum \$5,750 and 5 repair days.

Kindly check and confirm.

Please note that the finalisation subject to insurer's approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: EM Auto <emautosolution@singnet.com.sg>
Sent: Thursday, 19 September 2019 2:39 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: RE: KINDLY ADVISE THE STATUS OF GBE 6377Z (DOA: 30/07/2019)

Hi Shiau Chan,

Base on those parts dismantle photos as per attachment.

We estimate the Cost of Repair to be around \$6.600/- before Excess \$600/-

Please confirm and approve. 😊

Thanks & regards,

Bernard

HP: 91018302

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Thursday, 19 September, 2019 2:15 PM
To: EM Auto <emautosolution@singnet.com.sg>
Subject: RE: KINDLY ADVISE THE STATUS OF GBE 6377Z (DOA: 30/07/2019)

Dear Bernard,

WITHOUT PREJUDICE

Offer Lump Sum \$5,400 and 5 repair days.

Kindly check and confirm.

Please note that the finalisation subject to insurer's approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 18 September 2019 5:04 PM
To: EM Auto <emautosolution@singnet.com.sg>
Subject: RE: KINDLY ADVISE THE STATUS OF GBE 6377Z (DOA: 30/07/2019)

Dear Bernard,

Please find the attached.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: EM Auto <emautosolution@singnet.com.sg>
Sent: Wednesday, 18 September 2019 4:59 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: RE: KINDLY ADVISE THE STATUS OF GBE 6377Z (DOA: 30/07/2019)

Hi Shiau Chan,

Shiau Chan (LKKAuto)

From: EM Auto <emautosolution@singnet.com.sg>
Sent: Thursday, 19 September 2019 2:39 PM
To: Shiau Chan (LKKAuto)
Subject: RE: KINDLY ADVISE THE STATUS OF GBE 6377Z (DOA: 30/07/2019)
Attachments: IMG_7443.jpg; IMG_7444.jpg; IMG_7445.jpg; IMG_7446.jpg; IMG_7447.jpg; IMG_7448.jpg; IMG_7449.jpg; IMG_7450.jpg; IMG_7452.jpg; IMG_7453.jpg

Hi Shiau Chan,

Base on those parts dismantle photos as per attachment.

We estimate the Cost of Repair to be around \$6.600/- before Excess \$600/-

Please confirm and approve. 😊

Thanks & regards,

Bernard

HP: 91018302

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Thursday, 19 September, 2019 2:15 PM
To: EM Auto <emautosolution@singnet.com.sg>
Subject: RE: KINDLY ADVISE THE STATUS OF GBE 6377Z (DOA: 30/07/2019)

Dear Bernard,

WITHOUT PREJUDICE

Offer Lump Sum \$5,400 and 5 repair days.

Kindly check and confirm.

Please note that the finalisation subject to insurer's approval.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 18 September 2019 5:04 PM
To: EM Auto <emautosolution@singnet.com.sg>
Subject: RE: KINDLY ADVISE THE STATUS OF GBE 6377Z (DOA: 30/07/2019)



MSIG

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

www.msig.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____ Policy No : _____
 Date : _____ Claim No : _____

Insured Vehicle No : GBE 6377Z Date of Accident : 30-07-19
 TP Vehicle No : - Place of Survey : Em Solution
 Make & Model : Nissan NV350 Date of Survey : 02-08-19.

Point of Impact / Damages :

Front Right.

Recommended Reserve :

Repairer's Estimate : \$ 12923.65
 Interim Adjustment : \$ 6982.94
 Check Items : \$ 2661.21



Proposed : Part by Part / Lump Sum Repair \$7700/- Excess : \$ 600/-

Estimate Repair Period : 05 days

Pre-accident Market Value (for total loss consideration) : \$ 46000.00

COE / PARF to owner : \$ 29789.00

Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

OD Claim
Excess : \$ 600/-
(Authorised / Revert)

TP Claim
(Without Prejudice)

Vehicle No. # GBE 6377Z

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 05 days

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 02-08-19

Victor_Seng @ sq.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
 www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: Vimmala D/O Raja Singam

Date: 05 Aug 2019

Preliminary Advice

Vehicle No	: GBE6377Z	Accident Date	: 30/07/2019
Make	: NISSAN NV350	Policy No.	: A29068091MKC
Assignment Date	: 01/08/2019	Excess	: S\$600.00
Date of Inspection	: 02/08/2019	Est. Duration of Repair	: 5.00
Inspection At	: EM SOLUTION PTE LTD (160 SIN MING) (HQ) 160 SIN MING DRIVE, #03-19 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front right portion.

Repairer's Estimate (Gross)	:S\$	12,923.65
Revised Amount	:S\$	6,982.94
Check Items (Estimated)	:S\$	2,661.21
Total	:S\$	
Lump Sum Repair	:S\$	7,700

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	46,000
COE / PARF Rebate	:S\$	29,789
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- (X) The vehicle is economical/~~not economical~~ for repair.
- () The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	150R
Vehicle Details	
Vehicle No.:	GBE6377Z
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Sep 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	YD25387330A
Chassis No.:	JN1MC2E26Z0005801
Maximum Power Output:	-
Open Market Value:	\$22,153.00
Original Registration Date:	29 Jan 2016
First Registration Date:	29 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$1,108.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jan 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,001.00
COE Rebate Amount:	\$29,368.00
Total Rebate Amount:	\$29,368.00

The information contained herein is correct as at 09 Sep 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No.:	GBE6377Z
Vehicle Type:	A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Chassis No.:	JN1MC2E26Z0005801
Propellant:	Diesel
Engine No.:	YD25387330A
Engine Capacity:	2488 cc
Maximum Power Output:	-
Maximum Laden Weight:	3300 kg
Unladen Weight:	1800 kg
Year Of Manufacture:	2015
Original Registration Date:	29 Jan 2016
Lifespan Expiry Date:	28 Jan 2036
COE Category:	C - Goods Vehicle & Bus
Quota Premium:	\$46,001.00
COE Expiry Date:	28 Jan 2026
Road Tax Expiry Date:	28 Jan 2020
Inspection Due Date:	28 Jan 2020
Intended Transfer Date:	09 Sep 2019
CO2 Emission:	232.00 (g/km)
CEV/VES Rebate Utilised Amount:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

Message

This vehicle has a road tax Over Payment of \$158.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

You may print this page for reference.

OK

Print

EM SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226 Fax: 64584500

Registration No: 201016308 K

01.08.2019

MSIG Insurance (Singapore) Pte Ltd
4, Shenton Way, #21-01
SGX Centre 2
Singapore 068807

REPAIR ESTIMATE FOR NISSAN NV350 - GBE 6377 Z

1 pc	front bumper / Deformed		554.70	N
1/2 pcs	front bumper fog lamp grilles RH / cracked	117.80	235.60	N
1 pc	front bumper reinforcement X NN		630.00	N
1/2 pcs	front bumper side bracket RH / cracked	157.00	314.00	N
1 pc	RH headlamp assy ✓ CRA		433.00	N
1 pc	front grille X		475.00	N
1 pc	front grille emblem X NN		59.70	N
1 pc	RH front corner panel X		487.70	N
1 pc	RH door / Deformed		1,115.00	N
2 pcs	RH door hinges / Deformed X NN	65.10	130.20	N
1 pc	RH door stopper X NN		49.50	N
1 pc	RH door mirror X NN		520.30	N
1 pc	RH door rubber / DD		126.30	N
1 pc	RH door inner lock ?		186.70	N
1 pc	RH door regulator gear ? } X NN		167.90	N
1 pc	RH door regulator motor ?		544.40	N
1 pc	RH door inner trim ? CRA		491.70	N ✓
1 pc	RH door front pillar ?		1,133.20	N
1 pc	RH front step panel / Deformed		125.00	N
1 pc	RH front step garnish / Deformed		94.30	N
1 pc	RH front arch panel / Deformed		556.30	N
			<u>8,430.50</u>	
		Less 10%	<u>843.05</u>	
			7,587.45	
1 pc	turbo cooler / Dented	2,121.50	2,221.60	SN } LOSS 10%
1/2 pcs	front bumper fog lamps RH / cracked	311.80	623.60	SN
1 set	front bumper clips / necc		30 45.00	SN
1 pc	RH door vehicle specification sticker / necc		26.00	SN
1 set	RH door company sticker / necc	200	300.00	SN
1)	Check electrical wirings. /	30	60.00	
2)	Repair accident damages and renew above parts.		980.00	650
3)	Transfer RH door mechanisms. /	60	100.00	
4)	Spray paint on accident affected portions.		980.00	600
			<u>980.00</u>	
			<u>\$ 12,923.65</u>	

This estimate is base on surface examination only.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Aug 2019		14 Aug 2019 16:55 Edit Adj Rpt	S\$5,750.00 Edit Estimates	S\$5,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ROTARY SWITCHGEAR & TESTING PTE LTD, Co. Reg. No.: 198202150R								
Vehicle Reg. No.:	GBE6377Z	Date of Loss: 30/07/2019 20:00 - :59 [42 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type:	OD / 601592	Policy/Cover Note No.: A29068091MKC (Comprehensive) Coverage: 29/01/2019 - 28/01/2020							
		Excess: S\$600.00							
Repairer:	Em Solution Pte Ltd (160 Sin Ming) (HQ) 160 Sin Ming Drive, #03-19 Sin Ming Autocity, 575722 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by SIMON HO LEONG CHUAN] ... [Imm.Advice due 15/08/2019]								
Driver/Custodian:	LAN TECK HUA (55 / Male) , NRIC: S2606276D, Tel: +6598511619 Email: NOEMAIL								
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. Please revert first. Please arrange for the survey. Vehicle is presently at EM Solution 160 Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722. To call Bernard HP: 91018302 to arrange for survey. Surveyor to check on the market vlaue & rebate.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/> View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBE6377Z (601592)
 OD
 Jul 30 2019 8:00PM
[ROTARY SWITCHGEAR & TESTING PTE LTD]
 Em Solution Pte Ltd (160 Sin Ming)

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>		
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)				Thumbnail	Print	
1	31/07/19 16:46	Accident Statement				Load HTM		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)				Thumbnail	Print	
1	05/08/19 14:45	Adjuster Immediate Advice				Load HTM		
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)				Thumbnail	Print	
1	31/07/19 16:29	Accident Photo [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
2	31/07/19 16:29	Accident Photo [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
3	31/07/19 16:29	Accident Photo [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
4	31/07/19 16:29	Accident Photo [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
5	31/07/19 16:29	Accident Photo [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
6	31/07/19 16:29	Accident Photo [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
7	31/07/19 16:29	Accident Photo [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
8	31/07/19 16:29	Accident Photo [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
9	31/07/19 16:29	Accident Photo [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
10	31/07/19 16:29	Accident Photo [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
11	31/07/19 16:29	Accident Photo [Linked Accident Report Documents]				Load JPG	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)				Thumbnail	Print	
1	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
2	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
3	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
4	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
5	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
6	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
7	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
8	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
9	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
10	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
11	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
12	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
13	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
14	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
15	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
16	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
17	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
18	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
19	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
20	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
21	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
22	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
23	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	
24	05/08/19 09:53	SURVEY PHOTO				Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
25	05/08/19 09:53	STA INSPECTION PTE LTD (Boon Lay) SURVEY PHOTO		Load JPG <input checked="" type="checkbox"/>
26	05/08/19 09:53	SURVEY PHOTO		Load JPG <input checked="" type="checkbox"/>
27	05/08/19 09:53	SURVEY PHOTO		Load JPG <input checked="" type="checkbox"/>
28	05/08/19 09:53	SURVEY PHOTO		Load JPG <input checked="" type="checkbox"/>
29	05/08/19 09:53	SURVEY PHOTO		Load JPG <input checked="" type="checkbox"/>
30	05/08/19 09:53	SURVEY PHOTO		Load JPG <input checked="" type="checkbox"/>
31	05/08/19 09:53	SURVEY PHOTO		Load JPG <input checked="" type="checkbox"/>
32	05/08/19 09:53	SURVEY PHOTO		Load JPG <input checked="" type="checkbox"/>
33	05/08/19 09:53	SURVEY PHOTO		Load JPG <input checked="" type="checkbox"/>
34	05/08/19 09:53	SURVEY PHOTO		Load JPG <input checked="" type="checkbox"/>
35	05/08/19 09:53	SURVEY PHOTO		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
MSIG Insurance (Singapore) Pte. Ltd. (HQ)				
1	01/08/19 11:51	Estimate from repairer		Load PDF
2	01/08/19 11:52	Email from repairer to arrange for survey		Load PDF
3	01/08/19 13:18	Driving licence validity		Load PDF
STA INSPECTION PTE LTD (Boon Lay)				
1	31/07/19 16:28	Sketch Plan <small>[Linked Accident Report Documents]</small>		Load TIF
2	31/07/19 16:28	Sketch Plan #2 <small>[Linked Accident Report Documents]</small>		Load TIF
MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)				
1	05/08/19 15:51	Preliminary Loss Advise		Load PDF
2	06/08/19 09:08	email - authorize repair		Load PDF

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	31/07/19 16:46	STA INSPECTION PTE LTD (Boon Lay) Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
STA INSPECTION PTE LTD (Boon Lay)				
1	31/07/19 16:29	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	31/07/19 16:29	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	31/07/19 16:29	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	31/07/19 16:29	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	31/07/19 16:29	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	31/07/19 16:29	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	31/07/19 16:29	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	31/07/19 16:29	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	31/07/19 16:29	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	31/07/19 16:29	Accident Photo		Load JPG <input checked="" type="checkbox"/>
11	31/07/19 16:29	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
STA INSPECTION PTE LTD (Boon Lay)				
1	31/07/19 16:28	Sketch Plan		Load TIF
2	31/07/19 16:28	Sketch Plan #2		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CF/MSG19014375/CQF3E2

Date: 26/09/2019

REFERENCE

Insured/Claimant: ROTARY SWITCHGEAR & TESTING PTE LTD Policy No: A29068091MKC
Date of Loss: 30/07/2019 Nature of Claim: OD Claim No: 601592

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE6377Z**
Make & Model: NISSAN NV350, 2.5 (A) Engine No: YD25387330A
Reg. Date: 29/01/2016 (Man. Year: 2015) Chassis No: JN1MC2E26Z0005801
Colour: White Odometer: 72043 km
Engine Capacity: 2488 cc
Market Value/New Car Price: S\$46,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: OHTSU 4 mm Rear Left Side: OHTSU 4 mm
Front Right Side: OHTSU 4 mm Rear Right Side: OHTSU 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,803.65	5,840.05	4,963.60	45.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	1,340.00	780.00	36.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,923.65	7,180.05	5,743.60	44.44
Approved Total (Overridden) (S\$)		5,750.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	12,323.65	5,150.00	7,173.65	58.21

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 02/08/2019 Inspected At:

Em Solution Pte Ltd (160 Sin Ming)
(HQ)
160 Sin Ming Drive, #03-19 Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: SIMON HO LEONG CHUAN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 26 Sep 2019)
Parts:	N/A NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE6377Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	554.70 FN	*554.70 FN
2	1		*FRONTBUMPER FOG LAMP GRILLES	O/S Cracked	235.60 FN	*117.80 FN
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	630.00 FN	*- FN
4	1		*FRONT BUMPER SIDE BRACKET	O/S Cracked	314.00 FN	*157.00 FN
5	1		*RH HEADLAMP ASSY	Cracked	433.00 FN	*433.00 FN
6	1		*FRONT GRILLE	Not Necessary	475.00 FN	*- FN
7	1		*FRONT GRILLE EMBLEM	Not Necessary	59.70 FN	*- FN
8	1		*RH FRONT CORNER PANEL	Not Necessary	487.70 FN	*- FN
9	1		*RH DOOR	Deformed	1,115.00 FN	*1,115.00 FN
10	2		*RH DOOR HINGES	Not Necessary	130.20 FN	*- FN
11	1		*RH DOOR STOPPER	Not Necessary	49.50 FN	*- FN
12	1		*RH DOOR MIRROR	Not Necessary	520.30 FN	*- FN
13	1		*RH DOOR RUBBER	Dented	126.30 FN	*126.30 FN
14	1		*RH DOOR INNER LOCK	Not Necessary	186.70 FN	*- FN
15	1		*RH DOOR REGULATOR GEAR	Not Necessary	167.90 FN	*- FN
16	1		*RH DOOR REGULATOR MOTOR	Not Necessary	544.40 FN	*- FN
17	1		*RH DOOR INNER TRIM	Cracked	491.70 FN	*491.70 FN
18	1		*RH DOOR FRONT PILLAR	Not Necessary	1,133.20 FN	*- FN
19	1		*RH FRONT STEP PANEL	Deformed	125.00 FN	*125.00 FN
20	1		*RH FRONT STEP GARNISH	Deformed	94.30 FN	*94.30 FN
21	1		*RH FRONT ARCH PANEL	Deformed	556.30 FN	*556.30 FN
22	1		*TURBO COOLER	Dented	2,221.60 F	*2,121.60 FL
23	1		*FRONT BUMPER FOG LAMPS	O/S Cracked	623.60 F	*311.80 FL
24	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
25	1		*RH DOOR VEHICLE SPECIFICATION STICKER	Necessary	26.00 FS	*26.00 FS
26	1		*SET RH DOOR COMPANY STICKER	Necessary	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	11,646.70	6,460.50
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	243.34
- Nett Item Discount on N Items 10.00/10.00% (\$)	843.05	377.11
Total Parts (\$)	10,803.65	5,840.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ELECTRICAL WIRINGS	New	60.00	30.00
2	REPAIR ACCIDENT DAMAGES AND RENEW ABOVE PARTS	New	980.00	650.00
3	TRANSFER RH DOOR MECHANISMS	New	100.00	60.00
4	SPRAY PAINT ON ACCIDENT AFFECTED PORTIONS	New	980.00	600.00
Gross Labour Cost (S\$)			2,120.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >