

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ABWIN 論輝
 Service Centre

ESTIMATED COST: HQQ000079

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

GW2288U ←
IBUILDERS PTE LTD
 45 KALLANG PUDDING
 ROAD
 #10-11, ALPHA BUILDING
 SINGAPORE 349317
 CONTACT NO : 81233113

Acknowledged by Repairer

DATE : 19-AUG-2019
 Signature : TOYOTA
 Date: MODEL : DYNA 150 M
 CHASSIS NO : JTFAT35Y00K200304
 ENGINE NO :
 SERVICE ADVISOR : ABBY LIM
 PAGE : 1 OF 2

m f Allocation
LKK
2/5 1500
19/8/19
367
Teo Jibb Althorp

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	TAIL LAMP R/H	17 250.70 X	
1	TAIL LAMP L/H	one 250.70	
1	TAIL LAMP BRACKET R/H	17 75.80 X	
1	TAIL LAMP BRACKET L/H	Set 214.53	214.53
1	TAIL GATE LOCK	2 155.60 X	
1	TAILGATE BRACKET	Set 85.60	
1	TAILGATE LOCK CATCH	11 95.60 X	
1	STEP END PANEL	Set 350.60	
1	REAR NUMBER PLATE BRACKET	2 191.60 X	
1	TOYOTA "DYNA" EMBLEM	one 35.70	
1	TAIL GATE STOPPER	11 59.70 X	937.13
1	EXHAUST PIPE	one 492.20 X	252
	Sub Total	2,119.60	702.84
			0.00

SPECIAL NETT

1	REAR BUMPER REVERSE SENSOR	one 350.00	200 5.00
1	REAR NUMBER PLATE	Set 50.00	14 5.00
	Sub Total	400.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	800.00	500
1	TO SPRAY PAINT ON AFFECTED AREAS	800.00	450
1	TO APPLY TUFF COAT ON AFFECTED AREAS	11 150.00 X	
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	150.00	50
1	TO DISMANTLE, REPLACE AND/OR REPAIR REAR TAILGATE COMPONENTS	11 150.00 X	
	Sub Total	2,050.00	0.00

1916.84
 1533

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000079**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

GW2288U
IBUILDERS PTE LTD
45 KALLANG PUDDING
ROAD
#10-11, ALPHA BUILDING
SINGAPORE 349317
CONTACT NO : 81233113

DATE : 19-AUG-2019
MAKE : TOYOTA
MODEL : DYNA 150 M
CHASSIS NO : JTFAT35Y00K200304
ENGINE NO :
SERVICE ADVISOR : ABBY LIM
PAGE : 2 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

SUB-TOTAL	4,569.60	0.00
GST - 7 %	319.87	0.00
TOTAL	4,889.47	0.00

ABWIN SERVICE PTE LTD

Prepared By