

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19014412/AKA3Q2

Date: 30/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SLN7699Y **Insured Vehicle No :** SLX3745X

Date of Loss: 02/08/2019 Nature of Claim: TP Claim No: 0871265909SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN7699Y		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN034021
Reg. Date:	17/05/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF45HA129155
Colour:	White	Odometer:	17724 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,851.00	1,556.80	11,294.20	87.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,202.00	2,152.00	3,050.00	58.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	18,053.00	3,708.80	14,344.20	79.46
+ GST 7.00/7.00% (\$\$)	1,263.71	259.62	1,004.09	79.46
Nett Amount (\$\$)	19,316.71	3,968.42	15,348.29	79.46
+ Loss of Use (4.0 x S\$50.00/day) (\$\$)		200.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,170.42		

INSPECTION

Date of Assignment: 16/08/2019

Date Inspected: 16/08/2019 Inspected At:

Premium Automobiles Pte Ltd -
Alexandra (HQ)
281 Alexandra Pte Ltd, Level B2
Singapore 159938

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,946.00 FS	*1,556.80 FS
2	1		*FRONT BUMPER FIXING PART	Not Necessary	258.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	191.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE -RH	Not Necessary	56.00 FS	*- FS
5	1		*AIR GUIDE GRILLE- RH	Not Necessary	333.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	34.00 FS	*- FS
7	1		*FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
8	1		*FRONT BUMPER CARRIER	Not Necessary	733.00 FS	*- FS
9	1		*FENDER-RH	Repair	700.00 FS	*- FS
10	1		*FENDER ATTACHMENT PARTS	Not Necessary	183.00 FS	*- FS
11	1		*CLOSING ELEMENT -RH	Not Necessary	45.00 FS	*- FS
12	1		*FENDER BRACKET -RH	Not Necessary	32.00 FS	*- FS
13	1		*DEFORMATION ELEMENT BRACKET-RH	Not Necessary	45.00 FS	*- FS
14	1		*FRONT FENDER SUPPORT -RH	Not Necessary	107.00 FS	*- FS
15	1		*WHEEL HOUSING LINER-RH	Not Necessary	220.00 FS	*- FS
16	1		*WHEEL HOUSING LINER ATTACHMENT PARTS -FRONT /REAR	Not Necessary	82.00 FS	*- FS
17	1		*WHEEL SPOILER	Not Necessary	66.00 FS	*- FS
18	1		*SPOILER RH	Not Necessary	33.00 FS	*- FS
19	1		*STONE CHIP GUARD	Not Necessary	46.00 FS	*- FS
20	2		*FENDER TOP LEDGE COVER	Not Necessary	49.00 FS	*- FS
21	1		*LED HEADLIGHT -RH	Not Necessary	7,087.00 FS	*- FS
22	1		*LIFT CYLINDER -RH	Not Necessary	192.00 FS	*- FS
23	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 12,851.00 1,556.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,450.00	500.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,200.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,202.00	2,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >