

ASS. REC. BY:

ASSIGNMENT

Kenneth

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ bus cob

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) _____

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 5913Y Yr Regn: 12, 14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995Colour M. white / Red A/C: Insured / Std / NI / NASp. Reading 361193 / Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: V1-1 ABZ 15 AUC 280979Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Mil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Ling LongFront 9 mm Rear 7 mmR/Bal. 9 mm R/Bal. 7 mmL/Bal. 9 mm L/Bal. 7 mmD.O.A. 17/6/17 D.O.I. 20/6/17Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body work

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC 5913Y - A
	AEK 7889 - N/A / INC 12019/1901 S2 ROA - 01/10/2012
19/08/19	Continued p/p @ 17,371.68 @ 8 days with Kenneth (\$ 42,826.78 red - 81%)
	RECEIVED 20 AUG 2019

Resurvey No. of Trip - 1

Date/Time, File Pass to? 20/08/19 Date/Time, File Return to? _____

1) Typist 2) _____

3) _____ 4) _____

5) _____ 6) _____

Prel. Report: \$ 17,371.68 p/p

TOTAL LOSS

KIV FOR LOD

Survey Fee: _____ Date: 80x15=120

Basic & Add. 170+1200

S + RS, SI 50

Photos 50

Others 37

TOTAL 80

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/06/2017 09:46
Date Of Accident	17/06/2017 09:35
Exact Location Of Accident	AYE SLIP ROAD TOWARDS ALEXANDRA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5913Y
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	TAN KEH GUAN
NRIC No	S1593587A
Date Of Birth	08/09/1963
Occupation	OUTDOOR
Date Of Driving Pass	10/05/1985
Driving Experience	32 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	+65-92322386
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 550 BEDOK NORTH AVE 1 #08-526
Postcode	460550
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE- SAME DIRECTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	AEK7889 (GOODS VEHICLE)
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer to Police Report - T/20170617/2111

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	AEK7889
Vehicle Make/Model/Colour	MALAYSIAN VEHICLE
Details Of Properties	
Name of Driver	MOGANDASS A/L FRANCIS
NRIC/Passport Number	881122-56-6241
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;




(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

<div style="text-align: center;"></div> <div>Policyholder's Signature / Date & Time</div>	<div style="text-align: center;"></div> <div>Driver's Signature (If driver is not the policyholder) / Date & Time</div>	<div style="text-align: center;"></div> <div>Witnessed by Reporting Centre Personnel</div>
--	--	---

Sketch Plan

A: SHC5913Y
B: AEK7889



Describe Circumstances of the Accident

PLS refer to police report

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel



**SINGAPORE
POLICE FORCE**



T/20170617/2111

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20170617/2111

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/06/2017 16:27	Vide Report No.: D/20170617/0051	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars			
Name of Informant: TAN KEH GUAN		Address: APT BLK 550 BEDOK NTH AVE 1 #08-526 SINGAPORE 460550	
ID Type / ID No.: NRIC NO / S1593587A		Contact No.: Home/Office: Mobile: 92322386	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 53	Date of Birth: 08/09/1963	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/06/2017 09:35	Type of Location: Bend
Location: Along Road 1 AYER RAJAH EXPRESSWAY (MCE) AFTER SLIP RD INTO ALEXANDRA RD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
AEK7889	TRAILER					0
SHC5913Y	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report Pg. 1

**POLICE FORCE**

CONTINUATION OF REPORT
T/20170617/2111

2 of 3

Report No. T/20170617/2111

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Driver			
Name	TAN KEH GUAN	ID No.	S1593587A
Related Vehicle	NIL	Contact No.	92322386
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE A/M DATE AND TIME, I WAS TRAVELLING ALONG THE A/M LOCATION ON THE MIDDLE OF 3 LANES, NEGOTIATING A RIGHT BEND INTO ALEXANDER ROAD. THERE WAS A TRAILER TRAVELLING ON MY LEFT. AS SUCH, I WAS TRAVELLING MORE TO THE RIGHT OF MY LANE, AS I KNOW THAT TRAILERS HAVE A LARGER TURNING DISTANCE. AS I WAS NEGOTIATING THE BEND, I SAW THE HEAD OF THE TRAILER SUDDENLY CUT INTO MY LANE AND SENSING THAT THE REAR OF THE TRAILER WAS GOING TO HIT MY VEHICLE, I IMMEDIATELY SWERVED TO THE FIRST LANE TO AVOID A COLLISION. HOWEVER, THE RIGHT REAR PORTION OF THE TRAILER COLLIDED INTO THE FRONT LEFT PASSENGER DOOR OF MY VEHICLE. AS I TRIED TO STEER MY VEHICLE TO THE EXTREME RIGHT LANE, MY VEHICLE MOUNTED THE KERB AND HIT INTO THE GUARD RAILING AFTER THE COLLISION.

**SINGAPORE
POLICE FORCE**

T/20170617/2111

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20170617/2111

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
MICHAEL CHIA YI CHUEN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt SALEHA BINTE MOHAMED SANI
Contact No.: 65476258

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
17/06/2017 16:27

Classification Of Case:

**SINGAPORE
POLICE FORCE**

Addendum Sheet Pg. 1

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MTCS17079841 Vehicle Registration No : SHC5913Y
Name(as shown in NRIC): _____
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No : S1593587A
Address : BLK 550 BEDOK NORTH AVE 1 #08-526 S'460550
Contact (Tel) : _____ (H/P) : 92322386
(Email) : _____
Date of Accident : 17/06/2017 Time of Accident : 09:35
Place of Accident : AYE slip road towards Alexandra Road
Insurance Company : AXA Insurance Pte Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Sketch plan amended

Signature of Vehicle Owner / Driver

Date:

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030
Operating Hours : Monday to Friday 9am to 5pm

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHC5913Y - MSIA

Not Authored
 17,371.48 **AAD1706-204**
Recovery B&Paint 71 : 918,587.70

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC5913Y - ROEL
VF1ABL15AUC280979
RENAULT
LATITUDE
17.06.2017
MSIA

		PART	LIST
1	1	BUMPER COVER FRT	\$ CMA 1,259.42 ✓
2	1	BUMPER RETAINER FRT LH	\$ M/Y 151.41 ✓
3	1	BUMPER BRACKET FRT LH	\$ S 181.75 X
4	1	BUMPER UNDERTRAY FRT	\$ S 472.83 X
5	1	BUMPER SPOILER FRT	\$ D/Y 181.75 ✓
6	1	BUMPER FOG LAMP GRILLE LH	\$ S 207.22 X
7	1	BUMPER GRILLE LOWER FRT	\$ S 266.80 X
8	1	BUMPER BEAM FRT	\$ R 914.08 X
9	1	RADAIOR GRILLE	\$ S 1,707.78 X
10	1	RADAIOR GRILLE BADGE 'RENAULT'	\$ M 225.36 X
11	1	RADAIOR GRILLE FRAME	\$ S 1,353.75 X
12	1	FRMAE FULL SUPPORT PANEL	\$ S 615.90 X
13	1	FRMAE FULL SUPPORT BRACKET	\$ R 89.79 X
14	1	AIR CLEANER LOWER	\$ S 352.64 X
15	1	AIR CLEANER HOSE	\$ S 76.14 X
16	1	STEERING PUMP ELECTRIC	\$ S 2,306.90 X
17	1	FENDER PANEL FRT LH	\$ M/Y 783.83 ✓
18	1	WHEELARCH FRT LH	\$ T 139.52 ✓
19	1	WHEEL HOUSING PANEL FRT LH	\$ R 5,173.47 X
20	1	HEADLAMP LH	\$ M/Y 1,184.43 ✓
21	1	HEADLAMP PANEL FRT LH	\$ R 152.15 X
22	1	ENGINE UNDERTRAY	\$ S 564.98 X
23	1	LOWER ARM LH	\$ B 685.76 ✓
24	1	KUNCKLE ARM LH	\$ B 846.98 ✓
25	1	KUNCKLE HUB+BEARING LH	\$ M 497.69 ✓
26	1	ABSORBER FRT LH	\$ B 360.54 ✓
27	1	ABSORBER DUST COVER	\$ S 228.72 X
28	1	STABILIZER BAR FRT	\$ S 604.65 X
29	2	STABILIZER LINK FRT	\$ D/Y 117.22 ✓
30	1	DRIVESHAFT LH	\$ R 1,914.79 X
31	1	VEHICLE HARNESS PASS ROOM	\$ S 10,003.86 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5913Y - MSIA

AAD1706-204

32	1	DOOR PANEL FRT LH	\$	CRU 2,844.66 ✓✓
33	1	DOOR HINGE UPPER LH	\$	B 274.50 ✓✓
34	1	DOOR HINGE LOWER LH	\$	B 300.55 ✓✓
35	1	DOOR CHECK FRT LH	\$	Sm 194.77 X
36	1	DOOR LOCK FRT LH	\$	Sm 908.75 ✓✓
37	1	DOOR CATCH FRT LH	\$	R 131.23 X
38	1	DOOR HANDLE OUTER FRT LH	\$	MIT 258.12 ✓✓
39	1	DOOR HANDLE CAP FRT LH	\$	MIT 26.44 ✓✓
40	1	DOOR HANDLE SEAL FRT LH	\$	MIT 7.89 ✓✓
41	1	DOOR HANDLE COVER FRT LH	\$	MIT 13.22 ✓✓
42	1	DOOR HANDLE MODULE FRT LH	\$	MIT 133.60 ✓✓
43	1	DOOR REGULATOR FRT LH	\$	DIT 505.19 ✓✓
44	1	DOOR REGULATOR MOTOR FRT LH	\$	TA 796.46 ✓✓
45	1	DOOR REGULATOR GUIDE FRT LH	\$	Sm 120.97 X
46	1	DOOR GLASS FRT LH	\$	Sm 722.26 X
47	1	DOOR FINISHER FRT LH	\$	Sm 515.06 X
48	1	DOOR MOULDING FRT LH	\$	MIT 176.82 ✓✓
49	1	DOOR FINISHER CLIP KIT FRT LH	\$	Sm 90.97 X
50	1	DOOR CASING LIGHT LH	\$	Sm 90.74 X
51	1	DOOR WATER SHIELD FRT LH	\$	Sm 184.32 X
52	1	DOOR FINISHER INNER FRT LH	\$	Sm 323.44 X
53	1	DOOR FINISHER BRACKET INNER FRT LH	\$	Sm 46.97 X
54	1	DOOR GRAB HANDLE FRT LH	\$	Sm 210.96 X
55	1	DOOR MIRROR LH	\$	MIT 1,483.40 ✓✓
56	1	DOOR MIRROR GLASS LH	\$	Sm 148.20 X
57	1	DOOR MIRROR BACK COVER LH	\$	Sm 218.46 X
58	1	DOOR WHETHERSTRIP FRT LH	\$	GT 474.21 ✓✓
59	1	DOOR SEAL LOWER FRT LH	\$	Sm 105.18 ✓✓
60	1	DOOR SEAL FRT LH	\$	Sm 68.67 ✓✓
61	1	DOOR SEAL FRT LH	\$	Hyundai 72.82 X
62	1	DOOR GLASS RUNNER SEAL FRT LH	\$	Sm 626.36 X
63	1	DOOR WAIST SEAL OUTER FRT LH	\$	Sm 291.27 X
64	1	DOOR WAIST SEAL INNER FRT LH	\$	Sm 107.75 X
65	1	DOOR HINGE PILLAR PANEL OUTER FRT LH	\$	R 2,896.14 X
66	1	DOOR HINGE PILLAR PANEL INNER FRT LH	\$	R 1,542.15 X
67	1	DOOR HARNESS FRT LH	\$	Sm 1,132.56 X
68	1	SEATBELT BUCKLE LH	\$	Sm 984.13 X
69	1	SEATBELT LH	\$	Sm 2,937.80 X
70	1	CENTRE PILLAR OUTER LH	\$	R 880.14 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5913Y - MSIA**AAD1706-204**

71	1	CENTER PILLAR INNER LH	\$	R	907.76	}	X
72	1	CENTER PILLAR REINFORCEMENT LH	\$	R	1,176.15		
73	1	CENTER PILLAR INNER GARNISH - TOP LH	\$	S ₂	168.82		
74	1	CENTER PILLAR INNER GARNISH - LOWER LH	\$	S ₂	365.99		
75	1	ROOF PANEL	\$	R	2,900.70		
76	1	ROCKER PANEL OUTER LH	\$	X	987.49	}	
77	1	ROCKER PANEL INNER LH	\$	R	1,024.79		
78	1	ROCKER PANEL CENTER LH	\$	R	990.25		
79	1	ROCKER PANER INNER GARNISH FRT LH	\$	CM	178.99	}	✓
80	1	ROCKER PANER INNER GARNISH RR LH	\$	S ₂	178.99		
81	1	ROOF SIDE PANEL OUTER LH	\$	R	704.21		X
82	1	DOOR PANEL REAR LH	\$	R	2,844.66	}	X S ₂
83	1	DOOR GUIDE REAR LH	\$		176.82		
84	1	DOOR HINGE UPPER LH	\$		315.74		
85	1	DOOR HINGE LOWER LH	\$		300.55		
86	1	DOOR CHECK REAR LH	\$		203.06		
87	1	DOOR LOCK REAR LH	\$		908.75		
88	1	DOOR HANDLE OUTER REAR LH	\$		126.49		
89	1	DOOR HANDLE CAP REAR LH	\$		35.52		
90	1	DOOR HANDLE SEAL REAR LH	\$		7.89		
91	1	DOOR HANDLE COVER REAR LH	\$		13.22		
92	1	DOOR HANDLE MODULE REAR LH	\$		133.60		
93	1	DOOR FINISHER REAR LH	\$		423.10		
94	1	DOOR MOULDING REAR LH	\$		176.82		
95	1	DOOR GRAB HANDLE REAR LH	\$		210.96		
96	1	DOOR SEAL LOWER RR LH	\$		115.69		
97	1	DOOR SEAL RR LH	\$		75.54		
98	1	DOOR SEAL LOWER RR LH	\$		80.10		
99	1	DOOR GLASS RUNNER SEAL RR LH	\$		688.99		
100	1	DOOR WAIST SEAL OUTER RR LH	\$		320.39		
101	1	DOOR WAIST SEAL INNER RR LH	\$		118.52		
102	1	DOOR HARNESS RR LH	\$		1,122.04		
103	1	FENDER PANEL REAR LH	\$		3,299.13		
104	1	WHEELARCH REAR LH	\$		543.47		
105	1	BUMPER COVER REAR	\$		1,108.46		
106	1	BUMPER LOWER REAR	\$		768.84		
107	1	BUMEPR BRACKET SIDE LH REAR	\$		135.97		
108	1	BUMEPR RETAINER LH REAR	\$		44.99		

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5913Y - MSIA**AAD1706-204**

TOTAL	\$	80,352.73
10%	\$	8,035.27
	\$	72,317.46

Specical Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	66.00	✓
2	1	CAP HUB LH FRT	\$	35.00	X
3	1	RIM LH FRT	\$	385.00	✓
4	1	TYRE LH FRT	\$	330.00	90% ✓
5	1	DOOR STICKER "Trans-cab"	\$	80.00	60% ✓
6	1	DOOR STICKER "Classic"	\$	30.00	15% ✓
7	1	DOOR STICKER "6555-3333"	\$	80.00	X
8	1SET	WHEELARCH CLIP RR LH	\$	66.00	X
9	1	CAP HUB LH RR	\$	35.00	X
10	1	RIM LH RR	\$	385.00	X
11	1	TYRE LH RR	\$	330.00	X
12	1SET	REAR BUMPER CLIP	\$	66.00	X
13	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	X
14	1SET	BUMPR BRACKET SIDE CLIP LH RR	\$	10.00	X
15	1SET	BUMPR RETAINER LH CLIP RR	\$	20.00	X
16	1	FENDER ADVERTISEMENT STICKER FRT LH	\$	300.00	150% ✓
17	1	DOOR ADVERTISEMENT STICKER FRT LH	\$	300.00	150% ✓
18	1	DOOR ADVERTISEMENT STICKER RR LH	\$	300.00	X
19	1	FENDER ADVERTISEMENT STICKER RR LH	\$	300.00	X
20	1	BUMPER ADVERTISEMENT STICKER	\$	200.00	X

TOTAL	\$	3,351.00
TOTAL PARTS	\$	75,668.46

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 5,600.00 1100% ✓

To Check Electrical Lighting Concerned.

\$ 170.00 30% ✓

Putty and spray painting of the affected portion.

\$ 6,000.00 1320% ✓

To check steering geometry and computer wheel alignment

\$ 220.00 60% ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5913Y - MSIA**AAD1706-204**

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00 ²⁰⁰¹ ✓
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	~ 440.00 X
Towing Fees	\$	120.00 501 ✓
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 601 ✓
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	~ 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00 X
To rust-proofing of the affected areas.	\$	170.00 901 ✓
To remove and replace corporate sticker	\$	330.00 501 ✓

TOTAL	\$	14,530.00
Over All Total	\$	90,198.46

(PARTS BY PARTS) Repair Days**20 Days***10 days*




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP19014413/Ksf3e2		
NO.2 ANG MO KIO STREET 63SINGAPORE 569111		Date : 21-08-2019		
		Code : TP378		
1. Policy Particulars :- THIRD PARTY (FOLLOW THROUGH INSPECTION)				
Insured Veh.	Veh. Inspected		SHC 5913Y	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		20/06/2017	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC280979	Colour	METALLIC WHITE / RED	
Odometer	361193	Steering	JAMMED	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	LING LONG	9 mm	
L/H Front Tyre	215/60 R16	LING LONG	9 mm	
R/H Rear Tyre	215/60 R16	LING LONG	7 mm	
L/H Rear Tyre	215/60 R16	LING LONG	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/06/2017	Inspection Date	20/06/2017	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5913Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT	CRACKED	1,259.42	1,259.42
1	BUMPER RETAINER FRT LH	MISSING	151.41	151.41
1	BUMPER BRACKET FRT LH	SERVICEABLE	181.75	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER SPOILER FRT	DISTORTED	181.75	181.75
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.22	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE 'RENAULT'	NOT NECESSARY	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	AIR CLEANER LOWER	SERVICEABLE	352.64	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	STEERING PUMP ELECTRIC	SERVICEABLE	2,306.90	-
1	FENDER PANEL FRT LH	MISSING	783.83	783.83
1	WHEELARCH FRT LH	TORN	139.52	139.52
1	WHEEL HOUSING PANEL FRT LH	TO REPAIR SEE LABOUR	5,173.47	-
1	HEADLAMP LH	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	LOWER ARM LH	BENT	685.76	685.76
1	KNUCKLE ARM LH	BENT	846.98	846.98
1	KNUCKLE HUB+BEARING LH	NECESSARY	497.69	497.69
1	ABSORBER FRT LH	BENT	360.54	360.54
1	ABSORBER DUST COVER	SERVICEABLE	228.72	-
1	STABILIZER BAR FRT	SERVICEABLE	604.65	-
2	STABILIZER LINK FRT	DISTORTED	117.22	117.22
1	DRIVESHAFT LH	TO REPAIR SEE LABOUR	1,914.79	-

Report Ref No. CS/TP19014413/Ksf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	VEHICLE HARNESS PASS ROOM	SERVICEABLE	10,003.86	-
1	DOOR PANEL FRT LH	CRUMPLED	2,844.66	2,844.66
1	DOOR HINGE UPPER LH	BENT	274.50	274.50
1	DOOR HINGE LOWER LH	BENT	300.55	300.55
1	DOOR CHECK FRT LH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT LH	JAMMED	908.75	908.75
1	DOOR CATCH FRT LH	TO REPAIR SEE LABOUR	131.23	-
1	DOOR HANDLE OUTER FRT LH	MISSING	258.12	258.12
1	DOOR HANDLE CAP FRT LH	MISSING	26.44	26.44
1	DOOR HANDLE SEAL FRT LH	MISSING	7.89	7.89
1	DOOR HANDLE COVER FRT LH	MISSING	13.22	13.22
1	DOOR HANDLE MODULE FRT LH	MISSING	133.60	133.60
1	DOOR REGULATOR FRT LH	DISTORTED	505.19	505.19
1	DOOR REGULATOR MOTOR FRT LH	JAMMED	796.46	796.46
1	DOOR REGULATOR GUIDE FRT LH	SERVICEABLE	120.97	-
1	DOOR GLASS FRT LH	SERVICEABLE	722.26	-
1	DOOR FINISHER FRT LH	SERVICEABLE	515.06	-
1	DOOR MOULDING FRT LH	MISSING	176.82	176.82
1	DOOR FINISHER CLIP KIT FRT LH	SERVICEABLE	90.97	-
1	DOOR CASING LIGHT LH	SERVICEABLE	90.74	-
1	DOOR WATER SHIELD FRT LH	SERVICEABLE	184.32	-
1	DOOR FINISHER INNER FRT LH	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER FRT LH	SERVICEABLE	46.97	-
1	DOOR GRAB HANDLE FRT LH	SERVICEABLE	210.96	-
1	DOOR MIRROR LH	MISSING	1,483.40	1,483.40
1	DOOR MIRROR GLASS LH	NOT NECESSARY	148.20	-
1	DOOR MIRROR BACK COVER LH	NOT NECESSARY	218.46	-
1	DOOR WEATHERSTRIP FRT LH	CUT	474.21	474.21
1	DOOR SEAL LOWER FRT LH	NECESSARY	105.18	105.18
1	DOOR SEAL FRT LH	NECESSARY	68.67	68.67
1	DOOR SEAL FRT LH	REPEATED	72.82	-
1	DOOR GLASS RUNNER SEAL FRT LH	SERVICEABLE	626.36	-
1	DOOR WAIST SEAL OUTER FRT LH	SERVICEABLE	291.27	-
1	DOOR WAIST SEAL INNER FRT LH	SERVICEABLE	107.75	-
1	DOOR HINGE PILLAR PANEL OUTER FRT LH	TO REPAIR SEE LABOUR	2,896.14	-

Report Ref No. CS/TP19014413/Ksf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HINGE PILLAR PANEL INNER FRT LH	TO REPAIR SEE LABOUR	1,542.15	-
1	DOOR HARNESS FRT LH	SERVICEABLE	1,132.56	-
1	SEATBELT BUCKLE LH	SERVICEABLE	984.13	-
1	SEATBELT LH	SERVICEABLE	2,937.80	-
1	CENTRE PILLAR OUTER LH	TO REPAIR SEE LABOUR	880.14	-
1	CENTER PILLAR INNER LH	TO REPAIR SEE LABOUR	907.76	-
1	CENTER PILLAR REINFORCEMENT LH	TO REPAIR SEE LABOUR	1,176.15	-
1	CENTER PILLAR INNER GARNISH - TOP LH	SERVICEABLE	168.82	-
1	CENTER PILLAR INNER GARNISH - LOWER LH	SERVICEABLE	365.99	-
1	ROOF PANEL	TO REPAIR SEE LABOUR	2,900.70	-
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	987.49	-
1	ROCKER PANEL INNER LH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL CENTER LH	TO REPAIR SEE LABOUR	990.25	-
1	ROCKER PANEL INNER GARNISH FRT LH	CRACKED	178.99	178.99
1	ROCKER PANEL INNER GARNISH RR LH	SERVICEABLE	178.99	-
1	ROOF SIDE PANEL OUTER LH	TO REPAIR SEE LABOUR	704.21	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR LH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER LH	SERVICEABLE	315.74	-
1	DOOR HINGE LOWER LH	SERVICEABLE	300.55	-
1	DOOR CHECK REAR LH	SERVICEABLE	203.06	-
1	DOOR LOCK REAR LH	SERVICEABLE	908.75	-
1	DOOR HANDLE OUTER REAR LH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH	SERVICEABLE	133.60	-
1	DOOR FINISHER REAR LH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR LH	SERVICEABLE	176.82	-
1	DOOR GRAB HANDLE REAR LH	SERVICEABLE	210.96	-

Report Ref No. CS/TP19014413/Ksf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR SEAL LOWER RR LH	SERVICEABLE	115.69	-
1	DOOR SEAL RR LH	SERVICEABLE	75.54	-
1	DOOR SEAL LOWER RR LH	SERVICEABLE	80.10	-
1	DOOR GLASS RUNNER SEAL RR LH	SERVICEABLE	688.99	-
1	DOOR WAIST SEAL OUTER RR LH	SERVICEABLE	320.39	-
1	DOOR WAIST SEAL INNER RR LH	SERVICEABLE	118.52	-
1	DOOR HARNESS RR LH	SERVICEABLE	1,122.04	-
1	FENDER PANEL REAR LH	SERVICEABLE	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	BUMPER COVER REAR	SERVICEABLE	1,108.46	-
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
	LESS 10% DISCOUNT		-8,035.27	-1,476.52
			72,317.42	13,288.68
	SPECIAL NETT ITEMS			
1	SET WHEELARCH CLIP FRT LH (SN)	NECESSARY	66.00	66.00
1	CAP HUB LH FRT (SN)	SERVICEABLE	35.00	-
1	RIM LH FRT (SN)	BENT	385.00	385.00
1	TYRE LH FRT (SN) (90%)	PUNCTURE	330.00	297.00
1	DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	DOOR STICKER "CLASSIC" (SN)	NECESSARY	30.00	15.00
1	DOOR STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	SET WHEELARCH CLIP RR LH (SN)	NOT NECESSARY	66.00	-
1	CAP HUB LH RR (SN)	SERVICEABLE	35.00	-
1	RIM LH RR (SN)	SERVICEABLE	385.00	-
1	TYRE LH RR (SN)	SERVICEABLE	330.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER LH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	FENDER ADVERTISEMENT STICKER FRT LH (SN)	MISSING	300.00	150.00
1	DOOR ADVERTISEMENT STICKER FRT LH (SN)	MISSING	300.00	150.00
1	DOOR ADVERTISEMENT STICKER RR LH (SN)	NOT NECESSARY	300.00	-
1	FENDER ADVERTISEMENT STICKER RR LH (SN)	NOT NECESSARY	300.00	-

Report Ref No. CS/TP19014413/Ksf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER ADVERTISEMENT STICKER (SN)	NOT NECESSARY	200.00	-
			3,351.00	1,123.00
	LABOUR			
	TO REMOVE AND REPLACE CORPORATE STICKER.		330.00	50.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT, FRAME FULL SUPPORT BRACKET, WHEEL HOUSING PANEL FRT LH, HEADLAMP PANEL FRT LH, DRIVESHAFT LH, DOOR CATCH FRT LH, DOOR HINGE PILLAR PANEL OUTER FRT LH, DOOR HINGE PILLAR PANEL INNER FRT LH, CENTRE PILLAR OUTER LH, CENTER PILLAR INNER LH, CENTER PILLAR REINFORCEMENT LH, ROOF PANEL, ROCKER PANEL OUTER LH, ROCKER PANEL INNER LH, } ROCKER PANEL CENTER LH, ROOF SIDE PANEL OUTER LH AND DOOR PANEL REAR LH. }		5,600.00	1,100.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	30.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	1,320.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.		380.00	200.00
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TOWING FEES.		120.00	50.00
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
			-	-
			-	-
			-	-
			14,530.00	2,960.00
GRAND TOTAL			90,198.42	17,371.68

Report Ref No. CS/TP19014413/Ksf3e2



RECOMMENDED COST OF REPAIRS			17,371.68
-----------------------------	--	--	-----------

Report Ref No. CS/TP19014413/Ksf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.