COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHA 2026M

MAKE

ARK/Kalvn pbyP 14/8/2019 16:35 1. Re CHINA

DEL	: TOYOTA PRIUS	1				
	PARTS DESCRIPTION	QTY	UNIT PRICE	AN	IOUNT	
	REAR BUMPER / July			\$	458.60	
	REAR BUMPER SIDE RETAINER 750			\$	112.70	
	REAR BUMPER CLIPS /			\$	22.00	
	REAR BUMPER UNDER COVER			\$	552.60	
	RETAINER, REAR BUMPER, SIDE, RH			\$	94.80	-
	SEAL, REAR BUMPER SIDE, RH			\$	148.40	
	TAIL LAMP ASSY (UPPER) (RH) × 5			\$	557.90	
	TAIL LAMP ASSY (LOWER) (RH)			\$	548.40	-
	SUB TOTAL			\$	2,495.40	
	LESS 25%	1		\$	623.85	1
	DISCOUNTED TOTAL			\$	1,871.55	-
	REAR BUMPER REVERSE SENSOR × 600			\$	135.70	N
		MO : 10 10 10 10 10 10 10 10 10 10 10 10 10	Solution of the solution of th			
	LABOUR CHARGE		Salvania Sal		200	
	Panel Beating	. No. 1119 12 13 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	The season of	\$	400.00	
	Spray Painting Charge		1500	\$	300.00	2
	Wiring Charge	1 2 S. 10 11 11 11 11 11 11 11 11 11 11 11 11	10 No. 10	\$	50.00	12
	Towing Fee		10 10 10 10 10 10 10 10 10 10 10 10 10 1	\$	90.00	16
	Remove/Refix Reverse Sensor			\$	80.00	3
	TOTAL LABOUR		~	\$	920.00	$\frac{1}{2}$
	Kalan IIII			Ψ	920.00	1
	ESTIMATE TOTAL			\$	2,927.25	1
	TOTAL LABOUR Kalmin Il ((14) ESTIMATE TOTAL 15/8/19 1100h 2 Parys Before Paint ploto					
	Refore Paint oldo					

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline +65 6383 6280 Facsimile +65 6280 9755

Service Centres
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
45 Pandan Road Singapore 609266
383 Sin Ming Drive Singapore 5757
7 Sungell Kadul, Way Singapore 728791
24 Senoko Loop Singapore 758156





JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition		o VIII - Tana	1	Type of Towing:	
1. Date: 13/08/19 Time Received 2. New SPARK Kanne of Customer: My. T	3. Vehicle Type: Private Taxi (CTPL/CCPL) Fleet STK (Boon Lay)		Normal Tow King Dolly Flat Bed Crane-up		
Contact No. : 98501	STR (Boott Eay)				
Vehicle No. : SHA? Make/Model/Colour: Prive Email :	5. Nature of Service: Jumpstart Recovery Change Tyre / Battery		6. Parts Replaced/Remarks:		
7. Location: 5 0 2 A 9. Preferred Workshop: Braddell Loyang Sin Ming Sungei Kadut Senoko Komoco (UBI Others:		Pandan Ubi Cycle & Carriage (PD)	8. Vehicle Tow - Smoky E Overheat Brake Fa Starting F Accident Return Ta	xhaust	
10. Odometer Reading :	1/4 1/2 3/4 E	11. Radio / CD OK Fault	/	PROSIT	
Job Attended		11 17		and	
12. Tow Truck / Recovery Van : V Name of Driver : Vehicle No. :	123135 6122 PM 6159 PM	TZ YISHUN TOWING	OTHERS	#: Cracked X: Dented /: Scatched O: Missing Signature of Customer	
Cash Invoice Details (if applicable)					
13. Cash Invoice No. : Customer Acknowledgement					
 a. I have been advised to remove all valuable cash cards, spectacles, pen, etc. b. I understand that any items left behind are c. Surcharge: Towing fee will be levied if the company of the	at my own risk and SPARK customer decides neither to	Car Care™ will not be held	iable for such losse pairs in SPARK Car	os. Care TM	
Date	Time		Signa	ture of Customer	
14. <u>WORKSHOP</u>				CALL STREET OF THE CONTRACT	
Name of Attending Staff/Guard	Date & Time of	f Arrival*	Signature o	f Attending Staff/Guard WORKSHOP CO	
				WORKSHOP	