

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD19014441/UPS3Q2

**Date:** 16/04/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00011498

**Claimant**  
**Vehicle No :** SJT3825T **Insured Vehicle No :** SKD8828A

Date of Loss: 13/08/2019 Nature of Claim: TP Claim No: 1201900024444

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT3825T		
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 (A)	Engine No:	CAV112364
Reg. Date:	06/10/2009 (Man. Year: 2009)	Chassis No:	WVWZZZ13ZAV410435
Colour:	Blue	Odometer:	187902 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,425.73	5,125.46	1,300.27	20.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,380.00	880.00	38.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$)</b>	<b>8,685.73</b>	<b>6,505.46</b>	<b>2,180.27</b>	<b>25.10</b>
<b>Approved Total (Overridden) (\$)</b>		<b>5,200.00</b>		
<b>(S\$)</b>	8,685.73	5,200.00	3,485.73	40.13
<b>+ GST 7.00/7.00% (S\$)</b>	608.00	364.00	244.00	40.13
<b>Nett Amount (S\$)</b>	<b>9,293.73</b>	<b>5,564.00</b>	<b>3,729.73</b>	<b>40.13</b>
<b>+ Car Rental (7.0 x S\$100.00/day) (S\$)</b>		700.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>6,266.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>6,200.00</b>		

### INSPECTION

Date of Assignment: 19/08/2019

Date Inspected: 19/08/2019 Inspected At:

Focus Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #02-48/50 Autobay  
Singapore 417883

Estimated Period of Repair: 5.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2019)
<b>Parts:</b>	M1-COUPE	VOLKSWAGEN SCIROCCO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJT3825T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented / Buckled	1,450.00 FL	*1,355.26 FL
2	1		*BONNET LOCK	Not Necessary	150.00 FL	*- FL
3	2		*BONNET HINGE	Not Necessary	200.00 FL	*- FL
4	1		*FENDER -RIGHT	Repair	490.00 FL	*- FL
5	1		*FENDER DUST COVER -RIGHT	Torn	135.00 FL	*135.00 FL
6	1		*HEADLAMP	Cracked	680.00 FL	*680.00 FL
7	1		*HEADLAMP TOP PANEL	Repair	110.00 FL	*- FL
8	1		*FRONT SUPPORT	Cracked	750.00 FL	*750.00 FL
9	1		*FRONT GRILLE	Not Necessary	260.00 FL	*- FL
10	1		*FRONT GRILLE GARNISH	Cracked	220.00 FL	*220.00 FL
11	1		*FRONT BUMPER	Distorted	820.00 FL	*820.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	420.00 FL	*420.00 FL
13	1		*FRONT BUMPER SIDE RETAINER	Cracked	52.00 FL	*52.00 FL
14	1		*FRONT BUMPER INNER SPONGE	Torn	126.00 FL	*126.00 FL
15	1		*FRONT BUMPER LOWER GRILLE	Deformed / Torn	280.70 FL	*280.70 FL
16	1		*FRONT BUMPER FOG LAMP-RIGHT	Cracked	298.00 FL	*298.00 FL
17	1		*FRONT BUMPER FOG LAMP COVER -RIGHT	Cut	120.00 FL	*120.00 FL
18	1		*FRONT BUMPER TOWING COVER	Not Necessary	60.00 FL	*- FL
19	1		*FRONT BUMPER UNDER COVER	Torn	298.00 FL	*298.00 FL
20	1		*FRONT WASHER TANK	Deformed	140.00 FL	*140.00 FL
21	1		*FRONT WASHER TANK TUBE JOINT	Not Necessary	80.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,139.70</b>	<b>5,694.96</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	713.97	569.50
<b>Total Parts (\$\$)</b>	<b>6,425.73</b>	<b>5,125.46</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING	New	1,200.00	600.00
2	CHECK WIRING	New	60.00	30.00
3	RUST PROOFING	New	80.00	50.00
4	SPRAY PAINTING	New	920.00	700.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,260.00</b>	<b>1,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >