

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19014442/KKA3Q2

Date: 22/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994322

Claimant
Vehicle No : SHC5216B **Insured Vehicle No :** SLZ2721K

Date of Loss: 14/08/2019 **Nature of Claim:** TP **Claim No:** 3334888296SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5216B
Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) **Engine No:** M9R8839C000701
Reg. Date: 19/02/2014 (Man. Year: 2013) **Chassis No:** VF1ABL15AUC276169
Colour: Metallic White/Red **Odometer:** 804581 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 **Rear Tyre Size:** 215/60 R16
Front Left Side: Touring 9 mm **Rear Left Side:** Giti 6 mm
Front Right Side: Touring 9 mm **Rear Right Side:** Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,336.26	8,945.88	27,390.38	75.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,200.00	1,520.00	17,680.00	92.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	55,536.26	10,465.88	45,070.38	81.15
Approved Total (Overridden) (S\$)		8,350.00		
(S\$)	55,536.26	8,350.00	47,186.26	84.96
+ GST 7.00/7.00% (S\$)	3,887.54	584.50	3,303.04	84.96
Nett Amount (S\$)	59,423.80	8,934.50	50,489.30	84.96
+ Car Rental (7.0 x S\$81.13/day) (S\$)		567.91		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		9,509.90		
Global Sum Settlement (S\$)		9,500.00		

INSPECTION

Date of Assignment: 16/08/2019

Date Inspected: 16/08/2019 **Inspected At:**

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER REAR	Bent	1,108.46 FL	*1,108.46 FL
2	1	*BUMPER LOWER REAR	Bent	768.84 FL	*768.84 FL
3	1	*BUMPER BRACKET CTR REAR	Cracked	113.47 FL	*113.47 FL
4	1	*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1	*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1	*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1	*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1	*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1	*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1	*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1	*BUMPER BEAM BRACKET LH REAR	Bent	225.95 FL	*225.95 FL
12	1	*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1	*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1	*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1	*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1	*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1	*BOOT REFLECTOR LAMP RH	Dented	493.35 FL	*493.35 FL
18	1	*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1	*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1	*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1	*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1	*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1	*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1	*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1	*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1	*BOOT LOCK	Repair	202.67 FL	*- FL
27	1	*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2	*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2	*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1	*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
31	1	*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
32	1	*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
33	1	*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
34	1	*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
35	1	*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
36	1	*TAILLAMP RH	Mtg Cracked	552.55 FL	*552.55 FL
37	1	*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
38	1	*TAILLAMP LH	Serviceable	552.55 FL	*- FL
39	1	*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
40	1	*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
41	1	*OUTER PANEL REAR (END PANEL) TRIM	Dented	404.56 FL	*404.56 FL
42	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
43	1	*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
44	1	*EXHAUST REAR	Repair	7,489.05 FL	*- FL
45	1	*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
46	1	*FUEL FLAP	Serviceable	343.57 FL	*- FL
47	1	*SET PARKING AID	Shorted	700.00 FS	*400.00 FS
48	1	*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
49	1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
50	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
51	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
52	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
53	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
55	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
56	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
57	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
58	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
59	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
60	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
61	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
62	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
63	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS
64	1		*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*- FS
65	1		*TAILLAMP CLIP RH	Necessary	5.00 FS	*5.00 FS
66	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
67	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
68	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
69	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
70	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
71	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
72	1		*REAR LEFT TYRE	Serviceable	330.00 FS	*- FS
73	1		*REAR LEFT TYRE RIM	Serviceable	380.00 FS	*- FS
74	1		*REAR RIGHT TYRE	Serviceable	330.00 FS	*- FS
75	1		*REAR RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
76	1		*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	39,957.51	9,869.87
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,621.25	923.99
Total Parts (\$\$)	36,336.26	8,945.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	7,500.00	660.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	7,500.00	600.00
3	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	New	380.00	0.00
4	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
5	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	New	170.00	0.00
6	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
7	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	60.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
10	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
11	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
12	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
13	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
14	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	0.00
15	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
16	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
17	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
18	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
19	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	New	380.00	0.00
Gross Labour Cost (\$\$)			19,200.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >