

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19014447/GPA3Q2

Date: 18/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : FBN9258S	Insured Vehicle No :	SH7044K
Date of Loss: 24/07/2019	Nature of Claim: TP	Claim No: MCT19070685

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN9258S		
Make & Model:	YAMAHA YZF-R155, 155cc	Engine No:	G3J6E0176151
Reg. Date:	07/01/2019 (Man. Year: 2018)	Chassis No:	MH3RG4710KK093824
Colour:	Black	Odometer:	0 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/60Z R17	Rear Tyre Size:	160/60Z R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,513.00	3,843.70	7,669.30	66.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	450.00	1,130.00	71.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,093.00	4,293.70	8,799.30	67.21
Approved Total (Overridden) (\$\$)		3,400.00		
(\$\$)	13,093.00	3,400.00	9,693.00	74.03
+ GST 7.00/7.00% (\$\$)	916.51	238.00	678.51	74.03
Nett Amount (\$\$)	14,009.51	3,638.00	10,371.51	74.03
+ Loss of Use (6.0 x S\$25.00/day) (\$\$)		150.00		
+ Doc/Search Fee (\$\$)		29.00		
+ Other Costs (\$\$)		60.00		
Nett Liability (\$\$)		3,877.00		

INSPECTION

Date of Assignment: 16/08/2019

Date Inspected: 19/08/2019 Inspected At:

Yew Tee Automobile Tech Pte Ltd
(Kaki Bukit)
Blk 25 Kaki Bukit Road 4, #01-61
SYNERGY @ KAKI BUKIT
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Apr 2020)	
Parts:	N/A	YAMAHA YZF-R155 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN9258S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP FAIRING	Cracked	430.00 FL	*285.00 FL
2	1		*FRONT HEADLAMP	Cracked	480.00 FL	*380.00 FL
3	1		*FRONT HEADLAMP INNER FAIRING	Cracked	370.00 FL	*185.00 FL
4	1		*FRONT HEADLAMP BRACKET	Not Necessary	80.00 FL	*- FL
5	1		*FRONT HEADLAMP LOWER PROTECTOR LH	Deformed	110.00 FL	*55.00 FL
6	1		*FRONT HEADLAMP LOWER PROTECTOR RH	Deformed	110.00 FL	*55.00 FL
7	1		*FRONT VISOR	Cracked	180.00 FL	*60.00 FL
8	1		*FRONT SIDE MIRROR LH	Cut	170.00 FL	*55.00 FL
9	1		*FRONT SIDE MIRROR RH	Missing	170.00 FL	*55.00 FL
10	1		*FRONT SIDE FAIRING LH	Cut	440.00 FL	*156.00 FL
11	1		*FRONT SIDE FAIRING RH	Cut	440.00 FL	*156.00 FL
12	1		*FRONT SIDE INNER FAIRING LH	Cracked	380.00 FL	*55.00 FL
13	1		*FRONT SIDE INNER FAIRING RH	Cracked	380.00 FL	*55.00 FL
14	1		*FRONT SIDE FAIRING TOP PROTECTOR LH	Cut	110.00 FL	*55.00 FL
15	1		*FRONT SIDE FAIRING TOP PROTECTOR RH	Deformed	110.00 FL	*55.00 FL
16	1		*FRONT SIGNAL LAMP LH	Distorted	77.00 FL	*28.00 FL
17	1		*FRONT SIGNAL LAMP RH	Distorted	77.00 FL	*28.00 FL
18	1		*FRONT SIDE LOWER FAIRING LH	Cracked	270.00 FL	*55.00 FL
19	1		*FRONT SIDE LOWER FAIRING RH	Cracked	270.00 FL	*55.00 FL
20	1		*FRONT CENTRE INNER COVER	Cracked	120.00 FL	*60.00 FL
21	1		*FRONT FORK LH	Bent	280.00 FL	*220.00 FL
22	1		*FRONT FORK RH	Bent	280.00 FL	*220.00 FL
23	1		*FRONT WHEEL CENTRE THRU AXLE	Bent	115.00 FL	*48.00 FL
24	1		*FRONT BRAKE ROTOR	Bent	265.00 FL	*265.00 FL
25	1		*FRONT BRAKE CALIPER	Not Necessary	310.00 FL	*- FL
26	1		*FRONT FENDER	Cracked	150.00 FL	*90.00 FL
27	1		*SPEEDOMETER	Not Necessary	1,400.00 FL	*- FL
28	1		*RADIATOR	Cut	700.00 FL	*295.00 FL
29	1		*RADIATOR BRACKET	Not Necessary	40.00 FL	*- FL
30	1		*RADIATOR SIDE COVER LH	Not Necessary	80.00 FL	*- FL
31	1		*RADIATOR SIDE COVER RH	Not Necessary	80.00 FL	*- FL
32	1		*RADIATOR SPARE TANK	Not Necessary	190.00 FL	*- FL
33	1		*RADIATOR HOSE	Not Necessary	30.00 FL	*- FL
34	1		*FRONT EXHAUST PIPE	Not Necessary	1,650.00 FL	*- FL
35	1		*FRONT HANDLE BAR CENTRE	Broken	180.00 FL	*180.00 FL
36	1		*FRONT HANDLE BAR LH	Bent	130.00 FL	*60.00 FL
37	1		*FRONT HANDLE BAR RH	Bent	130.00 FL	*60.00 FL
38	1		*FRONT STEERING STEM	Necessary	140.00 FL	*140.00 FL
39	1		*FRONT STEERING CONE AND BEARING	Necessary	135.00 FL	*60.00 FL
40	1		*FRONT STEERING UPPER BRACKET	Not Necessary	70.00 FL	*- FL
41	1		*FRONT STEERING LOWER BRACKET	Not Necessary	70.00 FL	*- FL
42	1		*BALANCER LH	Cut	20.00 FL	*20.00 FL
43	1		*BALANCER RH	Cut	20.00 FL	*20.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FRONT CLUTCH LEVER LH	Cut	28.00 FL	*28.00 FL
45	1		*FRONT CLUTCH LEVER RH	Cut	28.00 FL	*28.00 FL
46	1		*FRONT CHASSIS FRAME (NPA)	Repair	0.00 FL	*- FL
47	1		*FRONT FOOTREST LH	Broken	45.00 FL	*34.00 FL
48	1		*FRONT FOOTREST BRACKET LH	Bent	140.00 FL	*60.00 FL
49	1		*FRONT FOOT GEAR LEVER LH	Bent	60.00 FL	*45.00 FL
50	1		*REAR SIDE FAIRING LH	Cut	280.00 FL	*77.00 FL
51	1		*REAR SIGNAL LAMP LH	Not Necessary	80.00 FL	*- FL
52	1		*REAR EXHAUST SILENCER COVER RH	Cut	110.00 FL	*75.00 FL
53	1		*REAR EXHAUST SILENCER TAILPIPE	Cut	60.00 FL	*30.00 FL
54	1		*FRONT NUMBER PLATE	Necessary	30.00 FS	*15.00 FS
55	1		*FRONT WHEEL RIM	Cut	300.00 FS	*200.00 FS
56	1		*FRONT TYRE (50%)	Scratched	260.00 FS	*60.00 FS
57	1		*RADIATOR COOLANT	Necessary	60.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,720.00	4,238.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,207.00	394.30
Total Parts (\$\$)	11,513.00	3,843.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND RECONNECT ,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS ,REPLACE DAMAGED PARTS	New	30.00	20.00
2	TO REMOVE AND REFIT ,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS	New	180.00	0.00
3	TO PRESSURE TEST AIR CON CONDENSER AND RADIATOR FOR LEAKAGE	New	120.00	60.00
4	TOWING CHARGES	New	80.00	40.00
5	TO CONDUCT WHEEL BALANCING	New	60.00	30.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	650.00	300.00
7	TO CARRY -OUT BODY CAVITY PRESERVATION	New	60.00	0.00
8	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	400.00	0.00
Gross Labour Cost (S\$)			1,580.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >