

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19014463/KHA3Q2

Date: 11/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800010415

Claimant
Vehicle No : SJL5922A **Insured Vehicle No :** SCL190K

Date of Loss: 16/08/2019 Nature of Claim: TP Claim No: 6191486668SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL5922A	Engine No:	L13Z11009850
Make & Model:	HONDA JAZZ, 1.3 L (A)	Chassis No:	JHMGE68509S209856
Reg. Date:	03/12/2008 (Man. Year: 2008)	Odometer:	176096 km
Colour:	Metallic Grey		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,584.80	3,404.44	180.36	5.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	2,440.00	200.00	7.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,224.80	5,844.44	380.36	6.11
Approved Total (Overridden) (S\$)		4,650.00		
(S\$)	6,224.80	4,650.00	1,574.80	25.30
+ GST 7.00/7.00% (S\$)	435.74	325.50	110.24	25.30
Nett Amount (S\$)	6,660.54	4,975.50	1,685.04	25.30
+ Loss of Use (12.0 x S\$60.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		5,703.50		
Global Sum Settlement (S\$)		5,700.00		

INSPECTION

Date of Assignment: 19/08/2019

Date Inspected: 19/08/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	523.40 FL	*523.40 FL
2	2		*REAR BUMPER SIDE RETAINERS	Distorted	36.60 FL	*36.60 FL
3	1		*REAR BUMPER TOW COVER	Missing	19.60 FL	*19.60 FL
4	6		*REAR BUMPER CLIPS	Necessary	22.20 FL	*22.20 FL
5	1		*REAR CENTRE PANEL	Bent	276.40 FL	*276.40 FL
6	1		*REAR CENTRE PANEL TOP GARNISH	Mtg Distorted	68.50 FL	*68.50 FL
7	2		*TAILLAMPS	Mtg Cracked	477.00 FL	*477.00 FL
8	1		*REAR TAILGATE	Bent	781.50 FL	*781.50 FL
9	1		*TAILGATE EMBLEM (JAZZ)	Necessary	29.80 FL	*29.80 FL
10	1		*TAILGATE INNER LOCK	Dented	189.50 FL	*189.50 FL
11	1		*TAILGATE INNER RUBBER (50%)	Distorted / Dented	74.56 FS	*46.60 FS
12	1		*REAR TOOL BOX	Deformed	129.10 FL	*129.10 FL
13	1		*REAR SPARE TYRE TOP BOARD	Serviceable	190.50 FL	*- FL
14	1		*REAR SPARE TYRE COMPARTMENT	Bent	751.40 FL	*751.40 FL
15	2		*REAR FENDER INNER GARNISHS	Buckled	501.60 FL	*501.60 FL
16	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	90.70 FL	*90.70 FL
17	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
18	1		*REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,402.36	4,183.90
- List Item Discount on L Items 20.00/20.00% (\$)	817.56	779.46
Total Parts (\$)	3,584.80	3,404.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,TAILGATE ASSY ,REAR WIPER ,THIRD BRAKE LIGHT ,CUT ,WELD & RENEW REAR PANEL,REAR SPARE TYRE COMPARTMENT ,KNOCK & REPAIR REAR RH CHASSIS ,REAR BOTH FENDERS & REALIGN THE SAME	New	1,200.00	1,100.00
3	REMOVE & REFIX REAR GARNISHS ,SEAT ,SPEAKER & BOARD ETC	New	100.00	100.00
4	PUTTY & RESPRAY ON REAR BUMPER ,TAILGATE ,REAR FENDERS ,REAR PANEL,REAR SPARE TYRE COMPARTMENT & REAR AFFECTED AREAS	New	1,100.00	1,000.00
5	REMOVE & REFIX REAR EXHAUST PIPE & CHECK LEAKING	New	60.00	60.00
6	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			2,640.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >