

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19014465/R1EA3Q2
Date: 27/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100507367
Claimant
Vehicle No : SBS6404E **Insured Vehicle No :** SLM9073U
 Date of Loss: 03/08/2019 Nature of Claim: TP Claim No: 9646262538SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS6404E**
 Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D (A) Engine No: 902926C1002703
 Reg. Date: 01/07/2013 (Man. Year: 2013) Chassis No: WEB62808323125105
 Colour: Green Odometer: 362478 km
 Engine Capacity: 6374 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
 Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8/8 mm
 Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	80.00	80.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,065.00	1,515.00	58.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,660.00	1,145.00	1,515.00	56.95
+ GST 7.00/7.00% (S\$)	186.20	80.15	106.05	56.95
Nett Amount (S\$)	2,846.20	1,225.15	1,621.05	56.95
+ Loss of Use (3.0 x S\$250.00/day) (S\$)		750.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,977.15		

INSPECTION

Date of Assignment: 19/08/2019
 Date Inspected: 20/08/2019 Inspected At: Tower Transit Singapore Pte Ltd (HQ)
 21 Bulim Drive, Bulim Bus Depot
 Singapore 648170
 Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WHITE & GREY COLOR STICKER	Necessary	80.00 F	*80.00 F
					Total Parts (\$)	80.00
						80.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE STICKER	New	650.00	100.00
2	TO REMOVE & REFIX WHEEL ARCH PANEL	New	650.00	325.00
3	TO PUTTY & SPRAY PAINT WHEEL ARCH PANEL	New	1,280.00	640.00
Gross Labour Cost (\$\$)			2,580.00	1,065.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >