

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19014505/T1SF3E2

Date: 01/12/2020

REFERENCE

Insured/Claimant:	SIMON THOMAS WISE	Policy No:	
Date of Loss:	11/08/2019	Nature of Claim:	OD Claim No: 2864941324SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW4633J	Engine No:	CVK050740
Make & Model:	AUDI A5, 1.8 SPORTSBACK TFSI MU (A)	Chassis No:	WAUZZZF57JA049452
Reg. Date:	12/02/2018 (Man. Year: 2017)	Odometer:	21049 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$147,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,589.00	7,374.64	4,214.36	36.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	21,592.00	11,867.00	9,725.00	45.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,181.00	19,241.64	13,939.36	42.01
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	31,581.00	17,641.64	13,939.36	44.14
+ GST 7.00/7.00% (S\$)	2,210.67	1,234.91	975.76	44.14
Nett Amount (S\$)	33,791.67	18,876.55	14,915.12	44.14

INSPECTION

Date of Assignment: 20/08/2019

Date Inspected: 16/08/2020 Inspected At:

281 Alexandra Road

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 14.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER-LH	Bent	2,285.00 FS	*1,828.00 FS
2	1		*REAR SIDE PANEL INNER-LH	Not Necessary	1,087.00 FS	*- FS
3	1		*REAR SIDE WINDOW-LH	Necessary	653.00 FS	*522.40 FS
4	1		*REAR DOOR-LH	Bent	2,829.00 FS	*2,263.20 FS
5	1		*REAR DOOR OUTER SEAL-LH	Necessary	201.00 FS	*160.80 FS
6	1		*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
7	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
8	1		*REAR DOOR CATCH-LH	Not Necessary	109.00 FS	*- FS
9	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	117.00 FS	*- FS
10	1		*REAR SIDE MEMBER TRIM-LH	Distorted	754.00 FS	*602.80 FS
11	1		*REAR SIDE MEMBER ATTACHMENT PARTS	Necessary	118.00 FS	*94.00 FS
12	1		*SET OF ADHESIVE TAPES	Necessary	192.00 FS	*153.20 FS
13	1		*REAR DOOR HANDLE TRIM PLATE-LH	Cut	80.00 FS	*63.52 FS
14	1		*REAR DOOR HANDLE CHROME TRIM-LH	Not Necessary	124.00 FS	*- FS
15	1		*REAR DOOR HANDLE HOUSING-LH	Not Necessary	7.00 FS	*- FS
16	1		*REAR DOOR HANDLE SENSOR-LH	Not Necessary	208.00 FS	*- FS
17	1		*REAR DOOR HANDLE COVER-LH	Not Necessary	6.00 FS	*- FS
18	1		*REAR DOOR HANDLE EXTERIOR-LH	Not Necessary	35.00 FS	*- FS
19	1		*REAR WHEEL HOUSING LINER-LH	Not Necessary	256.00 FS	*- FS
20	1		*REAR WHEEL HOUSING LINER ATTACHMENT PARTS-LH	Not Necessary	82.00 FS	*- FS
21	1		*REAR ALUMINIM RIM-LH	Cut	943.00 FS	*770.80 FS
22	4		*RUBBER VALVE	Not Necessary	13.00 FS	*- FS
23	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
24	1		*CAVITI WAX	Necessary	140.00 FS	*140.00 FS
25	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
26	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
27	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
28	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 11,589.00 7,374.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	300.00
3	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	360.00	360.00
4	TO DISLODGE AND REINSTALL REAR WIRE HANRESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAYS,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
5	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
6	TO DISMANTLE REAR BUMPER,REAR LID,LHS SILL PANEL TRIM AND LHS REAR DOOR.CUT OUT AND WELD LHS REAR FENDER,LHS REAR INNER SIDE PANEL.RENEW LHS REAR DOOR AND LHS SILL PANEL TRIM.RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	10,400.00	4,000.00
7	TO RESPRAY LHS REAR FENDER,LHS REAR DOOR,LHS SILL PANEL,LHS SILL PANEL TRIM,DOOR ENTRANCES,ROOF CHANNEL,DRAIN PANEL,END PANELLING AND LHS SIDE INNER PANEL.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	6,900.00	3,575.00
8	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (S\$)	11,867.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >