

SKZ6065 G

Toyota Harrier

TP FWD
Vivian

ZSU600061870

Front Bumper	torn	1450.50 ✓
Front Bumper Clips	NA	30 ✓
Front Bumper Side Holder RH.	NA	67 x
Front RH Fender	dented	781.90 ✓
Front RH Fender Inner Shield	?	218.30 x
Front RH Fender Inner Shield Clips	?	30 x
Headlamp RH.	cracked	3303.10 ✓
Front RH wheel rim int		880(SN) 500(SN)
Front RH Lower Arm.	?	435.10 ✓
Front RH Knuckle Arm.	?	665.10 ✓
Front RH wheel Hub c/w bearing	?	371.50 x
Front RH Shock Absorber.	?	591.60 x

5565.50

SN: 500

4174.12

SKZ6005G,

Panel Beating

~~600~~ 300

Spray Painting

~~600~~ 400

Wiring.

~~50~~ 30

To dismantle front undercarriage.

380 x

To perform wheel alignment

150 x 730

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 5404.12

L/S 4.3K

04 Days