

ASS. REC. BY:

REF:

CF/MSG19014526/Cqd3er

Special Instruction:

Surveyor: Simon

Meiimen

ASSIGNMENT (Office)

From (Person): Jasmine Lok

of

M81G

Date/Time: 14/8/19 @ 5-06pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDF 385K

Insured:

XD 5934S

at Workshop in/s

Confines Autolub

Tel:

6471 5111

of

160 Sin Ming Drive # 02-04

Policy No:

27944826

Claim No:

600687

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

2017/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Yuki

Vehicle IN / OUT

Date/Time	Action/Instruction
	SDF 385K-CC41 / M19/80 05337 / Aj4 3q.2
	XD 5934S-X
29/10/19 @ 5:04pm	Confirmed with Yuki final fig \$7842.40, 6 days (Red to 4604.00, 37%)

150
11
161

RECEIVED 8 OCT 2019

**MSIG**

MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)
 4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

Executive
Claims Services

Inspection Report**Type of Survey:**

OD - Excess	
TP Without Prejudice	<input checked="" type="checkbox"/>

Vehicle Details:

Vehicle Reg No
 Make
 Model
 Passenger capacity
 Paint colour & code
 Paint type

SDF 385K
Hyundai
Tucson 1.6T
05
brown

Vehicle Extras:

In-built camera
 Modification

Yes/No
 Yes/No

Vehicle Data:

Odometer reading
 Engine No
 VIN No
 Engine capacity
 Engine modification

3317km

Vehicle Condition:

Seviceable Yes / No

Handbrake
 Footbrake
 Steering
 Body
 Paint

Tyre Condition:

Tread mm

Size

Condition

Front right
 Front left
 Rear left
 Rear right

5	kumho 225 / 60 / 17	
5		
4		
4		

General Data:

Date of accident
 Date of inspection
 Date of assignment
 Inspection location

20-07-19
30-07-19
29-07-19
Cartimes

Painting Process:

Prepare off vehicle
 Painting off vehicle
 Neither (default)

Cost Details:

Parts
 Supplementary
 Miscellaneous
 Body Labour
 Paint labour
 Paint material
 TOTAL
 Towing
 Excess
 Total less excess
 Estimated days for repair

Repairer

Adjuster

Body Panel Repair:

Panel repair calculator used
 Yes / No

--

Remarks:

Lump / Global Sum

--

Reason(s)

Margin Repair / Fast-line

Others:

Repair Authorised
 Date:

--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jul 2019		14 Aug 2019 17:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	T. T. CHUA CONSTRUCTION PTE LTD, Co. Reg. No.: 198901247D		
Main Claimant:	C & P RENT-A-CAR (PTE) LTD, Co. Reg. No.: 197900477H		
Vehicle Reg. No.:	SDF385K	Date of Loss:	20/07/2019 15:00 - :59 [7 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 600687	Policy/Cover Note No.:	27944826 (Comprehensive) Coverage: 01/09/2018 - 31/08/2019
Vehicle Reg. No. (Insured):	XD5934S	Policy No. (Claimant):	
		Excess:	
Repairer:	Cartimes Autolotion Pte Ltd () 160 Sin Ming Drive #02-04 Autocity,, 575722 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]		
Driver/Custodian (Insured):	LU YANSHENG (), NRIC: G5376011U, Tel: +6591431008 Email:		
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. Liab: 100%. TP agree on SJE - assign Axel Lee from FormTeam Consultancy. Contact: Yuki @ 6471 5111		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: claims@cartimes.com.sg
Sent: Tuesday, 29 October 2019 5:04 PM
To: Shiau Chan (LKKAUTO)
Cc: Don
Subject: Re: SDF 385K (D.O.A 20/07/2019) - (YOUR REF: XD 5934 S) - COR

Dear Shiau Chan,

We agreed with the P/P \$7,842.40 with 06 repair days. Please take note that we are still waiting for the supplier memo as a proof showing that in the market does not have any stock for reinforcement bar. There will be a delay on the LOD submission. Thanks.

Regards,

Yuki Peck



CarTimes Autolution Pte Ltd

160 Sin Ming Drive AutoCity #02-04 Singapore 575722

Tel 6471 5111

www.cartimes.com.sg

Journey Together

On 2019-10-29 14:20, Shiau Chan (LKKAUTO) wrote:
Dear Yuki,

Refer to the below matter, we still remain at 6 repair days.

Best Regards,

SHIAU CHAN (MS) | Case Handler

LKK AUTO CONSULTANTS PTE LTD

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

FROM: claims@cartimes.com.sg <claims@cartimes.com.sg>

SENT: Friday, 25 October 2019 5:38 PM

TO: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>

CC: Don <don@cartimes.com.sg>

SUBJECT: Re: SDF 385K (D.O.A 20/07/2019) - (YOUR REF: XD 5934 S) -
MARKED ESTIMATE



MSIG

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

www.msig.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____
Date : _____

Policy No : _____
Claim No : _____

Insured Vehicle No : X7 59345

Date of Accident : 20-07-19

TP Vehicle No : SDF 385K

Place of Survey : Cartimes

Make & Model : Hyundai Tucson
1.6T

Date of Survey : 30-07-19.

Point of Impact / Damages :


Rear

Recommended Reserve :

Repairer's Estimate : \$ 12447.40

Interim Adjustment : \$ 7164.40

Check Items : \$ 2248.00



Proposed : Part by Part / Lump Sum Repair

Excess : \$ -

Estimate Repair Period : 06 days

Pre-accident Market Value (for total loss consideration) : \$ 102000.00

COE / PARF to owner : \$ 47898.00

Vehicle within / not within limit of economical repair.

Others :

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☐ OD Claim
Excess : \$ _____
(Authorised / Revert)

☒ TP Claim
(Without Prejudice)

Vehicle No. SDF 385 K

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 06 days.

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 30-07-19

Victor - Seng @ sg.msig-asia.com


MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
 www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: Jasmine Lok Kheng Kwei

Date: 31 Jul 2019

Preliminary Advice

Insured Vehicle No	: XD5934S	Accident Date	: 20/07/2019
TP Vehicle No	: SDF385K	Assignment Date	: 29/07/2019
Make	: HYUNDAI TUCSON	Est. Duration of Repair	: 6.00
Date of Inspection	: 30/07/2019		
Inspection At	: CARTIMES AUTOLUTION PTE LTD 160 SIN MING DRIVE #02-04 AUTOCITY, SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the rear portion.

Repairer's Estimate (Gross)	:S\$	12,447.40
Revised Amount	:S\$	7,164.40
Check Items (Estimated)	:S\$	2,248.00
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	102,000
COE / PARF Rebate	:S\$	47,898
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- (X) The vehicle is economical/~~not economical~~ for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	477H
Vehicle Details	
Vehicle No.:	SDF385K
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	TL TUCSON FL 1.6 GLS T-GDI DCT 2WD SR
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	G4FJJU564998
Chassis No.:	KMHJ3812VKU879569
Maximum Power Output:	130.0 kW (174 bhp)
Open Market Value:	\$23,592.00
Original Registration Date:	21 Nov 2018
First Registration Date:	21 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$25,029.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Nov 2028
PARF Rebate Amount:	\$18,771.00
Intended COE Rebate Details	
COE Expiry Date:	20 Nov 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,301.00
COE Rebate Amount:	\$28,353.00
Total Rebate Amount:	\$47,124.00

The information contained herein is correct as at 30 Oct 2019

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
SDF385K

Make / Model
HYUNDAI / TL TUCSON FL 1.6 GLS T-GDI DCT 2WD SR

Vehicle Type :
R11 - Private Hire (Self-Drive) Station Wagon/Jeep/Land Rover

Vehicle Attachment 1 :
With Sun Roof

Vehicle Scheme :
Normal

Chassis No. :
KMHJ3812VKU879569

Propellant :
Petrol

Engine No. :
G4FJJU564998

Motor No. :
-

Engine Capacity :
1591 cc

Power Rating :
-

Maximum Power Output :
130.0 kW (174 bhp)

Maximum Laden Weight :

2040 kg

Unladen Weight :

1594 kg

Year Of Manufacture :

2018

Original Registration Date :

21 Nov 2018

Lifespan Expiry Date :

-

COE Category :

B - Car above 1600cc or 97kW (130bhp)

Quota Premium :

\$31,301.00

COE Expiry Date :

20 Nov 2028

Road Tax Expiry Date :

20 Nov 2019

PARF Eligibility Expiry Date :

20 Nov 2028

Inspection Due Date :

20 Nov 2021

Intended Transfer Date :

30 Oct 2019

CO2 Emission :

165.00 (g/km)

CEV/VES Rebate Utilised Amount :

-

CO Emission :

0.109200 (g/km)

HC Emission :

0.029520 (g/km)

NOx Emission :

0.006150 (g/km)

PM Emission :

1.680000 (mg/km)

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (21 Nov 2019 to 20 May 2020)	\$369.00
Road Tax Renewal - 12 months (21 Nov 2019 to 20 Nov 2020)	\$738.00

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees.

Any road tax that has been paid for the vehicle will be transferred to the next owner.

Print

OK →

Save as PDF

Copy as Text



KMHJ 3812VK

Vehicle No.SDF385K

Car Model : HYUNDAI TUCSON 1.6

QTY	DESCRIPTION	REPAIRER'S ESTIMATE(\$\$)	SURVEYORS ADJUSTMENT(\$\$)
LIST ITEM			
1	REAR TAILGATE / Deformed	\$ 1,630.00	
2	REAR TAILGATE TAILLAMP LH & RH ? X N H	\$ 1,742.00	
1	REAR TAILGATE INNER TRIM / Deformed	\$ 288.00	
1	REAR TAILGATE LOCK / Dented	\$ 399.00	
1	REAR TALGATE WINDSCREEN / shattered	\$ 1,257.00	
1	REAR TAIL GATE WINDSCREEN MOULDING / necc	\$ 120.00	
2	REAR TAILGATE REFLECTOR LH&RH 10? X N H	\$ 170.00	
1	HYUNDAI LOGO / necc	\$ 67.00	
1	TUCSON WORDING / necc	\$ 43.00	
1	1.6T WORDING / necc	\$ 34.00	
1	S WORDING / necc	\$ 40.00	
1	REAR BUMPER / Deformed	\$ 666.00	
1	REAR BUMPER LOWER LID / Deformed	\$ 484.00	
1	REAR RENEFORCEMENT BAR / Deformed	\$ 435.00	
2	REAR TAILLAMP LH & RH / Deformed / Cracked @ 593	\$ 1,786.00	1,186
1	REAR END PANEL ? X R	\$ 769.00	
1	REAR END PANE TOP GARNISH ? CRA	\$ 129.00	
1	WIPER MOTOR 10 / Dented X N H	\$ 469.00	
		\$ 10,528.00	
		20% \$ 2,105.60	
		\$ 8,422.40	
Special Nett Items			
1	Rear Reverse sensor	\$ 200.00	/ cracked
1	Rear Reverse camera	300 \$ 400.00	/ cracked Dented
1	Rear end panel sealant	40 \$ 70.00	/ necc
1	Rear end panel top garnish clips	20 \$ 30.00	/ necc
1	Rear bumper clips	\$ 45.00	20 necc
1	Rear number plate w/holder	\$ 45.00	/ Deformed
1	REAR RECORDING CAMERA	150 \$ 180.00	/ missing
1	Rear windscreen selant	\$ 35.00	/ necc
	special nett	\$ 1,005.00	
	TOTAL PART	\$ 9,427.40	



Vehicle No.SDF385K

Car Model : HYUNDAI TUCSON 1.6

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYORS ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,000.00	750
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 900.00	600
3	To remove & replace fittings to rear boot compartment, fender inner trims, end panel etc so as to facilitate repairs.	\$ 80.00	50
4	To remove & replace reverse sensors & refix reverse camera & check for proper function.	\$ 60.00	40
5	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 60.00	30
6	To provide anti-rust treatment on affected areas	\$ 80.00	50
7	Replace rear tailgate windscreen	\$ 120.00	80
	Labour Total :	\$ 3,020.00	2400
	TOTAL (PARTS & LABOUR):	\$ 12,447.40	

11227.40

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jul 2019		14 Aug 2019 17:06 Edit Adj Rpt	S\$7,842.40 Edit Estimates	S\$7,842.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------








































CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	T. T. CHUA CONSTRUCTION PTE LTD, Co. Reg. No.: 198901247D								
Main Claimant:	C & P RENT-A-CAR (PTE) LTD, Co. Reg. No.: 197900477H								
Vehicle Reg. No.:	SDF385K	Date of Loss: 20/07/2019 15:00 - :59 [7 Months and 29 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 600687	Policy/Cover Note No.: 27944826 (Comprehensive) Coverage: 01/09/2018 - 31/08/2019							
Vehicle Reg. No. (Insured):	XD5934S	Policy No. (Claimant):							
		Excess:							
Repairer:	Cartimes Autolution Pte Ltd () 160 Sin Ming Drive #02-04 Autocity,, 575722 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by SIMON HO LEONG CHUAN] ... [Imm.Advice due 15/08/2019]								
Driver/Custodian (Insured):	LU YANSHENG (), NRIC: G5376011U, Tel: +6591431008 Email:								
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. Liab: 100%. TP agree on SJE - assign Axel Lee from FormTeam Consultancy. Contact: Yuki @ 6471 5111								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



























Claim Documents

*SDF385K (600687)
[XD5934S]
TP
C & P RENT-A-CAR (PTE) LTD
Jul 20 2019 3:00PM
[T. T. CHUA CONSTRUCTION PTE LTD]
Cartimes Autolution Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser v

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/07/19 13:01	Accident Statement From: SC - Reg. No: XD5934S, Claimant: T. T. CHUA CONSTRUCTION PTE LTD	 Load HTM	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	31/07/19 14:34	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/09/19 11:32	Photos - Before paint	 Load JPG	<input checked="" type="checkbox"/>
2	09/09/19 11:32	Photos - Before paint	 Load JPG	<input checked="" type="checkbox"/>
3	09/09/19 11:32	Photos - Before paint	 Load JPG	<input checked="" type="checkbox"/>
4	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
5	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
6	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
7	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
8	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
9	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
10	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
11	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
12	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
13	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
14	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
15	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
16	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
17	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
18	09/09/19 11:35	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	30/07/19 19:31	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
2	30/07/19 19:31	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
3	30/07/19 19:31	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
4	30/07/19 19:31	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
5	30/07/19 19:31	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
6	30/07/19 19:31	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
7	30/07/19 19:31	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
8	30/07/19 19:31	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
9	30/07/19 19:31	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
10	30/07/19 19:31	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
11	30/07/19 19:31	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
12	30/07/19 19:32	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
13	30/07/19 19:32	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
14	30/07/19 19:32	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
15	30/07/19 19:32	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
16	30/07/19 19:32	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
17	30/07/19 19:32	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
18	30/07/19 19:32	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
19	30/07/19 19:32	SURVEY PHOTO	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
20	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
21	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
22	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
23	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
24	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
25	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
26	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
27	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
28	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
29	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
30	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
31	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
32	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
33	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
34	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
35	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
36	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
37	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
38	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
39	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
40	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
41	30/07/19 19:33	SURVEY PHOTO	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/07/19 13:12	TP SDF385K E-FILE REPORT	 Load PDF	
2	26/07/19 13:12	PRI from Cartimes Autolotion	 Load PDF	
3	29/07/19 09:03	Agree on SJE.	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	31/07/19 15:57	Preliminary Loss Advise	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014526/CQD3E2

Date: 08/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27944826

Claimant

Vehicle No : SDF385K

Insured Vehicle No : XD5934S

Date of Loss: 20/07/2019

Nature of Claim: TP

Claim No: 600687

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDF385K

Make & Model: HYUNDAI TUCSON, 1.6 GLS T-GDI DCT 2WD (A) Engine No: G4FJJU564998

Reg. Date: 21/11/2018 (Man. Year: 2018)

Chassis No: KMHJ3812VKU879569

Colour: Brown

Odometer: 3317 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17

Rear Tyre Size: 225/60 R17

Front Left Side: Kumho 5 mm

Rear Left Side: Kumho 4 mm

Front Right Side: Kumho 5 mm

Rear Right Side: Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,427.40	6,242.40	3,185.00	33.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,600.00	700.00	30.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	11,727.40	7,842.40	3,885.00	33.13

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 30/07/2019 Inspected At:

Cartimes Autolution Pte Ltd
160 Sin Ming Drive #02-04 Autocity,
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: SIMON HO LEONG CHUAN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2019)
Parts:	M1-SUV	HYUNDAI TUCSON 1.6 GLS T-GDI DCT 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDF385K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Deformed	1,630.00 FL	*1,630.00 FL
2	2		*REAR TAILGATE TAILLAMP LH & RH	Not Necessary	1,742.00 FL	*- FL
3	1		*REAR TAILGATE INNER TRIM	Deformed	288.00 FL	*288.00 FL
4	1		*REAR TAILGATE LOCK	Dented	399.00 FL	*399.00 FL
5	1		*REAR TAILGATE WINDSCREEN	Shattered	1,257.00 FL	*1,257.00 FL
6	1		*REAR TAIL GATE WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
7	2		*REAR TAILGATE REFLECTOR LH & RH	Not Necessary	170.00 FL	*- FL
8	1		*HYUNDAI LOGO	Necessary	67.00 FL	*67.00 FL
9	1		*TUCSON WORDING	Necessary	43.00 FL	*43.00 FL
10	1		*1.6T WORDING	Necessary	34.00 FL	*34.00 FL
11	1		*S WORDING	Necessary	40.00 FL	*40.00 FL
12	1		*REAR BUMPER	Deformed	666.00 FL	*666.00 FL
13	1		*REAR BUMPER LOWER LID	Deformed	484.00 FL	*484.00 FL
14	1		*REAR REINFORCEMENT BAR	Deformed	435.00 FL	*435.00 FL
15	2		*REAR TAILLAMP LH & RH	Grazed / Cracked	1,786.00 FL	*1,186.00 FL
16	1		*REAR END PANEL	Repair	769.00 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Cracked	129.00 FL	*129.00 FL
18	1		*WIPER MOTOR	Not Necessary	469.00 FL	*- FL
19	1		*REAR REVERSE SENSOR	Cracked	200.00 FS	*200.00 FS
20	1		*REAR REVERSE CAMERA	Dented	400.00 FS	*300.00 FS
21	1		*REAR END PANEL SEALANT	Necessary	70.00 FS	*40.00 FS
22	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
23	1		*REAR BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
24	1		*REAR NUMBER PLATE W/HOLDER	Deformed	45.00 FS	*45.00 FS
25	1		*REAR RECORDING CAMERA	Missing	180.00 FS	*150.00 FS
26	1		*REAR WINDSCREEN SEALANT	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,533.00	7,598.00
- List Item Discount on L Items 20.00/20.00% (S\$)	2,105.60	1,355.60
Total Parts (S\$)	9,427.40	6,242.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS	New	1,000.00	750.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	900.00	600.00
3	TO REMOVE & REPLACE FITTINGS TO REAR BOOT COMPARTMENT, FENDER INNER TRIMS, END PANEL ETC SO AS TO FACILITATE REPAIRS	New	80.00	50.00
4	TO REMOVE & REPLACE REVERSE SENSORS & REFIX REVERSE CAMERA & CHECK FOR PROPER FUNCTION	New	60.00	40.00
5	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	80.00	50.00
6	REPLACE REAR TAILGATE WINDSCREEN	New	120.00	80.00
7	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	60.00	30.00
Gross Labour Cost (\$\$)			2,300.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >