

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014526/CQD3E2
Date: 24/06/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27944826
Claimant Vehicle No :	SDF385K	Insured Vehicle No :	XD5934S
Date of Loss:	20/07/2019	Nature of Claim:	TP
		Claim No:	600687

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDF385K	Engine No:	G4FJJU564998
Make & Model:	HYUNDAI TUCSON, 1.6 GLS T-GDI DCT 2WD (A)	Chassis No:	KMHJ3812VKU879569
Reg. Date:	21/11/2018 (Man. Year: 2018)	Odometer:	3317 km
Colour:	Brown		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 4 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,427.40	5,589.52	3,837.88	40.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,600.00	700.00	30.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,727.40	7,189.52	4,537.88	38.69
Approved Total (Overridden) (S\$)		7,189.51		
(S\$)	11,727.40	7,189.51	4,537.89	38.69
+ GST 7.00/7.00% (S\$)	820.92	503.27	317.65	38.69
Nett Amount (S\$)	12,548.32	7,692.78	4,855.54	38.69

INSPECTION

Date of Assignment:	14/08/2019	
Date Inspected:	30/07/2019	Inspected At: Cartimes Autolution Pte Ltd 160 Sin Ming Drive #02-04 Autocity, Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: SIMON HO LEONG CHUAN**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jun 2020)

Parts: M1-SUV HYUNDAI TUCSON 1.6 GLS T-GDI DCT 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: LKK Auto Consultants Pte Ltd/SDF385K/24/06/2020 09:51

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Deformed	1,630.00 FL	*1,630.00 FL
2	2		*REAR TAILGATE TAILLAMP LH & RH	Not Necessary	1,742.00 FL	*- FL
3	1		*REAR TAILGATE INNER TRIM	Deformed	288.00 FL	*288.00 FL
4	1		*REAR TAILGATE LOCK	Dented	399.00 FL	*399.00 FL
5	1		*REAR TAILGATE WINDSCREEN	Shattered	1,257.00 FL	*440.90 FL
6	1		*REAR TAIL GATE WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
7	2		*REAR TAILGATE REFLECTOR LH & RH	Not Necessary	170.00 FL	*- FL
8	1		*HYUNDAI LOGO	Necessary	67.00 FL	*67.00 FL
9	1		*TUCSON WORDING	Necessary	43.00 FL	*43.00 FL
10	1		*1.6T WORDING	Necessary	34.00 FL	*34.00 FL
11	1		*S WORDING	Necessary	40.00 FL	*40.00 FL
12	1		*REAR BUMPER	Deformed	666.00 FL	*666.00 FL
13	1		*REAR BUMPER LOWER LID	Deformed	484.00 FL	*484.00 FL
14	1		*REAR REINFORCEMENT BAR	Deformed	435.00 FL	*435.00 FL
15	2		*REAR TAILLAMP LH & RH	Grazed / Cracked	1,786.00 FL	*1,186.00 FL
16	1		*REAR END PANEL	Repair	769.00 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Cracked	129.00 FL	*129.00 FL
18	1		*WIPER MOTOR	Not Necessary	469.00 FL	*- FL
19	1		*REAR REVERSE SENSOR	Cracked	200.00 FS	*200.00 FS
20	1		*REAR REVERSE CAMERA	Dented	400.00 FS	*300.00 FS
21	1		*REAR END PANEL SEALANT	Necessary	70.00 FS	*40.00 FS
22	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
23	1		*REAR BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
24	1		*REAR NUMBER PLATE W/HOLDER	Deformed	45.00 FS	*45.00 FS
25	1		*REAR RECORDING CAMERA	Missing	180.00 FS	*150.00 FS
26	1		*REAR WINDSCREEN SEALANT	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,533.00	6,781.90
- List Item Discount on L Items 20.00/20.00% (\$)	2,105.60	1,192.38
Total Parts (\$)	9,427.40	5,589.52

LKK Auto Consultants Pte Ltd/SDF385K/24/06/2020 09:51. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS	New	1,000.00	750.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	900.00	600.00
3	TO REMOVE & REPLACE FITTINGS TO REAR BOOT COMPARTMENT, FENDER INNER TRIMS, END PANEL ETC SO AS TO FACILITATE REPAIRS	New	80.00	50.00
4	TO REMOVE & REPLACE REVERSE SENSORS & REFIX REVERSE CAMERA & CHECK FOR PROPER FUNCTION	New	60.00	40.00
5	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	80.00	50.00
6	REPLACE REAR TAILGATE WINDSCREEN	New	120.00	80.00
7	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	60.00	30.00
Gross Labour Cost (\$)			2,300.00	1,600.00

LKK Auto Consultants Pte Ltd/SDF385K/24/06/2020 09:51. Not valid without Reference section.

< END OF ESTIMATES >