

ASS. REC. BY:

REF:

CF/MSG19014532/Cgd3

112

Special Instruction:

Signature: Simon

ASSIGNMENT (Office)

From (Person): Vimmula

of

M81A

Date/Time: 14/8/19 @ 5pm

Estimated Cost:

Bill to:

③D-IT/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJX 6623T

Insured:

at Workshop m/s

E-Care Auto

Tel:

93885988-98897557

of

Buk S, ubi Ave 1 # 01-29

Sng Ann.

Policy No: 29062166 QMY

Claim No:

600907

Sum Insured:

Excess:

\$700.00

Make of Veh:

(Client's Record)

D.O.A.

23/07/2019

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle: IN/OUT

Date/Time	Action/Instruction
	SJX 6623T-NA/MSG19013091/24
28/8/19 @ 10.41m	confirmed with Sngly 4 & 4500, 5 days.
	(Red & 17528.44, 741.7)
	MV. \$21.56.

RECEIVED 04 SEP 2019

150  
11  
161



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)  
4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807  
Tel +65 6827 7888, Fax +65 6827 7800  
[www.msig.com.sg](http://www.msig.com.sg)

Executive  
Claims Services

## Inspection Report

### Type of Survey:

OD - Excess	700
TP Without Prejudice	

### Vehicle Details:

Vehicle Reg No

Make

Model

Passenger capacity

Paint colour & code

Paint type

SJX 6623 T
Toyota
Camri 2.0
05
Silver

### Vehicle Data:

Odometer reading

Engine No

VIN No

Engine capacity

Engine modification

94014 Km

### Vehicle Extras:

In-built camera

Modification

Yes / No

Yes / No

### Vehicle Condition:

Seviceable

Yes / No

Handbrake

Footbrake

Steering

Body

Paint


### Tyre Condition:

Tread mm

Size

Condition

Front right

Front left

Rear left

Rear right

5	Yokohama	215 / 60 R16	
5		u	
4		Li	
4		u	

### General Data:

Date of accident

Date of inspection

Date of assignment

Inspection location

23-07-19
31-07-19
30-07-19
E-care Auto

### Painting Process:

Prepare off vehicle

Painting off vehicle

Neither (default)


### Cost Details:

Repairer

Adjuster

Parts

Supplementary

Miscellaneous

Body Labour

Paint labour

Paint material

TOTAL

Towing

Excess

Total less excess

Estimated days for repair


### Body Panel Repair:

Panel repair calculator used

Yes / No

--

### Remarks:

Lump / Global Sum

--

Reason(s)

Margin Repair / Fast-line

### Others:


Repair Authorised

Date:

--


**MSIG**

**MSIG Insurance (Singapore) Pte. Ltd.** (Co. Reg. No. 200412212G)  
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581  
 Tel 6220 9644, Fax 6225 6371  
[www.msig.com.sg](http://www.msig.com.sg)

To: MSIG Insurance (Singapore) Pte. Ltd.  
 4 Shenton Way  
 #21-01 SGX Centre 2  
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.  
 16 Raffles Quay  
 #24-01 Hong Leong Building  
 Singapore 048581

Attn: Vimimala D/O Raja Singam

Date: 01 Aug 2019

### Preliminary Advice

Vehicle No	: SJX6623T	Accident Date	: 23/07/2019
Make	: TOYOTA CAMRY	Policy No.	: 29002166QMY
Assignment Date	: 30/07/2019	Excess	: S\$700.00
Date of Inspection	: 31/07/2019	Est. Duration of Repair	: 5.00
Inspection At	: E-CARE AUTO SERVICES PTE LTD (HQ) BLOCK 51, UBI AVE 1, #01-29, PAYA UBI IND PK SINGAPORE 408933		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the rear portion.

Repairer's Estimate (Gross)	:S\$	17,028.44
Revised Amount	:S\$	9,688.37
Check Items (Estimated)	:S\$	3,035.37
Total	:S\$	
Lump Sum Repair	:S\$	10,200

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	21,500
COE / PARF Rebate	:S\$	17,271
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

- ( X ) The vehicle is ~~eeconomical~~/not economical for repair.
- ( ) The above survey was conducted on a 'without prejudice' basis.

A Member of MS & AD INSURANCE GROUP



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jul 2019		14 Aug 2019 17:00 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LAU CHEE KEONG, ID: S6937965F, Tel: +6594790608, Email: NOEMAIL		
Vehicle Reg. No.:	SJX6623T	Date of Loss:	23/07/2019 16:00 - :59 [114 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 600907	Policy/Cover Note No.:	29002166QMY (Comprehensive) Coverage: 31/07/2018 - 30/07/2019
		Excess:	S\$700.00
Repairer:	E-Care Auto Services Pte Ltd (HQ) Block 51, Ubi Ave 1, #01-29, Paya Ubi Ind Pk, 408933 Ubi - Tel: 9388 5988		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]		
Driver/Custodian:	LAU CHEE KEONG (49 / Male) , NRIC: S6937965F, Tel: +6594790608 Email: NOEMAIL		
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. Please revert first. No estimate yet. Repairer requested for survey on 31/07/2019 at 2pm.		

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 28 August 2019 10:41 AM  
**To:** E-Care Auto  
**Cc:** E-Care Auto; E-Care Auto  
**Subject:** RE: LOD AND AFTER REPAIR PHOTO SJX6623T (OD) - Please proceed immediate repair at Lump sum \$4,500/-

Dear Sally,

WITHOUT PREJUDICE

Confirm Lump Sum \$4,500.00 before excess \$700.00 & GST and 5 repair days.

Please note that the finalisation subject to insurer's approval.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** E-Care Auto <info\_ecare@yahoo.com>

**Sent:** Thursday, 22 August 2019 3:05 PM

**To:** SUR <sur@lkkauto.com>

**Cc:** E-Care Auto <ec\_auto@ymail.com>; E-Care Auto <ec\_auto@outlook.com>

**Subject:** Fw: LOD AND AFTER REPAIR PHOTO SJX6623T (OD) - Please proceed immediate repair at Lump sum \$4,500/-

Dear Shiau Chan,

As your requested, please find the attached file for your perusal.

Thank You.

Sally  
Motor Claim Department  
E-Care Auto Services Pte Ltd  
51, Ubi Ave 1,

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

[www.msig.com.sg](http://www.msig.com.sg)**PRELIMINARY ADVICE**

OD Claim / TP Claim


Attn : \_\_\_\_\_  
Date : \_\_\_\_\_Policy No : \_\_\_\_\_  
Claim No : \_\_\_\_\_

Insured Vehicle No : SJX 6623T Date of Accident : 23-07-19  
TP Vehicle No : - Place of Survey : E-care Auto  
Make & Model : Toyota Camry 2.0 Date of Survey : 31-07-19

Point of Impact / Damages :  
  

Recommended Reserve :

Repairer's Estimate : \$ 17028.44  
Interim Adjustment : \$ 9688.37  
Check Items : \$ 3035.37

Proposed : Part by Part / Lump Sum Repair \$ 10200/-Excess : \$ 700/-Estimate Repair Period : 05 daysPre-accident Market Value (for total loss consideration) : \$ 21500.00COE / PARF to owner : \$ 17271.00

Vehicle within / not within limit of economical repair.

Others :  
  

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.



OD Claim  
Excess: \$ 700/-  
(Authorised / Revert)



TP Claim  
(Without Prejudice)

Vehicle No. SJX 6623 T

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 05 days

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 31-07-19

Victor - Seng @ sg.msig-asia.com

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	965F
Vehicle Details	
Vehicle No.:	SJX6623T
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1AZE153979
Chassis No.:	MR053BK4107051712
Maximum Power Output:	108.0 kW (144 bhp)
Open Market Value:	\$27,271.00
Original Registration Date:	30 Jun 2010
First Registration Date:	30 Jun 2010
Transfer Count:	2
Actual ARF Paid:	\$27,271.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2020
PARF Rebate Amount:	\$13,635.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$39,911.00
COE Rebate Amount:	\$3,259.00
<b>Total Rebate Amount:</b>	<b>\$16,894.00</b>

The information contained herein is correct as at 05 Sep 2019

OK



> Back to OneMotoring

### Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SJX6623T		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	CAMRY 2.0 AUTO ABS AIRBAG		
Chassis No. :	MR053BK4107051712		
Propellant :	Petrol		
Engine No. :	1AZE153979		
Engine Capacity :	1998 cc		
Maximum Power Output :	108.0 kW ( 144 bhp )		
Maximum Laden Weight :	1970 kg		
Unladen Weight :	1530 kg		
Year Of Manufacture :	2009		
Original Registration Date :	30 Jun 2010		
Lifespan Expiry Date :	-		
COE Category :	B - Car (1601cc & above)		
Quota Premium :	\$39,911.00		
COE Expiry Date :	29 Jun 2020		
Road Tax Expiry Date :	29 Dec 2019		
PARF Eligibility Expiry Date :	29 Jun 2020		
Inspection Due Date :	29 Jun 2021		
Intended Transfer Date :	05 Sep 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print



## E-CARE AUTO SERVICES PTE LTD

51 Ubi Ave 1, #01-29 Paya Ubi Industrial Park Singapore 408933

Tel: +65 68418892 Hotline: +65 97223678

GST Reg. No.: 20102442D

### MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Tel: 6220 9644 Fax: 62257402

### OWN DAMAGE CLAIM

DEAR SIR / MADAM :

**ACCIDENT REPAIR ON: SJX6623T**

Date: 29/07/2019

MODEL : TOYOTA CAMRY 2.0 AUTO

CHASSIS NO : MR053BK4107051712

YEAR OF MANUFACTURE : 2010

DATE / TIME OF ACCIDENT: 23/07/2019 Time: 1635Hrs at BARTLEY ROAD EAST.

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price S\$	Net S\$	Amount S\$
S/N					
1	Bonnet / <i>Deformed</i>	1	1,833.00		1,833.00 <i>1069</i>
2	Bonnet hinge LH / <i>Dented</i>	1	78.00		78.00
3	Bonnet hinge RH / <i>Dented</i>	1	78.00		78.00
4	Bonnet rubber / <i>Deformed</i>	1	80.60		80.60
5	Bonnet stopper LH <i>X NN</i>	1	22.10		22.10
6	Bonnet stopper RH <i>X NN</i>	1	22.10		22.10
7	Bonnet lock / <i>Dented</i>	1	169.00		169.00
8	Bonnet insulator / <i>Torn</i>	1	630.50		630.50 <i>280</i>
9	Bonnet insulator clip / <i>necc</i>	<i>106</i>	<i>7.00</i> <i>5</i>		<i>70.00</i> <i>30</i>
10	Front grille / <i>cracked</i>	1	713.70		713.70 <i>290</i>
11	Front grille emblem / <i>nussing</i>	1	59.80		59.80
12	Front grille clip / <i>necc</i>	<i>85</i>	<i>7.20</i> <i>5</i>		<i>57.60</i> <i>25</i>
13	Front grille stopper LH <i>X NN</i>	1	22.10		22.10
14	Front grille stopper RH <i>X NN</i>	1	22.10		22.10
15	Front brace panel <i>? X R</i>	1	506.87		506.87
16	Front support panel / <i>Dented</i>	1	506.87		506.87
17	Horn high pitch / <i>Dented</i>	1	156.00		156.00 <i>105</i>
18	Horn low pitch <i>X NN</i>	1	156.00		156.00
19	Headlamp LH / <i>grazed</i>	1	1,495.00		1,495.00
20	Headlamp RH <i>? X NN</i>	1	1,495.00		1,495.00
21	Front bumper <i>? X R</i>	1	742.30		742.30
22	Front bumper side bracket LH <i>? X NN</i>	1	123.50		123.50
23	Front bumper side bracket RH <i>? X NN</i>	1	123.50		123.50
24	Front bumper clip / <i>necc</i>	<i>128</i>	<i>7.20</i> <i>5</i>		<i>86.40</i> <i>40</i>
25	Front bumper number plate garnish <i>X NN</i>	1	85.00		85.00
26	Aircon condenser <i>? / Dented</i>	1	1,982.50		1,982.50 <i>1248</i>
27	Front fender LH <i>X necc</i>	1	1,053.00		1,053.00
28	Front fender shield LH <i>X NN</i>	1	201.50		201.50
29	Front fender shield clip <i>X NN</i>	12	7.20		86.40

*Less 2590*

Sub-Total: 12,658.44

Total Parts : 12,658.44

### Special Nett Items

1	Anti-rust coating	3	80.00	<i>100 240.00</i>
2	Front number plate <i>NN</i>	1	80.00	<i>X 80.00</i>

3	Front panel seal	1	120.00	60 <del>120.00</del> nec
4	Refill aircon gas R134	1	100.00	50 <del>100.00</del>
				<hr/> 540.00

**Total Parts:** 13,198.44

**Labour Charges For Damaged Portion**

1	Labour for panel beating, cut, weld, straighten and replace rear damage parts	800	1,500.00
2	To putty and spray paint affected damaged area	800	1,500.00
3	To apply sealant and tuff kote to affected area	120	250.00
4	To disconnect and check electrical wiring	30	80.00
5	To mount vehicle onto chassis alignment bench	X	350.00
6	To remove and replace aircon condenser, pipes, vacuum aircon system	80	150.00

**Total Labour:**

3,830.00

**Total Parts & Labour:** 17,028.44

**GST 7%** 1,191.99

**Grand Total:** 18,220.43

**Repair duration 12 days**



## E-CARE AUTO SERVICES PTE LTD

51 Ubi Ave 1, #01-29 Paya Ubi Industrial Park Singapore 408933  
Tel: +65 68418892 Hotline: +65 97223678  
GST Reg. No.: 20102442D

---

**PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING**

---

Your Reference: GBG2436C  
Our Reference: SJX6623T

Date: 13/08/2019

M/s MSIG Insurance (Singapore) Pte Ltd  
16 Raffles Quay  
#24-01 Hong Leong Building  
Singapore 048581

BY POST & EMAIL

Attention: Claims Department  
**CLAIMANT: LAU CHEE KEONG**

**PROPERTY DAMAGED CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 23/07/2019 ALONG BARTLEY RD EAST, INVOLVING VEHICLE NO SJX6623T & GBG2436C.**

We act for LAU CHEE KEONG who was the owner of motor vehicle no. SJX6623T.


We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 23/07/2019 involving our client's vehicle registration number SJX6623T and vehicle registration number GBG2436C driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/you insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1	Cost of Repair	\$ 4500.00
2	Excess	\$ - 700.00
	<b>Total : + 7% GST</b>	<b>\$ 4066.00</b>

Kindly revert to our client's claim within the next 7 days.

Yours faithfully,

Sally   
Phone: 8239 3100  
Email: info\_ecare@yahoo.com



## E-CARE AUTO SERVICES PTE LTD

51 Ubi Ave 1, #01-29 Paya Ubi Industrial Park Singapore 408933

Tel: +65 68418892 Hotline: +65 97223678

GST Reg. No.: 20102442D

### TAX INVOICE

### Final Repair Bill

Our Ref: SJX6623T

Date:13/08/2019

M/s MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581


Vehicle No : SJX6623T  
Make/ Model : TOYOTA CAMRY  
Year of Manufacture : 2009  
Chassis No. :MR053BK4107051712  
Colour : SILVER  
D.O.A : 23/07/2019

QTY	ITEM/PARTICULARS	AMOUNT (S\$)
-----	------------------	--------------

1. Repair Cost for Motor Vehicle No.  
Type of repair: LUMP SUM :S 4500.00

**TOTAL:SS 4500.00**

**Total : Singapore Dollars Four Thousand and Five Hundred Only.**

  
Signature

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CF/MSG19014532/CQD3N2

Date: 09/09/2019

## REFERENCE

Insured/Claimant: LAU CHEE KEONG Policy No: 29002166QMY  
Date of Loss: 23/07/2019 Nature of Claim: OD Claim No: 600907

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJX6623T  
Make & Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A) Engine No: 1AZE153979  
Reg. Date: 30/06/2010 (Man. Year: 2009) Chassis No: MR053BK4107051712  
Colour: Silver Odometer: 94014 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: S\$21,500.00  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 4 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,858.44	4,225.70	8,632.74	67.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	1,980.00	2,190.00	52.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,028.44</b>	<b>6,205.70</b>	<b>10,822.74</b>	<b>63.56</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		
<b>- Excess (S\$)</b>	700.00	700.00	0.00	0.00
<b>(S\$)</b>	16,328.44	3,800.00	12,528.44	76.73
<b>+ GST 7.00/7.00% (S\$)</b>	1,142.99	266.00	876.99	76.73
<b>Nett Amount (S\$)</b>	<b>17,471.43</b>	<b>4,066.00</b>	<b>13,405.43</b>	<b>76.73</b>

## INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 31/07/2019 Inspected At:

E-Care Auto Services Pte Ltd (HQ)  
Block 51, Ubi Ave 1, #01-29, Paya Ubi  
Ind Pk  
Singapore 408933

Estimated Period of Repair: 5.0 days

Adjuster: SIMON HO LEONG CHUAN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Sep 2019)
<b>Parts:</b>	143	TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJX6623T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Deformed	1,833.00 F	*1,069.00 FL
2	1	*BONNET HINGE LH	Dented	78.00 F	*78.00 FL
3	1	*BONNET HINGE RH	Dented	78.00 F	*78.00 FL
4	1	*BONNET RUBBER	Deformed	80.60 F	*80.60 FL
5	1	*BONNET STOPPER LH	Not Necessary	22.10 F	*- FL
6	1	*BONNET STOPPER RH	Not Necessary	22.10 F	*- FL
7	1	*BONNET LOCK	Dented	169.00 F	*169.00 FL
8	1	*BONNET INSULATOR	Torn	630.50 F	*280.00 FL
9	1	*BONNET INSULATOR CLIP (10 Pcs)	Necessary (6 pcs only)	70.00 F	*30.00 FL
10	1	*FRONT GRILLE	Cracked	713.70 F	*290.00 FL
11	1	*FRONT GRILLE EMBLEM	Missing	59.80 F	*59.80 FL
12	1	*FRONT GRILLE CLIP (8 Pcs)	Necessary (5 Pcs only)	57.60 F	*25.00 FL
13	1	*FRONT GRILLE STOPPER LH	Not Necessary	22.10 F	*- FL
14	1	*FRONT GRILLE STOPPER RH	Not Necessary	22.10 F	*- FL
15	1	*FRONT BRACE PANEL	Repair	506.87 F	*- FL
16	1	*FRONT SUPPORT PANEL	Dented	506.87 F	*506.87 FL
17	1	*HORN HIGH PITCH	Dented	156.00 F	*105.00 FL
18	1	*HORN LOW PITCH	Not Necessary	156.00 F	*- FL
19	1	*HEADLAMP LH	Grazed	1,495.00 F	*1,495.00 FL
20	1	*HEADLAMP RH	Not Necessary	1,495.00 F	*- FL
21	1	*FRONT BUMPER	Repair	742.30 F	*- FL
22	1	*FRONT BUMPER SIDE BRACKET LH	Not Necessary	123.50 F	*- FL
23	1	*FRONT BUMPER SIDE BRACKET RH	Not Necessary	123.50 F	*- FL
24	1	*FRONT BUMPER CLIP (12 Pcs)	Necessary (8 Pcs only)	86.40 F	*40.00 FL
25	1	*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	85.00 F	*- FL
26	1	*AIRCON CONDENSER	Dented	1,982.50 F	*1,248.00 FL
27	1	*FRONT FENDER LH	Repair	1,053.00 F	*- FL
28	1	*FRONT FENDER SHIELD LH	Not Necessary	201.50 F	*- FL
29	12	*FRONT FENDER SHIELD CLIP	Not Necessary	86.40 F	*- FL
30	1	*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
31	1	*FRONT BRACE SEAL	Necessary	120.00 FS	*60.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,858.44</b>	<b>5,614.27</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00</b>	<b>1,388.57</b>
<b>Total Parts (\$\$)</b>	<b>12,858.44</b>	<b>4,225.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	ANTI-RUST COATING	New	240.00	100.00
2	REFILL AIRCON GAS R134	New	100.00	50.00
3	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN AND REPLACE REAR DAMAGE PARTS	New	1,500.00	800.00
4	TO PUTTY AND SPRAY PAINT AFFECTED DAMAGED AREA	New	1,500.00	800.00
5	TO APPLY SEALANT AND TUFF KOTE TO AFFECTED AREA	New	250.00	120.00
6	TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	80.00	30.00
7	TO MOUNT VEHICLE ONTO CHASSIS ALIGNMENT BENCH	New	350.00	0.00
8	TO REMOVE AND REPLACE AIRCON CONDENER,PIPES,VACUUM AIRCON SYSTEM	New	150.00	80.00
Gross Labour Cost (\$\$)			<b>4,170.00</b>	<b>1,980.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;