



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2202608

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 09/05/2022
Reference CC6/CTI19014538/Kea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GX 1576P
Insured Veh. SMH 7032R
Claim No. SNM19D203795
Policy No. DMPCSN3009431900
Accident Date 14/08/2019
Inspection Date 19/08/2019

Description	Total
Survey Inspection	350.00
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI19014538/Kea3q2	Date: 09/05/2022
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMH 7032R	Veh. Inspected	GX 1576P	
Policy No.	DMPCSN3009431900	Coverage (\$)	0.00	
Claim No.	SNM19D203795	Excess (\$)	0.00	
Assign From		Assign Date	19/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2986	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	LH1621010591	Colour	LIGHT GREEN	
Odometer	424462 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14X8	FALKEN	9 mm	
L/H Front Tyre	185 R14X8	FALKEN	9 mm	
R/H Rear Tyre	185 R14X8	FALKEN	9 mm	
L/H Rear Tyre	185 R14X8	FALKEN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/08/2019	Inspection Date	19/08/2019	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 1576P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER FASCIA	BUCKLED	442.10	442.10
1	REAR BUMPER REINFORCEMENT	BENT	305.30	305.30
1	REAR END PANEL -OUTER	BENT	359.10	359.10
1	REAR END PANEL -INNER	* CHECK	688.50	-
1	TAIL GATE LOCK	* CHECK	234.90	-
1	TAIL GATE CENTRE LOGO	NECESSARY	42.50	42.50
	LESS 25% DISCOUNT		-518.10	-287.25
			1,554.30	861.75
1	TAIL GATE RUBBER (50%) (SN)	TORN	293.10	146.55
	LESS 25% DISCOUNT		-73.28	-
			219.82	146.55
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	300.00	200.00
1	TAIL GATE 70KM/H STICKER (SN)	NECESSARY	15.00	15.00
			315.00	215.00
	<u>LABOUR</u>			
	TO APPLY UNDERSEALING.		60.00	30.00
	TO PUTTY AND SPRAY REPLACED PARTS.		600.00	500.00
	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS.		700.00	600.00
			1,360.00	1,130.00
	GRAND TOTAL		3,449.12	2,353.30



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$692.55 NETT)			1,900.00
---	--	--	-----------------

Report Ref No. CC6/CTI19014538/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GX 1576P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

