

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06034

Vehicle Insured : SMH7032R
Accident Date : 14-Aug-2019

Date : 16-Aug-2019

Our Ref : 219130 (CHINA) / CHAN

PAGE : 1

WKV SERVICES PTE LTD
268 WESTWOOD AVE WESTVILLE
Singapore 648468

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE GX1576P

1 pc Rear bumper fascia
1 pc Rear bumper reinforcement
1 pc Rear end panel -outer
1 pc Rear end panel -inner
1 pc Tail gate lock
1 pc Tail gate rubber
1 pc Tail gate centre logo

*Not withain
61 days @ 7
Recovery After Paint
5 days*

Bur	442.10	✓
Mr	305.30	✓
Mr	359.10	✓
	688.50	?
	234.90	?
Mr	293.10	50% in
Mr	42.50	✓

2,365.50

Less 25% : 591.38

1 pc Rear bumper reverse sensor
1 pc Tail gate 70km/h sticker

1,774.12 200% in
shar 300.00 sn
Mr 15.00 sn ✓

To apply undersealing

60.00 30%

To putty and spray replaced parts

600.00 50%

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

700.00 60%

Total : S\$ 3,449.12

Singapore Dollars Three Thousand Four Hundred
and Forty Nine and Cents Twelve Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items to be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: