Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER: LONPAC INSURANCE BHD

PARTICULARS OF CLAIM

Claim Type:

Policy No: Vehicle Reg. No.:

Driver Age: Any Injuries?

Insured/Claimant:

TP

5103849113 SMG9013M

13/06/2020

TRUST LIMO SERVICE

Ref. No: Date of Loss:

Driveable? Third Party Vehicle No.:

Contact No:

Driver:

MT/1057240-001

09/08/2019

SJN5063T

no

KOO YONGDA ANTHONY

(XU YONGDA)

Make/Model:

Vehicle Colour:

Chassis No: Total Loss?

Toyota, Vellfire 2.5 - AGH30 Vehicle Reg. Date:

BLACK

AGH300033216

Engine Number:

Odometer:

Est, Duration of Repair(Day)

13/08/2019

2ARH608345

Description of Accident/loss

Remarks:

Present Location:

COLLISION - PARKED VEHICLE

Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

	14,552.53
GST 7.00%(S\$):	952.03
Gross Total(S\$):	13,600.50
	0.00
	920.00
	850.00
	463.00
	11,367.50
	Amount
	Gross Total(S\$): GST 7.00%(S\$): Nett Amount(S\$):

This claim is handled by: SHUYI

2 Days.

part by prt.

perfore part photos.

Guo Qiang - 82880282

20/8/19.

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insura

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Estima	ates On Parts		MATERIAL PROPERTY OF THE PARTY	0/ D:	After
No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT BUMPER / Cut	3,400.00	-30.00	2,380.00
2	1	FRONT BUMPER SIDE RETAINER LH / LE	- 220.00	-10.00	198.00
3	1	FRONT BUMPER BRACKET LH ?_	220.00	-10.00	198.00
4	1	FRONT BUMPER FOG LAMP LH	440.00	-10.00	396.00
5	1	FRONT BUMPER FOG LAMP GARNISH LH	500.00	-10.00	450.00
6	1	FRONT BUMPER FOG LAMP CHROME LH / Se	R 180.00	-10.00	162.00
7	1	FRONT BUMPER UNDERCOVER LH	075 00	-10.00	337.50
8	1	FRONT BUMPER LOWER GRILLE X	400.00	-10.00	360.00
9	1	FRONT BUMPER INNER SPONGE ?	210.00	-10.00	189.00
10	1	FRONT BUMPER REINFORCEMENT, ?	600.00	-30.00	420.00
11	1	FRONT FENDER LH X NV	1,330.00	-30.00	931.00
12	1	FRONT FENDER INNER SHIELD LH X N//	540.00	-10.00	486.00
13	1	FRONT HEADLAMP HID LH	5,400.00	-10.00	4,860.00
14	1	FRONT HEADLAMP HID LOWER BRACKET	0.00	-10.00	0.00

Total Parts (S\$)	11,367.50

No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	FRONT BUMPER CLIPS / KC	45.00	0.00	45.00	
2	1	FRONT FENDER INNER SHIELD CLIPS	X N/V 38.00	0.00	38.00	
3	1	FRONT BUMPER SENSORS / DM	380.00	0.00	380.00	200
			Sub Total (S\$)		463.00	-

No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	50.00	0.00	50.00	30
2	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power	800.00	0.00	800.00	200
		tools.				

Gross Labour Cost (S\$) 85	
Gloss Laboul Cost (54)	50.00

EStillia	ates on Pa	int Work Labour	,abo	La company		
No.	Qty	Particulars	Amountular	%Disc	After	
-			- 40	E. Francis	Disc	1000
Table	1	To Carry-Out Body Cavity Preservation.	60.00	0.00	60.00	XC
2	1	To Apply Undercoating On The Repaired and	60.00	0.00	60.00	x INN
		Replaced Panels For Rust Protection.	9			_ /
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	0.00	800.00	200.

Estima	ates On Pa	int Work Labour		CHARLES &	THE REAL PROPERTY.
No.	Qty	Particulars	Amount	%Disc	After Disc
			Gross Labour Cost (S\$)		920.00

abou.

< END OF ESTIMATES >

abou tilars

abo.