

Surveyor: NA2

REF:

CS/SPF19014563/Nyd3⁵⁷

Special Instruction:

20/8/19
call still
repair

ASSIGNMENT (Office)

From (Person): Perry of SPFDate/Time: 16/08/2019 03:53pm

Estimated Cost: _____ Bill to: _____

① OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: TP 87D Insured: _____at Workshop m/s Bun Hock Hin Tel: 9787 7084or No. 6 Defunct Lane 4Policy No: _____ Claim No: MHA SPF 0300000113Sum Insured: _____ Excess: TBA

Make of Veh: _____ D.O.A. _____

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 10:35am Person Contacted: Mike

H.O.D. Endorsement: _____

Vehicle IN OUT

Date/Time	Action/Instruction
	TP 87D - N/A / INCD 9002637 / T1
	21/8/19 Sent Preli Revise by Email
	26/8/19 Perry sent email for quotes. Please see attach Doc
	5/9/19 Resent Amended report to Perry by email

DOA: 5/2/2009

APP. REC. BY:

NA2

REF:

SPF

ASSIGNMENT

From:

Date:

20/8/19

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

TP 87D

at Workshop m/s

Ben Hock Hin

of

No-6 Defn June 6

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$ 7BA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

TP 87D

Yr Regn:

Type: M.Car / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA XT 900

c.c

Colour

WHITE

A/C: Insured / Std / NI / ☒ NA

Sp. Reading

78,691

T/Radio: Insured / Std / NI / ☒ NA

Eng/No:

C/No:

SYA 4KM 00000 127606

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size:

F:

120/70 R17

R:

180/55 R17

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5 mm

R/Bal.

5 mm

L/Bal.

- mm

L/Bal.

- mm

D.O.A.

D.O.I.

20/8/19

Survey held at

BAN HOCK HIN

Des. of Damages: Frt / Rear / ☒ O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/11/19 Pat \$4660-20
Har 25-5hrs

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

29/11/19 Typist

Report Format:

Lump Sum / L.B.I.:

\$ 4660-20

PIP

Days Of Repair:

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

180

Transportation:

S + FS \$

Photos

Others

TOTAL

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 9 September 2019 3:34 PM
To: 'Perry HE (SPF)'; Yvonne Wong (LKK Auto)
Cc: SUR; Kim Pang CHAY (SPF); Kwee Huat TAN (SPF)
Subject: RE: Appraisal Services for SPF vehicle at BHH - TP87D

Dear Perry,

Refer to our conversation.

The item is neither crack or damage.

Therefore there is not a need to replace.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Monday, 9 September 2019 12:19 PM
To: Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicle at BHH - TP87D

Hi Yvonne,

What is the meaning for 'serviceable'?

Meaning no need to replace?

1.13	LAMP SIGNAL REAR LH	1	SERVICEABLE	\$4
------	---------------------	---	-------------	-----

Thanks.

Perry He Junyun
Contract Management Engineer
Capability Sustainment, MHA STG (Forward Deployment to SPF)
DID: (65) 6478 4869 | HP: (65) 9191 5725



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

Nivitha (LKK Auto)

From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Friday, 16 August 2019 3:53 PM
To: 'assignments'
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); 'Denise Tay (LKKAuto)'
Subject: Appraisal Services for SPF vehicle at BHH - TP87D

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF motorbike at BHH, with new contractual rate.

Ref: MHASPF0300000113

Vehicle: TP87D

Parts:

- 1.1 BOLT
- 1.2 BOLT FLANGE
- 1.3 BOLT FLANGE
- 1.4 BOLT REAR SIGNAL LAMP
- 1.5 BOX SIDE LH
- 1.6 BRACKET FOOTREST REAR RH
- 1.7 BRACKET SIGNAL LAMP REAR LH
- 1.8 COVER SIDE BOX (TP) RH
- 1.9 COVER SIDE LH (STK 19991) WITH SPRAY PAINTING POLICE LIVERY (LINING)
- 1.10 COVER SIDE RH (STK 26550) WITH SPRAY PAINTING POLICE LIVERY (LINING)
- 1.11 CRASH BAR FRONT
- 1.12 CRASH BAR REAR RH
- 1.13 LAMP SIGNAL REAR LH
- 1.14 LATCH (#20-J) WITH LOCK - S/STEEL
- 1.15 SCREW BINDING LH
- 1.16 STICKER (TP) SIDE BOX LH (NEW MODEL) - SUPPLY BY AEMD
- 1.17 STICKER (TP) SIDE BOX RH (NEW MODEL) - SUPPLY BY AEMD

Labour


REPLACE ITEM 1.5
REPLACE ITEM 1.6
REPLACE ITEM 1.7
REPLACE ITEM 1.8
REPLACE ITEM 1.9
REPLACE ITEM 1.10
REPLACE ITEM 1.11
REPLACE ITEM 1.12
REPLACE ITEM 1.13
Dismantle & Install SIREN
Dismantle & Install FRONT PROTECTOR LH
Dismantle & Install FRONT PROTECTOR RH
REPAIR & WELDING BRACKET FRONT CRASH BAR
REPAIR & SPRAY PAINTING SIREN
REPAIR & SPRAY PAINTING FRONT PROTECTOR LH WITH POLICE LIVERY (LINING)
REPAIR & SPRAY PAINTING FRONT PROTECTOR RH WITH POLICE LIVERY (LINING)

Thanks.

Perry He Junyun
Contract Management Engineer
Capability Sustainment, MHA STG (Forward Deployment to SPF)
DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



1 to provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

Reference No.
MHA/SPF/2019/07-0065 1100028019

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	BOLT	38.00	1	20%	45.60	45.60
1.2	BOLT FLANGE	1.05	2	20%	1.26	2.52
1.3	BOLT FLANGE	3.00	2	20%	3.60	7.20
1.4	BOLT REAR SIGNAL LAMP	48.00	1	20%	57.60	57.60
1.5	BOX SIDE LH	1800.00	1	20%	2160.00	2160.00
1.6	BRACKET FOOTREST REAR RH	70.00	1	20%	84.00	84.00
1.7	BRACKET SIGNAL LAMP REAR LH	195.00	1	20%	234.00	234.00
1.8	COVER SIDE BOX (TP) RH	360.00	1	20%	432.00	432.00
1.9	COVER SIDE LH (STK 19991) WITH SPRAY PAINTING POLICE LIVERY (LINING)	260.00	1	20%	312.00	312.00
1.10	COVER SIDE RH (STK 26550) WITH SPRAY PAINTING POLICE LIVERY (LINING)	260.00	1	20%	312.00	312.00
1.11	CRASH BAR FRONT	550.00	1	20%	660.00	660.00
1.12	CRASH BAR REAR RH	144.00	1	20%	172.80	172.80
1.13	LAMP SIGNAL REAR LH	340.00	1	20%	408.00	408.00
1.14	LATCH (#20-J) WITH LOCK - S/STEEL	48.00	4	20%	57.60	230.40
1.15	SCREW BINDING LH	1.60	4	20%	1.92	7.68
1.16	STICKER (TP) SIDE BOX LH (NEW MODEL) - SUPPLY BY AEMD	0.00	1	20%	0.00	0.00
1.17	STICKER (TP) SIDE BOX RH (NEW MODEL) - SUPPLY BY AEMD	0.00	1	20%	0.00	0.00
2	Additional Services					
2.1						
Remarks:		SUBJECT TO PARTS AVAILABILITY *Spare parts subjected to availability (By air/sea 70 days)			Parts Total:	\$ 5,125.80

~~NA2 LXX~~

~~20/8/19 1430~~

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Thursday, September 05, 2019 1:59 PM
To: Perry HE (SPF)
Cc: SUR; Kim Pang CHAY (SPF); Kwee Huat TAN (SPF)
Subject: RE: Appraisal Services for SPF vehicle at BHH - TP87D
Attachments: TP 87D.xls

Dear Perry

Attach amended report for your ref.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Monday, August 26, 2019 10:30 AM
To: Yvonne Wong (LKK Auto) <yvonne.wong@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicle at BHH - TP87D

Hi Yvonne,

Our contractor has gotten back, replies as below:

Please refer to the photos attached

1. LH rear bracket is bent
2. RH rear bracket is ok

We refer to LKK's report remarks "Unnecessary" for item - BRACKET SIGNAL LAMP REAR LH. If replaced side box without replacing the bent bracket, after fixed the box will slant, and unable to fit in proper, when riding with vibrate may causes it drops.

Also, item 1.1 to 1.4 bolt, bolt flange state "Not necessary" It is bent, unable to hold proper, when we replace crash bar it will slant to the side and collision to the box

Pls confirm whether these statements are correct and amend the report if necessary.

Thanks.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Wednesday, August 21, 2019 5:48 PM
To: Perry_HE@spf.gov.sg
Cc: SUR; Kim Pang CHAY (SPF); Kwee Huat TAN (SPF)
Subject: Appraisal Services for SPF vehicle at BHH - TP87D
Attachments: TP 87D PHOTO.pdf; TP 87D.xls

Dear Perry,

Enclose as attached

Thank you.

Best Regards,

Yvonne Wong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Friday, 16 August 2019 3:53 PM
To: 'assignments' <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; 'Denise Tay (LKKAuto)' <denisetay@lkkauto.com>
Subject: Appraisal Services for SPF vehicle at BHH - TP87D

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF motorbike at BHH, with new contractual rate.

Ref: MHASPF0300000113

Vehicle: TP87D

Parts:

- 1.1 BOLT
- 1.2 BOLT FLANGE
- 1.3 BOLT FLANGE
- 1.4 BOLT REAR SIGNAL LAMP
- 1.5 BOX SIDE LH
- 1.6 BRACKET FOOTREST REAR RH
- 1.7 BRACKET SIGNAL LAMP REAR LH
- 1.8 COVER SIDE BOX (TP) RH

- 1.9 COVER SIDE LH (STK 19991) WITH SPRAY PAINTING POLICE LIVERY (LINING)
- 1.10 COVER SIDE RH (STK 26550) WITH SPRAY PAINTING POLICE LIVERY (LINING)
- 1.11 CRASH BAR FRONT
- 1.12 CRASH BAR REAR RH
- 1.13 LAMP SIGNAL REAR LH
- 1.14 LATCH (#20-J) WITH LOCK - S/STEEL
- 1.15 SCREW BINDING LH
- 1.16 STICKER (TP) SIDE BOX LH (NEW MODEL) - SUPPLY BY AEMD
- 1.17 STICKER (TP) SIDE BOX RH (NEW MODEL) - SUPPLY BY AEMD

Labour

REPLACE ITEM 1.5
REPLACE ITEM 1.6
REPLACE ITEM 1.7
REPLACE ITEM 1.8
REPLACE ITEM 1.9
REPLACE ITEM 1.10
REPLACE ITEM 1.11
REPLACE ITEM 1.12
REPLACE ITEM 1.13
Dismantle & Install SIREN
Dismantle & Install FRONT PROTECTOR LH
Dismantle & Install FRONT PROTECTOR RH
REPAIR & WELDING BRACKET FRONT CRASH BAR
REPAIR & SPRAY PAINTING SIREN
REPAIR & SPRAY PAINTING FRONT PROTECTOR LH WITH POLICE LIVERY (LINING)
REPAIR & SPRAY PAINTING FRONT PROTECTOR RH WITH POLICE LIVERY (LINING)

Thanks.

Perry He Junyun
Contract Management Engineer
Capability Sustainment, MHA STG (Forward Deployment to SPF)
DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Wednesday, August 21, 2019 5:48 PM
To: Perry_HE@spf.gov.sg
Cc: SUR; Kim Pang CHAY (SPF); Kwee Huat TAN (SPF)
Subject: Appraisal Services for SPF vehicle at BHH - TP87D
Attachments: TP 87D PHOTO.pdf; TP 87D.xls

Dear Perry,

Enclose as attached

Thank you.

Best Regards,

Yvonne Wong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Friday, 16 August 2019 3:53 PM
To: 'assignments' <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; 'Denise Tay (LKKAuto)' <denisetay@lkkauto.com>
Subject: Appraisal Services for SPF vehicle at BHH - TP87D

Hi Catherine and Ashley,

Please provide Appraisal Service (Parts and Labour-man hours) for the following SPF motorbike at BHH, with new contractual rate.

Ref: MHASPF0300000113

Vehicle: TP87D

Parts:

- 1.1 BOLT
- 1.2 BOLT FLANGE
- 1.3 BOLT FLANGE
- 1.4 BOLT REAR SIGNAL LAMP
- 1.5 BOX SIDE LH
- 1.6 BRACKET FOOTREST REAR RH
- 1.7 BRACKET SIGNAL LAMP REAR LH
- 1.8 COVER SIDE BOX (TP) RH

- 1.9 COVER SIDE LH (STK 19991) WITH SPRAY PAINTING POLICE LIVERY (LINING)
- 1.10 COVER SIDE RH (STK 26550) WITH SPRAY PAINTING POLICE LIVERY (LINING)
- 1.11 CRASH BAR FRONT
- 1.12 CRASH BAR REAR RH
- 1.13 LAMP SIGNAL REAR LH
- 1.14 LATCH (#20-J) WITH LOCK - S/STEEL
- 1.15 SCREW BINDING LH
- 1.16 STICKER (TP) SIDE BOX LH (NEW MODEL) - SUPPLY BY AEMD
- 1.17 STICKER (TP) SIDE BOX RH (NEW MODEL) - SUPPLY BY AEMD

Labour

REPLACE ITEM 1.5
REPLACE ITEM 1.6
REPLACE ITEM 1.7
REPLACE ITEM 1.8
REPLACE ITEM 1.9
REPLACE ITEM 1.10
REPLACE ITEM 1.11
REPLACE ITEM 1.12
REPLACE ITEM 1.13
Dismantle & Install SIREN
Dismantle & Install FRONT PROTECTOR LH
Dismantle & Install FRONT PROTECTOR RH
REPAIR & WELDING BRACKET FRONT CRASH BAR
REPAIR & SPRAY PAINTING SIREN
REPAIR & SPRAY PAINTING FRONT PROTECTOR LH WITH POLICE LIVERY (LINING)
REPAIR & SPRAY PAINTING FRONT PROTECTOR RH WITH POLICE LIVERY (LINING)

Thanks.

Perry He Junyun
Contract Management Engineer
Capability Sustainment, MHA STG (Forward Deployment to SPF)
DID: (65) 6478 4869 | HP: (65) 9191 5725



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

New

[illegible]

[illegible]

[illegible]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS/SPF19014563/Nyd3s2

CONTRACT MANAGEMENT SECTION(SPORE
POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK Date : 09-12-2019
8 OLD POLICE ACADEMYSINGAPORE 298333
ATTN: PERRY HE Code : SPF3



1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	TP 87D
Policy No.	Coverage (\$)	0.00
Claim No. MHASPF0300000113	Excess (\$)	0.00
Assign From PERRY HE	Assign Date	16/08/2019

2. Vehicle Particulars & Condition

Make & Model	YAMAHA XJ900	c.c	0
Engine No.	HIDDEN	Year of Reg.	0
Chassis No.	JYA4KM00000127606	Colour	WHITE
Odometer	78691	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70 R17	BRIDGESTONE	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	180/55 R17	BRIDGESTONE	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	Inspection Date	20/08/2019
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410	

5a. Remarks

--	--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Registration No. TP 87D

S/N	ITEM DESCRIPTION	PARTS				MAN- HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	BOLT	1	NECESSARY	\$45.60	\$45.60	
1.2	BOLT FLANGE	2	NECESSARY	\$1.26	\$2.52	
1.3	BOLT FLANGE	2	NECESSARY	\$3.60	\$7.20	
1.4	BOLT REAR SIGNAL LAMP	1	NOT NECESSARY	\$57.60		
1.5	BOX SIDE LH	1	BENT	\$2,160.00	\$2,160.00	
1.6	BRACKET FOOTREST REAR RH	1	SCRATCHED	\$84.00	\$84.00	
1.7	BRACKET SIGNAL LAMP REAR LH	1	BENT	\$234.00	\$234.00	
1.8	COVER SIDE BOX (TP) RH	1	DEFORND	\$432.00	\$432.00	
1.9	COVER SIDE LH (STK 19991) WITH SPRAY PAINTING POLICE LIVERY (LINING)	1	NECESSARY	\$312.00	\$312.00	
1.10	COVER SIDE RH (STK 26550) WITH SPRAY PAINTING POLICE LIVERY (LINING)	1	NECESSARY	\$312.00	\$312.00	
1.11	CRASH BAR FRONT	1	SCRATCHED	\$660.00	\$660.00	
1.12	CRASH BAR REAR RH	1	SCRATCHED	\$172.80	\$172.80	
1.13	LAMP SIGNAL REAR LH	1	SERVICEABLE	\$408.00		
1.14	LATCH (#20-J) WITH LOCK - S/STEEL	4	NECESSARY	\$57.60	\$230.40	
1.15	SCREW BINDING LH	4	NECESSARY	\$1.92	\$7.68	
1.16	STICKER (TP) SIDE BOX LH (NEW MODEL) - SUPPLY BY AEMD	1			\$0.00	
1.17	STICKER (TP) SIDE BOX RH (NEW MODEL) - SUPPLY BY AEMD	1			\$0.00	
2	LABOUR DESCRIPTION					
1.1	REPLACE ITEM 1.5					1
1.2	REPLACE ITEM 1.6					1
1.3	REPLACE ITEM 1.7					1
1.4	REPLACE ITEM 1.8					1.5
1.5	REPLACE ITEM 1.9					3

1.6	REPLACE ITEM 1.10					3
1.7	REPLACE ITEM 1.11					2
1.8	REPLACE ITEM 1.12					0.5
1.9	REPLACE ITEM 1.13					0.5
SE	DISMANTLE & INSTALL SIREN					1
1.11	DISMANTLE & INSTALL FRONT PROTECTOR LH					1
1.12	DISMANTLE & INSTALL FRONT PROTECTOR RH					1
1.13	REPAIR & WELDING BRACKET FRONT CRASH BAR					2
1.14	REPAIR & SPRAY PAINTING SIREN					1
1.15	REPAIR & SPRAY PAINTING FRONT PROTECTOR LH WITH POLICE LIVERY (LINING)					3
1.16	REPAIR & SPRAY PAINTING FRONT PROTECTOR RH WITH POLICE LIVERY (LINING)					3
COSTING		TOTAL PARTS COST			\$4,660.20	
		TOTAL MAN-HOUR				25.5

Registration No. TP 87D

Registration No. TP 87D

Vehicle Inspected By



MUHD NAZRIL (NAZ)

Technical Investigator
LL.B. (Hons) London



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.