

ASS. REC. BY:

REF:

CF/MS4/9014582/Ugd30r

Special Instruction:

Surveyor: Simon

ASSIGNMENT (Office)

Mainmen

From (Person):

Christina Way

of

MSLH

Date/Time:

14/8/19 @ 4:39pm

Estimated Cost:

Bill to:

OD ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

QZ1094C

Insured:

SLL7227L

at Workshop m/s

Liu's Brother

Tel:

67411730

of

1 Kelki Bukit Ave 6 #01-01

Policy No:

28816137

Claim No:

600486

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19/07/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Susan

Vehicle:

☒ IN/OUT

Date/Time	Action/Instruction
	estimate ✓
	QZ1094C-CC6/M915002037/Uha342
	SLL7227L-X
	next 3827
17/9/19	1/s @ 3700 confirmed with Susan 6ly. (Red # 7143, 66%)

DOR: 27/1/2015



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)
4 Shenton Way. #27-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

Executive
Claims Services

Liu Bro

Inspection Report

Type of Survey:

OD - Excess	
TP Without Prejudice	/

Vehicle Data:

Odometer reading	452164 km
Engine No	
VIN No	
Engine capacity	
Engine modification	

Vehicle Details:

Vehicle Reg No
Make
Model
Passenger capacity
Paint colour & code
Paint type

GZ 1094C
Mitsubishi
L300
02
white

Vehicle Extras:

In-built camera
Modification

Yes / No
Yes / No

Vehicle Condition:

Seviceable Yes / No

Handbrake	
Footbrake	
Steering	
Body	
Paint	

Tyre Condition:

Tread mm Size Condition

Front right	5	Dunlop	185 / R14	
Front left	5		"	
Rear left	4		"	
Rear right	4		"	

General Data:

Date of accident
Date of inspection
Date of assignment
Inspection location

19-07-19
24-07-19
23-07-19
Liu's brother.

Painting Process:

Prepare off vehicle	
Painting off vehicle	
Neither (default)	

Cost Details:

Parts
Supplementary
Miscellaneous
Body Labour
Paint labour
Paint material
TOTAL
Towing
Excess
Total less excess
Estimated days for repair

Repairer Adjuster

Body Panel Repair:

Panel repair calculator used
Yes / No

RECEIVED 18 SEP 2019

Remarks:

Lump / Global Sum

--

Reason(s) Margin Repair / Fast-line

Others:

Repair Authorised
Date:

--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2019		14 Aug 2019 16:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	Lee Cher Ling, ID: S7315723D			
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N			
Vehicle Reg. No.:	GZ1094C	Date of Loss:	19/07/2019 07:00 - :59 [163 Months and 10 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 600486	Policy/Cover Note No.:	28816137 (Comprehensive) Coverage: 26/07/2018 - 25/01/2020	
Vehicle Reg. No. (Insured):	SLL7227L	Policy No. (Claimant):		
		Excess:		
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]			
Driver/Custodian (Insured):	TAN CHEONG CHIN (46 / Male) , NRIC: S7274413F Email:			
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. Car in. To use IHS as spoken, to survey on 24/07/19 (morning) by IHS anytime.			

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS [View All] [Search Tasks] [Create New Task] [Complete]

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : _____ Policy No : _____
Date : _____ Claim No : _____

Insured Vehicle No : SL 7227L Date of Accident : 19-07-19
TP Vehicle No : GZ 1094C Place of Survey : Liu's brother
Make & Model : Mitsubishi L300 Date of Survey : 24-07-19

Point of Impact / Damages :

Rear.

Recommended Reserve :

Repairer's Estimate : \$ 10843.00
Interim Adjustment : \$ 4533.00
Check Items : \$ 3180.00



Proposed : Part by Part / Lump Sum Repair \$6100/- Excess : \$ —

Estimate Repair Period : 06 days

Pre-accident Market Value (for total loss consideration) : \$ 10000.00

COE / PARF to owner : \$ 6173.00

Vehicle within / not within limit of economical repair.

Others :

* Repairer agree to repair vehicle within the repair limit.

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

☐ OD Claim
Excess : \$ _____
(Authorised / Revert)

☒ TP Claim
(Without Prejudice)

Vehicle No. GZ 1094C

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 06 days.

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 24/07/2019.

Victor - Seng @ sg.msig-asia.com


MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200412212G)
 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581
 Tel 6220 9644, Fax 6225 6371
www.msig.com.sg

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: MSIG Insurance (Singapore) Pte. Ltd.
 16 Raffles Quay
 #24-01 Hong Leong Building
 Singapore 048581

Attn: Christina Wong

Date: 25 Jul 2019

Preliminary Advice

Insured Vehicle No	: SLL7227L	Accident Date	: 19/07/2019
TP Vehicle No	: GZ1094C	Assignment Date	: 23/07/2019
Make	: MITSUBISHI L300 HR M	Est. Duration of Repair	: 6.00
Date of Inspection	: 24/07/2019		
Inspection At	: LIU'S BROTHER AUTO ENGINEERING WORKSHOP (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages Rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,843.00
Revised Amount	:S\$	4,533.00
Check Items (Estimated)	:S\$	3,180.00
Total	:S\$	

Lump Sum Repair	:S\$	6,100.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	10000.00
COE / PARF Rebate	:S\$	6173.00
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- (x) The vehicle is ~~economical~~/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.
- (x) * Repairer agree to repair vehicle within the repair Limit.

A Member of MS & AD INSURANCE GROUP



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 196N

Vehicle Details

Vehicle No.: GZ1094C
Vehicle to be Exported: No
Intended Deregistration Date: 22 Jul 2019
Vehicle Make: MITSUBISHI
Vehicle Model: L300 HR M
Primary Colour: White
Manufacturing Year: 2005
Engine No.: 4D56LA3897
Chassis No.: JMAJNP15V6A000585
Maximum Power Output: -
Open Market Value: \$12,700.00
Original Registration Date: 09 Dec 2005
First Registration Date: 09 Dec 2005
Transfer Count: 1
Actual ARF Paid: \$635.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 08 Dec 2020
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$22,416.00
COE Rebate Amount: \$6,173.00
Total Rebate Amount: \$6,173.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.
The information contained herein is correct as at 22 Jul 2019

OK

> Back to OneMotoring

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	GZ1094C		
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	MITSUBISHI		
Vehicle Model :	L300 HR M		
Chassis No. :	JMAJNP15V6A000585		
Propellant :	Diesel		
Engine No. :	4D56LA3897		
Engine Capacity :	2477 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	2505 kg		
Unladen Weight :	1390 kg		
Year Of Manufacture :	2005		
Original Registration Date :	09 Dec 2005		
Lifespan Expiry Date :	08 Dec 2025		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$22,416.00		
COE Expiry Date :	08 Dec 2020		
Road Tax Expiry Date :	08 Dec 2019		
Inspection Due Date :	08 Dec 2019		
Intended Transfer Date :	18 Sep 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 08 Dec 2019. You may renew the road tax from 09 Sep 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 08 Dec 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 09 Dec 2019 to 08 Jun 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	0.00	-	0.00
Total Amount Payable :			25.00
Message			
This vehicle has a road tax Over Payment of \$159.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.			

You may print this page for reference.

OK

Print

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GZ1094C190719

Estimate

Customer	
Name: MSIG Insurance (Singapore) Pte Ltd	Date: 22-07-19
Address: Motor Claims Department	Vehicle No: GZ1094C
4 Shenton Way #21-01	Model/Make: Mitsubishi
SGX Centre 2 Singapore 068807	L300 HR M

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>Deformed</i>	\$ 988.00	
2	Tailgate Lock <i>Deformed</i>	\$ 147.00	
3	Tailgate Weatherstrip <i>nn</i>	\$ 195.00	X
4	Tailgate Number Plate Outer Garnish <i>Deformed</i>	\$ 232.00	X
5	Tailgate Number Plate Lamp 02 pcs (@ S\$85.00) <i>nn</i>	\$ 170.00	X
6	Tailgate Number Plate "Metal" <i>Deformed</i>	\$ 35.00	SN 145.~
7	Tailgate Inner Trim Board <i>nn</i>	\$ 265.00	X
8	Tailgate Inner Trim Board Clips 1 set <i>nn</i>	\$ 50.00	X
9	Tailgate Windscreen Glass Rubber <i>nn</i>	\$ 198.00	X
10	Tailgate "70 KM/H" Sticker <i>nn</i>	\$ 14.00	SN 105.~
11	Tailgate "8 PAX" Sticker <i>nn</i>	\$ 14.00	SN 105.~
12	Bumper <i>Deformed</i>	\$ 453.00	X
13	Bumper Clips 1 set <i>nn</i>	\$ 65.00	SN 405.~
14	Bumper Side 02 pcs (@ S\$235.00) <i>nn</i>	\$ 470.00	X 370
15	Bumper Side Clips Rh & Lh 2 set (@ S\$50.00) <i>nn</i>	\$ 100.00	SN 60 X
16	Bumper Side Bracket 02 pcs (@ S\$98.00) <i>nn</i>	\$ 196.00	1AC 65
17	Bumper Reflector 02 pcs (@ S\$146.00) <i>nn</i>	\$ 292.00	1AC 38
18	Bumper Reverse Sensor <i>nn</i>	\$ 220.00	SN X
19	Bumper Lower Lamp <i>nn</i>	\$ 185.00	X
20	Tail Lamp 02 pcs (@ S\$356.00) <i>nn</i>	\$ 712.00	X
21	Tail Lamp Panel 02 pcs (@ S\$185.00) <i>nn</i>	\$ 370.00	X
22	End Panel Outer <i>nn</i>	\$ 395.00	X
23	End Panel Inner <i>nn</i>	\$ 485.00	X
24	End Panel Sealant <i>nn</i>	\$ 50.00	SN 5.~
25	Spare Tyre Carrier <i>nn</i>	\$ 417.00	X
26	Exhaust Silencer <i>nn</i>	\$ 875.00	X
27	Wooden Board "Plywood" <i>nn</i>	\$ 280.00	SN X
28	Tailgate "Corporate" Advertisement & Artwork <i>nn</i>	\$ 400.00	SN 3005.~
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water	\$ 120.00	60
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,200.00	800
	To putty & spray painting & including touch up paint on accident affected	\$ 800.00	400 600
	To check all wiring & electrical component for proper function	\$ 80.00	30
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	60
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 90.00	50
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 200.00	X

Total Parts & Labour of estimate for damaged vehicle

\$ 10,843.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

not added

msib

2/5 3700

6m. 24/7/19



M/s Liu's Brother Auto Engrg Wks

p-2819

102

p-2627-1

SN-424-00

L-1600-00

4651-1

202

372088

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2019		14 Aug 2019 16:39 Edit Adj Rpt	S\$3,700.00 Edit Estimates	S\$3,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	Lee Cher Ling, ID: S7315723D	
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N	
Vehicle Reg. No.:	GZ1094C	Date of Loss: 19/07/2019 07:00 - :59 [163 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 600486	Policy/Cover Note No.: 28816137 (Comprehensive) Coverage: 26/07/2018 - 25/01/2020
Vehicle Reg. No. (Insured):	SLL7227L	Policy No. (Claimant):
		Excess:
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 15/08/2019]	
Driver/Custodian (Insured):	TAN CHEONG CHIN (46 / Male) , NRIC: S7274413F Email:	
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. Car in. To use IHS as spoken, to survey on 24/07/19 (morning) by IHS anytime.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GZ1094C (600486)
[SLL7227L]
TP
GOLDBELL LEASING PTE LTD
Jul 19 2019 7:00AM
[Lee Cher Ling]
Liu's Brother Auto Engineering Workshop

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print	
1	25/07/19 11:27	Adjuster Immediate Advice	Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print	
1	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
2	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
3	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
4	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
5	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
6	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
7	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
8	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
9	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
10	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
11	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
12	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
13	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
14	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
15	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
16	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
17	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
18	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
19	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
20	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
21	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
22	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
23	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
24	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
25	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
26	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
27	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
28	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	
29	24/07/19 23:26	SURVEY PHOTO	Load JPG	<input checked="" type="checkbox"/>	

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	23/07/19 10:53	PRI	Load PDF		
2	23/07/19 10:53	OI Accident Report	Load PDF		
3	23/07/19 10:53	TP GZ1094C E-REPORT	Load PDF		
4	23/07/19 10:53	GIA SEARCH	Load PDF		
5	23/07/19 11:24	email to workshop SJE	Load PDF		
6	23/07/19 13:32	email car in	Load PDF		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print	
1	25/07/19 14:33	Preliminary Loss Advise	Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014582/UQD3E2

Date: 19/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28816137

Claimant

Vehicle No : GZ1094C

Insured Vehicle No : SLL7227L

Date of Loss: 19/07/2019

Nature of Claim: TP

Claim No: 600486

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GZ1094C**

Make & Model: MITSUBISHI L300 HR M, 2.5 D (M)

Engine No: 4D56LA3897

Reg. Date: 09/12/2005 (Man. Year: 2005)

Chassis No: JMAJNP15V6A000585

Colour: White

Odometer: 452164 km

Engine Capacity: 2477 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R14

Rear Tyre Size: 185 R14

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,273.00	3,051.10	5,221.90	63.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	1,600.00	970.00	37.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,843.00	4,651.10	6,191.90	57.11
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	10,843.00	3,700.00	7,143.00	65.88
+ GST 7.00/7.00% (S\$)	759.01	259.00	500.01	65.88
Nett Amount (S\$)	11,602.01	3,959.00	7,643.01	65.88

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 24/07/2019 Inspected At:

Liu's Brother Auto Engineering
Workshop (HQ)

BLK 1 KAKI BUKIT AVE 6, #01-01

AUTO BAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Sep 2019)	
Parts:	N/A	MITSUBISHI L300 HR M 2.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ1094C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Distorted	988.00 F	*988.00 FL
2	1		*REAR TAILGATE LOCK	Dented / Jammed	147.00 F	*147.00 FL
3	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	195.00 F	*- FL
4	1		*REAR TAILGATE NUMBER PLATE OUTER GARNISH	Not Necessary	232.00 F	*- FL
5	2		*REAR TAILGATE NUMBER PLATE LAMP	Not Necessary	170.00 F	*- FL
6	1		*REAR TAILGATE NUMBER PLATE METAL	Bent	35.00 FS	*14.00 FS
7	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	265.00 F	*- FL
8	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 F	*- FL
9	1		*REAR TAILGATE WINDSCREEN GLASS RUBBER	Necessary	198.00 F	*198.00 FL
10	1		*REAR TAILGATE 70KM/H STICKER	Necessary	14.00 FS	*10.00 FS
11	1		*REAR TAILGATE 8 PAX STICKER	Necessary	14.00 FS	*10.00 FS
12	1		*REAR BUMPER	Deformed	453.00 F	*453.00 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	65.00 FS	*40.00 FS
14	2		*REAR BUMPER SIDE	Distorted / Torn	470.00 F	*370.00 FL
15	2		*SET REAR BUMPER SIDE CLIPS RH & LH	Not Necessary	100.00 F	*- FL
16	1		*REAR BUMPER SIDE BRACKET	O/S Bent	196.00 F	*65.00 FL
17	1		*REAR BUMPER REFLECTOR	O/S Missing	292.00 F	*38.00 FL
18	1		*REAR BUMPER REVERSE SENSOR	Not fitted	220.00 FS	*- FS
19	1		*REAR BUMPER LOWER LAMP	Not Necessary	185.00 F	*- FL
20	2		*REAR TAIL LAMP	Not Necessary	712.00 F	*- FL
21	2		*REAR TAIL LAMP PANEL	Repair	370.00 F	*- FL
22	1		*REAR END PANEL OUTER	Bent	395.00 F	*395.00 FL
23	1		*REAR END PANEL INNER	Repair	485.00 F	*- FL
24	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
25	1		*REAR SPARE TYRE CARRIER	Bent	417.00 F	*265.00 FL
26	1		*REAR EXHAUST SILENCER	Not Necessary	875.00 F	*- FL
27	1		*REAR WOODEN BOARD PLYWOOD	Not Necessary	280.00 F	*- FL
28	1		*REAR TAILGATE CORPORATE ADVERTISEMENT & ARTWORK)	Necessary	400.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,273.00	3,343.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	291.90

Total Parts (\$\$)	8,273.00	3,051.10
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM WATER	New	120.00	60.00
2	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	800.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	800.00	600.00
4	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	30.00
5	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	60.00
6	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	90.00	50.00
7	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS	New	200.00	0.00
Gross Labour Cost (\$\$)			2,570.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >