Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014582/UQD3E2

Date: 19/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28816137

Claimant Vehicle No: Insured Vehicle No: SLL7227L

Date of Loss: 19/07/2019 Nature of Claim: TP Claim No: 600486

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GZ1094C

Make & Model: MITSUBISHI L300 HR M, 2.5 D (M) Engine No: 4D56LA3897

Reg. Date: 09/12/2005 (Man. Year: 2005) Chassis No: JMAJNP15V6A000585

Colour: White Odometer: 452164 km

Engine Capacity: 2477 cc
Market Value/New Car
N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R14 Rear Tyre Size: 185 R14
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 4 mm
Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,273.00	3,051.10	5,221.90	63.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	1,600.00	970.00	37.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,843.00	4,651.10	6,191.90	57.11
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	10,843.00	3,700.00	7,143.00	65.88
+ GST 7.00/7.00% (S\$)	759.01	259.00	500.01	65.88
Nett Amount (S\$)	11,602.01	3,959.00	7,643.01	65.88

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 24/07/2019 Inspected At: Liu's Brother Auto Engineering

Workshop (HQ)

BLK 1 KAKI BÚKIT AVE 6, #01-01

AUTO BAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Reference					
Part Source:		(Last Synchronised: 19 Sep 2019)			
Parts:	N/A	MITSUBISHI L300 HR M 2.5 D (M) (Model not available in database)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	: (Unsubmitted, no print-code for GZ1094C)				
Validity:	Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page				
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.					

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR TAILGATE	Distorted	988.00 F	*988.00 FL	
2	1		*REAR TAILGATE LOCK	Jammed	147.00 F	*147.00 FL	
3	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	195.00 F	*-FL	
4	1		*REAR TAILGATE NUMBER PLATE OUTER GARNISH	Not Necessary	232.00 F	*-FL	
5	2		*REAR TAILGATE NUMBER PLATE LAMP	Not Necessary	170.00 F	*-FL	
6	1		*REAR TAILGATE NUMBER PLATE METAL	Bent	35.00 FS	*14.00 FS	
7	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	265.00 F	*-FL	
8	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	RIM BOARD CLIPS Not Necessary		*-FL	
9	1		*REAR TAILGATE WINDSCREEN GLASS RUBBER	Necessary	198.00 F	*198.00 FL	
10	1		*REAR TAILGATE 70KM/H STICKER	Necessary	14.00 FS	*10.00 FS	
11	1		*REAR TAILGATE 8 PAX STICKER	Necessary	14.00 FS	*10.00 FS	
12	1		*REAR BUMPER	Distorted	453.00 F	*453.00 FL	
13	1		*SET REAR BUMPER CLIPS	Necessary	65.00 FS		
14	2		*REAR BUMPER SIDE	Distorted / Torn	470.00 F	*370.00 FL	
15	2		*SET REAR BUMPER SIDE CLIPS RH & LH	Not Necessary	100.00 F	*-FL	
16	1		*REAR BUMPER SIDE BRACKET	O/S Bent	196.00 F	*65.00 FL	
17	1		*REAR BUMPER REFLECTOR	O/S Missing	292.00 F	*38.00 FL	
18	1		*REAR BUMPER REVERSE SENSOR	Not fitted	220.00 FS	*-FS	
19	1		*REAR BUMPER LOWER LAMP	Not Necessary	185.00 F	*-FL	
20	2		*REAR TAIL LAMP	Not Necessary	712.00 F	*-FL	
21	2		*REAR TAIL LAMP PANEL	Repair	370.00 F	*- FL	
22	1		*REAR END PANEL OUTER	Bent	395.00 F	*395.00 FL	
23	1		*REAR END PANEL INNER	Repair	485.00 F	*-FL	
24	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS	
25	1		*REAR SPARE TYRE CARRIER	Bent	417.00 F	*265.00 FL	
26	1		*REAR EXHAUST SILENCER	Not Necessary	875.00 F	*-FL	
27	1		*REAR WOODEN BOARD PLYWOOD	Not Necessary	280.00 F	*-FL	
28	1		*REAR TAILGATE CORPORATE ADVERTISEMENT & ARTWORK)	Necessary	400.00 FS	*300.00 FS	
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	•	3,343.00	
			- List Item Discount on L Items 0	.00/10.00% (S\$)	0.00	291.90	
				Total Parts (S\$)	8,273.00	3,051.10	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars		Condition	Repairer's	Amount
						,	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM WATER	New	120.00	60.00				
2	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	800.00				
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	800.00	600.00				
4	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	30.00				
5	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	60.00				
6	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	90.00	50.00				
7	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS	New	200.00	0.00				
	Gross Labou	r Cost (S\$)	2,570.00	1,600.00				

< END OF ESTIMATES >

Report was unsubmitted during this print-out.