

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CF/MSG19014583/CQD3E2

Date: 24/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28897769MKC
Claimant		
Vehicle No : SMD7470E	Insured Vehicle No :	GZ9665C
Date of Loss: 28/06/2019	Nature of Claim: TP	Claim No: 598918

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD7470E		
Make & Model:	JAGUAR XF, 2.0 GTDI Luxury (A)	Engine No:	041214113235204PT
Reg. Date:	30/04/2015 (Man. Year: 2015)	Chassis No:	SAJAC05M3FPU67437
Colour:	Black	Odometer:	55371 km
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,219.82	11,613.51	11,606.31	49.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,770.00	1,410.00	44.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	26,399.82	13,383.51	13,016.31	49.30
Approved Total (Overridden) (\$)		10,700.00		
(\$)	26,399.82	10,700.00	15,699.82	59.47
+ GST 7.00/7.00% (\$)	1,847.99	749.00	1,098.99	59.47
Nett Amount (\$)	28,247.81	11,449.00	16,798.81	59.47

INSPECTION

Date of Assignment:	14/08/2019	
Date Inspected:	04/07/2019 Inspected At:	BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
		Repairer : Twincar Automotive Pte Ltd
Estimated Period of Repair:	7.0 days	

Adjuster: SIMON HO LEONG CHUAN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2019)
Parts:	143	JAGUAR XF 2.0 GTDI Luxury (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD7470E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Deformed	2,363.22 F	*2,363.22 F
2	1		*REAR BOOTLID JAGUAR EMBLEM	Necessary	209.20 F	*209.20 F
3	1		*REAR BOOTLID LOGO EMBLEM	Necessary	223.15 F	*223.15 F
4	1		*REAR BOOTLID XF EMBLEM	Necessary	109.03 F	*109.03 F
5	1		*REAR BOOTLID CAMERA	Not Necessary	1,098.70 F	*- F
6	1		*REAR BOOTLID CENTER LOCK CONTROL	Not Necessary	199.89 F	*- F
7	2		*REAR BOOTLID DAMPER L/R	Not Necessary	417.20 F	*- F
8	2		*REAR BOOTLID HINGE L/R	Not Necessary	363.14 F	*- F
9	1		*REAR BOOTLID INNER TRIM BOARD	Not Necessary	986.04 F	*- F
10	1		*REAR BOOTLID LOCK STRIKER	Not Necessary	37.93 F	*- F
11	1		*REAR BOOTLID MECHANISM LOCK	Dented	233.59 F	*233.59 F
12	2		*REAR BOOTLID NUMBER PLATE LAMP L/R	Not Necessary	277.20 F	*- F
13	1		*REAR BOOTLID OUTER CHROME HANDLE	Grazed	798.70 F	*798.70 F
14	1		*REAR BOOTLID OUTER LOCK SWITCH	Not Necessary	79.90 F	*- F
15	2		*REAR BOOTLID REFLECTOR L/R	Cracked	751.58 F	*751.58 F
16	1		*REAR BOOTLID WEATHER STRIP	Deformed	158.85 F	*158.85 F
17	1		*REAR BUMPER	Deformed	2,149.83 F	*2,149.83 F
18	1		*REAR BUMPER ANTENNA SENSOR	Not Necessary	30.64 F	*- F
19	1		*REAR BUMPER CENTER BRACKET	Cracked	154.40 F	*154.40 F
20	1		*REAR BUMPER LOWER LID	Cut	646.33 F	*646.33 F
21	1		*REAR BUMPER REINFORCEMENT	Dented	841.20 F	*841.20 F
22	1		*REAR BUMPER REVERSE SENSOR (4PCS)	Shorted-2pcs only	876.16 F	*400.00 F
23	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	182.24 F	*182.24 F
24	2		*REAR BUMPER SIDE RETAINER L/R	Cracked	142.64 F	*142.64 F
25	1		*REAR BUMPER WIRE HARNESS	Not Necessary	701.76 F	*- F
26	1		*REAR END PANEL	Repair	1,339.69 F	*- F
27	1		*REAR END PANEL INNER TOP GARNISH	Not Necessary	259.33 F	*- F
28	2		*REAR EXHAUST HEAT COVER L/R	Not Necessary	352.52 F	*- F
29	4		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	242.28 F	*- F
30	1		*REAR EXHAUST SILENCER BOX L/R (2PCS)	Dented-1pc only	2,769.56 F	*1,384.78 F
31	1		*REAR FENDER INNER TRIM L/R	O/S Torn / N/S Not Necessary	613.26 F	*306.63 F
32	1		*REAR FLOOR PANEL TOP BOARD COVER	Not Necessary	696.70 F	*- F
33	2		*REAR TAILLAMP L/R	Not Necessary	1,880.82 F	*- F
34	2		*REAR TAILLAMP SIDE GARNISH L/R	Torn	148.14 F	*148.14 F
35	1		*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
36	1		*REAR BOOTLID NUMBER PLATE }	Cracked	25.00 FS	*40.00 FS
37	1		*REAR BOOTLID NUMBER PLATE HOLDER }	Bent	50.00 FS	*- FS
38	1		*SET REAR BOOTLID OUTER CHROME HANDLE CLIPS	Necessary	60.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*40.00 FS
40	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
41	2		*SET REAR FENDER INNER TRIM CLIPS L/R	Necessary	120.00 FS	*40.00 FS
42	1		*REAR FLOOR PANEL INSULATOR MAT	Not Necessary	300.00 FS	*150.00 FS
43	2		*SET REAR TAILLAMP CLIPS L/R	Not Necessary	80.00 FS	*40.00 FS
44	2		*SET REAR TAILLAMP SIDE GARNISH CLIPS L/R	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 23,219.82 11,613.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	New	140.00	60.00
2	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER	New	1,500.00	800.00
3	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	120.00	80.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,100.00	700.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	40.00
6	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	40.00
7	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	120.00	50.00
Gross Labour Cost (\$\$)			3,180.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >