

ASS. REC. BY:

REF: CF1MS419014588/Cyd321

Special Instruction:

Surveyor: Simon  
Munir

ASSIGNMENT (Office)

From (Person): Katherine Wong

of MsLg

Date/Time: 14/8/19 @ 4.46pm

Estimated Cost: Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

546 M

To Inspect Vehicle No: SKD 6437H

Insured: GBG 3713X

at Workshop m/s - torque 5

Tel: 6452 4457

of 8 Kerki Bukit Ave 4 # 01-50

Policy No: A29087777MKC

Claim No: 598540

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 1/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted: Lucas

Vehicle IN/OUT

Date/Time	Action/Instruction
	SKD 6437H - X
	GBG 3713X - X
28/8/19 @ 10.47am	confirmed with Lucas LS \$3000, 5 days. (Paid \$10809.60, 78%)

RECEIVED 04 SEP 2019



MSIG Insurance (Singapore Pte. Ltd) (Co. Reg. No 200412212G)  
 4 Shenton Way, #27-01, SGX Centre 2, Singapore 068807  
 Tel +65 6827 7888, Fax +65 6827 7800  
[www.msig.com.sg](http://www.msig.com.sg)

Executive  
Claims Services

**Inspection Report**

Type of Survey: 

OD - Excess	
TP Without Prejudice	<input checked="" type="checkbox"/>

Vehicle Data: 

Odometer reading	129688 km
Engine No	
VIN No	
Engine capacity	
Engine modification	

Vehicle Details: 

Vehicle Reg No	SKD 6437H
Make	Honda
Model	Accord 2.0A
Passenger capacity	05
Paint colour & code	black
Paint type	

Vehicle Condition: 

Seviceable	Yes / No
Handbrake	
Footbrake	
Steering	
Body	
Paint	

Vehicle Extras: 

In-built camera	Yes / <input checked="" type="radio"/> No
Modification	Yes / <input checked="" type="radio"/> No

Tyre Condition:	Tread mm	Size	Condition
Front right	5	245/40/18 Firenza	
Front left	5		
Rear left	4		
Rear right	4		

General Data: 

Date of accident	01-07-2019
Date of inspection	03-07-2019
Date of assignment	02-07-2019
Inspection location	Torque 5

Painting Process: 

Prepare off vehicle	
Painting off vehicle	
Neither (default)	

Cost Details:	Repairer	Adjuster
Parts		
Supplementary		
Miscellaneous		
Body Labour		
Paint labour		
Paint material		
TOTAL		
Towing		
Excess		
Total less excess		
Estimated days for repair		

Body Panel Repair: 

Panel repair calculator used	
Yes / No	<input type="checkbox"/>

Remarks: 

Lump / Global Sum	<input type="text"/>
Reason(s)	Margin Repair / Fast-line

Others: 


Repair Authorised  
Date:

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2019 17:24		14 Aug 2019 16:46 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	FAXMECH ENGINEERING SERVICES PTE LTD, Co. Reg. No.: 198900781E		
Main Claimant:	SWEE HENG MOTOR TRADING, Co. Reg. No.: 53035546M		
Vehicle Reg. No.:	SKD6437H	Date of Loss:	01/07/2019 10:00 - :59 [114 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 598540	Policy/Cover Note No.:	A29087777MKC (Comprehensive) Coverage: 28/07/2018 - 27/07/2019
Vehicle Reg. No. (Insured):	GBG3713X	Policy No. (Claimant):	
		Excess:	
Repairer:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4, #01-50, 415875 Kaki Bukit - Tel: 64524457		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/08/2019]		
Driver/Custodian (Insured):	CHAI SER TAI ( / Male) , NRIC: F7665206Q Email:		
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. VEH IN. Liab: 100%. TP req for IHS. Contact: Lucas (8131 6518)		

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS	<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 28 August 2019 10:47 AM  
**To:** 'Torque 5 Assessment'  
**Cc:** claims@torque5.com; sam.chang@torque5.com  
**Subject:** RE: KINDLY ADVISE THE STATUS OF SKD 6437H (DOA: 01/07/2019)

Dear Lucas,

WITHOUT PREJUDICE

Confirm Lump Sum \$3,000.00 before GST and 5 repair days.

Please note that the finalisation subject to insurer's approval.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Torque 5 Assessment <[assessment@torque5.com](mailto:assessment@torque5.com)>  
**Sent:** Thursday, 22 August 2019 4:33 PM  
**To:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Cc:** 'Torque 5 Assessment' <[assessment@torque5.com](mailto:assessment@torque5.com)>; [claims@torque5.com](mailto:claims@torque5.com); [sam.chang@torque5.com](mailto:sam.chang@torque5.com)  
**Subject:** RE: KINDLY ADVISE THE STATUS OF SKD 6437H (DOA: 01/07/2019)

Dear Shiau Chan ,



Attach as per request , kindly confirm the finalise amount .

Thank you .

*Warmest Regards,*

*Lucas Chow*

Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584  
Mobile (65) 8131 6518  
Email [lucas.chow@torque5.com](mailto:lucas.chow@torque5.com)  
Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54  
Premier @ KB, Singapore 415875  
[www.torque5.com](http://www.torque5.com)





### PRELIMINARY ADVICE

OD Claim / TP Claim

Attn : \_\_\_\_\_ Policy No : \_\_\_\_\_  
 Date : \_\_\_\_\_ Claim No : \_\_\_\_\_


Insured Vehicle No : SKD 6437 H Date of Accident : 01-07-19  
 TP Vehicle No : \_\_\_\_\_ Place of Survey : Torque 5  
 Make & Model : Honda Accord 2.0A Date of Survey : 03-07-19

Point of Impact / Damages :

Side Rn Left

Recommended Reserve :

Repairer's Estimate : \$ ~~4000~~  
 Interim Adjustment : \$ \_\_\_\_\_  
 Check Items : \$ -



Proposed : Part by Part / Lump Sum Repair

Excess : \$ -

Estimate Repair Period : 05 days

Pre-accident Market Value (for total loss consideration) : \$ 20,000.00

COE / PARF to owner : 16,725.00  
~~4000~~

Vehicle within / not within limit of economical repair.

Others :

\* Repairer agree at \$3000 all in for repair.

Surveyed By :

MSIG Insurance (Singapore) Pte. Ltd.

OD Claim  
Excess : \$ \_\_\_\_\_  
(Authorised / Revert)

TP Claim  
(Without Prejudice)

Vehicle No. SKD 6437H

Part by Part / Lump Sum Repair

Kindly arrange for surveyor to take before / after painting photos

Number of Repair Days 05

Surveyed by VICTOR SENG (Hp) 87747011

Date of Survey 03/07/2019

Victor\_Seng @ sg. msig-asia.com

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 546M

### Vehicle Details

Vehicle No.: SKD6437H

Vehicle to be Exported: No

Intended Deregistration Date: 30 Aug 2019

Vehicle Make: HONDA

Vehicle Model: ACCORD 2.0L

Primary Colour: Black

Manufacturing Year: 2009

Engine No.: R20A32800092

Chassis No.: MRHCP16309P020113

Maximum Power Output: 115.0 kW (154 bhp)

Open Market Value: \$31,922.00

Original Registration Date: 08 Dec 2009

First Registration Date: 08 Dec 2009

Transfer Count: 3

Actual ARF Paid: \$31,922.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 07 Dec 2019

PARF Rebate Amount: \$15,961.00

### Intended COE Rebate Details

COE Expiry Date: 07 Dec 2019

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$18,002.00

COE Rebate Amount: \$483.00

**Total Rebate Amount: \$16,444.00**

The information contained herein is correct as at 27 Aug 2019

OK

> Back to OneMotoring

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SKD6437H		
Vehicle Type :	R10 - Private Hire (Self-Drive) Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	ACCORD 2.0L		
Chassis No. :	MRHCP16309P020113		
Propellant :	Petrol		
Engine No. :	R20A32800092		
Engine Capacity :	1997 cc		
Maximum Power Output :	115.0 kW ( 154 bhp )		
Maximum Laden Weight :	2000 kg		
Unladen Weight :	1505 kg		
Year Of Manufacture :	2009		
Original Registration Date :	08 Dec 2009		
Lifespan Expiry Date :	-		
COE Category :	B - Car (1601cc & above)		
Quota Premium :	\$18,002.00		
COE Expiry Date :	07 Dec 2019		
Road Tax Expiry Date :	07 Dec 2019		
PARF Eligibility Expiry Date :	07 Dec 2019		
Inspection Due Date :	07 Dec 2020		
Intended Transfer Date :	05 Sep 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Total Amount Payable :</b>			<b>25.00</b>

You may print this page for reference.

OK

Print



**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

**ESTIMATION REPORT**

**Vehicle No** : SKD6437H  
**Make & Model** : HONDA, ACCORD 2.0L, MRHCP16309P020113  
**Year of Manufacture** : 2009

**Estimation No.** : E19070004  
**DOA** : 01/07/2019

No	Description	Qty	U/P	Amt
<b>Section: List Items</b>				
1	Front door (LH)	1.00	0.00	<del>0.00</del> 1536.00
2	Front door lock (LH)	1.00	0.00	<del>0.00</del> 392.00 NN
3	Rear door (LH)	1.00	0.00	<del>0.00</del> 1530.00
4	Rear door lock (LH)	1.00	0.00	<del>0.00</del> 392.00
5	Rear door rubber beading (LH)	1.00	0.00	<del>0.00</del> 187.50
6	Rear door outer handle (LH)	1.00	0.00	<del>0.00</del> 410.00
7	Rear door window frame	1.00	0.00	<del>0.00</del> 325.60
8	Rear door checker	1.00	0.00	<del>0.00</del> 132.40
9	Rear door hinge top	1.00	0.00	<del>0.00</del> 98.20
10	Rear door hinge bottom	1.00	0.00	<del>0.00</del> 98.20
11	Rear door regulator	1.00	0.00	<del>0.00</del> 480.00
12	Rear door power window motor	1.00	0.00	<del>0.00</del> 460.00
13	Rear door inner trim (LH)	1.00	0.00	<del>0.00</del> 560.00
14	Rear fender (LH)	1.00	0.00	<del>0.00</del> 1355.00
15	Rear bumper	1.00	0.00	<del>0.00</del> 932.70
				<b>Amt</b> S\$ 0.00
<b>Discount (0.00%)</b>				S\$ 0.00 - 20%
<b>Subtotal</b>				S\$ 0.00
<b>Section: Special Nett Items</b>				
16	Rocker panel (LH)	1.00	800.00	<del>800.00</del> 500 Buc
17	Rear bumper lower lip	1.00	700.00	<del>700.00</del> repair
18	Rear wheel rim (LH)	1.00	700.00	<del>700.00</del> / grozed
19	Rear door inner trim clip set	1.00	45.00	<del>45.00</del> 30 necc
20	Door visor set	1.00	120.00	<del>120.00</del> 80 cracked
21	Rear bumper clip set	1.00	45.00	<del>45.00</del> 30 necc

Continue on next page...



# Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

**Vehicle No** : SKD6437H  
**Make & Model** : HONDA, ACCORD 2.0L, MRHCP16309P020113  
**Year of Manufacture** : 2009

**Estimation No.** : E19070004  
**DOA** : 01/07/2019

No	Description	Qty	U/P	Amt
				<b>Amt</b> S\$ 2,410.00
				<b>Discount (0.00%)</b> S\$ 0.00
				<b>Subtotal</b> S\$ 2,410.00

### Section: Labour Items

22	To R&R rear bumper reverse sensor	1.00	80.00	<del>80.00</del> 50
23	To check wiring & electrical mechanism	1.00	100.00	<del>100.00</del> 40
24	To supply under-coating & anti rust treatment on affected areas	1.00	80.00	<del>80.00</del> 50
25	To R&R front door mechanism (LH)	1.00	250.00	<del>250.00</del> 100
26	To R&R rear door mechanism (LH)	1.00	250.00	<del>250.00</del> 100
27	To R&R rear wheel rim, tyre & balancing	1.00	50.00	<del>50.00</del> 40
28	To repair, replace & realign damaged areas	1.00	700.00	<del>700.00</del> 600
29	To spray painting on affected areas	1.00	800.00	<del>800.00</del> 700
30	To perform water seepage test after repair	1.00	150.00	<del>150.00</del> 90
31	Sundries	1.00	50.00	<del>50.00</del> 30
				<b>Amt</b> S\$ 2,510.00
				<b>Discount (0.00%)</b> S\$ 0.00
				<b>Subtotal</b> S\$ 2,510.00

05 days.  
03/07/19 @ 1600hrs.  
Victor\_Seng@sg.msig-asia.com  
87747011  
LIS After paint.  
Victor

<b>List Items Subtotal</b>	S\$ 0.00
<b>Special Nett Items</b>	S\$
<b>Subtotal</b>	2,410.00
<b>Labour Items Subtotal</b>	S\$
	2,510.00
<b>Total</b>	S\$
	4,920.00

13,804.60



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

**ESTIMATION REPORT**

Vehicle No : SKD6437H  
 Make & Model : HONDA, ACCORD 2.0L, MRHCP16309P020113  
 Year of Manufacture : 2009

Estimation No. : E19070004  
 DOA : 01/07/2019

No	Description	Qty	U/P	Amt	
<b>Section: List Items</b>					
1	Front door (LH)	1.00	0.00	<del>0.00</del> 1536.00 <i>Panel Repair</i>	
2	Front door lock (LH)	1.00	0.00	<del>0.00</del> 392.00 <i>Panel</i>	
3	Rear door (LH)	1.00	0.00	<del>0.00</del> 1530.00 <i>Refined</i>	
4	Rear door lock (LH)	1.00	0.00	<del>0.00</del> 392.00 <i>Revised</i>	
5	Rear door rubber beading (LH)	1.00	0.00	<del>0.00</del> 187.50 <i>Refined</i>	
6	Rear door outer handle (LH)	1.00	0.00	<del>0.00</del> 410.00 <i>Revised</i>	
7	Rear door window frame	1.00	0.00	<del>0.00</del> 325.60 <i>necc</i>	
8	Rear door checker	1.00	0.00	<del>0.00</del> 132.40 <i>X</i>	
9	Rear door hinge top	1.00	0.00	<del>0.00</del> 98.20 <i>X</i>	
10	Rear door hinge bottom	1.00	0.00	<del>0.00</del> 98.20 <i>X</i>	
11	Rear door regulator	1.00	0.00	<del>0.00</del> 480.00 <i>Refined</i>	
12	Rear door power window motor	1.00	0.00	<del>0.00</del> 460.00 <i>Revised</i>	
13	Rear door inner trim (LH)	1.00	0.00	<del>0.00</del> 560.00 <i>cracked</i>	
14	Rear fender (LH)	1.00	0.00	<del>0.00</del> 1355.00 <i>cracked</i>	
15	Rear bumper	1.00	0.00	<del>0.00</del> 932.70 <i>repair</i>	
				<b>Amt</b>	S\$ 0.00
<b>Discount (0.00%)</b>					S\$ 0.00 <i>20%</i>
<b>Subtotal</b>					S\$ 0.00
<b>Section: Special Nett Items</b>					
16	Rocker panel (LH)	1.00	800.00	<del>800.00</del> 500	
17	Rear bumper lower lip	1.00	700.00	<del>700.00</del> <i>X repair</i>	
18	Rear wheel rim (LH)	1.00	700.00	<del>700.00</del> <i>cracked</i>	
19	Rear door inner trim clip set	1.00	45.00	<del>45.00</del> 30 <i>necc</i>	
20	Door visor set	1.00	120.00	<del>120.00</del> 80 <i>cracked</i>	
21	Rear bumper clip set	1.00	45.00	<del>45.00</del> 30 <i>necc</i>	

Continue on next page...

3095



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKD6437H  
Make & Model : HONDA, ACCORD 2.0L, MRHCP16309P020113  
Year of Manufacture : 2009

Estimation No. : E19070004  
DOA : 01/07/2019

No	Description	Qty	U/P	Amt
				Amt S\$ 2,410.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 2,410.00
<b>Section: Labour Items</b>				
22	To R&R rear bumper reverse sensor	1.00	80.00	<del>80.00</del> 50
23	To check wiring & electrical mechanism	1.00	100.00	<del>100.00</del> 40
24	To supply under-coating & anti rust treatment on affected areas	1.00	80.00	<del>80.00</del> 50
25	To R&R front door mechanism (LH)	1.00	250.00	<del>250.00</del> 100
26	To R&R rear door mechanism (LH)	1.00	250.00	<del>250.00</del> 100
27	To R&R rear wheel rim, tyre & balancing	1.00	50.00	<del>50.00</del> 40
28	To repair, replace & realign damaged areas	1.00	700.00	<del>700.00</del> 600
29	To spray painting on affected areas	1.00	800.00	<del>800.00</del> 700
30	To perform water seepage test after repair	1.00	150.00	<del>150.00</del> 90
31	Sundries	1.00	50.00	<del>50.00</del> 30

Parts = 5700.10 - 20% AAA  
= 4560

Amt S\$ 2,510.00  
Discount (0.00%) S\$ 0.00  
Subtotal S\$ 2,510.00

S/N = 1340

Labour = 1800

PTSL = 7700 - 20% LIS  
= 6160

Limit Repair 3k.

05 days.  
03/07/19 @ 1600hrs.  
Victor\_Seng @ sg.msig-asia.com  
87747011  
LIS After paint.  
Victor

List Items Subtotal	S\$ 0.00
Special Nett Items	S\$
Subtotal	2,410.00
Labour Items Subtotal	S\$
	2,510.00
Total	S\$
	4,920.00

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2019 17:24		14 Aug 2019 16:46 <a href="#">Edit Adj Rpt</a>	<b>S\$3,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	FAXMECH ENGINEERING SERVICES PTE LTD, Co. Reg. No.: 198900781E								
Main Claimant:	SWEE HENG MOTOR TRADING, Co. Reg. No.: 53035546M								
Vehicle Reg. No.:	SKD6437H	Date of Loss:	01/07/2019 10:00 - :59 [114 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 598540	Policy/Cover Note No.:	A2908777MKC (Comprehensive) Coverage: 28/07/2018 - 27/07/2019						
Vehicle Reg. No. (Insured):	GBG3713X	Policy No. (Claimant):							
		Excess:							
Repairer:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4, #01-50, 415875 Kaki Bukit - Tel: 64524457								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by SIMON HO LEONG CHUAN] ... [Imm.Advice due 15/08/2019]								
Driver/Custodian (Insured):	CHAI SER TAI ( / Male), NRIC: F7665206Q Email:								
Adj Asg. Remarks:	As per Jason instruction, re-assigned to LKK to follow-up this case. on WP. VEH IN. Liab: 100%. TP req for IHS. Contact: Lucas (8131 6518)								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SKD6437H (598540)**  
**[GBG3713X]**  
**TP**  
**SWEE HENG MOTOR TRADING**  
**Jul 1 2019 10:00AM**  
**[FAXMECH ENGINEERING SERVICES PTE LTD]**  
**Torque 5 Pte Ltd**

[Upload Documents](#) | 
 [Upload Photos](#) | 
 [Compose New Letter](#)

View View in Browser

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
2	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
3	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
4	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
5	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
6	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
7	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
8	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
9	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
10	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
11	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
12	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
13	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
14	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
15	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
16	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
17	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
18	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
19	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
20	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
21	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
22	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
23	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
24	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
25	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
26	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
27	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
28	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
29	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
30	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
31	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
32	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
33	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
34	03/07/19 23:34	<b>SURVEY PHOTO</b>	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/07/19 17:27	<b>OI GBG3713X E-FILE REPORT</b>	Load PDF	
2	02/07/19 17:27	<b>TP SKD6437H E-FILE REPORT</b>	Load PDF	
3	02/07/19 17:27	<b>PRI from Torque 5</b>	Load PDF	
4	03/07/19 11:51	<b>Agree on SJE</b>	Load PDF	

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CF/MSG19014588/CQD3E2**Date:** 16/09/2019REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29087777MKC  
**Claimant**  
**Vehicle No :** SKD6437H **Insured Vehicle No :** GBG3713X  
**Date of Loss:** 01/07/2019 **Nature of Claim:** TP **Claim No:** 598540

DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** SKD6437H  
**Make & Model:** HONDA ACCORD, 2.0 L VTI-L (A) **Engine No:** R20A32800092  
**Reg. Date:** 08/12/2009 (Man. Year: 2009) **Chassis No:** MRHCP16309P020113  
**Colour:** Black **Odometer:** 129688 km  
**Engine Capacity:** 1997 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (S\$):** **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

**Front Tyre Size:** 245/40 R18 **Rear Tyre Size:** 245/40 R18  
**Front Left Side:** Firenza 5 mm **Rear Left Side:** Firenza 4 mm  
**Front Right Side:** Firenza 5 mm **Rear Right Side:** Firenza 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	11,349.60	5,930.08	5,419.52	47.75	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,460.00	1,770.00	690.00	28.05	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>13,809.60</b>	<b>7,700.08</b>	<b>6,109.52</b>	<b>44.24</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>			
	(S\$)	13,809.60	3,000.00	10,809.60	78.28
<b>+ GST 7.00/7.00% (S\$)</b>	966.67	210.00	756.67	78.28	
<b>Nett Amount (S\$)</b>	<b>14,776.27</b>	<b>3,210.00</b>	<b>11,566.27</b>	<b>78.28</b>	

INSPECTION

**Date of Assignment:** 14/08/2019  
**Date Inspected:** 03/07/2019 **Inspected At:** Torque 5 Pte Ltd (Kaki Bukit)  
 No. 8 Kaki Bukit Ave 4, #01-50  
 Singapore 415875  
**Estimated Period of Repair:** 5.0 days

**Adjuster:** SIMON HO LEONG CHUAN**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



**REPAIR DETAILS**

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 16 Sep 2019)
<b>Parts:</b> 143	HONDA ACCORD 2.0 L VTI-L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKD6437H)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR (LH)	Repair	1,536.00 F	*- FL
2	1		*FRONT DOOR LOCK (LH)	Not Necessary	392.00 F	*- FL
3	1		*REAR DOOR (LH)	Deformed	1,530.00 F	*1,530.00 FL
4	1		*REAR DOOR LOCK (LH)	Dented	392.00 F	*392.00 FL
5	1		*REAR DOOR RUBBER BEADING (LH)	Deformed	187.50 F	*187.50 FL
6	1		*REAR DOOR OUTER HANDLE (LH)	Grazed	410.00 F	*410.00 FL
7	1		*REAR DOOR WINDOW FRAME	Necessary	325.60 F	*325.60 FL
8	1		*REAR DOOR CHECKER	Not Necessary	132.40 F	*- FL
9	1		*REAR DOOR HINGE TOP	Not Necessary	98.20 F	*- FL
10	1		*REAR DOOR HINGE BOTTOM	Not Necessary	98.20 F	*- FL
11	1		*REAR DOOR REGULATOR	Deformed	480.00 F	*480.00 FL
12	1		*REAR DOOR POWER WINDOW MOTOR	Shorted	460.00 F	*460.00 FL
13	1		*REAR DOOR INNER TRIM (LH)	Cracked	560.00 F	*560.00 FL
14	1		*REAR FENDER (LH)	Dented	1,355.00 F	*1,355.00 FL
15	1		*REAR BUMPER	Repair	932.70 F	*- FL
16	1		*ROCKER PANEL (LH)	Buckled	800.00 FS	*500.00 FS
17	1		*REAR BUMPER LOWER LIP	Repair	700.00 FS	*- FS
18	1		*REAR WHEEL RIM (LH)	Grazed	700.00 FS	*700.00 FS
19	1		*SET REAR DOOR INNER TRIM CLIP	Necessary	45.00 FS	*30.00 FS
20	1		*SET DOOR VISOR	Cracked	120.00 FS	*80.00 FS
21	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
22	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,349.60</b>	<b>7,070.10</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	1,140.02
<b>Total Parts (\$\$)</b>	<b>11,349.60</b>	<b>5,930.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO R&R REAR BUMPER REVERSE SENSOR	New	80.00	50.00
2	TO CHECK WIRING & ELECTRICAL MECHANISM	New	100.00	40.00
3	TO SUPPLY UNDER-COATING & ANTI RUST TREATMENT ON AFFECTED AREAS	New	80.00	50.00
4	TO R&R FRONT DOOR MECHANISM (LH)	New	250.00	100.00
5	TO R&R REAR DOOR MECHANISM (LH)	New	250.00	100.00
6	TO R&R REAR WHEEL RIM, TYRE & BALANCING	New	50.00	40.00
7	TO REPAIR, REPLACE & REALIGN DAMAGED AREAS	New	700.00	600.00
8	TO SPRAY PAINTING ON AFFECTED AREAS	New	800.00	700.00
9	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	150.00	90.00
<b>Gross Labour Cost (S\$)</b>			<b>2,460.00</b>	<b>1,770.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >