

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AXA	DATE	: 19/08/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLH2296R		
MODEL	: TOYOTA WISH 1.8A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 17-Aug-19
		TIME	: 18:30HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,520.30	\$ 1,520.30 1,209
2	TAIL GATE LOGO <i>new</i>	1	\$ 60.00	\$ 60.00 ✓
3	TAIL GATE EMBLEM 'VALVE MATIC' <i>new</i>	1	\$ 85.00	\$ 85.00 ✓
4	TAIL GATE INNER TRIM <i>cracked</i>	1	\$ 422.00	\$ 422.00 ✓
5	TAIL GATE TOP LOCK <i>Damaged</i>	1	\$ 360.20	\$ 360.20 ✓
6	TAILGATE WEATHER STRIP <i>at</i>	1	\$ 366.20	\$ 366.20 ✓
7	TAILGATE REFLECTOR RH <i>new</i>	1	\$ 320.20	\$ 320.20 ✓
8	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 180.00	\$ 180.00 ✓
9	TAILGATE DETECTOR <i>cracked</i>	1	\$ 160.00	\$ 160.00 ✓
10	REAR BUMPER <i>Deformed</i>	1	\$ 633.50	\$ 633.50 ✓
11	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 72.00	\$ 144.00 ✓
12	REAR BUMPER STAY <i>Dented RH</i>	2	\$ 74.50	\$ 149.00 74.50 ✓
13	NUMBER PLATE GARNISH (CHROME) <i>cracked</i>	1	\$ 288.90	\$ 288.90 ✓
14	TAILLAMP RH <i>cracked</i>	1	\$ 360.20	\$ 360.20 ✓
15	REAR END PANEL <i>Dented</i>	1	\$ 568.00	\$ 568.00 ✓
16	REAR END PANEL TOP GARNISH <i>cracked</i>	1	\$ 255.30	\$ 255.30 ✓

TOTAL PRICE \$ 5,872.80

LESS 25% \$ 1,468.20

4733.90

3550.42

SUB TOTAL PRICE

\$ 4,404.60

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>could</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
2	TAILGATE WINDSCREEN SEALANT <i>2mm</i>	1	\$ 60.00	\$ 60.00 <i>40</i>
3	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00 <i>40</i>
4	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00 <i>—</i>
5	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 35.00	\$ 35.00 <i>+</i>
6	REAR END PANEL TOP GARNISH CLIPS (SET) <i>me</i>	1	\$ 50.00	\$ 50.00 <i>10</i>
7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
8	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00 <i>200</i>
TOTAL			\$	655.00 <i>410</i>

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	<i>800</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>800</i>	
3	WIRING CHECK	\$ 150.00	<i>30</i>	
4	TUFF COAT	\$ 200.00	<i>60</i>	
5	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 180.00	<i>60</i>	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 180.00	<i>50</i>	
7	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>	
8	TRANSFER TAILGATE MECHANISM	\$ 180.00	<i>80</i>	

TOTAL

\$3,610.00

2000

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,059.60

TOTAL LABOUR COST : \$ 3,610.00

TOTAL REPAIR COST : \$ 8,669.60

LKK Auto Consultants hence not the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- All prices are subject to confirmation

APPROVED DETAILS

EXCESS • Third party survey is on a "Without Prejudice" basis

NO. OF WORKING DAYS • No illegal modification(s) is allowed

RE-SURVEY

Acknowledged by Repairer

Signature:

Date:

Adrian King total: 5960.42
 2/5 20/08/19. 4/5: A.T.K
 06 Days.