

ASS. REC. BY:

REF: CS/CT219014601/Df3 n2

Special Instruction:

Surveyor:

Bryan

ASSIGNMENT (Office)

From (Person):

James Tay Hui Ping

of

CTI

Date/Time:

20.8.19 17.23pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SAC 1001E

Insured:

SKN 2849B

at Workshop m/s

Chunni Motor

Tel:

65427162

of

BK 10 Ame Industrial Park 2A #03-19

Policy No:

DMPCSN 30408219022

Claim No:

SNMMB20380/C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15.8.19

CA / REV / REP. / REV 24 HRS

"rep"

H.O.D. Endorsement:

Date/Time:

21.8.19 9.29am

Person Contacted:

Lynn

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SAC 1001E - CC4 / TP 1910 16527/9h3
	SKN 2849B - X

DOA - 15/08/2019

Minimum


Bryan

REF:

ASSIGNMENT

COE July 2025

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 159 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



Veh No: SHC 1001E Yr Regn: 2017 July
 Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /
 Truck / Trailer or
 Make: Toyota Prius c.c. 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 320280 T/Radio: Insured / Std / NI / NA
 Eng/No: 2ZR3055810
 C/No: JTDKB3FU103561255
 Gen. Cond: (Good) Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65 R15
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Davanti
 Front Rear
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 15/08/2019 D.O.I. 21/08/2019
 Survey held at Chunni AMK
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Front 4 Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	China Teiping SKN2849B
19/09/19	Invoice 2/5 189001 - with 15 days of repair (Red: 30,917.25; 62%)

RECEIVED 20 SEP 2019

Date/Time, File Pass to? : Preli. Report
 1) 19/09 Typist : Final Report
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: 15
 Resurvey No. of Trip: 2

Report Format: TP
 Lump Sum / I.B.I: (\$ 189001)

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee: _____
 Transportation: _____
 \$ - RS. - SI _____
 Photos _____
 Others _____
 TOTAL _____

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Aug 2019		20 Aug 2019 17:23 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:			
Main Claimant:	COMFORT TRANSPORTATION PTE LTD		
Vehicle Reg. No.:	SHC1001E	Date of Loss:	15/08/2019 21:00 - :59
Claim Type:	TP / SNM19D203807C02	Policy/Cover Note No.:	DMPCSN30408219022
Vehicle Reg. No. (Insured):	SKN2849B	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hul Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/08/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

View Sent Message

This mail is associated with :

***SHC1001E (SNM19D203807C02)
[SKN2849B]**

TP
COMFORT TRANSPORTATION PTE LTD
Aug 15 2019 9:00PM

Chunni Motor Work Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 26/08/2019 14:31 PM.
To irene.tay@cnaiping.com
CC claimsdept@sg.cnaiping.com
Subject *SHC1001E (SNM19D203807C02) [SKN2849B]

Dear Irene,

Please be inform the repair cost exceed \$50K.

Regards,
Denise
LKK Auto

DOCUMENTS SUMMARY

There are no documents.

MCD819107415 / ComfonDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 16/08/2019 14:14
 SUBMITTED BY: Catherine For Moy Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/08/2019 14:14
Date Of Accident	15/08/2019 21:45
Exact Location Of Accident	OPHIR ROAD >> ECP(AIRPORT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC1001E
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD (CO
Co Reg No	199303821R
Email Address	FLEETSAFTY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No. Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	TAN CHYE SENG
NRIC No	S1698225C
Date Of Birth	13/04/1965
Occupation	OUTDOOR
Date Of Driving Pass	31/10/2003
Driving Experience	15 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97986161
Fax Number	
Contact Number	
EEmail Address	MOSTAN8888@GMAIL.COM

Address 864 12-529 JURONG WEST STREET 81
 Postcode 640864
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES
 Foreign Vehicle Registration Number JSS6906 (PRIVATE CAR)
 Number of vehicles (including own vehicle) involved in the accident 5
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] NANYANG NPC
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKN2849B
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver LIM KAI XIANG
 NRIC/Passport Number S8605676C
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage FRT & REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMN2151G
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver ZHONG JIAN BING
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage FRT & REAR
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number UNKNOWN
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage REAR
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number JSS6906
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage FRT
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN CHYE SENG
 Approximate Age 54
 Injuries Sustain NECK,BACK,SHOULDER
 Injured person in which vehicle? SHC1001E
 Were seat belts worn? YES
 Was this injured conveyed to hospital by ambulance? NO
 Address
 Postcode

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)


Date & Time: 16.08.2019@1230HRS

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.: June

SKETCH PLAN

- A- SHC 1001E
- B- SKN-2849B
- C-SMN 2151G
- D- Unknown
- E- JSS 6906



Along SLE Twds BKE after Thomson Exit

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report: T/ 20190816/2009

After the accident I felt pain on my neck,back and shoulder pain. 7 days of MC was given.

DECLARATION

Confirmed that the foregoing particulars are true in every respect.

CHUNNI MOTOR TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time:

[Signature]
Driver's Signature

(If driver is not the policyholder)

Date & Time: 16.08.2019@1230HRS

[Signature]
Reporting Centre Personnel's Signature

Name:

MC/FIN No.: June


**SINGAPORE
POLICE FORCE**


T/20190816/2009

1 of 4

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Report No. T/20190816/2009

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/08/2019 02:28	Vide Report No.: L/20190815/0147	Station Diary No.: 27
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: TAN CHYE SENG		Address: APT BLK 864 JURONG WEST STREET 81 #12-529 SINGAPORE 640864	
ID Type / ID No.: NRIC NO / S1698225C		Contact No.: Home/Office: Mobile: 97986161	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 54	Date of Birth: 13/04/1965	Type of Informant: Driver
Race: Chinese		Language: Chinese	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 2B,3	Date of Expiry:

General Information of the Accident

Type of Accident: Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 15/08/2019 21:45	Type of Location: Straight Road
Location: Along Road 1 SELETAR EXPRESSWAY ALONG SLE TOWARDS BKE, AFTER UPPER THOMASON EXIT			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way	Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
JSS6906	Car					0
SHC1001E	Car	TOYOTA	PRIUS HYBRID 1.8 CVT	Blue	Slightly Damaged	0
SKN2849B	Car	AUDI		Grey		0
SMN2151G	Car	MAZDA		Grey		0


**SINGAPORE
POLICE FORCE**


T/20190816/2009

2 of 4

Report No. T/20190816/2009

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN CHYE SENG	ID No.	S1698225C
Related Vehicle	SHC1001E (Car)	Contact No.	97986161
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LIM KAI XIANG	ID No.	S8605676C
Related Vehicle	SKN2849B (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ZHONG JIAN BING	ID No.	S8974178E
Related Vehicle	SMN2151G (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 15/08/2019 at about 2145hrs, I was travelling along SLE towards BKE in my vehicle SHC1001E. After Upper Thomson exit, I noticed the vehicle SMN2151G which was travelling in front of me has engaged his brake. I followed suit. Thereafter, from my rear view mirror, I saw the vehicle SKN2849B which was behind my car also slowed down and came to a stop. However, out of sudden, there was an impact from my rear and the impact caused my vehicle to move in front and collided onto the rear of SMN2151G. SMN2151G has also collided onto a BMW which was in front of him but I did not take down the plate number. The last vehicle in the chain collision was a Malaysian car JSS6906.



**SINGAPORE
POLICE FORCE**



T/20190816/2009

3 of 4

Report No. T/20190816/2009

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

CONTINUATION OF REPORT

Nobody was conveyed to hospital however I am currently experiencing pain on my back and will visit a doctor. My vehicle's front and rear portion was damaged and was towed away.

I have handed my in-vehicle camera SD card to the traffic police at scene. I was issued with a case card reference L/20190815/0147 with TP IO Esmond Phua as in the in-charge and was advised to lodge a traffic accident report.



**SINGAPORE
POLICE FORCE**



T/20190816/2009

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

4 of 4

Report No. T/20190816/2009

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J/ Staff Sgt NALINEE CHUA	
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / GIT / Insp TAN CHIN YONG Contact No: 65476178	 SN 127 L
Authentication Stamp NP168	

Signature Of Informant:
Date/Time: 16/08/2019 02:28
Classification Of Case:

Singapore Police Force

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHC 1001E

DATE : 16.08.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039 *China Wiping*

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
BONNET <i>1st</i>			S 950.50	✓
INSULATOR, HOOD <i>2H</i>			S 398.10	X
INSULATOR CLIPS <i>2H</i>			S 3.60	X
BONNET RUBBER <i>2H</i>			S 35.50	X
BONNET HINGE (RH) <i>2H</i>			S 57.70	X
BONNET HINGE (LH) <i>2H</i>			S 57.70	X
BONNET LOCK <i>1st</i>			S 132.60	✓
CATCH, HOOD AUXILIARY HOOK <i>2H</i>			S 8.60	X
RADIATOR GRILLE <i>broken</i>			S 438.00	✓
RADIATOR GRILLE EMBLEM <i>1st</i>			S 88.00	✓
LAMP ASSY, FOG, RH <i>2H</i>			S 920.00	X
LAMP ASSY, FOG, LH <i>monty broken</i>			S 920.00	✓
FRONT BUMPER COVER <i>Dental</i>			S 499.90	✓
FRONT BUMPER REINFORCEMENT <i>1st</i>			S 696.40	✓
FRONT BUMPER REINFORCEMENT ABSORBER <i>2H</i>			S 115.70	X
FRONT BUMPER SPONGE <i>tone</i>			S 78.80	✓
FRONT BUMPER CENTRE GRILLE <i>2H</i>			S 301.90	X
FRONT BUMPER LOWER GRILLE <i>2H</i>			S 166.90	X
FRONT BUMPER CLIPS <i>2cc</i>			S 22.00	✓
FRONT BUMPER SIDE RETAINER <i>2H</i>		S 77.00	S 154.00	X
FRONT RADIATOR LOWER SUPPORT PANEL <i>2H</i>			S 357.70	X
FRONT UNDER COVER <i>2H</i>			S 180.80	X
COVER, FRONT BUMPER HOLE, RH <i>2H</i>			S 28.38	X
COVER, FRONT BUMPER HOLE, LH <i>2H</i>			S 28.38	X
FRONT BUMPER LOWER REINFORCEMENT BRACKET (LH/RH) <i>2H</i>		S 165.00	S 330.00	X
BRACKET, FRONT BUMPER EXTENTION MOUNTING <i>2H</i>			S 110.40	X
BRACKET, FRONT BUMPER SIDE, RH <i>2H</i>			S 82.30	X
BRACKET, FRONT BUMPER SIDE, LH <i>2H</i>			S 82.30	X
BRACKET, FRONT BUMPER MOUNTING <i>2H</i>			S 29.60	X
BRACKET, FRONT BUMPER MOUNTING, NO.2 <i>2H</i>			S 97.80	X
ABSORBER, FRONT BUMPER, LOWER (SPONGE LOWER) <i>2H</i>			S 127.70	X
UNIT ASSY, HEADLAMP, RH (LED) <i>monty white</i>			S 3,455.00	✓
UNIT ASSY, HEADLAMP, LH (LED) <i>monty white</i>			S 3,455.00	✓
HEAD LAMP PANEL (RH) <i>1st</i>			S 240.10	✓
HEAD LAMP PANEL (LH) <i>1st</i>			S 240.10	✓
TOP PANEL CENTRE <i>Dental</i>			S 364.90	✓
TOP PANEL, LH <i>1st</i>			S 145.90	✓
TOP PANEL, RH <i>1st</i>			S 145.90	✓
BRACE PANEL <i>1st</i>			S 75.20	✓
BRACKET, HEADLAMP MOUNTING, RH <i>2H</i>			S 25.50	X
BRACKET, HEADLAMP MOUNTING, LH <i>2H</i>			S 25.50	X
RADIATOR ASSY <i>1st</i>			S 1,841.80	✓
RADIATOR FAN COWLING ASSY <i>2H</i>			S 661.30	X
RADIATOR BOTTOM MOUNTING <i>2H</i>			S 27.50	X
STAY, RADIATOR SUPPORT, RH <i>2H</i>			S 65.70	X
STAY, RADIATOR SUPPORT, LH <i>2H</i>			S 65.70	X

SHC 1001E

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER <i>1st</i>			S 1,126.60
REAR TRUNK LID LOCK <i>Down</i>			S 457.90
REAR TRUNK LID COVER TRIM BOARD <i>NH</i>			S 254.40
REAR TRUNK LID RUBBER <i>detached</i>			S 365.20
REAR TRUNK LID GLASS (BLACK COLOR) <i>Nec</i>			S 1,569.70
BOARD ASSY, BACK DOOR TRIM <i>NH</i>			S 246.90
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>broken / cut</i>			S 889.70
REAR TRUNK LID LOGO(PRIUS) <i>Nec</i>			S 52.90
REAR TRUNK LID LOGO(HYBRID) <i>Nec</i>			S 52.90
REAR TRUNK LID LOGO(TOYOTA STAR) <i>Nec</i>			S 47.00
REAR BUMPER <i>Detached</i>			S 458.60
REAR BUMPER RE-INFORCEMENT <i>1st</i>			S 318.80
REAR BUMPER UNDER COVER <i>trim</i>			S 552.60
REAR BUMPER SIDE RETAINER <i>NH</i>			S 112.70
REAR BUMPER UNDER SIDE CENTRE COVER <i>trim</i>			S 552.60
REAR BUMPER TOWING COVER <i>trim</i>			S 82.70
REAR BUMPER CLIPS <i>Nec</i>			S 22.00
RETAINER, REAR BUMPER, SIDE, RH <i>NH</i>			S 94.80
SEAL, REAR BUMPER SIDE, RH <i>dislodged</i>			S 148.40
TAIL LAMP ASSY (UPPER) (LH/RH) <i>crack / scratched</i>		S 557.90	S 1,115.80
TAIL LAMP ASSY (LOWER) (LH/RH) <i>crack / scratched</i>		S 548.40	S 1,096.80
REAR END PANEL <i>Detached</i>			S 602.10
REAR END PANEL GARNISH <i>mounting detached</i>			S 165.80
REAR SPARE TYRE PANEL <i>Detached / repair</i>			S 667.70
REAR SPARE TYRE CHUSHION (FLR BOARD CENTRE) <i>NH</i>			S 101.40
REAR EXHAUST PIPE <i>NH</i>			S 1,163.40
REAR EXHAUST PIPE INSULATOR <i>NH</i>			S 314.60
REAR FENDER, LH/RH <i>NH</i>		S 836.70	S 1,673.40
REAR FENDER INNER PANEL, RH <i>NH</i>			S 728.00
REAR FENDER OUTER PANEL, RH <i>NH</i>			S 486.00
REAR FENDER PANEL, ROOF SIDE OUTER, RH <i>NH</i>			S 311.00
REAR FENDER REINFORCEMENT SUB.ROCKER PANEL, RH <i>NH</i>			S 552.30
REAR FENDER EXTENSION, ROOF SIDE INNER FRT, RH <i>NH</i>			S 265.10
REAR FENDER SHEILD (RH) <i>NH</i>			S 134.20
REAR FENDER TRIMBOARD (RH) <i>NH</i>			S 725.00
REAR FENDER SIDE PANEL <i>NH</i>			S 165.00
REAR FENDER AIR DUCT <i>NH</i>			S 165.10
REAR FENDER TOP PANEL INNER <i>NH</i>			S 340.20
REAR CHASSIS MEMBER, RH <i>NH</i>			S 1,180.80
REAR FLOOR PANEL SIDE (RH) <i>NH</i>			S 276.20
REAR FLOOR BOARD (LH) <i>NH</i>			S 301.00
REAR FLOOR UNDER COVER CENTRE <i>NH</i>		11456.40	S 322.00
REAR FLOOR UNDER COVER <i>NH</i>			S 334.00
REAR CROSSMEMBER UNDER COVER <i>NH</i>		8592.30	S 353.00
REAR FLOOR PANEL <i>NH</i>			S 2,850.50
REAR WINDSCREEN GLASS WITH MOULDING <i>Nec</i>			S 1,778.30
SUB TOTAL			S 25,575.10
LESS 20% <i>25%</i>			S 5,115.02
DISCOUNTED TOTAL			S 20,460.08

Handwritten checkmarks and 'X' marks in the right margin of the table, indicating the status of each item.

Plat

SHC 1001E

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
CONDENSER ASSY, W/RECEIVER <i>✓ 1st</i>			\$ 1,336.60	<i>✓</i>
SENSOR, AIR BAG, FRONT(LH) <i>MM</i>			\$ 313.50	<i>X</i>
WIRE, SKID CONTROL SENSOR <i>MM</i>			\$ 78.80	<i>X</i>
WIRING FRONT <i>MM photo taken</i>			\$ 6,685.90	<i>X</i>
		<i>15126.70</i>		
		<i>11345.00</i>		
SUB TOTAL			\$ 26,751.16	
LESS 20% <i>25%</i>			\$ 5,350.23	
DISCOUNTED TOTAL			\$ 21,400.93	
FRONT NO. PLATE <i>✓</i>			\$ 25.00	NETT <i>✓</i>
FRONT NO PLATE TRIM COVER <i>broken</i>			\$ <i>45</i> 30.00	NETT <i>✓</i>
FRONT NO.PLATE GARNISH <i>broken</i>			\$ 99.00	NETT <i>✓</i>
FRONT BUMPER LOGO <i>MF</i>			\$ 87.10	NETT <i>X</i>
		<i>144.00</i>		
			\$ 241.10	
LABOUR CHARGE				
Panel Beating			\$ 1,200.00	<i>600/-</i>
Spray Painting Charge			\$ -500.00	<i>400/-</i>
Wiring Charge			\$ 50.00	<i>30/-</i>
Tuff Kote			\$ -50.00	<i>40/-</i>
Towing Charge			\$ 90.00	<i>11/-</i>
Remove/Refix Aircon & Refill Gas			\$ 150.00	<i>80/-</i>
Remove/Refix Engine <i>photo taken</i>			\$ 450.00	<i>114</i>
Remove/Refix Dashboard <i>photo taken</i>			\$ 400.00	<i>114</i>
Remove/Refix Fuse Box			\$ 120.00	<i>114</i>
Diagnosis & Resetting To Erase Fault Code			\$ 480.00	<i>114 150/-</i>
		<i>1150.00</i>		
TOTAL LABOUR			\$ 3,490.00	

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 1001E (Supplementary)

DATE : 26.08.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Air Duct broken			\$ 134.60 ✓
	Air Duct Hose 4H			\$ 351.00 X
	Horn Unit (LH/RH) 2/2m		\$ 73.80	\$ 147.60 ✓
	SUB TOTAL		282.20	\$ 633.20
	LESS 20% 257.2			\$ 126.64
	DISCOUNTED TOTAL		211.65	\$ 506.56
	Wheel aligned			80.00 60.00 N/A
	 Dyan 2 KK Auto			
			49817.25	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119014601/DTF3N2

Date: 26/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30408219022		
Claimant Vehicle No :	SHC1001E	Insured Vehicle No :	SKN2849B		
Date of Loss:	15/08/2019	Nature of Claim:	TP	Claim No:	SNM19D203807C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1001E	Engine No:	2ZRS055810
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Chassis No:	JTDKB3FU103561255
Reg. Date:	05/07/2017 (Man. Year: 2017)	Odometer:	320280 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Davanti 5 mm	Rear Left Side:	Davanti 5 mm
Front Right Side:	Davanti 5 mm	Rear Right Side:	Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %	
Parts	43,040.37	20,624.67	22,415.70	52.08	
Miscellaneous Items	0.00	0.00	0.00		
Labour	7,870.00	3,080.00	4,790.00	60.86	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	50,910.37	23,704.67	27,205.70	53.44	
Approved Total (Overridden) (S\$)		18,900.00			
	(S\$)	50,910.37	18,900.00	32,010.37	62.88
	+ GST 7.00/7.00% (S\$)	3,563.73	1,323.00	2,240.73	62.88
	Nett Amount (S\$)	54,474.10	20,223.00	34,251.10	62.88

INSPECTION

Date of Assignment:	20/08/2019		
Date Inspected:	21/08/2019	Inspected At:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint Singapore 568047
Estimated Period of Repair:	15.0 days		

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Sep 2019)
Parts: 144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC1001E)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	950.50 FL	*950.50 FL
2	1		*INSULATOR,HOOD	Not Necessary	398.10 FL	*- FL
3	1		*INSULATOR CLIPS	Not Necessary	3.60 FL	*- FL
4	1		*BONNET RUBBER	Not Necessary	35.50 FL	*- FL
5	1		*BONNET HINGE (RH)	Not Necessary	57.70 FL	*- FL
6	1		*BONNET HINGE (LH)	Not Necessary	57.70 FL	*- FL
7	1		*BONNET LOCK	Bent	132.60 FL	*132.60 FL
8	1		*CATCH,HOOD AUXILIARY HOOK	Not Necessary	8.60 FL	*- FL
9	1		*RADIATOR GRILLE	Broken	438.00 FL	*438.00 FL
10	1		*RADIATOR GRILLE EMBLEM	Bent	88.00 FL	*88.00 FL
11	1		*LAMP ASSY,FOG,RH	Not Necessary	920.00 FL	*- FL
12	1		*LAMP ASSY,FOG,LH	Mounting Broken	920.00 FL	*920.00 FL
13	1		*FRONT BUMPER COVER	Dented	499.90 FL	*499.90 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	696.40 FL	*696.40 FL
15	1		*FRONT BUMPER REINFORCEMENT ABSORBER	Not Necessary	115.70 FL	*- FL
16	1		*FRONT BUMPER SPONGE	Torn	78.80 FL	*78.80 FL
17	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	301.90 FL	*- FL
18	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	166.90 FL	*- FL
19	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
20	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	154.00 FL	*- FL
21	1		*FRONT RADIATOR LOWER SUPPORT PANEL	Not Necessary	357.70 FL	*- FL
22	1		*FRONT UNDER COVER	Not Necessary	180.80 FL	*- FL
23	1		*COVER,FRONT BUMPER HOLE,RH	Not Necessary	28.38 FL	*- FL
24	1		*COVER,FRONT BUMPER HOLE,LH	Not Necessary	28.38 FL	*- FL
25	2		*FRONT BUMPER LOWER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	330.00 FL	*- FL
26	1		*BRACKET FRONT BUMPER EXTENSION MOUNTING	Not Necessary	110.40 FL	*- FL
27	1		*BRACKET FRONT BUMPER SIDE,RH	Not Necessary	82.30 FL	*- FL
28	1		*BRACKET FRONT BUMPER SIDE,LH	Not Necessary	82.30 FL	*- FL
29	1		*BRACKET FRONT BUMPER MOUNTING	Not Necessary	29.60 FL	*- FL
30	1		*BRACKET FRONT BUMPER MOUNTING,NO,2	Not Necessary	97.80 FL	*- FL
31	1		*ABSORBER,FRONT BUMPER,LOWER (SPONGE LOWER)	Not Necessary	127.70 FL	*- FL
32	1		*UNIT ASSY,HEADLAMP,RH (LED)	Mounting Cracked	3,455.00 FL	*3,455.00 FL
33	1		*UNIT ASSY,HEADLAMP,LH (LED)	Mounting Cracked	3,455.00 FL	*3,455.00 FL
34	1		*HEAD LAMP PANEL (RH)	Bent	240.10 FL	*240.10 FL
35	1		*HEAD LAMP PANEL (LH)	Bent	240.10 FL	*240.10 FL
36	1		*TOP PANEL CENTRE	Dented	364.90 FL	*364.90 FL
37	1		*TOP PANEL,LH	Bent	145.90 FL	*145.90 FL
38	1		*TOP PANEL,RH	Bent	145.90 FL	*145.90 FL
39	1		*BRACE PANEL	Bent	75.20 FL	*75.20 FL
40	1		*BRACKET,HEADLAMP MOUNTING,RH	Not Necessary	25.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*BRACKET,HEADLAMP MOUNTING,LH	Not Necessary	25.50 FL	*- FL
42	1		*RADIATOR ASSY	Bent	1,841.80 FL	*1,841.80 FL
43	1		*RADIATOR FAN COWLING ASSY	Not Necessary	661.30 FL	*- FL
44	1		*RADIATOR BOTTOM MOUNTING	Not Necessary	27.50 FL	*- FL
45	1		*STAY RADIATOR SUPPORT,RH	Not Necessary	65.70 FL	*- FL
46	1		*STAY RADIATOR SUPPORT,LH	Not Necessary	65.70 FL	*- FL
47	1		*CONDENSER ASSY,W/RECEIVER	Bent	1,336.60 FL	*1,336.60 FL
48	1		*SENSOR,AIR BAG,FRONT (LH)	Not Necessary	313.50 FL	*- FL
49	1		*WIRE,SKID CONTROL SENSOR	Not Necessary	78.80 FL	*- FL
50	1		*WIRING FRONT	Not Necessary	6,685.90 FL	*- FL
51	1		*REAR TRUNK LID COVER	Bent	1,126.60 FL	*1,126.60 FL
52	1		*REAR TRUNK LID LOCK	Damaged	457.90 FL	*457.90 FL
53	1		*REAR TRUNK LID COVER TRIM BOARD	Not Necessary	254.40 FL	*- FL
54	1		*REAR TRUNK LID RUBBER	Deformed	365.20 FL	*365.20 FL
55	1		*REAR TRUNK LID GLASS (BLACK COLOR)	Necessary	1,569.70 FL	*1,569.70 FL
56	1		*BOARD ASSY,BACK DOOR TRIM	Not Necessary	246.90 FL	*- FL
57	1		*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Broken/Cut	889.70 FL	*889.70 FL
58	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	52.90 FL	*52.90 FL
59	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	52.90 FL	*52.90 FL
60	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	47.00 FL	*47.00 FL
61	1		*REAR BUMPER	Dented	458.60 FL	*458.60 FL
62	1		*REAR BUMPER RE-INFORCEMENT	Bent	318.80 FL	*318.80 FL
63	1		*REAR BUMPER UNDER COVER	Torn	552.60 FL	*552.60 FL
64	1		*REAR BUMPER SIDE RETAINER	Not Necessary	112.70 FL	*- FL
65	1		*REAR BUMPER UNDER SIDE CENTRE COVER	Torn	552.60 FL	*552.60 FL
66	1		*REAR BUMPER TOWING COVER	Torn	82.70 FL	*82.70 FL
67	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
68	1		*RETAINER,REAR BUMPE,SIDE RH	Not Necessary	94.80 FL	*- FL
69	1		*SEAL,REAR BUMPER SIDE,RH	Dislodged	148.40 FL	*148.40 FL
70	2		*TAIL LAMP ASSY (UPPER)(LH/RH)	Cracked/Scratched	1,115.80 FL	*1,115.80 FL
71	2		*TAIL LAMP ASSY (LOWER)(LH/RH)	Cracked/Scratched	1,096.80 FL	*1,096.80 FL
72	1		*REAR END PANEL	Dented	602.10 FL	*602.10 FL
73	1		*REAR END PANEL GARNISH	Mounting Deformed	165.80 FL	*165.80 FL
74	1		*REAR SPARE TYRE PANEL	Repair	667.70 FL	*- FL
75	1		*REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	Not Necessary	101.40 FL	*- FL
76	1		*REAR EXHAUST PIPE	Not Necessary	1,163.40 FL	*- FL
77	1		*REAR EXHAUST PIPE INSULATOR	Not Necessary	314.60 FL	*- FL
78	2		*REAR FENDER,LH/RH	Not Necessary	1,673.40 FL	*- FL
79	1		*REAR FENDER INNER PANEL,RH	Not Necessary	728.00 FL	*- FL
80	1		*REAR FENDER OUTER PANEL,RH	Not Necessary	486.00 FL	*- FL
81	1		*REAR FENDER PANEL,ROOF SIDE OUTER,RH	Not Necessary	311.00 FL	*- FL
82	1		*REAR FENDER REINFORCEMENT SUB,ROCKER PANEL,RH	Not Necessary	552.30 FL	*- FL
83	1		*REAR FENDER EXTENSION,ROOF SIDE INNER FRT,RH	Not Necessary	265.10 FL	*- FL
84	1		*REAR FENDER SHIELD (RH)	Not Necessary	134.20 FL	*- FL
85	1		*REAR FENDER TRIMBOARD (RH)	Not Necessary	725.00 FL	*- FL
86	1		*REAR FENDER SIDE PANEL	Not Necessary	165.00 FL	*- FL
87	1		*REAR FENDER AIR DUCT	Not Necessary	165.10 FL	*- FL
88	1		*REAR FENDER TOP PANEL INNER	Not Necessary	340.20 FL	*- FL
89	1		*REAR CHASSIS MEMBER,RH	Not Necessary	1,180.80 FL	*- FL
90	1		*REAR FLOOR PANEL SIDE (RH)	Not Necessary	276.20 FL	*- FL
91	1		*REAR FLOOR BOARD (LH)	Not Necessary	301.00 FL	*- FL
92	1		*REAR FLOOR UNDER COVER CENTRE	Not Necessary	322.00 FL	*- FL
93	1		*REAR FLOOR UNDER COVER	Not Necessary	334.00 FL	*- FL
94	1		*REAR CROSSMEMBER UNDER COVER	Not Necessary	353.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
95	1		*REAR FLOOR PANEL	Not Necessary	2,850.50 FL	*- FL
96	1		*REAR WINDSCREEN GLASS WITH MOULDING	Necessary	1,778.30 FL	*1,778.30 FL
97	1		*AIR DUCT	Broken	134.60 FL	*134.60 FL
98	1		*AIR DUCT HOSE	Not Necessary	351.00 FL	*- FL
99	2		*HORN UNIT (LH/RH)	Bent/Damaged	147.60 FL	*147.60 FL
100	1		*FRONT NO PLATE TRIM COVER }	Broken	30.00 FS	*45.00 FS
101	1		*FRONT NO PLATE }	Bent	25.00 FS	*- FS
102	1		*FRONT NO PLATE GARNISH	Broken	99.00 FS	*99.00 FS
103	1		*FRONT BUMPER LOGO	Not fitted	87.10 FS	*- FS
104	1		*REAR NO PLATE WITH TRIM COVER	Not Necessary	100.00 FS	*- FS
105	1		*REAR TRUNK LID APPS STICKER	Necessary	40.00 FS	*40.00 FS
106	1		*REAR TRUNK LID COMFORT & TEL NO STICKER	Necessary	60.00 FS	*60.00 FS
107	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
108	1		*REAR BUMPER RUBBER MAT	Bent	50.00 FS	*50.00 FS
109	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	53,632.26	27,341.00
- List Item Discount on L Items 20.00/25.00% (S\$)	10,591.89	6,716.33
Total Parts (S\$)	43,040.37	20,624.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	3,200.00	1,400.00
2	SPRAY PAINTING CHARGE	New	2,000.00	1,200.00
3	WIRING CHARGE	New	100.00	60.00
4	TUFF KOTE	New	100.00	80.00
5	TOWING CHARGE	New	90.00	0.00
6	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
7	REMOVE/REFIX ENGINE	New	450.00	0.00
8	REMOVE/REFIX DASHBOARD	New	400.00	0.00
9	REMOVE/REFIX FUSE BOX	New	120.00	0.00
10	DIAGNOSIS & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
11	REAR CHASSIS ALIGNMENT CHARGE	New	200.00	0.00
12	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
13	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
14	REMOVE/REFIX REVERSE SENSOR	New	80.00	40.00
15	REMOVE/REFIX EXHAUST PIPE	New	150.00	60.00
16	WHEEL ALIGNMENT	New	80.00	0.00
Gross Labour Cost (S\$)			7,870.00	3,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >