



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2004550
INV Date 25/06/2020
Reference CC6/LPC19014628/Uka3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SGQ 116C
Insured Veh. GBA 7196T
Claim No. 19/19/19/VC05/022253
Policy No. Z19VC05002692
Accident Date 20/08/2019
Inspection Date 21/08/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC19014628/Uka3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 25-06-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 7196T	Veh. Inspected	SGQ 116C
Policy No.	Z19VC05002692	Coverage (\$)	0.00
Claim No.	19/19/19/VC05/022253	Excess (\$)	0.00
Assign From		Assign Date	21/08/2019

2. Vehicle Particulars & Condition

Make & Model	FORD KUGA TITANIUM (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WF0AXXWPMAFP80660	Colour	WHITE
Odometer	60093	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 ZR18	NEXEN	7 mm
L/H Front Tyre	235/50 ZR18	NEXEN	7 mm
R/H Rear Tyre	235/50 ZR18	NEXEN	7 mm
L/H Rear Tyre	235/50 ZR18	NEXEN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/08/2019	Inspection Date	21/08/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGQ 116C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED / DEFORMED	2,100.00	1,650.00
1	FRONT BUMPER SIDE RETAINER O/S	BENT	150.00	105.00
1	SET FRONT BUMPER CLIPS	NECESSARY	60.00	60.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	820.00	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	285.00	-
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	988.00	-
1	FRONT FENDER OUTER PROTECTOR O/S	DEFORMED / TORN	385.00	385.00
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NOT NECESSARY	50.00	-
1	HEADLAMP ASSY O/S	CRACKED	3,200.00	2,280.00
1	FRONT SUPPORT PANEL	CRACKED	1,650.00	1,050.00
	LESS 20% DISCOUNT		-	-1,106.00
			9,688.00	4,424.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REFIX FRONT PDC SENSOR .		80.00	40.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO REFILL AIRCON GAS.	NOT NECESSARY	150.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER O/S .		980.00	600.00
	TO PUTTY & SPRAY PAINTING.		900.00	600.00
	-		-	-
	-		-	-
	-		-	-
			2,340.00	1,260.00
GRAND TOTAL			12,028.00	5,684.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDNET CONDITION)				4,500.00

Report Ref No. CC6/LPC19014628/Uka3n2



Report Ref No. CC6/LPC19014628/Uka3n2

A handwritten signature in black ink, appearing to be 'Chua' followed by a stylized 'K' and 'S'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGQ 116C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGQ 116C

RE-INSPECTION

