

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19014631/APA3Q2

**Date:** 05/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant**

**Vehicle No :** SJG6775C

**Insured Vehicle No :** SFF678S

Date of Loss: 10/08/2019

Nature of Claim: TP

Claim No: 8322590657SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG6775C**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4777704

Reg. Date: 11/07/2008 (Man. Year: 2008)

Chassis No: MR053ZEE106112288

Colour: Silver

Odometer: 156617 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,444.45	2,429.87	1,014.58	29.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,430.00	830.00	36.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$)</b>	<b>5,704.45</b>	<b>3,859.87</b>	<b>1,844.58</b>	<b>32.34</b>
<b>Approved Total (Overridden) (\$)</b>		<b>3,100.00</b>		
<b>(S\$)</b>	5,704.45	3,100.00	2,604.45	45.66
<b>+ GST 7.00/7.00% (S\$)</b>	399.31	217.00	182.31	45.66
<b>Nett Amount (S\$)</b>	<b>6,103.76</b>	<b>3,317.00</b>	<b>2,786.76</b>	<b>45.66</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		360.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,679.00</b>		

### INSPECTION

Date of Assignment: 20/08/2019

Date Inspected: 20/08/2019 Inspected At:

Success United Pte Ltd (HQ)

2 Kaki Bukit Ave 2 #01-33, Kaki Bukit

AutoHub

Singapore 417921

Estimated Period of Repair: 5.0 days

---

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	591.80 FL	*591.80 FL
2	1		*REAR BUMPER SIDE HOLDER LH	Necessary	217.45 FL	*45.00 FL
3	1		*REAR BUMPER BRACKET LH	Bent	191.40 FL	*85.60 FL
4	1		*REAR BUMPER REFLECTOR LH	Not Necessary	187.10 FL	*- FL
5	1		*REAR LAMP LH	Cracked	344.45 FL	*344.45 FL
6	1		*REAR END PANEL	Dented	787.90 FL	*787.90 FL
7	1		*REAR LAMP BRACKET LH	Not Necessary	217.10 FL	*- FL
8	1		*REAR BOOT LID	Buckled	873.94 FL	*753.00 FL
9	1		*REAR BOOT LID 1.6 EMBLEM	Necessary	53.40 FL	*53.40 FL
10	1		*REAR BOOT LID COROLLA EMBLEM	Necessary	55.71 FL	*55.71 FL
11	1		*REAR BOOT LID ALTIS EMBLEM	Necessary	54.30 FL	*54.30 FL
12	1		*REAR BOOT LID LAMP	Not Necessary	219.90 FL	*- FL
13	1		*REAR END PANEL INNER TOP GARNISH	Deformed	371.48 FL	*202.00 FL
14	1		*SET REVERSE SENSOR	Damaged	320.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,485.93</b>	<b>3,173.16</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,041.48	743.29
<b>Total Parts (\$\$)</b>	<b>3,444.45</b>	<b>2,429.87</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REARRAGE ELECTRICAL WIRING CHECK LIGHTING	New	60.00	30.00
2	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
3	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	1,000.00	600.00
<b>Gross Labour Cost (\$)</b>			<b>2,260.00</b>	<b>1,430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >