

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19014636/AEA3Q2

Date: 08/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700080345

Claimant
Vehicle No : SML8549P **Insured Vehicle No :** SDT8080M

Date of Loss: 11/08/2019 Nature of Claim: TP Claim No: 0860422330SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML8549P		
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Engine No:	LEB5625162
Reg. Date:	07/06/2019 (Man. Year: 2018)	Chassis No:	GB71087182
Colour:	Red	Odometer:	22016 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,916.00	1,328.88	3,587.12	72.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	430.00	450.00	51.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,796.00	1,758.88	4,037.12	69.65
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	5,796.00	1,400.00	4,396.00	75.85
+ GST 7.00/7.00% (S\$)	405.72	98.00	307.72	75.85
Nett Amount (S\$)	6,201.72	1,498.00	4,703.72	75.85
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,685.45		

INSPECTION

Date of Assignment: 20/08/2019

Date Inspected: 20/08/2019 Inspected At:

Green Forest Automobile Pte Ltd (Kaki Bukit)
8 Kaki Bukit Avenue 4, #05-25,,
Premier@Kaki Bukit
Singapore 415875

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT HEAD LAMP	Not Necessary	1,902.00 F	*- FL
2	2		*FRONT HEAD LAMP LOWER BRACKET	Not Necessary	156.40 F	*- FL
3	1		*FRONT BUMPER	Deformed	950.00 F	*950.00 FL
4	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	136.40 F	*- FL
5	10		*FRONT BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
6	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	50.00 F	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	380.00 F	*- FL
8	1		*FRONT BUMPER CENTER GARNISH	Damaged	220.10 F	*220.10 FL
9	1		*FRONT BUMPER CENTER LOWER COVER	Not Necessary	295.10 F	*- FL
10	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	285.00 F	*- FL
11	1		*FRONT GRILLE	Cracked	385.00 F	*385.00 FL
12	1		*FRONT GRILLE EMBLE LOGO	Necessary	56.00 F	*56.00 FL
13	10		*FRONT GRILLE CLIPS	Necessary	50.00 F	*20.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,916.00	1,661.10
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	332.22

Total Parts (\$)	4,916.00	1,328.88
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING SYSTEM	New	80.00	30.00
2	PANEL BEATING	New	400.00	200.00
3	SPRAY PAINTING	New	400.00	200.00
Gross Labour Cost (\$\$)			880.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >