# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

3 Anson Road

51 Ubi Ave 1 #01-25 #16-00 Springleaf Tower Paya Ubi Industrial Park Singapore 079909 Singapore 408933

22 Aug 2019 Attn: Irene Tay Hui Ping Date:

## **Preliminary Advice**

Vehicle No : E9A Accident Date : 15/08/2019

Policy No. : DMPCSN16360618022 Make : TOYOTA LEXUS

Assignment Date : 21/08/2019 **Excess** : S\$1,500.00

Date of Inspection :21/8/2019 Est. Duration of Repair :5

Inspection At :LIAN HENG PAINTER COMPANY

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,875.65
Revised Amount	:S\$	10,597.90
Check Items (Estimated)	:S\$	13,815.75
Total	:S\$	24,413.65

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 210,000.00 COE / PARF Rebate :S\$ 181,830.00

Salvage Value :S\$

:S\$ 28,170.00 Margin for Repair

### Remarks

( X )	The vehicle is repairable at our adjusted amoun	t. We have also confirmed	excess and policy coverage	. Kindly let us
	have your authorisation.			

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: PENDING COST PRICE FROM REPAIRER