

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19014658/GYF3E2**Date:** 27/12/2019**REFERENCE**

Insured/Claimant: BSG LANDSCAPE & CONSTRUCTION PTE LTD

Policy No: DMCVSN3048911900

Date of Loss: 17/08/2019

Nature of Claim: OD

Claim No: SNM19D203838C01

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBJ6377Y**

Make & Model: FIAT FIORINO, 1.2 MULTIJET (A)

Engine No: 225A20006494044

Reg. Date: 27/06/2019 (Man. Year: 2017)

Chassis No: ZFA22500006H33732

Colour: Black

Odometer: 3197 km

Engine Capacity: 1248 cc

Market Value/New Car Price: S\$49,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Pirelli 8 mm

Rear Left Side: Pirelli 8 mm

Front Right Side: Pirelli 8 mm

Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,384.50	3,636.50	1,748.00	32.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,600.00	540.00	25.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,524.50	5,236.50	2,288.00	30.41
- Excess (S\$)	350.00	350.00	0.00	0.00
(S\$)	7,174.50	4,886.50	2,288.00	31.89
+ GST 7.00/7.00% (S\$)	502.22	342.06	160.16	31.89
Nett Amount (S\$)	7,676.72	5,228.56	2,448.16	31.89

INSPECTION

Date of Assignment: 21/08/2019

Date Inspected: 21/08/2019 Inspected At:

160 Sin Ming Drive #08-09
Repairer : Vin's Auto Pte Ltd (Vin's Auto)

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Dec 2019)	
Parts:	N/A	FIAT FIORINO 1.2 MULTIJET (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ6377Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT RH DOOR (WCP)	Buckled	1,100.00 F	*1,100.00 F
2	1	*FRONT RH DOOR GLASS OUTER MOULDING (WCP)	Torn	150.00 F	*150.00 F
3	1	*FRONT RH DOOR STICKER (WCP)	Necessary	50.00 F	*50.00 F
4	1	*FRONT RH DOOR PROTECTOR (WCP)	Cracked	190.00 F	*190.00 F
5	1	*FRONT RH DOOR TOP HINGE (WCP)	Not Necessary	130.00 F	*- F
6	1	*FRONT RH DOOR LOWER HINGE (WCP)	Not Necessary	130.00 F	*- F
7	1	*FRONT RH DOOR POWER WINDOW MOTOR ASSY (WCP)	Bent	380.00 F	*380.00 F
8	1	*FRONT RH ROCKER PANEL (WCP)	Repair	580.00 F	*- F
9	1	*REAR RH SLIDING DOOR (WCP)	Buckled	1,100.00 F	*1,100.00 F
10	1	*REAR RH SLIDING DOOR PROTECTOR (WCP)	Cut	140.00 F	*140.00 F
11	1	*REAR RH FENDER (WCP)	Repair	680.00 F	*- F
12	1	*REAR RH SLIDING DOOR WINDOW GLASS GUM	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,690.00	3,170.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	694.50	466.50
Total Parts (\$\$)	5,384.50	3,636.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIX REAR RH DOOR WINDOW GLASS	New	120.00	60.00
2	TO TRANSFER FRONT RH DOOR ITEMS	New	180.00	80.00
3	TO TRANSFER REAR RH DOOR ITEMS	New	180.00	80.00
4	TO REPAIR RH DAMAGES	New	780.00	600.00
5	TO SPRAY PAINTING	New	880.00	780.00
Gross Labour Cost (\$\$)			2,140.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >