

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	YTHQ/TP/1908/010
Policy No:	5082169896-03	Date of Loss:	06/08/2019
Vehicle Reg. No.:	SJF5793L	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SMK9511X
Any Injuries?	no	Contact No:	
Insured/Claimant:	SCIVEZ	Driver:	MOHAMAD FARHAN BIN MOHAMAD
<hr/>			
Make/Model:	Honda, Fit - GD1	Vehicle Reg. Date:	20/08/2019
Vehicle Colour:	Silver	Engine Number:	L13A4078553
Chassis No:	GE61076373	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	10

Description of Accident/loss COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS	Amount
Parts	2,137.30
Miscellaneous Items	824.00
Labour	1,340.00
Paintwork Labour	925.00
Towing	0.00
Gross Total(S\$):	5,226.30
GST 7.00%(S\$):	365.84
Nett Amount(S\$):	5,592.14

This claim is handled by: Vinnie Lim M H

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER / DD	155.00	+10.00	170.50 /
2	1	REAR BUMPER SIDE RETAINER LH / DR	12.00	+10.00	13.20 /
3	1	REAR BUMPER SIDE RETAINER RH	12.00	+10.00	13.20 /
4	1	RR BUMPER TOWING COVER X NAI	15.00	+10.00	16.50 X
5	1	RR TAILGATE / DD	250.00	+10.00	275.00 /
6	1	RR TAILGATE INNER BOOT X NAI	100.00	+10.00	110.00 X
7	1	RR TAILGATE LOCK / BT	120.00	+10.00	132.00 /
8	1	RR TAILGATE LOCK CATCH X NAI	50.00	+10.00	55.00 X
9	1	REAR TAILGATE RUBBER X NAI	80.00	+10.00	88.00 X
10	1	RR TAILGATE FIT EMBLEM / MC	50.00	+10.00	55.00 /
11	1	RR END PANEL X R	384.00	+10.00	422.40 X
12	1	RR END PANEL INNER GARNISH X NAI	60.00	+10.00	66.00 X
13	1	RR TAILAMP RH X NAI	120.00	+10.00	132.00 X
14	1	RR TAILAMP LH X NAI	120.00	+10.00	132.00 X
15	1	REAR WINDSCREEN MOULDING / MC	95.00	+10.00	104.50 /
16	1	REAR WINDSCREEN X NAI	320.00	+10.00	352.00 X

Total Parts (\$\$) 2,137.30

763.40

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR CARPLATE X	35.00	0.00	35.00 X
2	1	REAR REVERSE SENSOR / DR	300.00	0.00	300.00 200 /
3	1	REAR REVERSE CAMERA X	400.00	0.00	400.00 X
4	1	REAR BUMPER CLIPS / MC	35.00	0.00	35.00 30 /
5	1	RR TAILGATE INNER BOOT CLIPS X	30.00	0.00	30.00 X
6	1	RR WINDSCREEN SEALANT / MC	24.00	0.00	24.00 /

Sub Total (\$\$) 824.00

254

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00 30
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 20
3	1	To Transfer Rear Tailgate.	80.00	0.00	80.00 50
4	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00 /
5	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00 /
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	950.00	0.00	950.00 500

Gross Labour Cost (\$\$) 1,340.00

730

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	0.00	40.00 ³⁰
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00	45.00 ^X
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	40.00	0.00	40.00 ³⁰
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	0.00	800.00 ⁵⁰⁰

Gross Labour Cost (S\$)

925.00

560

< END OF ESTIMATES >

Stew (LKK) W/L M/Tu dic 21/8/19, 11.00 am
8322 8813 4 chys

L/S

Ry AL SM

P- 763.40

N- 254

L- 1290

2307.40

L/S- 1845.92

= 1850

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	YTHQ/TP/1908/010
Policy No:	5082169896-03	Date of Loss:	06/08/2019
Vehicle Reg. No.:	SJF5793L	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SMK9511X
Any Injuries?	no	Contact No:	
Insured/Claimant:	SCIVEZ	Driver:	MOHAMAD FARHAN BIN MOHAMAD

Make/Model:	Honda, Fit - GD1	Vehicle Reg. Date:	20/08/2019
Vehicle Colour:	Silver	Engine Number:	L13A4078553
Chassis No:	GE61076373	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	10

Description of Accident/loss COLLISION - HEAD TO REAR
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS	Amount
Parts	2,137.30
Miscellaneous Items	824.00
Labour	1,340.00
Paintwork Labour	925.00
Towing	0.00
Gross Total(S\$):	5,226.30
GST 7.00%(S\$):	365.84
Nett Amount(S\$):	5,592.14

This claim is handled by: Vinnie Lim M H

LSP = \$ 763.40
 81N = \$ 254.00
 Labour = \$ 730.00
 81P = \$ 560.00
 Total = \$ 2307.40
 - 70%
 \$ 1800 LIS (4 days)

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER / <i>DR</i>	155.00	+10.00	170.50
2	1	REAR BUMPER SIDE RETAINER LH / <i>DR</i>	12.00	+10.00	13.20
3	1	REAR BUMPER SIDE RETAINER RH / <i>DR</i>	12.00	+10.00	13.20
4	1	RR BUMPER TOWING COVER <i>X</i>	15.00	+10.00	16.50
5	1	RR TAILGATE / <i>DR</i>	250.00	+10.00	275.00
6	1	RR TAILGATE INNER BOOT <i>X</i>	100.00	+10.00	110.00
7	1	RR TAILGATE LOCK / <i>DR</i>	120.00	+10.00	132.00
8	1	RR TAILGATE LOCK CATCH <i>X</i>	50.00	+10.00	55.00
9	1	REAR TAILGATE RUBBER <i>X</i>	80.00	+10.00	88.00
10	1	RR TAILGATE FIT EMBLEM / <i>MC</i>	50.00	+10.00	55.00
11	1	RR END PANEL <i>X R</i>	384.00	+10.00	422.40
12	1	RR END PANEL INNER GARNISH <i>X</i>	60.00	+10.00	66.00
13	1	RR TAILAMP RH <i>X</i>	120.00	+10.00	132.00
14	1	RR TAILAMP LH <i>X</i>	120.00	+10.00	132.00
15	1	REAR WINDSCREEN MOULDING / <i>MC</i>	95.00	+10.00	104.50
16	1	REAR WINDSCREEN <i>X</i>	320.00	+10.00	352.00

Total Parts (S\$) 2,137.30

\$763.40

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR CARPLATE <i>X</i>	35.00	0.00	35.00
2	1	REAR REVERSE SENSOR / <i>DR</i>	300.00	0.00	300.00
3	1	REAR REVERSE CAMERA <i>X</i>	400.00	0.00	400.00
4	1	REAR BUMPER CLIPS / <i>MC</i>	35.00	0.00	35.00
5	1	RR TAILGATE INNER BOOT CLIPS <i>X</i>	30.00	0.00	30.00
6	1	RR WINDSCREEN SEALANT / <i>MC</i>	24.00	0.00	24.00

Sub Total (S\$) 824.00

\$254

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00
3	1	To Transfer Rear Tailgate.	80.00	0.00	80.00
4	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00
5	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	950.00	0.00	950.00

Gross Labour Cost (S\$) 1,340.00

\$730

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	0.00	40.00 30
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00	45.00 X
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	40.00	0.00	40.00 30
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	0.00	800.00 500

Gross Labour Cost (S\$)

925.00

\$560

< END OF ESTIMATES >

Stew (LKK) ML Mtu dw 21/8/19, 11.00 am
 8322 8813 4 rhy
 L/S
 Ry AL sm

