



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583 Contact No 64771154	Cust No/Name	/Mr Lin Junhong
	Reg No/Reg Date	SJT731A / 16/08/2017
	Date In/Mileage	19/08/2019/ 42035
	Chassis No	KNACC81CVJ5096512
	Engine No	G4LEHS216257
	Make/Model	KIA/NIRO 1.6 A G979
	Colour/Trim	C3U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
F0000056	Credit	20/08/2019/ 09:45	DS	218 / MarsLer	30725		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	SUNDRY					ru	50.00
	C & C LOGO					surf	100.00
S	MIPNT88088						
	FRONT AND REAR NUMBER PLATE WITH CASING						
S	MIPNT88088					Page/shed	750.00
	BLACKVUE DR430 (2 CHANNEL) video					600	1200.00
S	MIPNT88088						
	TO REMOVE AND RE-INSTALL REAR LOWER SEAT TO GIVE WAY ACCESS						
	REMOVE AND RE-INSTALL HIGH VOLTAGE CABLE						250.00
S	MIPNT88088						
	DIAGNOSTIC / SCANNING						160.00
S	MIPNT88088						
	TO CHECK LIGHTING AND WIRING ON FRONT & REAR ACCIDENT AFFECTED AREAS						280.00
S	MIPNT88088					180	
	TO REMOVE AND RE-INSTALL RAD & A/C CONDENSOR TO GIVE WAY ACCESS						
	REPAIR ON FRONT ACCIDENT AFFECTED AREAS					2400	4200.00
S	MIPNT88088						
	TO REPLACE FRONT BUMPER, REINFORCEMENT, FRT CARRIER, HOOD PNL, RHF FENDER PNL, ETC						
	-REPAIR RHF DOOR PNL						
	STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS						
S	MIPNT88088					100	200.00
	TO APPLY SEALANT KIT ON FRONT NEW PANEL						
S	MIPNT98088					2000	2100.00
	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS						300.00
S	MIPNT88088						
	TO REPLACE FRONT TAILGATE GLASS						100.00
S	MIPNT88088						
	SEALANT KIT ON TAILGATE GLASS						220.00
S	MIPNT88088						
	TO INSTALL RIKE COOL SOLAR FILM ON TAILGATE GLASS						600.00
S	MIPNT88088						

Estimate

not Allowed

300

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583 Contact No 64771154	Cust No/Name	/Mr Lin Junhong
	Reg No/Reg Date	SJT731A / 16/08/2017
	Date In/Mileage	19/08/2019/ 42035
	Chassis No	KNACC81CVJ5096512
	Engine No	G4LEHS216257
	Make/Model	KIA/NIRO 1.6 A G979
	Colour/Trim	C3U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000056	Credit	20/08/2019/ 09:45	DS	218 / MarsLer	30725			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
TO REMOVE AND RE-INSTALL TRIMMING AND CARPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS								
S	MIPNT88088					100		600.00
TO VACUUM & CLEAN GLASS DEBRIS ON INTERIOR CARPERTING AND REAR SEAT								
S	MIPNT88088					250		600.00
TO REPLACE REAR EXHAUST MUFFLER ASSY								
S	MIPNT88088					300		600.00
TO TRANSFER TAILGATE COMPOMENT & MECHANIMS PARTS								
S	MIPNT88088					1800		3600.00
TO REPLACE TAILGATE PNL, REAR BUMPER, REINFORGEMENT, ETC -CUT & RE-WELD REAR END PANEL STRAIGH, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS								
S	MIPNT88088					100		300.00
TO APPLY SEALANT KIT ON REAR NEW PANEL								
S	MIPNT98088					2000		2100.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS								
M	KS 86511 G5 000	COVER - FRONT BUMPER		Dis	1.00	637.00	0.00	637.00
M	KS 86512 G5 000	COVER ASSY - FRONT B		cu	1.00	346.00	0.00	346.00
M	KS 86357 G5 000	STRIP ASSY - FRONT B		nu	1.00	28.00	0.00	28.00
P	KS 86320 1W 250	LOGO ASSY - KIA SUB		nu	1.00	51.00	0.00	51.00
M	KS 86350 G5 000	GRILLE ASSY - RADIAT		cu	1.00	441.00	0.00	441.00
M	KS 86560 G5 000	GRILLE - FRONT BUMPE			1.00	232.00	0.00	232.00
M	KS 86513 G5 000	LH SIDE BRACKET - FR		11	1.00	12.00	0.00	12.00
M	KS 86514 G5 000	RH SIDE BRACKET - FR		11	1.00	12.00	0.00	12.00
M	KS 86520 G5 000	ABSORBER - FRONT BUM			1.00	68.00	0.00	68.00
M	KS 86571 G5 000	STIFFENER - FRONT BU			1.00	116.00	0.00	116.00
M	KS 86951 G5 000	FLAP ASSY - ACTIVE A			1.00	328.00	0.00	328.00
M	KS 86958 G5 000	DUCT ASSY-ACTIVE AIR			1.00	78.00	0.00	78.00
M	KS 86568 G5 000	RH DUCT ASSY - AIR C			1.00	32.00	0.00	32.00
M	KS 86558 G5 000	RH PIECE - FRONT BUM			1.00	16.00	0.00	16.00
M	KS 86557 G5 000	LH PIECE - FRONT BUM			1.00	16.00	0.00	16.00
M	KS 86517 G5 000	CAP - FRONT HOOK		11	1.00	7.00	0.00	7.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583 Contact No 64771154	Cust No/Name /Mr Lin Junhong
	Reg No/Reg Date SJT731A / 16/08/2017
	Date In/Mileage 19/08/2019/ 42035
	Chassis No KNACC81CVJ5096512
	Engine No G4LEHS216257
	Make/Model KIA/NIRO 1.6 A G979
	Colour/Trim C3U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
F0000056	Credit	20/08/2019/ 09:45	DS	218 / MarsLer	30725		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	KS	91840 G5 040	WIRING HARNESS - FRO	1.00	134.00	0.00	134.00
M	KS	92202 G5 000	RH LAMP ASSY - FRONT	1.00	638.00	0.00	638.00
P	KS	0G032 50 037A	CLIP - FRONT BUMPER	10.00	2.00	0.00	20.00
M	KS	92102 G5 020	RH HEADLAMP ASSY	1.00	904.00	0.00	904.00
M	KS	64900 G5 000	BEAM COMPLETE - FRON	1.00	551.00	0.00	551.00
M	KS	64101 G5 000	CARRIER ASSY - FRONT	1.00	675.00	0.00	675.00
M	KS	66321 G5 000	RH FENDER PANEL	1.00	385.00	0.00	385.00
M	KS	84142 G5 000	INSULATOR - FENDER,	1.00	46.00	0.00	46.00
M	KS	66400 G5 000	HOOD PANEL ASSY	1.00	1438.00	0.00	1438.00
M	KS	79120 G5 000	RH HINGE ASSY - HOOD	1.00	40.00	0.00	40.00
M	KS	81130 G5 900	LATCH ASSY - HOOD	1.00	123.00	0.00	123.00
M	KS	93880 G5 900	SWITCH ASSY - HOOD	1.00	50.00	0.00	50.00
M	KS	81190 G5 800	CABLE ASSY - HOOD LA	1.00	27.00	0.00	27.00
M	KS	86154 G5 000	RH COVER - COWL TOP	1.00	6.00	0.00	6.00
M	KS	73700 G5 000	TAIL GATE PANEL ASSY	1.00	1309.00	0.00	1309.00
M	KS	81771 G5 000	LIFTER ASSY - TAILGA	1.00	76.00	0.00	76.00
M	KS	81781 G5 000	LIFTER ASSY - TAILGA	1.00	76.00	0.00	76.00
M	KS	81230 G5 000	LATCH ASSY - TAILGAT	1.00	201.00	0.00	201.00
M	KS	81720 G5 000	HANDLE ASSY - TAILGA	1.00	99.00	0.00	99.00
M	KS	81750 G5 000W K	TAILGATE TRIM PANEL	1.00	164.00	0.00	164.00
M	KS	87321 G5 000	WEATHERSTRIP - TAILG	1.00	99.00	0.00	99.00
P	KS	87110 G5 140	GLASS ASSY - TAILGAT	1.00	1179.00	0.00	1179.00
M	KS	86114 3D 000	PAD-W/SHLD GLASS	8.00	2.00	0.00	16.00
M	KS	87115 A4 000	STOPPER-RR WINDOW GL	2.00	15.00	0.00	30.00
M	KS	95760 G5 000	CAMERA ASSY - BACK V	1.00	758.00	0.00	758.00
M	KS	87210 G5 000	SPOILER - REAR	1.00	522.00	0.00	522.00
M	KS	92700 G5 000	HIGH MOUNT STOP LAMP	1.00	0.00	0.00	0.00
M	KS	87370 G5 000	RH GARNISH ASSY - "D	1.00	98.00	0.00	98.00
M	KS	98812 G5 000	CAP - REAR WIPER ARM	1.00	3.00	0.00	3.00
M	KS	98811 G5 000	ARM ASSY - REAR WIPE	1.00	59.00	0.00	59.00
P	KS	98850 G5 000	BLADE ASSY - WIPER,	1.00	41.00	0.00	41.00
M	KS	98700 G5 000	MOTOR & LINKAGE ASSY	1.00	357.00	0.00	357.00
M	KS	92403 G5 120	LH INSIDE LAMP ASSY	1.00	636.00	0.00	636.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583 Contact No 64771154	Cust No/Name /Mr Lin Junhong
	Reg No/Reg Date SJT731A / 16/08/2017
	Date In/Mileage 19/08/2019/ 42035
	Chassis No KNACC81CVJ5096512
	Engine No G4LEHS216257
	Make/Model KIA/NIRO 1.6 A G979
	Colour/Trim C3U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000056	Credit	20/08/2019/ 09:45	DS	218 / MarsLer	30725			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	KS	92404	G5 120	RH INSIDE LAMP ASSY	1.00	636.00	0.00	636.00
M	KS	92401	G5 120	LH OUTSIDE LAMP ASSY	1.00	645.00	0.00	645.00
M	KS	92402	G5 120	RH OUTSIDE LAMP ASSY	1.00	645.00	0.00	645.00
M	KS	86310	G5 000	LOGO - KIA	1.00	42.00	0.00	42.00
M	KS	86311	G5 000	EMBLEM-NIRO	1.00	25.00	0.00	25.00
M	KS	86316	G5 000	EMBLEM-ECO HYBRID	1.00	29.00	0.00	29.00
M	KS	86611	G5 010	COVER - REAR BUMPER,	1.00	423.00	0.00	423.00
M	KS	86612	G5 010	COVER - REAR BUMPER	1.00	392.00	0.00	392.00
M	KS	86665	G5 000	SKID PLATE - REAR BU	1.00	122.00	0.00	122.00
P	KS	86628	G5 000	RH PIECE-RR BUMPER S	1.00	16.00	0.00	16.00
M	KS	86696	G5 001	COVER-RR BUMPER SIDE	1.00	27.00	0.00	27.00
M	KS	86681	G5 000	LH SIDE MOULDING ASS	1.00	20.00	0.00	20.00
P	KS	86682	G5 000	RH SIDE MOULDING ASS	1.00	20.00	0.00	20.00
M	KS	86613	G5 000	LH SIDE BRACKET ASSY	1.00	25.00	0.00	25.00
M	KS	86614	G5 000	RH SIDE BRACKET ASSY	1.00	25.00	0.00	25.00
M	KS	95720	D3 000C 3U	SENSOR ASSY-PARKING	3.00	135.00	0.00	405.00
M	KS	91880	G5 030	WIRING HARNESS-RR BU	1.00	361.00	0.00	361.00
M	KS	92501	F6 000	LH LAMP ASSY - LICEN	1.00	27.00	0.00	27.00
M	KS	92502	F6 000	RH LAMP ASSY - LICEN	1.00	27.00	0.00	27.00
M	KS	92406	G5 000	RH REFLECTOR/REFLEX	1.00	104.00	0.00	104.00
P	KS	86631	G5 100	BEAM - REAR BUMPER	1.00	261.00	0.00	261.00
M	KS	86635	G5 000	BRACKET - REAR RAIL	1.00	6.00	0.00	6.00
M	KS	86636	G5 100	BRACKET - REAR BEAM	1.00	6.00	0.00	6.00
M	KS	86637	C5 000	BRACKET-SMART KEY MT	1.00	5.00	0.00	5.00
M	KS	86633	G5 000	BRACKET - REAR BEAM	1.00	6.00	0.00	6.00
P	KS	86634	G5 000	BRACKET - REAR BEAM	1.00	6.00	0.00	6.00
P	KS	86641	G5 000	LH STAY - REAR BUMPE	1.00	67.00	0.00	67.00
P	KS	86642	G5 000	RH STAY - REAR BUMPE	1.00	67.00	0.00	67.00
M	KS	95420	G2 300	ANTENNA ASSY-SMARTKE	1.00	39.00	0.00	39.00
M	KS	87712	G5 000	GARNISH ASSY - FENDE	1.00	123.00	0.00	123.00
M	KS	87742	G5 000	GARNISH ASSY - QUART	1.00	144.00	0.00	144.00
M	KS	85910	G5 000	SCREEN ASSY - CARGO	1.00	812.00	0.00	812.00
M	KS	85770	G5 100W K	TRIM ASSY - REAR TRA	1.00	60.00	0.00	60.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
QBE Insurance (Singapore) Pte Ltd 1 Raffles Quay #29-10 South Tower Singapore 048583	Cust No/Name /Mr Lin Junhong
Contact No 64771154	Reg No/Reg Date SJT731A / 16/08/2017
	Date In/Mileage 19/08/2019/ 42035
	Chassis No KNACC81CVJ5096512
	Engine No G4LEHS216257
	Make/Model KIA/NIRO 1.6 A G979
	Colour/Trim C3U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
F0000056	Credit	20/08/2019/ 09:45	DS	218 / MarsLer	30725		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	KS 69100 G5 500	PANEL ASSY - BACK		1.00	526.00	0.00	526.00
M	KS 28710 G5 130	MUFFLER ASSY-REAR		1.00	840.00	0.00	840.00
P	KS 0G032 50 037A	CLIP - RR BUMPER		10.00	2.00	0.00	20.00
M	JJMZ313950	COOLANT		4.00	26.00	0.00	104.00
Z	NOTES						
ACCIDENT ON 19/08/2019 ALONG BKE TWDS PIE AFTER EXIT 7							
OWNER CLAIMING THIRD PARTY							
REQUIRED REPLACEMENT CAR							
TP # YK6655S TP INS : QBE							

Estimate

Insurance Company must be notified immediately of the following:

- To resurvey
- To displace
- To replace
- To repair
- To replace
- To repair
- To replace
- To repair

Insurance Company must be resurveyed and approved by Insurance Company

Acknowledged by Repairer

Signature:

Date:

5/24

Estimate

Customer to sign and notify
this repair shop for following:

- * To resurvey
- * To display
- * To provide information
- * To provide a "Without Prejudice" basis
- * To provide a "Without Prejudice" basis
- * To provide a "Without Prejudice" basis
- * To provide a "Without Prejudice" basis

Acknowledged by Repairer
Signature:
Date:

5/2/24

Confirm & accepted by	Parts	20,288.00
	Labour	0.00
	Standard Menu	0.00
	Specialist Job	18,260.00
	Others(Lub,etc)	0.00
	Sundry	50.00
Authorized signatory and company stamp	Total(w/o GST)	38,598.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.