

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19014676/AEA3Q2

Date: 27/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100472829

Claimant
Vehicle No : SBW30T **Insured Vehicle No :** SGL9189J

Date of Loss: 17/08/2019 Nature of Claim: TP Claim No: 5581253670SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBW30T		
Make & Model:	NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A)	Engine No:	HR16954867B
Reg. Date:	02/01/2015 (Man. Year: 2014)	Chassis No:	MNTBBAB17Z0021875
Colour:	Bronze	Odometer:	119220 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,335.70	7,413.84	10,921.86	59.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,440.00	3,230.00	1,210.00	27.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,775.70	10,643.84	12,131.86	53.27
Approved Total (Overridden) (S\$)		8,500.00		
Nett Amount (S\$)	22,775.70	8,500.00	14,275.70	62.68
+ Car Rental (13.0 x S\$100.00/day) (S\$)		1,300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,807.45		

INSPECTION

Date of Assignment: 20/08/2019

Date Inspected: 20/08/2019 Inspected At: Kiang Motor (HQ)
BLK 25 KAKI BUKIT ROAD 4, #08-26
SYNERGY @ KB
Singapore 417800

Estimated Period of Repair: 11.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	541.00 F	*541.00 FL
2	1		*FRONT BUMPER NUMBER PLATE	Bent	50.00 F	*50.00 FL
3	2		*FRONT BUMPER SIDE FOG LAMP COVER	Not Necessary	240.00 F	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	561.90 F	*561.90 FL
5	1		*FRONT BUMPER INNER SPONGE	Not Necessary	222.40 F	*- FL
6	2		*FRONT BUMPER BRACKET	Not Necessary	336.80 F	*- FL
7	1		*FRONT SUPPORT PANEL	Repair	669.60 F	*- FL
8	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	307.00 F	*- FL
9	1		*REAR BOOT LID	Buckled	850.90 F	*850.90 FL
10	12		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	420.00 F	*- FL
11	2		*REAR TAIL LAMP PANEL	Repair	265.80 F	*- FL
12	1		*REAR BUMPER	Deformed	784.40 F	*607.00 FL
13	1		*REAR SPARE TIRE PANEL	Repair	727.80 F	*- FL
14	1		*REAR END PANEL	Dented	464.00 F	*464.00 FL
15	2		*REAR FENDER	Repair	1,915.80 F	*- FL
16	1		*FRONT BUMPER TOWING COVER	Not Necessary	56.10 F	*- FL
17	2		*FRONT BUMPER SIDE BRACKET	Necessary	134.40 F	*134.40 FL
18	1		*FRONT BUMPER CENTER LOWER GARNISH	Not Necessary	215.00 F	*- FL
19	8		*FRONT BUMPER CLIPS	Necessary	40.00 F	*30.00 FL
20	1		*FRONT GRILLE	Cracked	266.70 F	*266.70 FL
21	1		*FRONT GRILLE CENTRE GARNISH	Not Necessary	325.00 F	*- FL
22	1		*FRONT GRILLE EMBLE LOGO	Necessary	50.00 F	*50.00 FL
23	8		*FRONT GRILLE CLIPS	Necessary	40.00 F	*20.00 FL
24	2		*FRONT HEADLAMP	Cracked	1,396.00 F	*1,396.00 FL
25	1		*AIR COND CONDENSER	Dented	1,150.00 F	*1,150.00 FL
26	1		*REAR BOOT LID CENTER MOULDING	Not Necessary	242.90 F	*- FL
27	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	325.00 F	*- FL
28	2		*REAR BOOT LID HINGES	Not Necessary	178.40 F	*- FL
29	1		*REAR BOOT LID LOWER MOULDING	Cut	216.20 F	*216.20 FL
30	2		*REAR BUMPER SIDE BRACKET	Necessary	170.00 F	*64.00 FL
31	1		*REAR BUMPER BRACKET	N/S Dented	157.00 F	*78.50 FL
32	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	571.20 F	*- FL
33	1		*REAR WINDSCREEN MOULDING	Not Necessary	165.20 F	*- FL
34	1		*REAR TAIL LAMP	N/S Cracked	770.40 F	*385.20 FL
35	1		*REAR END PANEL TOP GARNISH	Deformed	167.80 F	*167.80 FL
36	1		*REAR SPARE TIRE PANEL TOP COVER	Deformed	425.00 F	*425.00 FL
37	6		*FRONT GRILLE CLIPS	Repeated	21.00 F	*- FL
38	8		*FRONT BUMPER CLIPS	Repeated	28.00 F	*- FL
39	1		*REAR BOOT LID INNER LOCK	Damaged	185.20 F	*185.20 FL
40	1		*REAR BOOT LID NISSAN LOGO	Necessary	45.00 F	*45.00 FL
41	1		*REAR BOOT LID SYLPHY LOGO	Necessary	42.00 F	*42.00 FL
42	2		*REAR BOOT LID SIDE REFLECTOR	Not Necessary	570.00 F	*- FL
43	1		*REAR BOOT LID RUBBER	Cut	125.00 F	*125.00 FL
44	1		*REAR BUMPER SIDE REFLECTOR	N/S Missing	136.40 F	*68.20 FL
45	1		*REAR BUMPER REVERSE SENSOR	Damaged	300.00 F	*200.00 FL
46	1		*REAR BUMPER LOWER COVER	Not Necessary	358.00 F	*- FL
47	1		*REAR BUMPER INNER SPONGE	Cracked	78.60 F	*78.60 FL
48	1		*REAR BUMPER CLIPS (8 PCS)	Necessary	35.00 F	*35.00 FL
49	1		*REAR EXHAUST	Not Necessary	825.60 F	*- FL
50	2		*REAR NUMBER PLATE LAMP	Not Necessary	116.20 F	*- FL
51	1		*REAR NUMBER PLATE	Not Necessary	50.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	18,335.70	8,237.60
				- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	823.76
				Total Parts (S\$)	18,335.70	7,413.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	0.00
2	GUM	New	50.00	0.00
3	REMOVE AND REFIX REAR REVERSE SENSOR	New	100.00	50.00
4	REMOVE AND REFIX REAR EXHAUST	New	220.00	0.00
5	TOWING FEE	New	100.00	60.00
6	TO REMOVE & REFIX AIRCOND & TOP UP GAS	New	180.00	120.00
7	WHEEL ALIGNMENT (COMPUTER)	New	120.00	0.00
8	TO CHECK WIRING SYSTEM	New	80.00	60.00
9	TO REMOVE & REFIX REAR CUSHION	New	120.00	80.00
10	TUFF KOTE	New	150.00	60.00
11	PANEL BEATING	New	1,600.00	1,400.00
12	SPRAY PAINTING	New	1,600.00	1,400.00
Gross Labour Cost (\$\$)			4,440.00	3,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >