

22/8/2007

ASS. REC. BY:

REF: CS/FC119014754/ksf3n2

Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Sithorn

of FC1

Date/Time: 22.8.19 9.30A.M

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 17434

Insured: SHA 0915K

at Workshop m/s Esteem Performance

Tel: 87990066

of 385 Sin Ming Drive

Policy No:

Claim No: D19005412 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 22.8.19 11.28A.M

Person Contacted: Jenny

H.O.D. Endorsement:

Vehicle-IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHA 0915K: CS/FC118008509/11sbe2 D.O.A. 28/04/2008

SLK 17434-X

29/08/19 @ 15:48pm revised PA to Sithorn via email

2/9 81870.65 Cash

C \$ 6,769.61 Red - 78%)

REF: FCI

Kenneth

ASSIGNMENT

From

Date:

27.8.19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK 1743

at Workshop m/s: Esteem Performance

of 385 on Ming Drive

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh: After 11.00am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$72k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lump Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

map

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SLK 1743H

Regn:

01, 17

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Toyota

C.C.

1788

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

169651

T/Radio: Insured / Std / NI / NA

Eng/No.

C/No:

JT DKB 3FU103539563

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: Nil / S/Rim / STD / ☒ R/Rim or

Tyre Size: F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

2.18/11P

D.O.I.

2.7/8/11P

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

MS Acc body

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 02 SEP 2019

Date/Time, File Pass to?

02/09/19

1)

Type

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

Transportation

\$ + R.S. + G

Photos

Others

TOTAL

160

50

50

16

276

Report Format:

Lump Sum (1.B.) (\$)

1,370.65 p/p



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005412MFSH

Date: 29 August 2019

Our Ref: CS/FCI19014754/Ksf3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLK 1743H

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/08/2019 at the premises of M/s Esteem Performance Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 8,640.26
Revised Estimate Amount	: S\$ 1,939.36
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 2 days

Yours faithfully

Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	21-08-2019	Our Ref No. D19005412MFSH
Accident Date	21-08-2019	Claim Type. Third Party
Insured Vehicle	SHA0915K	Third Party Vehicle. SLK1743H
Survey Location	385, SIN MING DRIVE (INSIDE VICOM)	
Contact Person.	JENNY CHONG	
Contact No.	65662112/ 87990066	Fax No. 62593326
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Re: SURVEY ASSESSMENT - D19005412MFSH/1

Shirley Hiew (LKK Auto)

Thu 29/8/2019 3:48 PM

To: 'Sithara' <Sithara@msfirstcapital.com.sg>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

 1 attachments (80 KB)

PRELI ADVISE - SLK 1743H.pdf;

Dear Sithara,

Enclosed preliminary revised of vehicle SLK 1743H.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>**Sent:** Thursday, 22 August 2019 2:31 PM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>;
SUR <sur@lkkauto.com>

Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>**Subject:** RE: SURVEY ASSESSMENT - D19005412MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Catherine Chong | Admin**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Thursday, 22 August, 2019 9:30 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005412MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

First Capital



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLK 1743 H

Parts	(a) Cost / List Price Items	\$	5,250.33
	Plus/Less 20%	\$	1,050.07
	Total of Cost / List	\$	4,200.26
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	350.00
Total Parts Cost		\$	4,550.26
Labour		\$	4,090.00
Total		\$	8,640.26

The above total will be subjected to 7% G.S.T.

NOT Withain
Repairing

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No litigation/claim(s) is allowed
- Supplier's item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:
Signature:
Date:

Name of Surveyor

Kenneth

Company

LKK

Survey conducted on

27/8/18 at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

Sc

Date: 27/8/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLK 1743 H
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU103539563

Submit By : SERENCE
Year Manufacture : 2017
Engine No. : 2ZRR974243

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH wing mirror (arm)	1			
2	LH wing mirror (signal lamp)	1	\$1,374.20		✓
3	LH wing mirror (glass)	1			
4	LH wing mirror (cover)	1	\$87.40		X
5	LH rear door	1	\$1,211.40		✓
6	LH rear door hinge top	1	\$78.34		✓
7	LH rear door hinge bottom	1	\$78.34		X
8	LH rear door weatherstrip	1	\$198.70		X
9	LHR door glass outer moulding	1	\$107.80		X
10	LH rear fender	1	\$883.60		X
11	LH rear fender undershield	1	\$92.30		X
12	LH rear fender undershield clip	10	\$30.00		X
13	LH rear tyre	1	\$350.00	S.N	X
14	LH rear hub cap	1	\$195.65		X
15	Rear bumper	1	\$497.50		X
16	Rear bumper clip	10	\$40.00		X
17	Rear bumper side retainer LH	1	\$112.70		X
18	Rear bumper side retainer RH	1	\$112.70		X
19	Rear bumper lower garnish LH	1	\$149.70		X
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLK 1743 H** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LH SIDE MIRROR, LHF DOOR, LHR DOOR, LHF DOOR STAND PILLAR, LH SIDE SKIRT, LHR FENDER, REAR BUMPER)	\$1,600.00	3000
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LH SIDE MIRROR, LHF DOOR, LHR DOOR, LHF DOOR STAND PILLAR, LH SIDE SKIRT, LHR FENDER, REAR BUMPER)	\$1,600.00	5200
3	To check wiring	\$50.00	200
4	To tuff coat. ~	\$150.00	X
5	To remove & refit Door trim, door glass, window regulator, door lock to assist work load. ~	\$150.00	X
6	To do wheel alignment. ~	\$120.00	X
7	To remove & refit inner seat & upholstery to assist work load. ~	\$150.00	X
8	To remove & refit petrol tank to assist work load. ~	\$150.00	X
9	To conduct water leakage tests to ensure proper air and sealing ~	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

First Capital



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLK 1743 H

Finalised

Parts	(a) Cost / List Price Items	\$ 1374.20	5,250.33
	Plus/Less ²⁵ 20%	\$ 274.84	1,050.07
	Total of Cost / List	\$ 1099.36	4,200.26
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	350.00
	Total Parts Cost	\$	4,550.26
	Labour	\$ 840.00	4,090.00
	Total	\$ 1439.36	8,640.26

1870.65

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

UIC

Survey conducted on

27/8/18 at 12:15

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

Le

Date: 27/8/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19014754/Ksf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 915K	Veh. Inspected	SLK 1743H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005412MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	22/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU103539563	Colour	METALLIC SILVER	
Odometer	169651	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/08/2019	Inspection Date	27/08/2019	
Survey held at	385 SIN MING DRIVE			
Repairer	ESTEEM PERFORMANCE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 1743H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LH WING MIRROR (SIGNAL LAMP) }	CRACKED	1,374.20	1,374.20
1	LH WING MIRROR (ARM) }		-	-
1	LH WING MIRROR (GLASS) }		-	-
1	LH WING MIRROR (COVER)	SERVICEABLE	87.40	-
1	LH REAR DOOR	TO REPAIR SEE LABOUR	1,211.40	-
1	LH REAR DOOR HINGE TOP	TO REPAIR SEE LABOUR	78.34	-
1	LH REAR DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	78.34	-
1	LH REAR DOOR WEATHERSTRIP	SERVICEABLE	198.70	-
1	LHR DOOR GLASS OUTER MOULDING	SERVICEABLE	107.80	-
1	LH REAR FENDER	TO REPAIR SEE LABOUR	883.60	-
1	LH REAR FENDER UNDERSHIELD	SERVICEABLE	92.30	-
10	LH REAR FENDER UNDERSHIELD CLIP	NOT NECESSARY	30.00	-
1	LH REAR HUB CAB	SERVICEABLE	195.65	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	497.50	-
10	REAR BUMPER CLIP	NOT NECESSARY	40.00	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.70	-
1	REAR BUMPER LOWER GARNISH LH	SERVICEABLE	149.70	-
	LESS 20% DISCOUNT		-1,050.07	-
	LESS 25% DISCOUNT		-	-343.55
			4,200.26	1,030.65
SPECIAL NETT ITEMS				
1	LH REAR TYRE (SN)	SERVICEABLE	350.00	-
			350.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(LH SIDE MIRROR,LHF DOOR,LHR DOOR,LHF DOOR STAND PILLAR,LH SIDE SKIRT,LHR FENDER,REAR BUMPER).INCLUSIVE OF THE REPAIR OF LH REAR DOOR,LH REAR DOOR HINGE TOP,LH REAR DOOR HINGE BOTTOM,LH REAR FENDER AND REAR BUMPER.		1,600.00	300.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA..(LH SIDE MIRROR,LHF DOOR,LHR DOOR,LHF DOOR STAND PILLAR,LH SIDE SKIRT,LHR FENDER,REAR BUMPER).		1,600.00	520.00
	TO CHECK WIRING.		50.00	20.00
	TO TUFF COAT.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT DOOR TRIM,DOOR GLASS,WINDOW REGULATOR,DOOR LOCK TO ASSIST WORK LOAD).	NOT NECESSARY	150.00	-
	TO DO WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT PETROL TANK TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	NOT NECESSARY	120.00	-
			4,090.00	840.00
	GRAND TOTAL		8,640.26	1,870.65
	RECOMMENDED COST OF REPAIRS			1,870.65

Report Ref No. CS/FCI19014754/Ksf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.