# **Esteem Performance Pte Ltd** 385 Sin Ming Drive, Vicom Vehicle **Inspection Centre (575718)**

**Insurer Reference: SJZ5444P** Repairer Reference: 014122

Date calculated: 27/11/2019 7:19 PM

**Full Report** Registration: SLS2139D Printed: 27/11/2019 7:20 PM

### **Summary Information**

Claim

Location: Printed by:

Claim Reference: Estimated Repair Time: Actual Repair Days:

Singapore (SG) Carmen SG

SJZ5444P

Work Provider: Currency: Date of Incident:

Hire Car Start: Hire Car End:

AXA Insurance Pte Ltd

SGD 21/08/19

#### **Vehicle Details**

Vehicle

Manufacturer: Model:

Sub Model: Model Sheet Number: Registration:

VIN number: Odometer: **Model Specs** 

TWO COAT METALLIC

TOYOTA PRIUS IV BASE MODEL 70 P5 01

SLS2139D


## **Vehicle Condition**

**Vehicle Status** 

Pre-Accident Damage: Date of Inspection:

**Damage Areas** 

All Underbody



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Code	Description				WU	Price SGD	
B420	RENEW REAR BUMPER INCLUDES: REAR BUMPER	AND REQUIRED			12.0	60.00	
B410)	ATTACHED PARTS R + R R + R REAR BUMPER REIN	IFOR CEMENT			1.0	5.00	
5110)	K I K KEAK BOTH EK KEIN	OKCEPIENT			210	0,00	
	Labour Cost			Hrs	WU		
	Panel / Mechanical Lab	our		1.30	13.0	65.00	
	Total of Labour					65.00	
Paint							
Paint Work	SYSTEM AZT				Time Basis 10 WU/h		
Code	Description - TWO COAT METALLIC				WU	Price SGD	
-	REAR BUMPER NEW PART	PAINT K1R			12.0		
Paint Material	Per Part						
Code	Description					Price SGD	
2583	REAR BUMPER NEW PART	PAINT K1R				55.10	
	Labour Cost - Paint Factor		50.00 SGD/h	Hrs	WU	Price SGD	
	Time Paint				12.0		
	Preparation Comp. Work P <b>Total</b>	lastic	40 1411 //-	0.90	9.0	45.00	
	Total		10 WU/h	2.10	21.0	105.00	
	Material Cost - Paint					Price SGD	
	New Part Painting - Plastic K1R					55.10	
	Material-constant Plastic					16.20	
	Total					71.30	
Spare Parts							
	Description	Part Number	Supplier	prices as	at 2015		
Code			Supplier	prices as	at 2015	Price SGD	
<b>Code</b> 2583	REAR BUMPER	52159 47913	Supplier	prices as	at 2015	Price SGD 497.50	
<b>Code</b> 2583 2587	REAR BUMPER REAR COVER BUMPER	52159 47913 52453 47010	Supplier	prices as		497.50 582.60	
<b>Code</b> 2583 2587 2640	REAR BUMPER REAR COVER BUMPER REAR BUMPER REINF	52159 47913 52453 47010 52023 47030		prices as		5-06-01/01 Price SGD 497.50 582.60 A <sub>1</sub> 398.80	
Code 2583 2587 2640 1000	REAR BUMPER REAR COVER BUMPER	52159 47913 52453 47010	Supplier	prices as		497.50 582.60	
Code 2583 2587 2640 1000 1004	REAR BUMPER REAR COVER BUMPER REAR BUMPER REINF RR BMP CLIP R&R R.SENSOR	52159 47913 52453 47010 52023 47030 RR BMP CLIP		prices as		497.50 582.60 A <sub>1</sub> 398.80 40.00 50.00	
Code  2583 2587 2640 1000 1004  f: OEM Parts n: Non-OEM Parts	REAR BUMPER REAR COVER BUMPER REAR BUMPER REINF RR BMP CLIP R&R R.SENSOR  Savings	52159 47913 52453 47010 52023 47030 RR BMP CLIP		prices as		497.50 582.60 84 398.80 40.00 50.00	
Spare Parts  Code  2583 2587 2640 1000 1004  f: OEM Parts n: Non-OEM Parts u: Used parts	REAR BUMPER REAR COVER BUMPER REAR BUMPER REINF RR BMP CLIP R&R R.SENSOR  Savings	52159 47913 52453 47010 52023 47030 RR BMP CLIP R&R R.SENSOR		prices as		97.50 582.60 398.80 40.00 50.00 0.00 1,568.90	
Code  2583 2587 2640 1000 1004  f: OEM Parts n: Non-OEM Parts	REAR BUMPER REAR COVER BUMPER REAR BUMPER REINF RR BMP CLIP R&R R.SENSOR  Savings Subtotal	52159 47913 52453 47010 52023 47030 RR BMP CLIP R&R R.SENSOR		prices as		497.50 582.60 A <sub>1</sub> 398.80 40.00 50.00	

Code	Description		Price SGD
1003	R.SENSOR R.SENSOR		200.00*
	Total Extras		
Final Cal	Iculation		
		SGD	SGD
Parts		1,568.90	
	scount(+30.00%)	-470.67	
Total Part	s		1,098.23
	ime Base 10 WU/h		
Total 13.0 WU X 50.00 SGD/h		65.00	
Total of La	abour		65.00
Total Of E	xtras		200.00
Paint Wor	k Time Base 10 WU/h		
	Cost 21.0 WU X 50.00 SGD/h	105.00	
Material		71.30	
Total Pain	t Including Material		176.30
	st Excludes GST		1,539.53
GST (+7			107.77
Repair Cos	st Included GST		1,647.30

### Comments

\* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

### **Assessment Note**

No assessment notes entered.