

Systematic nomenclature

Date/Time: 22.8.19 9.47am

EIM Inc.

Tel: (54) 5119

Excerpt:

D.O.A. 13.8.2019

H.O.D. Endorsement:

Vehicle ~~IN~~ OUT[illegible]

Surveyor

REF:

ASSIGNMENT

00B April 2019

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 28 21 days Res.: Yes or No


Lum Sum: 32 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 2924 K Regn: April 2019
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Prius c.c. 1798
 Colour: Blue A/C: Insured / Std / Nil / NA
 Sp. Reading: N.A. T/Radio: Insured / Std / Nil / NA
 Eng/No: 22R2C06264
 C/No: JTDKB3FU003079828
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65 R15
 R: 11



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Goodyear

Front Rear
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm

D.O.A. 13/08/2019 D.O.I. 23/08/2019 1123h

Survey held at Chunni Amk

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front 7 0/2 Front 7 0/2 Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NTUC SGU 8990X

Book Value 71,678.23

LTA rebate 27,437.00

Net Value 44,241.23

RECEIVED 25 OCT 2019

04/10/2019
Page

2/5 44000/- net 32 days from (Red \$51,000-79, 53%)

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: 32

Resurvey No. of Trip: 3

Survey Fee:

290

Date/Time, File Return to?

29/10/19 Typist

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Transportation:

☐ : B + RD, SI

Photos

Others

TOTAL

290

Report Format :

Lump Sum I.B.I. (\$) \$44,000

Catherine Chong (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Thursday, 22 August, 2019 10:15 AM
To: 'assignments@lkkauto.com'
Cc: admin-d@lkkauto.com
Subject: FW: TP CASES FARMED OUT TO LKK ON 22/8/2019

Dear LKK,

Resend herewith claim ref. number & OIC

From: Daniel Koh
Sent: Thursday, 22 August 2019 9:47 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 22/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA	Adi Rei
1	DAVID PHUA	MT/1058265-002	GBD8570Z	CARZ AUTO SERVICES PTE LTD	61 WOODLANDS INDUSTRIAL PARK E9 (E9 PREMIUM) #04-04 SINGAPORE 757047	Jeslyn Chua / 8322 7418		CB5965L	19/8/2019	
2	CHRYLLIS QUAH	MT/1058537-002	XE4126J	CHENG HOE MOTOR PTE LTD	38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05 ADMIRALTY IND PARK SINGAPORE 757700	Efeeda / 67556142	10:00-16:00	XD1384E	17/8/2019	
3	SERENE LIM	MT/1057986-002	YP1799S	CHEONG CHEONG MOTOR SERVICE PTE. LTD.	BLK 5032 #01-293 ANG MO KIO INDUSTRIAL PARK 2	Angela Ng / 6481 4152		YL552P	16/8/2019	

					SINGAPORE 569535					
4	JARED LIU	MT/1058602- 002	SLR6843H	L SOON AUTO SERVICES	10 ANG MO KIO INDUSTRIAL PARK 2A #03- 18 AMK AUTOPOINT SINGAPORE 568047	/ 6482 1513		GX7292T	19/8/2019	
5	WO JESSIE	MT/1058786- 001	SHC2924K	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2- A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SGU8990X	13/8/2019	65 or 71
6	AZHARI	MT/1058175- 002	PA9030J	THE ONE HOLDINGS PTE LTD	8 WOODLANDS INDUSTRIAL PARK E3 WOODLANDS INDUSTRIAL PARK E SINGAPORE 757786	Muhd.Hilmi Deres / 97480340	10:00- 12:00	SLZ2322D	16/8/2019	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Daniel Koh
Senior Admin Assistant
Motor Insurance
T +65 6430 7901
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

MCD019108363 / ComfortDelGro Engineering Pte Ltd - Loyang
ENTRY DATE & TIME: 20/08/2019 14:50
SUBMITTED BY: Huang XiaoYan

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 20/08/2019 15:11

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 20/08/2019 14:50
Date Of Accident 13/08/2019 13:15
Exact Location Of Accident T JUNCTION OF CHOA CHU KANG NORTH 5
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC2924K
Insured/Policyholder
Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
Co Reg No 199303821R
Email Address FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-65508768

Vehicle Particulars

Manufacturer TOYOTA
Model PRIUS
Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category TAXI

Insurance Company

Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy YES
Policy Number MCOM0015

Cover Note Number

Driver

Name of Driver TAN SOON CHEONG
NRIC No S0105311F
Date Of Birth 14/06/1951
Occupation OUTDOOR
Date Of Driving Pass 06/09/1978
Driving Experience 40 YEARS AND 11 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-94892533
Fax Number
Contact Number
Email Address TANSC98@HOTMAIL.COM

Address BLK 669 CHOA CHU KANG CRESCENT #04-357
 Postcode 680669
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] 10 UBI AVE 3 SINGAPORE 408865
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED / POLICE REPORT : T/20190819/2153 / Type Of Accident : HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGU8990X
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Nature Of Damage LEFT FRT
 No. Of Passenger (including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	TRAFFIC LIGHT POLE
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN SOON CHEONG
Approximate Age	68
Injuries Sustain	RIGHT LEG PAIN. HOSPITALISED FOR 7 DAYS AND 3 MONTHS OF MC.
Injured person in which vehicle?	SHC2924K
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 20.08.2019@1200HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June

SKETCH PLAN



A-SHC 2924K
B-SGU-8990X
C-Traffic Light Pole

Along Choa Chu Kang Junction Choa Chu Kang North 5.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Green
Light.

Refer to attachment: T/20190819/2153

The impact had caused my vehicle to lose control and hit onto the traffic light pole.

I was hospitalised for 7 days and was given 3 months of MC.

DECLARATION

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R
We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD

CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 20.08.2019@1200HRS

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: June


**SINGAPORE
POLICE FORCE**


T/20190819/2153

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190819/2153

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/08/2019 16:28		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: TAN SOON CHEONG			Address: 669 CHOA CHU KANG CRESCENT #04-357 SINGAPORE 680669		
ID Type / ID No.: NRIC NO / S0105311F			Contact No.: Home/Office: Mobile: 94892533		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 68	Date of Birth: 14/06/1951	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: TAXI DRIVER			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 13/08/2019 13:15	Type of Location:
Location: Along Road 1 CHOA CHU KANG WAY CHOA CHU KANG WAY X CHOA CHU KANG NORTH 5 JUNCTION				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Heavy
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGU8990X	Car				Seriously Damaged	0
SHC2924K	Car				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

**SINGAPORE
POLICE FORCE**

T/20190819/2153

2 of 3

Report No. T/20190819/2153

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Driver			
Name	TAN SOON CHEONG	ID No.	S0105311F
Related Vehicle	SHC2924K (Car)	Contact No.	94892533
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above date time and location,
I was travelling towards bukit batok. The traffic light was on my favour. Out of suddenly a car hit me on the front. The driver come out of the vehicle and rendered assistance. Someone called the ambulance and I was conveyed to Ng Teng Fong Hospital.

**SINGAPORE
POLICE FORCE**

T/20190819/2153

3 of 3

Report No. T/20190819/2153

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

TP /

FIRDAUS BIN ABU BAKAR

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

19/08/2019 16:28

Officer In Charge Of Case:

TP / GIT /

SI ONG CHEE HIEN

Contact No.: 65476437

Classification Of Case:

Authentication Stamp

NP168

**SINGAPORE
POLICE FORCE**

Signature:

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHC 2924K

MAKE :

MODEL : TOYOTA PRIUS

DATE : 20.08.2019

TEL NO : 6542 5119

FAX NO : 6542 6039

KfuiL

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
BONNET <i>Bnc</i>			\$ 950.50
INSULATOR, HOOD <i>St</i>			\$ 398.10
INSULATOR CLIPS <i>hlc</i>			\$ 3.60
BONNET RUBBER <i>NH</i>			\$ 35.50
BONNET CABLE <i>St / torn</i>			\$ 53.20
BONNET HINGE (RH) <i>St</i>			\$ 57.70
BONNET HINGE (LH) <i>St</i>			\$ 57.70
BONNET LOCK <i>St</i>			\$ 132.60
RADIATOR GRILLE <i>broken</i>			\$ 438.00
RADIATOR GRILLE EMBLEM <i>broken</i>			\$ 88.00
LAMP ASSY, FOG, RH <i>distorted</i>			\$ 920.00
LAMP ASSY, FOG, LH <i>distorted</i>			\$ 920.00
FRONT BUMPER COVER <i>torn</i>			\$ 499.90
FRONT BUMPER REINFORCEMENT <i>Bnc</i>			\$ 696.40
FRONT BUMPER REINFORCEMENT ABSORBER <i>Bnc</i>			\$ 115.70
FRONT BUMPER SPONGE <i>torn</i>			\$ 78.80
FRONT BUMPER CENTRE GRILLE <i>broken</i>			\$ 301.90
FRONT BUMPER CLIPS <i>hlc</i>			\$ 22.00
FRONT BUMPER SIDE RETAINER <i>o/s distorted n/s broken</i>	\$	77.00	\$ 154.00
FRONT RADIATOR LOWER SUPPORT PANEL <i>Distorted</i>			\$ 357.70
ENGINE UNDER COVER (RR) <i>torn</i>			\$ 457.40
FRONT BUMPER TOP GARNISH <i>torn</i>			\$ 225.40
COVER, FRONT BUMPER HOLE, RH <i>distorted</i>			\$ 28.38
COVER, FRONT BUMPER HOLE, LH <i>distorted</i>			\$ 28.38
FRONT BUMPER LOWER REINFORCEMENT BRACKET (LH/RH)	\$ <i>St</i>	165.00	\$ 330.00
FRONT BUMPER CENTRE FRAME <i>NH</i>			\$ 236.90
BRACKET, FRONT BUMPER SIDE, RH <i>NH</i>			\$ 82.30
BRACKET, FRONT BUMPER SIDE, LH <i>NH</i>			\$ 82.30
UNIT ASSY, HEADLAMP, RH (LED) <i>broken</i>			\$ 3,455.00
UNIT ASSY, HEADLAMP, LH (LED) <i>broken</i>			\$ 3,455.00
HEAD LAMP PANEL (RH) <i>St</i>			\$ 240.10
HEAD LAMP PANEL (LH) <i>St</i>			\$ 240.10
TOP PANEL CENTRE <i>St</i>			\$ 364.90
TOP PANEL, LH <i>St</i>			\$ 145.90
TOP PANEL, RH <i>St</i>			\$ 145.90
BRACE PANEL <i>St</i>			\$ 75.20
RADIATOR ASSY <i>punctured</i>			\$ 1,841.80
RADIATOR FAN COWLING ASSY <i>broken</i>			\$ 661.30
RADIATOR TOP HOSE, LH <i>distorted</i>			\$ 43.03
RADIATOR TOP HOSE, RH <i>distorted</i>			\$ 42.60
RADIATOR SPARE TANK <i>broken</i>			\$ 125.80
RADIATOR BOTTOM MOUNTING <i>NH</i>			\$ 27.50
STAY, RADIATOR SUPPORT, RH <i>NH</i>			\$ 65.70
STAY, RADIATOR SUPPORT, LH <i>NH</i>			\$ 65.70
RADIATOR FAN BLADE (RH) <i>broken</i>			\$ 233.10
RADIATOR FAN BLADE (LH) <i>broken</i>			\$ 233.10
RADIATOR FAN MOTOR (RH) <i>Distorted</i>			\$ 543.70

19161-89

SHC 2924K

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
RADIATOR FAN MOTOR (LH) <i>2 bt</i>			\$ 543.70	<i>2 ✓</i>
DEFLECTOR, RADIATOR SIDE, RH <i>turn</i>			\$ 83.50	<i>✓</i>
DEFLECTOR, RADIATOR SIDE, LH <i>turn</i>			\$ 77.00	<i>✓</i>
HORN <i>Dem / Dented</i>		\$ 112.71	\$ 225.42	<i>✓</i>
CLEANER ASSY, AIR <i>2 broken</i>			\$ 970.30	<i>2 ✓</i>
AIR CLEANER TOP COVER <i>2 broken</i>			\$ 446.50	<i>2 ✓</i>
AIR CLEANER BOTTOM COVER <i>2 broken NW</i>			\$ 947.80	<i>2 broken X</i>
AIR CLEANER HOSE <i>2 broken</i>			\$ 62.12	<i>2 ✓</i>
AIR DUCT <i>broken</i>			\$ 129.40	<i>✓</i>
INLET ASSY, AIR CLEANER <i>broken</i>			\$ 132.00	<i>✓</i>
AIR DUCT CENTRE <i>broken</i>			\$ 94.03	<i>✓</i>
COMPRESSOR ASSY, W/MOTOR <i>2 Dem</i>			\$ 2,924.20	<i>2 ✓</i>
CONDENSER ASSY, W/RECEIVER <i>Puncher, 2</i>			\$ 1,336.60	<i>✓</i>
AIRCON DISCHARGE HOSE <i>2 bt</i>			\$ 386.90	<i>2 ✓</i>
AIRCON LIQUID HOSE & PIPE <i>2 bt</i>			\$ 580.45	<i>2 ✓</i>
AIRCON HOSE SUCTION <i>2 bt</i>			\$ 548.50	<i>2 ✓</i>
FENDER SUB-ASSY, FRONT LH <i>Enc</i>			\$ 945.30	<i>✓</i>
FENDER SUB-ASSY, FRONT RH <i>Enc</i>			\$ 945.30	<i>✓</i>
FRONT FENDER SHIELD, LH <i>distorted</i>			\$ 196.60	<i>✓</i>
FRONT FENDER SHIELD, RH <i>distorted</i>			\$ 196.60	<i>✓</i>
FRONT FENDER SHIELD CLIP <i>Hec</i>			\$ 3.80	<i>✓</i>
FRONT FENDER HYBRID EMBLEM, LH <i>Hec</i>			\$ 53.50	<i>✓</i>
FRONT FENDER HYBRID EMBLEM, RH <i>Hec</i>			\$ 53.50	<i>✓</i>
TRAY, BATTERY <i>broken</i>			\$ 42.80	<i>✓</i>
CLAMP, BATTERY <i>3Vc</i>			\$ 58.00	<i>X</i>
PANEL SUB-ASSY, FRONT DOOR, RH <i>Enc</i>			\$ 1,264.00	<i>✓</i>
FRONT DOOR TRIMBOARD, RH <i>2 broken / distorted</i>			\$ 725.00	<i>2 ✓</i>
FRONT DOOR OUTER MOULDING <i>bt</i>			\$ 188.60	<i>✓</i>
FRONT DOOR HANDLE BASE <i>cut</i>			\$ 287.70	<i>✓</i>
FRONT DOOR KEY LOCK SET <i>Dem</i>			\$ 428.90	<i>✓</i>
PANEL SUB-ASSY, REAR DOOR, RH <i>Dented</i>			\$ 1,258.30	<i>✓</i>
REAR DOOR HINGE UPPER <i>2 bt</i>			\$ 82.30	<i>2 ✓</i>
REAR DOOR HINGE LOWER <i>2 bt</i>			\$ 82.30	<i>2 ✓</i>
REAR DOOR CHECK <i>2 Hec</i>			\$ 155.70	<i>2 X</i>
REAR DOOR TRIMBOARD <i>NW</i>			\$ 725.00	<i>X</i>
REAR DOOR OUTER MOULDING <i>3Vc</i>			\$ 141.00	<i>X</i>
REAR DOOR RUBBER SEAL OUTER <i>turn / distorted</i>			\$ 257.90	<i>✓</i>
DOOR CENTRE PILLAR <i>2 Enc</i>			\$ 1,590.60	<i>2 ✓</i>
FRONT DOOR SAFETY BELT (LH/RH) <i>activated</i>		\$ 846.10	\$ 1,692.20	<i>✓</i>
REAR DOOR SAFETY BELT (LH/RH) <i>activated</i>		\$ 838.00	\$ 1,676.00	<i>✓</i>
REAR DOOR SAFETY BELT, OUTER CENTRE <i>NW</i>			\$ 526.00	<i>X</i>
MOTOR ASSY, POWER WINDOW REGULATOR FRT, RH <i>NW</i>			\$ 941.80	<i>X</i>
MOTOR ASSY, POWER WINDOW REGULATOR REAR, RH <i>NW</i>			\$ 768.90	<i>X</i>
REGULATOR SUB-ASSY, FRONT DOOR WINDOW FRT, RH <i>NW</i>			\$ 233.70	<i>X</i>
REGULATOR SUB-ASSY, REAR DOOR WINDOW REAR, RH <i>NW</i>			\$ 233.70	<i>X</i>
GLASS, SUB-ASSY, FRONT DOOR, RH <i>Shattered</i>			\$ 780.00	<i>✓</i>
CENTRE ROCKER PANEL (GARNISH) <i>Enc</i>			\$ 576.00	<i>✓</i>

21867.82

SHC 2924K

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
FRONT PILLAR UPPER COVER, RH <i>dislodged</i>			\$ 96.00	✓
FRONT PILLAR UPPER COVER, LH <i>dislodged</i>			\$ 96.00	✓
FRONT WINDSCREEN GLASS <i>crack</i>			\$ 1,627.30	✓
FRONT WINDSCREEN GLASS MOULDING <i>N/A</i>			\$ 208.60	✓
WIPER TOP GARNISH <i>not broken</i>			\$ 668.32	X ✓
WIPER SPARE TANK <i>dislodged</i>			\$ 183.75	✓
WIPER SPARE TANK MOTOR <i>Done</i>			\$ 242.70	✓
WIPER SPARE TANK FLOAT (NECK) <i>not</i>			\$ 55.50	✓ X
FRONT WHEEL RIM (LH) <i>N/A</i>			\$ 1,555.10	X
FRONT WHEEL HUB BEARING (LH) <i>not Done</i>			\$ 560.10	X ✓
FRONT SHOCK ABSORBER (LH) <i>not dislodged</i>			\$ 401.80	X ✓
ABSORBER TOP MOUNTING, LH <i>N/A</i>			\$ 196.20	X
FRONT SUSPENSION LOWER ARM (LH) <i>not dislodged</i>			\$ 637.50	X ✓
FRONT DRIVE SHAFT (LH) <i>not Done / dislodged</i>			\$ 1,310.10	X ✓
RACK & PINION ASSY <i>not Done</i>			\$ 1,634.90	X ✓
BAR, STABILIZER <i>not dislodged</i>			\$ 360.00	X ✓
LINK ASSY, FRONT STABILIZER, LH <i>not</i>			\$ 199.00	X ✓
KNUCKLE, STEERING, LH <i>not dislodged</i>			\$ 562.30	X ✓
END SUB-ASSY, TIE ROD, LH <i>not dislodged</i>			\$ 158.10	X ✓
ENGINE UNDER COVER <i>Done</i>			\$ 457.20	✓
FRONT CHASSIS MEMBER (LH) <i>not</i>			\$ 2,035.10	X
ENGINE MOUNTING (LH/RH) <i>not Done / not</i>		\$ 386.60	\$ 773.20	X ✓
ENGINE MTG (FRONT) <i>N/A</i>			\$ 174.63	X
ENGINE MTG (REAR) <i>not</i>			\$ 172.90	X ✓
FRONT BRAKE ABS SENSOR ONLY <i>N/A</i>			\$ 450.70	X
FAN BELT <i>N/A</i>			\$ 155.00	X
AIR BAG ASSY, DRIVER SIDE LOWER, RH <i>activated not reported</i>			\$ 1,615.00	X
AIR BAG ASSY, FRONT SEAT, RH <i>activated reported</i>			\$ 857.90	X
AIR BAG ASSY, FRONT SEAT, LH <i>activated reported</i>			\$ 857.90	X
AIR BAG ASSY, INSTRUMENT PANEL PASSENGER W/O DOOR, LH <i>activated</i>			\$ 3,277.50	X
STEERING ANGLE SENSOR <i>not activated</i>			\$ 986.00	X
SENSOR, AIR BAG, FRONT (RH) <i>activated reported</i>			\$ 313.50	X
SENSOR, SPEED, FRONT RH <i>N/A</i>			\$ 455.10	X
SENSOR, SPEED, FRONT LH <i>N/A</i>			\$ 455.10	X
SENSOR ASSY, SIDE AIR BAG, RH <i>activated reported</i>			\$ 709.30	X
WIRING FRONT <i>not torn / housing broken</i>			\$ 6,685.90	X ✓
HYBRID INVERTER SPARE TANK <i>not broken</i>			\$ 371.30	X ✓
HYBRID INVERTER BYPASS HOSE (INLET) <i>N/A</i>			\$ 42.60	X
HYBRID INVERTER BYPASS HOSE (OUTLET) <i>N/A</i>			\$ 29.30	X
HYBRID COOLING PUMP MOTOR <i>N/A</i>			\$ 432.20	X
SUB TOTAL			\$ 78,417.81	
LESS 20% <i>26%</i>			\$ 15,683.56	
DISCOUNTED TOTAL			\$ 62,734.25	
			59422.68	
			44567.01	

SHC 2924K

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
FRONT NO. PLATE <i>distorted</i>			\$ 25.00	NETT ✓
FRONT NO PLATE TRIM COVER <i>broken</i>			\$ 45.00	NETT ✓
FRONT NO. PLATE GARNISH <i>trim</i>			\$ 99.00	NETT ✓
NEW BATTERY <i>broken 50%</i>			\$ 80.00	NETT ✓
FRONT DOOR COMFORT LOGO <i>N/L</i>			\$ 75.00	NETT ✓
REAR DOOR COMFORT & APPS STICKER <i>N/L</i>		425.00	\$ 80.00	NETT ✓
FRONT WINSCREEN SEALANT <i>N/L</i>			\$ 46.00	NETT ✓
FRONT TYRE (LH) <i>3/L</i>			\$ 216.00	NETT X
			\$ 731.00	
LABOUR CHARGE				
Panel Beating			\$ 1,900.00	1400/-
Spray Painting Charge			\$ 1,500.00	1000/-
Wiring Charge			\$ 50.00	30/-
Tuff Kote			\$ 80.00	40/-
Towing Charge			\$ 90.00	N/A
Front Chassis Alignment Charge			\$ 200.00	150/-
Transfer of Door		\$ 80.00	\$ 240.00	120/-
Remove/Refix Undercarriage (FRT)			\$ 100.00	80/-
FRT Wheel Alignment			\$ 100.00	60/-
Remove/Refix Aircon & Refill Gas			\$ 80.00	60/-
Remove/Refix Engine			\$ 150.00	✓
Remove/Refix Dashboard			\$ 200.00	150/-
Remove/Refix Fuse Box			\$ 80.00	50/-
Remove/Refix Front Windscreen Glass			\$ 90.00	80/-
Remove/Refix Cushion & Upholstery Front		3800.00	\$ 100.00	80/-
Remove /Refix Seat Adjuster			\$ 120.00	50/-
R/Refix Air Bag/Steering Wheel/Dashboard/Seat			\$ 120.00	100/-
Re-set Frt ABS System			\$ 100.00	
Re-set Frt & Rear Power Window System		\$ 100.00	\$ 200.00	
Diagnosis & Resetting To Erase Fault Code			\$ 300.00	250/-
			\$ 5,800.00	
TOTAL LABOUR				
ESTIMATE TOTAL			\$ 69,265.25	
<i>Provide BV before finalization</i>				
<i>23/08 pur e 1100ms 32</i>			48792.01	99000.29
<i>N/A Antimal 28</i>			23345.41	99276.29
<i>2/sum</i>				
<i>Ryan</i>			7213742	
<i>2KK Auto</i>			44000/-	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHC 2924K (Supplementary)

DATE : 5.09.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
THROTTLE BODY <i>broken</i>			\$ 1,625.00
COOLER MOTOR COOLING <i>1st</i>			\$ 420.00
HOSE, RAD-COOLER <i>tern</i>			\$ 60.00
HOSE, HV W/PUMP COOLER <i>defunct</i>			\$ 54.00
HV WATER PUMP <i>broken</i>			\$ 630.00
HOSE, R/TANK HV W/PUMP <i>defunct</i>			\$ 60.00
HOSE INVERTER R/TANK <i>defunct</i>			\$ 51.00
WATER PIPE NO.1 (3P) <i>defunct</i>			\$ 36.00
HOSE W/PIPE NO.1 -W/PIPE NO. 2 <i>defunct</i>			\$ 36.00
WATER PIPE (2P) <i>defunct</i>			\$ 36.00
HOSE W/PIPE NO.2 RAD LH <i>defunct</i>			\$ 36.00
HOSE R/TANK-W/PIPE NO. 1 <i>defunct</i>			\$ 27.00
HOSE THROTTLE B-EGR VALVE <i>broken</i>			\$ 54.00
HOSE THROTTLE B-W/PIPE NO. 6 <i>defunct</i>			\$ 48.00
AIR INTAKE RESONATOR <i>defunct</i>			\$ 30.00
AIR HOSE <i>defunct</i>			\$ 90.00
HOSE R/TANK-RAD. RH <i>defunct</i>			\$ 54.00
HOSE COOLER-COOLING PIPE NO.1 <i>defunct</i>			\$ 39.00
HOSE COOLER-COOLING PIPE NO.2 <i>defunct</i>			\$ 39.00
RADIATO R HOSE CLAMP 40MM <i>Nec</i>			\$ 9.60
RADIATO R HOSE CLAMP 44MM <i>Nec</i>	3	\$ 9.50	\$ 28.50
RADIATO R HOSE CLAMP 24MM <i>Nec</i>	6	7.50	\$ 45.00
RADIATO R HOSE CLAMP 26MM <i>Nec</i>	8	8.40	\$ 67.20
RADIATO R HOSE CLAMP 17MM <i>Nec</i>	10	2.20	\$ 22.00
RADIATO R HOSE CLAMP 13MM <i>Nec</i>	2	5.4	\$ 10.80
AIR HOSE CLAMP 65 MM <i>Nec</i>			\$ 10.50
ENGINE UNDER COVER FRT <i>defunct from repair</i>			\$ 457.20
FRT BUMPER TOP RUBBER <i>tone</i>			\$ 225.00
FRT BUMPER LOWER REINFORCEMENT <i>1st</i>			\$ 241.40
FRT BUMPER LOWER REINFORCEMENT ABSORBER <i>broken 1st</i>			\$ 165.00
ENGINE CROSSMEMBER <i>1st</i>			\$ 2,531.70
ENGINE CROSSMEMBER SUPPORT BRACKET (LH/RH) <i>1st</i>		\$ 129.50	\$ 259.00
WIPER SPARE TANK NECK <i>defunct</i>			\$ 135.00
FRT WINDSCREEN MOULDING LOWER <i>Nec</i>			\$ 218.00
STEERING WHEEL AIRBAG <i>activated</i>			\$ 2,402.20
PASSENGER AIR BAG <i>activated</i>			\$ 3,869.00
KNEE AIR BAG <i>activated</i>			\$ 1,593.60
ROOF TOP SIDE AIR BAG (LH/RH) <i>activated</i>		\$ 1,748.10	\$ 3,496.20
FRT SEAT AIR BAG (LH/RH) <i>activated</i>		\$ 826.96	\$ 1,653.92
ECU CONTROL UNIT <i>activated</i>			\$ 988.00
ABS PUMP BRACKET <i>1st</i>			\$ 360.00
HEAD LAMP CONTORL UNIT (LH/RH) <i>broken 1st</i>		\$ 1,280.00	\$ 2,560.00
CENTRE PILLAR NO. 2 <i>Down</i>			\$ 990.00
CENTRE PILLAR INNER NO. 3 <i>Down</i>			\$ 450.00
PIPE SUB-ASSY SUCTION <i>from 1st</i>			\$ 660.00

1/2

SHC 2924K

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
SUB TOTAL			\$ 26,873.82
LESS 20% ^{25%}			\$ 5,374.76
DISCOUNTED TOTAL			\$ 21,499.06
 2kk Anchu 		2575662 19317.46 =	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHC 2924K (Supplementary)

DATE : 11.09.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

MODEL	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	FRONT HOUSING ASSY,LH <i>Revised</i>			\$ 958.30
	FRONT HOUSING ASSY,RH <i>Revised</i>			\$ 958.30
	FRONT CHASSIS MEMBER COVER (LH/RH) <i>defective for Nat</i>		\$ 135.00	\$ 270.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHC 2924K (Supplementary)

DATE : 17.09.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
ACTUATOR ASSY, SHIFT CONTROL <i>Dem</i>			\$ 3,109.00 ✓
SUB TOTAL			\$ 3,109.00
LESS 20% <i>25%</i>			\$ 621.80
DISCOUNTED TOTAL			\$ 2,487.20
<i>17</i> <i>16/09/2019</i> <i>2KK Auto</i> <i>8</i>			<i>2331.75</i> <i>95000-79</i>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19014775/Dyf3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 30-10-2019



ATTN : WO JESSIE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGU 8990X	Veh. Inspected	SHC 2924K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1058786-001	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	22/08/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTDKB3FU003079828	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	5 mm
L/H Front Tyre	195/65 R15	GOODYEAR	5 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	5 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, FRONT AND O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/08/2019	Inspect Date / Time	23/08/2019 (11:23 AM)
Survey held at	SOON HOCK CAR CARE BLK 10 AMK IND PK 2A #01-05/06 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	32 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 8

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2924K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	BUCKLED	950.50	950.50
1	INSULATOR, HOOD	BENT	398.10	398.10
1	INSULATOR CLIPS	NECESSARY	3.60	3.60
1	BONNET RUBBER	NOT NECESSARY	35.50	-
1	BONNET CABLE	BENT / TORN	53.20	53.20
1	BONNET HINGE (RH)	BENT	57.70	57.70
1	BONNET HINGE (LH)	BENT	57.70	57.70
1	BONNET LOCK	BENT	132.60	132.60
1	RADIATOR GRILLE	BROKEN	438.00	438.00
1	RADIATOR GRILLE EMBLEM	BROKEN	88.00	88.00
1	LAMP ASSY, FOG, RH	DISLODGE	920.00	920.00
1	LAMP ASSY, FOG, LH	DISLODGE	920.00	920.00
1	FRONT BUMPER COVER	TORN	499.90	499.90
1	FRONT BUMPER REINFORCEMENT	BUCKLED	696.40	696.40
1	FRONT BUMPER REINFORCEMENT ABSORBER	BUCKLED	115.70	115.70
1	FRONT BUMPER SPONGE	TORN	78.80	78.80
1	FRONT BUMPER CENTRE GRILLE	BROKEN	301.90	301.90
1	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
2	FRONT BUMPER SIDE RETAINER @\$77.00	O/S DISLODGE / N/S BROKEN	154.00	154.00
1	FRONT RADIATOR LOWER SUPPORT PANEL	DENTED	357.70	357.70
1	ENGINE UNDER COVER (RR)	TORN	457.40	457.40
1	FRONT BUMPER TOP GARNISH	TORN	225.40	225.40
1	COVER, FRONT BUMPER HOLE, RH	DISLODGE	28.38	28.38
1	COVER, FRONT BUMPER HOLE, LH	DISLODGE	28.38	28.38
2	FRONT BUMPER LOWER REINFORCEMENT BRACKET (LH/RH) @\$165.00	BENT	330.00	330.00
1	FRONT BUMPER CENTRE FRAME	NOT NECESSARY	236.90	-
1	BRACKET, FRONT BUMPER SIDE, RH	NOT NECESSARY	82.30	-
1	BRACKET, FRONT BUMPER SIDE, LH	NOT NECESSARY	82.30	-
1	UNIT ASSY, HEADLAMP, RH (LED)	BROKEN	3,455.00	3,455.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	UNIT ASSY, HEADLAMP, LH (LED)	BROKEN	3,455.00	3,455.00
1	HEAD LAMP PANEL (RH)	BENT	240.10	240.10
1	HEAD LAMP PANEL (LH)	BENT	240.10	240.10
1	TOP PANEL CENTRE	BENT	364.90	364.90
1	TOP PANEL, LH	BENT	145.90	145.90
1	TOP PANEL, RH	BENT	145.90	145.90
1	BRACE PANEL	BENT	75.20	75.20
1	RADIATOR ASSY	PUNCTURE	1,841.80	1,841.80
1	RADIATOR FAN COWLING ASSY	BROKEN	661.30	661.30
1	RADIATOR TOP HOSE, LH	DEFORMED	43.03	43.03
1	RADIATOR TOP HOSE, RH	DEFORMED	42.60	42.60
1	RADIATOR SPARE TANK	BROKEN	125.80	125.80
1	RADIATOR BOTTOM MOUNTING	NOT NECESSARY	27.50	-
1	STAY, RADIATOR SUPPORT, RH	NOT NECESSARY	65.70	-
1	STAY, RADIATOR SUPPORT, LH	NOT NECESSARY	65.70	-
1	RADIATOR FAN BLADE (RH)	BROKEN	233.10	233.10
1	RADIATOR FAN BLADE (LH)	BROKEN	233.10	233.10
1	RADIATOR FAN MOTOR (RH)	DENTED	543.70	543.70
1	RADIATOR FAN MOTOR (LH)	BENT	543.70	543.70
1	DEFLECTOR, RADIATOR SIDE, RH	TORN	83.50	83.50
1	DEFLECTOR, RADIATOR SIDE, LH	TORN	77.00	77.00
2	HORN @\$112.71	DAMAGED / DENTED	225.42	225.42
1	CLEANER ASSY, AIR	BROKEN	970.30	970.30
1	AIR CLEANER TOP COVER	BROKEN	446.50	446.50
1	AIR CLEANER BOTTOM COVER	NOT NECESSARY	947.80	-
1	AIR CLEANER HOSE	BROKEN	62.12	62.12
1	AIR DUCT	BROKEN	129.40	129.40
1	INLET ASSY, AIR CLEANER	BROKEN	132.00	132.00
1	AIR DUCT CENTRE	BROKEN	94.03	94.03
1	COMPRESSOR ASSY, W/MOTOR	DAMAGED	2,924.20	2,924.20
1	CONDENSER ASSY, W/RECEIVER	PUNCTURE	1,336.60	1,336.60
1	AIRCON DISCHARGE HOSE	BENT	386.90	386.90

Report Ref No. CS/INC19014775/Dyf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIRCON LIQUID HOSE & PIPE	BENT	580.45	580.45
1	AIRCON HOSE SUCTION	BENT	548.50	548.50
1	FENDER SUB-ASSY, FRONT LH	BUCKLED	945.30	945.30
1	FENDER SUB-ASSY, FRONT RH	BUCKLED	945.30	945.30
1	FRONT FENDER SHIELD, LH	DISLODGE	196.60	196.60
1	FRONT FENDER SHIELD, RH	DEFORMED	196.60	196.60
1	FRONT FENDER SHIELD CLIP	NECESSARY	3.80	3.80
1	FRONT FENDER HYBRID EMBLEM, LH	NECESSARY	53.50	53.50
1	FRONT FENDER HYBRID EMBLEM, RH	NECESSARY	53.50	53.50
1	TRAY, BATTERY	BROKEN	42.80	42.80
1	CLAMP, BATTERY	SERVICEABLE	58.00	-
1	PANEL SUB-ASSY, FRONT DOOR, RH	BUCKLED	1,264.00	1,264.00
1	FRONT DOOR TRIMBOARD, RH	BROKEN / DEFORMED	725.00	725.00
1	FRONT DOOR OUTER MOULDING	BENT	188.60	188.60
1	FRONT DOOR HANDLE BASE	CUT	287.70	287.70
1	SET FRONT DOOR KEY LOCK	DAMAGED	428.90	428.90
1	PANEL SUB-ASSY, REAR DOOR, RH	DENTED	1,258.30	1,258.30
1	REAR DOOR HINGE UPPER	BENT	82.30	82.30
1	REAR DOOR HINGE LOWER	BENT	82.30	82.30
1	REAR DOOR CHECK	NOT NECESSARY	155.70	-
1	REAR DOOR TRIMBOARD	NOT NECESSARY	725.00	-
1	REAR DOOR OUTER MOULDING	SERVICEABLE	141.00	-
1	REAR DOOR RUBBER SEAL OUTER	TORN / DEFORMED	257.90	257.90
1	DOOR CENTRE PILLAR	BUCKLED	1,590.60	1,590.60
2	FRONT SAFETY BELT (LH/RH) @\$846.10	ACTIVATED	1,692.20	1,692.20
2	REAR SAFETY BELT (LH/RH) @\$838.00	ACTIVATED	1,676.00	1,676.00
1	REAR DOOR SAFETY BELT, OUTER	NOT NECESSARY	526.00	-
1	MOTOR ASSY, POWER WINDOW REGULATOR FRT, RH	NOT NECESSARY	941.80	-
1	MOTOR ASSY, POWER WINDOW REGULATOR REAR, RH	NOT NECESSARY	768.90	-
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW FRT, RH	NOT NECESSARY	233.70	-
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW REAR, RH	NOT NECESSARY	233.70	-

Report Ref No. CS/INC19014775/Dyf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GLASS, SUB-ASSY, FRONT DOOR, RH	SHATTETED	780.00	780.00
1	CENTRE ROCKER PANEL (GARNISH)	BUCKLED	576.00	576.00
1	FRONT PILLAR UPPER COVER, RH	DISLODGE	96.00	96.00
1	FRONT PILLAR UPPER COVER, LH	DISLODGE	96.00	96.00
1	FRONT WINDSCREEN GLASS	CRACKED	1,627.30	1,627.30
1	FRONT WINDSCREEN GLASS MOULDING	NECESSARY	208.60	208.60
1	WIPER TOP GARNISH	BROKEN	668.32	668.32
1	WIPER SPARE TANK	DEFORMED	183.75	183.75
1	WIPER SPARE TANK MOTOR	DAMAGED	242.70	242.70
1	WIPER SPARE TANK FLOAT (NECK)	NOT NECESSARY	55.50	-
1	FRONT WHEEL RIM (LH)	NOT NECESSARY	1,555.10	-
1	FRONT WHEEL HUB BEARING (LH)	DAMAGED	560.10	560.10
1	FRONT SHOCK ABSORBER (LH)	DISTORTED	401.80	401.80
1	ABSORBER TOP MOUNTING, LH	NOT NECESSARY	196.20	-
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	637.50	637.50
1	FRONT DRIVE SHAFT (LH)	DAMAGED / DISTORTED	1,310.10	1,310.10
1	RACK & PINION ASSY	DAMAGED	1,634.90	1,634.90
1	BAR, STABILIZER	DISTORTED	360.00	360.00
1	LINK ASSY, FRONT STABILIZER, LH	BENT	199.00	199.00
1	KNUCKLE, STEERING, LH	DISTORTED	562.30	562.30
1	END SUB-ASSY, TIE ROD, LH	DISTORTED	158.10	158.10
1	ENGINE UNDER COVER	TORN	457.20	457.20
1	FRONT CHASSIS MEMBER (LH)	TO REPAIR SEE LABOUR	2,035.10	-
2	ENGINE MOUNTING (LH/RH) @\$386.60	DAMAGED / BENT	773.20	773.20
1	ENGINE MTG (FRONT)	NOT NECESSARY	174.63	-
1	ENGINE MTG (REAR)	BENT	172.90	172.90
1	FRONT BRAKE ABS SENSOR ONLY	NOT NECESSARY	450.70	-
1	FAM BELT	NOT NECESSARY	155.00	-
1	AIR BAG ASSY, DRIVER SIDE LOWER, RH	REPEATED	1,615.00	-
1	AIR BAG ASSY, FRONT SEAT, RH	REPEATED	857.90	-
1	AIR BAG ASSY, FRONT SEAT, LH	REPEATED	857.90	-

Report Ref No. CS/INC19014775/Dyf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR BAG ASSY, INSTRUMENT PANEL PASSENGER W/O DOOR, LH	REPEATED	3,277.50	-
1	STEERING ANGLE SENSOR	ACTIVATED	986.00	986.00
1	SENSOR, AIR BAG, FRONT (RH)	REPEATED	313.50	-
1	SENSOR, SPEED, FRONT RH	NOT NECESSARY	455.10	-
1	SENSOR, SPEED, FRONT LH	NOT NECESSARY	455.10	-
1	SENSOR ASSY, SIDE AIR BAG, RH	REPEATED	709.30	-
1	WIRING FRONT	TORN / HOUSING BROKEN	6,685.90	6,685.90
1	HYBRID INVERTER SPARE TANK	BROKEN	371.30	371.30
1	HYBRID INVERTER BYPASS HOSE (INLET)	NOT NECESSARY	42.60	-
1	HYBRID INVERTER BYPASS HOSE (OUTLET)	NOT NECESSARY	29.30	-
1	HYBRID COOLING PUMP MOTOR	NOT NECESSARY	432.20	-
1	THROTTLE BODY (ADDITIONAL)	BROKEN	1,625.00	1,625.00
1	COOLER MOTOR COOLING (ADDITIONAL)	BENT	420.00	420.00
1	HOSE, RAD-COOLER (ADDITIONAL)	TORN	60.00	60.00
1	HOSE, HV W/PUMP COOLER (ADDITIONAL)	DEFORMED	54.00	54.00
1	HV WATER PUMP (ADDITIONAL)	BROKEN	630.00	630.00
1	HOSE, R/TANK HV W/PUMP (ADDITIONAL)	DEFORMED	60.00	60.00
1	HOSE INVERTER R/TANK (ADDITIONAL)	DEFORMED	51.00	51.00
1	WATER PIPE NO.1 (3P) (ADDITIONAL)	DEFORMED	36.00	36.00
1	HOSE W/PIPE NO.1-W/PIPE NO.2 (ADDITIONAL)	DEFORMED	36.00	36.00
1	WATER PIPE (2P) (ADDITIONAL)	DEFORMED	36.00	36.00
1	HOSE W/PIPE NO.2 RAD LH (ADDITIONAL)	DEFORMED	36.00	36.00
1	HOSE R-TANK-W/PIPE NO.1 (ADDITIONAL)	DEFORMED	27.00	27.00
1	HOSE THROTTLE B-EGR VALVE (ADDITIONAL)	BROKEN	54.00	54.00
1	HOSE THROTTLE B-W/PIPE NO.6 (ADDITIONAL)	DEFORMED	48.00	48.00
1	AIR INTAKE RESONATOR (ADDITIONAL)	DEFORMED	30.00	30.00
1	AIR HOSE (ADDITIONAL)	DEFORMED	90.00	90.00
1	HOSE R/TANK-RAD, RH (ADDITIONAL)	DEFORMED	54.00	54.00
1	HOSE COOLER-COOLING PIPE NO.1 (ADDITIONAL)	DEFORMED	39.00	39.00
1	HOSE COOLER-COOLING PIPE NO.2 (ADDITIONAL)	DEFORMED	39.00	39.00
1	RADIATOR HOSE CLAMP 40MM (ADDITIONAL)	NECESSARY	9.60	9.60
3	RADIATOR HOSE CLAMP 44MM @\$9.50 (ADDITIONAL)	NECESSARY	28.50	28.50

Report Ref No. CS/INC19014775/Dyf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 6 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
6	RADIATOR HOSE CLAMP 24MM @\$7.50 (ADDITIONAL)	NECESSARY	45.00	45.00
8	RADIATOR HOSE CLAMP 26MM @\$8.40 (ADDITIONAL)	NECESSARY	67.20	67.20
10	RADIATOR HOSE CLAMP 17MM @\$2.20 (ADDITIONAL)	NECESSARY	22.00	22.00
2	RADIATOR HOSE CLAMP 13MM @\$5.40 (ADDITIONAL)	NECESSARY	10.80	10.80
1	AIR HOSE CLAMP 65MM (ADDITIONAL)	NECESSARY	10.50	10.50
1	ENGINE UNDER COVER FRT (ADDITIONAL)	REPEATED	457.20	-
1	FRT BUMPER TOP RUBBER (ADDITIONAL)	TORN	225.00	225.00
1	FRT BUMPER LOWER REINFORCEMENT (ADDITIONAL)	BENT	241.40	241.40
1	FRT BUMPER LOWER REINFORCEMENT ABSORBER (ADDITIONAL)	BROKEN	165.00	165.00
1	ENGINE CROSSMEMBER (ADDITIONAL)	BENT	2,531.70	2,531.70
2	ENGINE CROSSMEMBER SUPPORT BRACKET (LH/RH) @\$129.50 (ADDITIONAL)	BENT	259.00	259.00
1	WIPER SPARE TANK NECK (ADDITIONAL)	DEFORMED	135.00	135.00
1	FRT WINDSCREEN MOULDING LOWER (ADDITIONAL)	NECESSARY	218.00	218.00
1	STEERING WHEEL AIRBAG (ADDITIONAL)	ACTIVATED	2,402.20	2,402.20
1	PASSENGER AIR BAG (ADDITIONAL)	ACTIVATED	3,869.00	3,869.00
1	KNEE AIR BAG (ADDITIONAL)	ACTIVATED	1,593.60	1,593.60
2	ROOF TOP SIDE AIR BAG (LH/RH) @\$1748.10 (ADDITIONAL)	ACTIVATED	3,496.20	3,496.20
2	FRT SEAT AIR BAG (LH/RH) @\$826.96 (ADDITIONAL)	ACTIVATED	1,653.92	1,653.92
1	ECU CONTROL UNIT (ADDITIONAL)	ACTIVATED	988.00	988.00
1	ABS PUMP BRACKET (ADDITIONAL)	BENT	360.00	360.00
2	HEAD LAMP CONTROL UNIT (LH/RH) @\$1280.00 (ADDITIONAL)	DAMAGED / DISLODGE	2,560.00	2,560.00
1	CENTRE PILLAR NO. 2 (ADDITIONAL)	DENTED	990.00	990.00
1	CENTRE PILLAR INNER NO.3 (ADDITIONAL)	DENTED	450.00	450.00
1	PIPE SUB-ASSY SUCTION AIRCON (ADDITIONAL)	NOT NECESSARY	660.00	-
1	FRONT HOUSING ASSY, LH (ADDITIONAL)	DENTED	958.30	958.30
1	FRONT HOUSING ASSY, RH (ADDITIONAL)	DENTED	958.30	958.30
2	FRONT CHASSIS MEMBER COVER (LH/RH) @\$135.00 (ADDITIONAL)	NOT NECESSARY	270.00	-
1	RADIATOR LOWER PANEL GARNISH (ADDITIONAL)	BROKEN	245.00	245.00
2	WIPER NOZZLE (ADDITIONAL)	SOCKET BROKEN	100.00	100.00
1	ACTUATOR ASSY, SHIFT CONTROL (ADDITIONAL)	DAMAGED	3,109.00	3,109.00

Report Ref No. CS/INC19014775/Dyf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 7 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-22,186.45	-
	LESS 25% DISCOUNT		-	-22,637.48
			88,745.78	67,912.42
	SPECIAL NETT ITEMS			
1	FRONT NO. PLATE (SN) }	DISLODGE	25.00	45.00
1	FRONT NO PLATE TRIM COVER (SN) }	BROKEN	30.00	-
1	FRONT NO. PLATE GARNISH (SN)	TORN	99.00	99.00
1	NEW BATTERY (SN) (50%)	BROKEN	160.00	80.00
1	FRONT DOOR COMFORT LOGO (SN)	NECESSARY	75.00	75.00
1	REAR DOOR COMFORT & APPS STICKER (SN)	NECESSARY	80.00	80.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	FRONT TYRE (LH) (SN)	SERVICEABLE	216.00	-
			731.00	425.00
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT CHASSIS MEMBER (LH).		1,900.00	1,400.00
	SPRAY PAINTING CHARGE.		1,500.00	1,000.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		80.00	40.00
	TOWING CHARGE.	NOT NECESSARY	90.00	-
	FRONT CHASSIS ALIGNMENT CHARGE.		200.00	150.00
	TRANSFER OF DOOR.		240.00	120.00
	REMOVE / REFIX UNDERCARRIAGE (FRT).		100.00	80.00
	FRT WHEEL ALIGNMENT.		100.00	60.00
	REMOVE / REFIX AIRCON & REFILL GAS.		80.00	60.00
	REMOVE / REFIX ENGINE		150.00	150.00
	REMOVE / REFIX DASHBOARD.		200.00	150.00
	REMOVE / REFIX FUSE BOX.		80.00	50.00
	REMOVE / REFIX FRONT WINDSCREEN GLASS.		90.00	80.00
	REMOVE / REFIX CUSHION & UPHOLSTERY FRONT.		100.00	80.00
	REMOVE / REFIX SEAT ADJUSTER.	NOT NECESSARY	120.00	-
	R/REFIX AIR BAG / STEERING WHEEL / DASHBOARD / SEAT.		120.00	100.00

Report Ref No. CS/INC19014775/Dyf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 8 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RE-SET FRT ABS SYSTEM.)		100.00	250.00
	RE-SET FRT & REAR POWER WINDOW SYSTEM.)		200.00	-
	DIAGNOSIS & RESETTING TO ERASE FAULT CODE.)		300.00	-
			5,800.00	3,800.00
	GRAND TOTAL		95,276.78	72,137.42
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				44,000.00

Report Ref No. CS/INC19014775/Dyf3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.