

ASS. REC. BY:

REF: CS/INC 19014779/11/08302

Special Instruction:

SURVEYOR KamellASSIGNMENT (Office)From (Person): Daniel Kohof INCDate/Time: 22-8-19 9.47a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XE 4126JInsured: XD 1384Eat Workshop m/s Chung Hoo Ding AutomotiveTel: 67556142of 3B Woodland Industrial Park E1 #105-04

Policy No:

Claim No: M1/1058537/002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17-8-2019

CA / REV / REP. / REV 24 HRS

rep

Date/Time: 22-8-19 9.56a.m

Person Contacted:

June

H.O.I. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

XD 1384E CCL/ET/19014779/11/08302 D.O.A. 21/04/2011XE 4126J X18/902/11/19Workshop change to Ding Automotive 31 Corporation Rd.Submit Prelim Report - The vehicle has not send in for repair.

ASS. REC. BY:

Tanghi

REF:

LNC

ASSIGNMENT

From

Date

Veh No:

XE4126J

Yr Regn:

2018 June

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

Garbage Truck

To Inspect Vehicle No:

Make:

MAN TG5

cc 10518

at Workshop m/s

Colour

white

A/C:

Insured / Std / NI / NA

of

Sp. Reading

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

WMIA 26522 7SM7R352

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:


F:

295/80R22.5

R:

7 1(D)

Remark: The veh had commenced its repair at the time of inspection.



BS / OUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

4145K

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

8 mm

R/Bal.

8/8 mm

GTA / PR. Seen:

Consistent? : Yes or No

L/Bal.

8 mm

L/Bal.

8/8 mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

D.O.I.

12/9/19 @ 545

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Dry into

CA / REV / REP. / 24 HRS ^{up}Des. of Damages: Fr / Rear / O/S / N/S / UIC / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

Guang

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

E-mail Guang, repair limit 4115,000.

RECEIVED 07 NOV 2019

Date/Time, File Pass to?



Prel. Report

Days Of Repair:

11/09/19 tanghi



Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee:

790

3

Add Fee:



Site Insp (\$)

Transportation:

3 + RS \$4



Interview (\$)

Photos



Tech. Insp (\$)

Notes



Wheel and (\$)

TOTAL

790

Report Format:

Lump Sum / A.B.J. (%)

ASS. REQ. BY:

REF: INC

ASSIGNMENT

From:

Date: 22.8.2019

Estimate Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XG 41263

at Workshop m/s Chung Hoi

of 38 woodland Industrial Park E1 905-04

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rump

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

XE 41263 Yr Regn: 06, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Rubbish Truck

Make:

Maz

TGS26

c.c.

10518

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading:

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WMA 26S 287 JM 770352

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inopdr / Jammed / Leaked / Burnt or

Brake: Inopdr / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

Wetlake 295/80R22.5

Return (0)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

17/8/19

Rear

R/Bal.

99

66 mm

L/Bal.

99

66 mm

D.O.I.

22/8/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

R/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/8

EH not ready, no

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L&L: £

☐

Prel. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Week end (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Nivitha (LKK Auto)

From: MTSurvey <MTSurvey@income.com.sg>
Sent: Wednesday, 18 September 2019 4:45 PM
To: Taxis Customer Service; Admin-D (LKKAuto); assignments
Cc: Claims@dingautomotive.com.sg; dd.hashim@dingauto.sg; kelly.ding@dingauto.sg; SU THO Chee How
Subject: FW: SURVEY ARRANGEMENT & CHECK LIABILITY - XE4126J / TP XD1384E / DOA:17/08/2019
Attachments: XE4126J GIA REPORT.PDF; receipt-20190918-112726.pdf

Dear LKK,

Please assist to survey the vehicle.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

in with you

From: Taxis Customer Service [mailto:taxiscs@stengg.com]
Sent: Wednesday, 18 September 2019 4:28 PM
To: MTSurvey <MTSurvey@income.com.sg>; MTCL@income.com.sg
Cc: Claims@dingautomotive.com.sg; dd.hashim@dingauto.sg; kelly.ding@dingauto.sg; SU THO Chee How <suthoch@stengg.com>
Subject: SURVEY ARRANGEMENT & CHECK LIABILITY - XE4126J / TP XD1384E / DOA:17/08/2019

Dear Officer,

Kindly arrange survey our client vehicle located at 31 Corporation Road as soon as possible.

Meanwhile please advise the liability for this case as per GIA attached.

Thanks

Best Regards,
Guang
Ding Automotive Pte Ltd
Hp : 93299929 / 62657130

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Catherine Chong (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Thursday, 22 August, 2019 10:15 AM
To: 'assignments@lkkauto.com'
Cc: admin-d@lkkauto.com
Subject: FW: TP CASES FARMED OUT TO LKK ON 22/8/2019

Dear LKK,

Resend herewith claim ref. number & OIC

From: Daniel Koh
Sent: Thursday, 22 August 2019 9:47 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 22/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA	Ad Re
1	DAVID PHUA	MT/1058265-002	GBD8570Z	CARZ AUTO SERVICES PTE LTD	61 WOODLANDS INDUSTRIAL PARK E9 (E9 PREMIUM) #04-04 SINGAPORE 757047	Jeslyn Chua / 8322 7418		CB5965L	19/8/2019	
2	CHRYLLIS QUAH	MT/1058537-002	XE4126J	CHENG HOE MOTOR PTE LTD	38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05 ADMIRALTY IND PARK SINGAPORE 757700	Efeeda / 67556142	10:00-16:00	XD1384E	17/8/2019	
3	SERENE LIM	MT/1057986-002	YP1799S	CHEONG CHEONG MOTOR SERVICE PTE. LTD.	BLK 5032 #01-293 ANG MO KIO INDUSTRIAL PARK 2	Angela Ng / 6481 4152		YL552P	16/8/2019	

					SINGAPORE 569535				
4	JARED LIU	MT/1058602- 002	SLR6843H	L SOON AUTO SERVICES	10 ANG MO KIO INDUSTRIAL PARK 2A #03- 18 AMK AUTOPOINT SINGAPORE 568047	/ 6482 1513		GX7292T	19/8/2019
5	WO JESSIE	MT/1058786- 001	SHC2924K	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2- A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SGU8990X	13/8/2019
6	AZHARI	MT/1058175- 002	PA9030J	THE ONE HOLDINGS PTE LTD	8 WOODLANDS INDUSTRIAL PARK E3 WOODLANDS INDUSTRIAL PARK E SINGAPORE 757786	Muhd.Hilmi Deres / 97480340	10:00- 12:00	SLZ2322D	16/8/2019

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Daniel Koh
Senior Admin Assistant
Motor Insurance
T +65 6430 7901
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Shiau Chan (LKKAUTO)

From: Kelly Ding <kelly.ding@dingauto.sg>
Sent: Tuesday, 5 November 2019 12:51 PM
To: Shiau Chan (LKKAUTO); Taufikh (LKKAUTO)
Cc: 'Ding Ding Auto'; 'Taxis Customer Service'; 'Dd hashim'
Subject: RE: XE 4126J REPAIR LIMIT - request for Part-by-Part repair / higher repair limit - pending clearance of liability

Dear Shiau Chan,

Repair currently KIV pending clearance of liability.

Thanks and regards,
Kelly Ding
6258 3009

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: 05 November 2019 12:02
To: Kelly Ding <kelly.ding@dingauto.sg>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: 'Ding Ding Auto' <ding@dingauto.sg>; 'Taxis Customer Service' <taxiscs@stengg.com>
Subject: RE: XE 4126J REPAIR LIMIT - request for Part-by-Part repair / higher repair limit

Dear Kelly,

Kindly advise the status of above vehicle.

If done for repair, please kindly send us the final bill for finalise.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kelly Ding <kelly.ding@dingauto.sg>
Sent: Wednesday, 9 October 2019 2:10 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: 'Ding Ding Auto' <ding@dingauto.sg>; 'Taxis Customer Service' <taxiscs@stengg.com>
Subject: RE: XE 4126J REPAIR LIMIT - request for Part-by-Part repair / higher repair limit

Dear Taufikh,

Thank you for your reply and follow up. I will advise Mr Ding accordingly and come back to you.

Thanks and regards,
Kelly Ding
6258 3009

> Back to OneMotoring

XE 4126J
TP/NTUC

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	155H
Vehicle Details	
Vehicle No.:	XE4126J
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Aug 2019
Vehicle Make:	MAN
Vehicle Model:	TGS 26.320 6X4 BB
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	50549540224948
Chassis No.:	WMA26SZZ7JM772352
Maximum Power Output:	-
Open Market Value:	\$125,549.00
Original Registration Date:	06 Jun 2018
First Registration Date:	06 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$6,278.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jun 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$34,001.00
COE Rebate Amount:	\$29,907.00
Total Rebate Amount:	\$29,907.00

The information contained herein is correct as at 19 Aug 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	155H
Vehicle Details	
Vehicle No.:	XE4126J
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2019
Vehicle Make:	MAN
Vehicle Model:	TGS 26.320 6X4 BB
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	50549540224948
Chassis No.:	WMA26SZZ7JM772352
Maximum Power Output:	-
Open Market Value:	\$125,549.00
Original Registration Date:	06 Jun 2018
First Registration Date:	06 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$6,278.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jun 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$34,001.00
COE Rebate Amount:	\$29,587.00
Total Rebate Amount:	\$29,587.00

The information contained herein is correct as at 23 Sep 2019

OK

CASH VOUCHER

清河汽车私人有限公司
CHENG HOE MOTOR PTE LTD

No. _____

Pay To

Yong Hwa Tong Sen

Date

20/8/19

DATE	DESCRIPTION	AMOUNT
	<i>X64476J</i>	<i>1190</i>
A/c	Cash/Cheque	Total
		<i>1190</i>

Payment Approved



Received





榮華拖車服務

No. 156658

YONG HUA TOWING SERVICE

41 JALAN SALANG SINGAPORE 769523 FAX: 6754 6162
TEL: 9711 3264 / 8344 7775 / 8204 5252
Email: yhtowingtransportation@gmail.com
Company Reg. No. 49596700M

Date: 16/8/19

M/s Cash

Transport of: XE 4126J MAN RUBBISH TRAY

Location: P12 TO WOODLAND PRZ 5.

To 150 WOODLAND PRZ 5

RELEASE BRABE & SWAIT

寶號

QTY/HRS/TRP	RATE	TOTAL	
		\$	cts
1		220	
1		400	
TOTAL		620	

Time from _____ a.m. to _____ a.m.

Time from 4 p.m. to 8 p.m.

Time from _____ p.m. to _____ p.m.

Total Time _____ Overtime _____

Conditions: It is understood that goods transported by us are to be insured accordingly by customers. It is understood that goods transported by us are to be insured accordingly by customers. It is understood that goods transported by us are to be insured accordingly by customers.

Our Company shall not be responsible for any losses or damages whatsoever. Our Company shall not be responsible for any losses or damages whatsoever. Our Company shall not be responsible for any losses or damages whatsoever.

Driver's Signature: [Signature]

Customer's Signature _____



榮華拖車服務

YONG HUA TOWING SERVICE

No. 156659

41 JALAN SALANG SINGAPORE 769523
TEL: 9711 3264 / 8344 7775 / 8204 5252 FAX: 6754 6162
Email: yhtowingtransportation@gmail.com
Company Reg. No. 49596700M

Date:

17/8/19

M/s

Cash

寶號

QTY/HR/TRIP	RATE	TOTAL	
		\$	cts

Transport of: XE 4126 JMH RUBBER TRUCK

H EASY

Location: 130 Woodland PK E5 To 66

WOODLAND PK E9 S To

PK 38 WOODLAND IND PK E1 #05-04

4 HR

\$400

170

TOTAL \$570

Time from _____ a.m. to _____ a.m.

Time from 9 am to 1 p.m.

Vehicle No.

XD55L

Total Time _____ Overtime _____

Tt. No. _____

Conditions

It is understood that goods transported by us are to be insured accordingly by customers.
Our Company shall not be responsible for any losses or damages whatsoever.
Incurred while carrying out the above assignment.
Using our tackles gear, slings, etc for loading and unloading of cargo is at customer's risks.
We will not be responsible for any consequences which may arise of breakages due to unforeseen circumstances.

Driver's Signature

Choy

Customer's Signature _____

清 河 汽 車 服 務
CHENG HOE MOTOR SERVICE

No. _____

Soon

Date: 6/9/19

DATE		DESCRIPTION	AMOUNT
		X841267	
A/c	Cash/Cheque	Total	150





YONG HUA TOWING SERVICE

No. 155374

41 JALAN SALANG SINGAPORE 769523

TEL: 9711 3284 / 8344 7775 / 8204 5252 FAX: 6754 6162

Email: yhtowingtransportation@gmail.com

Company Reg. No. 49596700M

Date: 20/01/11

M/S

Cash

賣號

Transport of

MMX 4641267 RUBISH Truck

Location

38 Woodland PK 2 70.31

Final Workshop

Time from

a.m. to _____ a.m.

Time from

p.m. to _____ p.m.

Total Time

Overtime _____

Conditions
It is understood that goods transported by us are to be insured accordingly by customers

ur Company shall not be responsible for any losses or damages whatsoever incurred while carrying out the above assignment.

of our tackle's gears, slings, etc for loading and unloading of cargo is at customer's risks. We will not be responsible for any consequences which may arise of breakages due to own circumstances.

Driver's Signature _____

Choy

Customer's Signature

TOTAL \$1502

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2019 15:43
Date Of Accident	17/08/2019 15:20
Exact Location Of Accident	ALONG JALAN AHMAD IBRAHIM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE4126J
Insured/Policyholder	
Name Of Registered Owner	800 SUPER WASTE MANAGEMENT PTE LTD
Co Reg No	198601155H
Email Address	SUPER800@SINGNET.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-63663800

Vehicle Particulars

Manufacturer	MAN
Model	TGS 26.320 6X4 BB
Exact Purpose for which vehicle was being used at time of accident	DISCARD RUBBISH
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109900713
Cover Note Number	01/06/19 - 31/05/20

Driver

Name of Driver	RAHMAT BIN TASHIM
NRIC No	S1207340B
Date Of Birth	20/09/1956
Occupation	OUTDOOR
Date Of Driving Pass	01/10/1991
Driving Experience	27 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97821141
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 553 BEDOK NTH AVE 1 #11-476
Postcode	460553
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was moving straight when I noticed vehicle C applied brake. I managed to brake and stopped behind. Next second, a great impact came from the rear that pushed my vehicle forward to hit onto vehicle C. It was a chain collision of total 3 vehicles including mine. No one was injured.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD1384E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ISMAIL BIN ABAS
NRIC/Passport Number	S2006147B
Contact Number	81438748
Address	CO.: CHUAN LIM
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	XD7754G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NATARASAN RAMESH
NRIC/Passport Number	G8192486X
Contact Number	90566482
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

VEHICLE NO.: XE 4126 J
INSURER : NTUC
DATE & TIME: 17/8/19 @ 15:20

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind the policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 19/8/19, 5:10 PM

Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Person's Signature
Name: (YS)
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

	↑	↑	↑	
Klong	↑			A: XE44563
Jalan	↑			B: XD1384E
Ahmad	↑			(Chuan Lina)
Ibrahim	↑			Ismail Bin Abas
	↑			S20061147B
	↑			HP-81438748
	↑			C: XD7754G
	↑			Natarasa Ramash
	↑			G6892486X
	↑			HP-40566482

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was moving straight when I noticed vehicle C applied brake. I managed to brake and stopped behind. Next second, a great impact came from the rear that pushed my vehicle forward to hit onto vehicle C. It was a chain collision of total 3 vehicles including mine. No one was injured.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

(We declare that the foregoing particulars are true in every respect.

Policyholder's Signature _____

Page & Time: 19/11/15

Driver's Signature _____

(If driver is not the policyholder.)

Date & Time:

 Representative's Signature

Nahrung:

N/A/C/W/N No. 2

0007-1226/96/0004-0000\$10.00/0

() Claim Own Policy (☒) Claim Third Party () Recapturing City

☐ Claim OD/TP at other workshop (

DING AUTOMOTIVE PTE LTD

Unit Sales Of Quotation

Quotation No: Q001-19092019

Date : 19/09/2019

Vehicle Number : XE4126J

S/N	Description	Qty	Unit Price	Selling Price
1	LABOUR TO PANEL BEAT ACCIDENT AREAS & DISMANTLE FRONT CABIN & BOTH FRONT CABIN ABSORBER & BOTH REAR CABIN ABSORBER & BOTH REAR CABIN LOCK & LOCATING ARM & CARRIER NARROW & WIND DEFLECTOR & PILLAR LINING & FRONT SERVICE DOOR & BOTH MUDGUARD GREY & BOTH MUDGUARD BEHIND CAB & FRONT BUMPER STEEL & GAS SPRING & FRONT MIRROR ASSEMBLY & BOTH SIDE CURB MIRROR & CABIN AIR DUCT ASSEMBLY	1	Let - 600/day 10,800	\$ 21,000.00
2	R&R FRONT WINDSCREEN GLASS & SIDE GLASS	1	600	\$ 1,040.00
3	R&R REAR WINDSCREEN GLASS & QUOTA GLASS	1	300	\$ 550.00
4	R&R FRONT DASH BOARD, DASH BOARD COMPONENTS	1	600	\$ 850.00
5	R&R DRIVER SEAT & CARPET & TRIM & INSULATION & FLOOR MAT & ENGINE COWLING	1	300	\$ 650.00
6	R&R WIRE HARNESS & FUSE BOX & FRONT WIRING CONDUIT & WHOLE FRONT RETAINING FRAME & COVERING ELECTRICAL SYSTEM	1	600	\$ 730.00
7	R&R AIR COND BLOWER & BRAKE MASTER PUMP CYLINDER & SURGE TANK & WIPER LINKAGE & AIR COND PIPE & PEDAL BRACKET & HEATER LINES & HEATER HOSE & SHAPE HOSE	1	600	\$ 1,150.00
8	R&R FRONT DOOR COMPONENTS LH	1	300	\$ 390.00
9	R&R FRONT DOOR COMPONENTS RH	1	300	\$ 390.00
10	R&R RADIATOR & CONDENSOR & FAN COWLING & VISCO FAN & INTERCOOLER	1	900	\$ 1,300.00
11	R&R STEERING, STEERING WHEEL AND COLUMN	1	600 ?	\$ photo 1,300.00
12	VACUUM AIRCOND SYSTEM & TOP UP AIR COND GAS R-134A	1	250	\$ 350.00
13	R&R ROOF TOP LINING & ROOF COVERING	1	200	\$ 390.00
14	ALIGNMENT CHASSIS	1	600 ?	\$ photo 1,560.00
15	REPAIR FRONT WIRING	1	200	\$ 500.00
16	DIAGNOSTIC & DO UP BRAKE SYSTEM	1	300	\$ 450.00
17	RESpray WHOLE CABIN INSIDE & CABIN FLOOR PANEL & FRONT CABIN & FRONT SERVICE DOOR & PILLAR LINING LEFT AND RIGHT & WIND DEFLECTOR LEFT AND RIGHT	1	2000	\$ 2,600.00
18	TOWING FEES (CHENG HOE MOTOR PTE LTD)	1	-	\$ 1,340.00
19	TOWING FEES (YONG HUA TOWING SERVICE)	1	-	\$ 1,340.00
20	1) Replacement of new binlifter ASSY for RCV XE4126J caused by accident. Supply labour and material for the repair of RCV XE4126J as follows. 2) Removing of damaged binlifter assy forming and welding fabrication of sub assembly, retrofitting new bin lifter onto RCV and testing and painting of binlifter assembly of affected area of repair. 3) To removing rear hopper cover door and replace new hopper cover door with paintwork. 4) To dismantle Ros Roca REL body and remount onto new chassis, existing load cell brackets. 5) CVP and LTA inspection	1	30,000	\$ 43,950.00
LIK Auto Consultants hence notify the insurer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: [Signature] Date: 22/9/19 Tan Kahin 97495745 WP 19/9/19 0545pm To check repair unit Resurvey new parts 40 days save 1/10/2019				81,830.00

Material Replace

1	MULTIPOINT CONNECTOR	2	\$	15.58	\$?	31.16
2	BRACKET MOUNTING LEFT	1	\$	77.34	\$?	77.34
3	BRACKET MOUNTING RIGHT	1	\$	77.34	\$?	77.34
4	MUDGUARDS RIGHT, REAR	1	\$	664.88	\$ C/A ✓	664.88
5	SPLASH SHIELD L/R15/32/37 RIGHT	1	\$	240.44	\$ R/C ✓	240.44
6	NUT (RIGHT)	9	\$	2.78	\$ R/C ✓	25.02
7	MUDGUARDS LEFT REAR	1	\$	701.80	\$ C/A ✓	701.80
8	SPLASH SHIELD L/R15/32/37 LEFT	1	\$	240.44	\$ C/A ✓	240.44
9	NUT (LEFT)	9	\$	2.78	\$ R/C ✓	25.02
10	WATER CONTAINER (81-26481-0079)	1	\$	126.08	\$?	126.08
11	SEAL FILLER TUBE WATER CONTAINER	1	\$	17.00	\$?	17.00
12	FILLER TUBE WATER CONTAINER	1	\$	275.58	\$?	275.58
13	SCREW CAP FOR WATER CONTAINER	1	\$	14.80	\$ de ✓	14.80
14	COVER PLATE WIPER ARM	2	\$	8.70	\$ C/A ✓	17.40
15	INTAKE DUCT ASSEMBLY	1	\$	252.04	\$ C/A ✓	252.04
16	STEEL BUMPER SIDE SECTION LEFT (81-41610-6629)	1	\$	1,272.84	\$ bt ✓	1,272.84
17	TRIM LEFT (81-41610-6629)	1	\$	41.80	\$?	41.80
18	BUMPER SIDE PART POWDER-COATED RIGHT (81-41610-6628)	1	\$	1,272.84	\$ R/C ✓	1,272.84
19	TRIM RIGHT (81-41610-6628)	1	\$	40.40	\$?	40.40
20	PEDAL BRACKET	1	\$	708.14	\$ C/A ✓	708.14
21	FOOT BRAKE VALVE	1	\$	1,707.34	\$ C/A ✓	1,707.34
22	GASKET	1	\$	31.20	\$ R/C ✓	31.20
23	HEATER LINE RETURN	1	\$	159.38	\$ bt ✓	159.38
24	HEATER LINE SUPPLY	1	\$	161.18	\$ bt ✓	161.18
25	SHAPED HOSE (TO HEATER LINE RETURN)	1	\$	47.80	\$?	47.80
26	SHAPED HOSE (TO HEATER LINE SUPPLY)	1	\$	31.80	\$?	31.80
27	BRACKET HEATER LINE	2	\$	6.18	\$ bt ✓	12.36
28	MOUNTING CLAMP 2X18-6-PA6	1	\$	4.04	\$ bt ✓	4.04
29	BRACKET ASSEMBLY (HEATER LINE)	1	\$	77.34	\$ bt ✓	77.34
30	HOSE CLAMP H16-27	4	\$	6.68	\$ R/C ✓	26.72
31	ADAPTER TOOL SUPPORT ELECTRICAL SYSTEM DRIVER'S SIDE	1	\$	37.38	\$ C/A ✓	37.38
32	RETAINING FRAME ON CAB ON DRIVER'S SIDE	1	\$	87.20	\$ C/A ✓	87.20
33	RETAINING FRAME ON CAB CO-DRIVER'S SIDE	1	\$	219.64	\$ C/A ✓	219.64
34	BRACKET TOOL SUPPORT ELECTRONIC CONTROL UNIT	1	\$	55.64	\$?	55.64
35	BRACKET TOOL SUPPORT RELAY	1	\$	55.64	\$?	55.64
36	ADAPTER TOOL SUPPORT ELECTRICAL SYSTEM CO-DRIVER'S SIDE	1	\$	40.70	\$ C/A ✓	40.70
37	BRACKET RELAY	1	\$	44.50	\$?	44.50
38	COVER ELECTRICAL SYSTEM	2	\$	39.68	\$ R/C ✓	79.36
39	COVER WIRING CONDUIT	1	\$	121.58	\$ C/A ✓	121.58
40	REFRIGERANT PIPE (CONDENSER TO HEATER)	1	\$	257.58	\$ bt ✓	257.58
41	REFRIGERANT PIPE (CONDENSER TO COMP)	1	\$	266.60	\$?	266.60
42	REFRIGERANT PIPE (HEATER TO COMP)	1	\$	257.58	\$ bt ✓	257.58
43	CLIP (REFRIGERANT PIPE COND-COMP)	1	\$	13.54	\$ bt ✓	13.54
44	CLIP (REFRIGERANT PIPE-HEATER-COMP)	1	\$	8.18	\$ bt ✓	8.18
45	CLAMP	1	\$	10.38	\$?	10.38
46	REFRIGERANT PIPE HEATER (BIG)	1	\$	266.60	\$ bt ✓	266.60
47	REFRIGERANT PIPE HEATER (SMALL)	1	\$	443.28	\$ bt ✓	443.28
48	MOUNTING CLAMP 10/18-6-PA6	4	\$	9.28	\$ bt ✓	37.12
49	NOISE INSULATION LEFT (81-19220-0981)	1	\$	234.94	\$ R/C ✓	234.94
50	NOISE INSULATION RIGHT (81-19220-0982)	1	\$	235.88	\$ R/C ✓	235.88
51	VISCO FAN	1	\$	3,693.54	\$?	3,693.54
52	VISCO FAN BRACKET	1	\$	66.68	\$?	66.68
53	FAN BEARING ASSEMBLY	1	\$	3,713.50	\$?	3,713.50
54	ENGINE COWLING F99L/R15/31/32/36/37	1	\$	704.14	\$?	704.14
55	ENGINE COWLING HALF-CAB F99L/R15	1	\$	639.78	\$?	639.78
56	FLANGE NUT M8	4	\$	6.00	\$?	24.00
57	FLY SCREEN	1	\$	144.00	\$ bt ✓	144.00
58	AIR DEFLECTOR	1	\$	126.08	\$ de ✓	126.08
59	HINGED SIDE FRAME	2	\$	100.84	\$?	201.68
60	SUPPORT LH	1	\$	353.44	\$ C/A ✓	353.44
61	SUPPORT RH	1	\$	353.44	\$ C/A ✓	353.44
62	COOLING WATER HOSE (0978)	1	\$	92.14	\$?	92.14
63	SHAPED HOSE (0472)	1	\$	66.14	\$?	66.14
64	BLEEDER LINE (5700)	1	\$	110.80	\$?	110.80
65	BLEEDER LINE (5686)	1	\$	68.50	\$?	68.50
66	BLEEDER LINE (5698)	1	\$	74.60	\$?	74.60
67	SHAPED HOSE (0467)	1	\$	55.14	\$?	55.14

21643.44

68	SHAPED HOSE (0463)	1	\$	68.50	\$?	68.50
69	COOLING WATER HOSE (0942)	1	\$	113.18	\$?	113.18
70	HOSE 7X1.5X1120-TR	1	\$	7.24	\$?	7.24
71	PLUG	1	\$	5.80	\$?	5.80
72	COOLING SYSTEM ASSEMBLY	1	\$	5,359.10	\$?	5,359.10
73	FAN COWL (NOZZLE)	1	\$	125.20	\$?	125.20
74	FILTER HOUSING ASSEMBLY AIR CONDITIONING	1	\$	2,785.18	\$ <i>any</i>	2,785.18
75	WATER DRAIN PIPE	1	\$	58.60	\$ <i>de</i>	58.60
76	BRACKET HOLDER	2	\$	22.64	\$?	45.28
77	LIQUEFIER (REFRIGERANT CONDENSER)	1	\$	836.14	\$ <i>bt</i>	836.14
78	WINDSCREEN NARROW (81-62450-0078)	1	\$	878.80	\$?	878.80
79	RETAINING SECTION 2002 mm	1	\$	26.90	\$ <i>nei</i>	26.90
80	RUBBER STRIP (81-62910-0303)	1	\$	75.10	\$ <i>new</i>	75.10
81	CARRIER NARROW	1	\$	1,911.10	\$ <i>bt</i>	1,911.10
82	REPLACEMENT CAB F99/R17 (CABIN) <i>✓</i>	1	\$	85,695.24	\$?	85,695.24
83	REAR WINDOW RIGHT 276,5/246	1	\$	172.08	\$ <i>coa</i>	172.08
84	GAS SPRING	2	\$	320.50	\$ <i>bt</i>	641.00
85	RADIATOR GRILLE ASSEMBLY NARROW	1	\$	2,182.58	\$ <i>coa</i>	2,182.58
86	FRONT SERVICE DOOR ASSEMBLY NARROW	1	\$	2,031.50	\$ <i>coa</i>	2,031.50
87	SEALING FRAME	1	\$	128.78	\$ <i>any</i>	128.78
88	HINGE LH	1	\$	76.24	\$ <i>bt</i>	76.24
89	HINGE RH	1	\$	76.24	\$ <i>bt</i>	76.24
90	LOCK PIN	2	\$	23.10	\$ <i>bt</i>	46.20
91	LOCK PIN ASSEMBLY	1	\$	45.08	\$ <i>bt</i>	45.08
92	WIND DEFLECTOR LEFT	1	\$	324.98	\$ <i>coa</i>	324.98
93	WIND DEFLECTOR LEFT PRIMED	1	\$	342.58	\$ <i>ar</i>	342.58
94	WIND DEFLECTOR RIGHT	1	\$	324.98	\$ <i>ar</i>	324.98
95	WIND DEFLECTOR RIGHT PRIMED	1	\$	342.58	\$ <i>ar</i>	342.58
96	GRIP MOLDING BLACK PLASTIC	1	\$	47.28	\$?	47.28
97	FLOOR MAT R.H DRIVE VEHICLE	1	\$	1,138.04	\$?	1,138.04
98	DOOR HINGE RIGHT, UPPER	1	\$	568.84	\$?	568.84
99	DOOR HINGE RIGHT, LOWER	1	\$	306.04	\$?	306.04
100	DOOR HINGE LEFT, UPPER	1	\$	568.84	\$?	568.84
101	DOOR HINGE LEFT, LOWER	1	\$	306.04	\$?	306.04
102	DOOR LOCK CENTRALIZED LOCKING RIGHT	1	\$	502.40	\$?	502.40
103	STRIKER PLATE RIGHT	1	\$	30.00	\$?	30.00
104	PIN RIGHT	1	\$	11.34	\$?	11.34
105	DOOR LOCK CENTRALIZED LOCKING LEFT	1	\$	502.40	\$?	502.40
106	STRIKER PLATE LEFT	1	\$	30.00	\$?	30.00
107	PIN LEFT	1	\$	11.34	\$?	11.34
108	SIDE MEMBER ASSEMBLY CROSS TUBE	1	\$	486.88	\$ <i>bt</i>	486.88
109	SPACER F99 L/R15-47	2	\$	25.80	\$ <i>bt</i>	51.60
110	HEX LOCK SCREW M10X80-10.9-MAN183-B1	4	\$	6.78	\$ <i>ne</i>	27.12
111	BRACKET ASSEMBLY (85-41701-6001)	2	\$	309.90	\$?	619.80
112	RUBBER PAD (85-41701-6001)	4	\$	39.30	\$?	157.20
113	BUSH 13X22X79,5-ST52-3BK (85-41701-6001)	2	\$	21.30	\$?	42.60
114	BRACKET ASSEMBLY (5094)	1	\$	1,317.68	\$?	1,317.68
115	BRACKET RIGHT	1	\$	201.20	\$ <i>bt</i>	201.20
116	BRACKET LEFT	1	\$	133.84	\$?	133.84
117	CAB LOCK	2	\$	547.04	\$?	1,094.08
118	CAB SUPPORT	2	\$	86.78	\$?	173.56
119	BRACKET RUBBER PAD	2	\$	61.80	\$?	123.20
120	SHOCK ABSORBER REAR	2	\$	619.44	\$ <i>bt</i>	1,238.88
121	BRACKET CABLE FASTENING	1	\$	44.50	\$?	44.50
122	BRACKET ASSEMBLY (CAB SUSPENSION)	2	\$	177.08	\$?	354.16
123	MOUNT BRACKET LEFT (LOCATING ARM)	1	\$	99.48	\$?	99.48
124	MOUNT BRACKET RIGHT (LOCATING ARM)	1	\$	99.48	\$?	99.48
125	MOUNT BRACKET LEFT	1	\$	688.08	\$?	688.08
126	MOUNT BRACKET RIGHT	1	\$	688.08	\$?	688.08
127	LOCATING ARM ASSEMBLY	1	\$	2,977.24	\$ <i>bt</i>	2,977.24
128	SHIM LEFT	4	\$	11.08	\$ <i>nei</i>	44.32
129	SHIM RIGHT	4	\$	5.48	\$ <i>ne</i>	21.92
130	BRACKET (FRONT ABSORBER)	2	\$	88.34	\$ <i>bt</i>	176.68
131	SHOCK ABSORBER FRONT	2	\$	619.44	\$ <i>bt</i>	1,238.88
132	PLATE	2	\$	11.58	\$?	23.16
133	PACKING	1	\$	8.00	\$?	8.00
134	BRACKET (CAB SUSPENSION INNER)	1	\$	44.50	\$?	44.50

135	PROTECTIVE CAP	1	\$	48.70	\$ ms ✓	48.70
136	BRACKET (HYDRAULIC CAB)	1	\$	11.50	\$?	11.50
137	SENSOR (HYDRAULIC CAB)	1	\$	86.54	\$ ms ✓	86.54
138	CONNECTOR HOUSING A-2-1,5-CODEA/ST-GRBA70	1	\$	13.78	\$?	13.78
139	CURB MIRROR ON DRIVER'S SIDE ELECTRIC WR300	1	\$	1,004.30	\$ ms ✓	1,004.30
140	FRONT MIRROR ASSEMBLY EG-Design right	1	\$	497.18	\$ ms ✓	497.18
141	ADAPTER PLATE LEFT for r.h. drive	1	\$	75.10	\$ ms ✓	75.10
142	GASKET LEFT for rh.drive	1	\$	18.00	\$ ms ✓	18.00
143	HINGE LEFT (FRONT SERVICE DOOR)	1	\$	104.48	\$?	104.48
144	HINGE PIN F99 L/R17,34,39,44,45,49	2	\$	11.58	\$?	23.16
145	HINGE RIGHT (FRONT SERVICE DOOR)	1	\$	104.48	\$?	104.48
146	LOCK PIN B-C60-DELTATONESW	2	\$	6.34	\$?	12.68
147	LOCK	1	\$	49.74	\$ ms ✓	49.74
148	SNAP LOCK ASSEMBLY LEFT	1	\$	88.08	\$ ms ✓	88.08
149	SNAP LOCK ASSEMBLY RIGHT	1	\$	88.08	\$ ms ✓	88.08
150	COVERING LEFT, LOWER PRIMED	1	\$	44.00	\$ ms ✓	44.00
151	COVERING RIGHT, LOWER PRIMED	1	\$	43.80	\$ ms ✓	43.80
152	COVERING LEFT, LOWER	1	\$	14.44	\$?	14.44
153	COVERING RIGHT, LOWER	1	\$	14.44	\$?	14.44
154	SPEED NUT B4,8-9,7/9,7X18,0-PA-NF	6	\$	3.54	\$ ms ✓	21.24
155	HOSE CLAMP L/R 17,34,39,44,45,49	2	\$	25.10	\$ ms ✓	50.20
156	PILLAR LINING LEFT PRIMED	1	\$	233.54	\$ ms ✓	233.54
157	PILLAR LINING RIGHT PRIMED	1	\$	233.54	\$ ms ✓	233.54
158	COVERING LEFT DOOR HINGE	1	\$	11.48	\$?	11.48
159	COVERING RIGHT DOOR HINGE	1	\$	11.48	\$?	11.48
160	COVERING L/R17,34,39,44,45,49 (81-62410-0109)	2	\$	5.38	\$?	10.76
161	WATER DEFLECTOR LEFT	1	\$	11.58	\$?	11.58
162	WATER DEFLECTOR RIGHT	1	\$	11.58	\$?	11.58
163	MOULDED FOAM LEFT	1	\$	15.74	\$?	15.74
164	SHAPED HOSE RIGHT	1	\$	21.48	\$?	21.48
165	MOULDED FOAM LEFT, UPPER	1	\$	27.98	\$?	27.98
166	MOULDED FOAM RIGHT, UPPER	1	\$	27.98	\$?	27.98
167	SHAPED HOSE (HEATER LINE) (0495)	1	\$	70.48	\$?	70.48
168	HEATER LINE 18x1,5	1	\$	130.60	\$?	130.60
169	HOSE BEND 18/18-30/20/30-MAN334-3-BL	1	\$	44.14	\$?	44.14
170	SHAPED HOSE (HEATER LINE) (0366)	1	\$	44.14	\$?	44.14
171	SHAPED HOSE (HEATER LINE) (0351)	1	\$	58.78	\$?	58.78
172	VALVE	1	\$	36.78	\$?	36.78
173	MOUNTING CLAMP 2X18-14-PP-SW	1	\$	6.18	\$?	6.18
174	TRIM (ROOF FAIRINGS INSIDE)	1	\$	33.34	\$?	33.34
175	AIR DUCT LEFT	1	\$	324.98	\$?	324.98
176	AIR DUCT RIGHT	1	\$	297.00	\$ ms ✓	297.00
177	WIRING CONDUIT UPPER PART RIGHT SIDE R.H DRIVE VEHICLE	1	\$	137.80	\$ ms ✓	137.80
178	WIRING CONDUIT LOWER PART RIGHT SIDE R.H DRIVE VEHICLE	1	\$	211.60	\$ ms ✓	211.60
179	WIRING CONDUIT UPPER PART LEFT SIDE	1	\$	143.18	\$ ms ✓	143.18
180	WIRING CONDUIT LOWER PART IN DRIVER'S SIDE	1	\$	243.94	\$ ms ✓	243.94
181	TRANSFORMER 20A	1	\$	471.64	\$?	471.64
182	SOCKET UNION FOR SYSTEM VOSS 232 (NG12-M22X2.5)	2	\$	25.54	\$ ms ✓	127.70
183	W PLUG FOR SYSTEM VOSS 232 (W-SN8-D6/31,5)	5	\$	11.80	\$ ms ✓	59.00
184	RADIATOR COOLANT	5	\$	45.46	\$ ms ✓	227.30
185	FRONT WINDSCREEN GLASS SEALANT	5	\$	30.00	\$ ms ✓	150.00
186	REAR CABIN WINDOW GLASS SEALANT	3	\$	30.00	\$ ms ✓	90.00
187	FRONT CARRIER NARROW SEALANT	4	\$	30.00	\$ ms ✓	120.00
188	FRONT ELECTRICAL RETAINING FRAME SEALANT	2	\$	30.00	\$ ms ✓	60.00
189	FRONT PADEL BRACKET SEALANT	2	\$	30.00	\$ ms ✓	60.00
					\$	148,746.94

Note :

1. This quotation is an estimate list based on our visual inspection. Additional parts need replacement will be advised accordingly.
2. During of repair : 180 - 240 working days.
3. Subject to parts availability.

Total	\$230,576.94
GST 7%	\$16,140.39
Grant Total	\$246,717.33

6129 64



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS/INC19014779/T1qf3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date : 08-11-2019	
ATTN: CHRYLLIS QUAH			Code : INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 1384E	Veh. Inspected	XE 4126J	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1058537-002	Excess (\$)	0.00	
Assign From	DANIEL KOH	Assign Date	22/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	MAN TGS	c.c	10518	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WMA26SZZ7JM772352	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
R/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	8/8 mm	
L/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/08/2019	Inspection Date	19/09/2019	
Survey held at	31 CORPORATION ROAD			
Repairer	DING AUTO PTE LTD			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		40 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 8

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 4126J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	MULTIPOINT CONNECTOR @\$15.58 (SN)	* CHECK	31.16	-
1	BRACKET MOUNTING LEFT (SN)	* CHECK	77.34	-
1	BRACKET MOUNTING RIGHT (SN)	* CHECK	77.34	-
1	MUDGUARDS RIGHT, REAR (SN)	CRACKED	664.88	664.88
1	SPLASH SHIELD L/R15/32/37 RIGHT (SN)	NECESSARY	240.44	240.44
9	NUT (RIGHT) @\$2.78 (SN)	NECESSARY	25.02	25.02
1	MUDGUARDS LEFT REAR (SN)	CRACKED	701.80	701.80
1	SPLASH SHIELD L/R15/32/37 LEFT (SN)	NECESSARY	240.44	240.44
9	NUT (LEFT) @\$2.78 (SN)	NECESSARY	25.02	25.02
1	WATER CONTAINER (81-26481-0079) (SN)	* CHECK	126.08	-
1	SEAL FILLER TUBE WATER CONTAINER (SN)	* CHECK	17.00	-
1	FILLER TUBE WATER CONTAINER (SN)	* CHECK	275.58	-
1	SCREW CAP FOR WATER CONTAINER (SN)	DEFORMED	14.80	14.80
2	COVER PLATE WIPER ARM @\$8.70 (SN)	CRACKED	17.40	17.40
1	INTAKE DUCT ASSEMBLY (SN)	CRACKED	252.04	252.04
1	STEEL BUMPER SIDE SECTION LEFT (81-41610-6629) (SN)	BENT	1,272.84	1,272.84
1	TRIM LEFT (81-41610-6629) (SN)	* CHECK	41.80	-
1	BUMPER SIDE PART POWDER-COATED RIGHT (81-41610-6628) (SN)	TO REPAIR SEE LABOUR	1,272.84	-
1	TRIM RIGHT (81-41610-6628) (SN)	* CHECK	40.40	-
1	PEDAL BRACKET (SN)	CRACKED	708.14	708.14
1	FOOT BRAKE VALVE (SN)	CRACKED	1,707.34	1,707.34
1	GASKET (SN)	NECESSARY	31.20	31.20
1	HEATER LINE RETURN (SN)	BENT	159.38	159.38
1	HEATER LINE SUPPLY (SN)	BENT	161.18	161.18
1	SHAPED HOSE (TO HEATER LINE RETURN) (SN)	* CHECK	47.80	-
1	SHAPED HOSE (TO HEATER LINE SUPPLY) (SN)	* CHECK	31.80	-
2	BRACKET HEATER LINE @\$6.18 (SN)	BENT	12.36	12.36
1	MOUNTING CLAMP 2X18-6,6-PA6 (SN)	BENT	4.04	4.04
1	BRACKET ASSEMBLY (HEATER LINE) (SN)	BENT	77.34	77.34

Report Ref No. CS/INC19014779/T1qf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	HOSE CLAMP H16-27 @\$6.68 (SN)	NECESSARY	26.72	26.72
1	ADAPTER TOOL SUPPORT ELECTRICAL SYSTEM DRIVER'SIDE (SN)	CRACKED	37.38	37.38
1	RETAINING FRAME ON CAB ON DRIVER'S SIDE (SN)	CRACKED	87.20	87.20
1	RETAINING FRAME ON CAB CO-DRIVER'S SIDE (SN)	CRACKED	219.64	219.64
1	BRACKET TOOL SUPPORT ELECTRONIC CONTROL UNIT (SN)	* CHECK	55.64	-
1	BRACKET TOOL SUPPORT RELAY (SN)	* CHECK	55.64	-
1	ADAPTER TOOL SUPPORT ELECTRICAL SYSTEM CO-DRIVER'S SIDE (SN)	CRACKED	40.70	40.70
1	BRACKET RELAY (SN)	* CHECK	44.50	-
2	COVER ELECTRICAL SYSTEM @\$39.68 (SN)	MISSING	79.36	79.36
1	COVER WIRING CONDUIT (SN)	CRACKED	121.58	121.58
1	REFRIGERANT PIPE (CONDENSER TO HEATER) (SN)	BENT	257.58	257.58
1	REFRIGERANT PIPE (CONDENSER TO COMP) (SN)	* CHECK	266.60	-
1	REFRIGERANT PIPE (HEATER TO COMP) (SN)	BENT	257.58	257.58
1	CLIP (REFRIGERANT PIPE COND-COMP) (SN)	BENT	13.54	13.54
1	CLIP (REFRIGERANT PIPE HEATER-COMP) (SN)	BENT	8.18	8.18
1	CLAMP (SN)	* CHECK	10.38	-
1	REFRIGERANT PIPE HEATER (BIG) (SN)	BENT	266.60	266.60
1	REFRIGERANT PIPE HEATER (SMALL) (SN)	BENT	443.28	443.28
4	MOUNTING CLAMP 10/18-6-PA6 @\$9.28 (SN)	BENT	37.12	37.12
1	NOISE INSULATION LEFT (81-19220-0981) (SN)	TORN	234.94	234.94
1	NOISE INSULATION RIGHT (81-19220-0982) (SN)	TORN	235.88	235.88
1	VISCO FAN (SN)	* CHECK	3,693.54	-
1	VISCO FAN BRACKET (SN)	* CHECK	66.68	-
1	FAN BEARING ASSEMBLY (SN)	* CHECK	3,713.50	-
1	ENGINE COWLING F99L/R15/31/32/36/37 (SN)	* CHECK	704.14	-
1	ENGINE COWLING HALF-CAB F99L/R15 (SN)	* CHECK	639.78	-
4	FLANGE NUT M8 @\$6.00 (SN)	* CHECK	24.00	-
1	FLY SCREEN (SN)	BENT	144.00	144.00
1	AIR DEFLECTOR (SN)	DEFORMED	126.08	126.08
2	HINGED SIDE FRAME @\$100.84 (SN)	* CHECK	201.68	-
1	SUPPORT LH (SN)	CRACKED	353.44	353.44

Report Ref No. CS/INC19014779/T1qf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUPPORT RH (SN)	CRACKED	353.44	353.44
1	COOLING WATER HOSE (0978) (SN)	* CHECK	92.14	-
1	SHAPED HOSE (0472) (SN)	* CHECK	66.14	-
1	BLEEDER LINE (5700) (SN)	* CHECK	110.80	-
1	BLEEDER LINE (5686) (SN)	* CHECK	68.50	-
1	BLEEDER LINE (5698) (SN)	* CHECK	74.60	-
1	SHAPED HOSE (0467) (SN)	* CHECK	55.14	-
1	SHAPED HOSE (0463) (SN)	* CHECK	68.50	-
1	COOLING WATER HOSE (0942) (SN)	* CHECK	113.18	-
1	HOSE 7X1.5X1120-TR (SN)	* CHECK	7.24	-
1	PLUG (SN)	* CHECK	5.80	-
1	COOLING SYSTEM ASSEMBLY (SN)	* CHECK	5,359.10	-
1	FAN COWL (NOZZLE) (SN)	* CHECK	125.20	-
1	FILTER HOUSING ASSEMBLY AIR CONDITIONING (SN)	CRACKED	2,785.18	2,785.18
1	WATER DRAIN PIPE (SN)	DEFORMED	58.60	58.60
2	BRACKET HOLDER @\$22.64 (SN)	* CHECK	45.28	-
1	LIQUEFIER (REFRIGERANT CONDENSER) (SN)	BENT	836.14	836.14
1	WINDSCREEN NARROW (81-62450-0078) (SN)	* CHECK	878.80	-
1	RETAINING SECTION 2002 MM (SN)	NECESSARY	26.90	26.90
1	RUBBER STRIP (81-62910-0303) (SN)	NECESSARY	75.10	75.10
1	CARRIER NARROW (SN)	BENT	1,911.10	1,911.10
1	REPLACEMENT CAB F99/R17 (CABIN) (SN)	* CHECK	85,695.24	-
1	REAR WINDOW RIGHT 276,5/246 (SN)	CRACKED	172.08	172.08
2	GAS SPRING @\$320.50 (SN)	BENT	641.00	641.00
1	RADIATOR GRILLE ASSEMBLY NARROW (SN)	CRACKED	2,182.58	2,182.58
1	FRONT SERVICE DOOR ASSEMBLY NARROW (SN)	CRACKED	2,031.50	2,031.50
1	SEALING FRAME (SN)	CRACKED	128.78	128.78
1	HINGE LH (SN)	BENT	76.24	76.24
1	HINGE RH (SN)	BENT	76.24	76.24
2	LOCK PIN @\$23.10 (SN)	BENT	46.20	46.20
1	LOCK PIN ASSEMBLY (SN)	BENT	45.08	45.08
1	WIND DEFLECTOR LEFT (SN)	CRACKED	324.98	324.98
1	WIND DEFLECTOR LEFT PRIMED (SN)	CRACKED	342.58	342.58

Report Ref No. CS/INC19014779/T1qf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No: 4 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WIND REFLECTOR RIGHT (SN)	CRACKED	324.98	324.98
1	WIND REFLECTOR RIGHT PRIMED (SN)	CRACKED	342.58	342.58
1	GRIP MOLDING BLACK PLASTIC (SN)	* CHECK	47.28	-
1	FLOOR MAT R.H DRIVE VEHICLE (SN)	* CHECK	1,138.04	-
1	DOOR HINGE RIGHT, UPPER (SN)	* CHECK	568.84	-
1	DOOR HINGE RIGHT, LOWER (SN)	* CHECK	306.04	-
1	DOOR HINGE LEFT, UPPER (SN)	* CHECK	568.84	-
1	DOOR HINGE LEFT, LOWER (SN)	* CHECK	306.04	-
1	DOOR LOCK CENTRALIZED LOCKING RIGHT (SN)	* CHECK	502.40	-
1	STRIKER PLATE RIGHT (SN)	* CHECK	30.00	-
1	PIN RIGHT (SN)	* CHECK	11.34	-
1	DOOR LOCK CENTRALIZED LOCKING LEFT (SN)	* CHECK	502.40	-
1	STRIKER PLATE LEFT (SN)	* CHECK	30.00	-
1	PIN LEFT (SN)	* CHECK	11.34	-
1	SIDE MEMBER ASSEMBLY CROSS TUBE (SN)	BENT	486.88	486.88
2	SPACER F99 L/R15-47 @\$25.80 (SN)	BENT	51.60	51.60
4	HEX LOCK SCREW M10X80-10.9-MAN183-B1 @\$6.78 (SN)	NECESSARY	27.12	27.12
2	BRACKET ASSEMBLY (85-41701-6001) @\$309.90 (SN)	* CHECK	619.80	-
4	RUBBER PAD (85-41701-6001) @\$39.30 (SN)	* CHECK	157.20	-
2	BUSH 13X22X79, 5-ST52-3BK (85-41701-6001) @\$21.30 (SN)	* CHECK	42.60	-
1	BRACKET ASSEMBLY (5094) (SN)	* CHECK	1,317.68	-
1	BRACKET RIGHT (SN)	BENT	201.20	201.20
1	BRACKET LEFT (SN)	* CHECK	133.84	-
2	CAB LOCK @\$547.04 (SN)	* CHECK	1,094.08	-
2	CAB SUPPORT @\$86.78 (SN)	* CHECK	173.56	-
2	BRACKET RUBBER PAD @\$61.60 (SN)	* CHECK	123.20	-
2	SHOCK ABSORBER REAR @\$619.44 (SN)	BENT	1,238.88	1,238.88
1	BRACKET CABLE FASTENING (SN)	* CHECK	44.50	-
2	BRACKET ASSEMBLY (CAB SUSPENSION) @\$177.08 (SN)	* CHECK	354.16	-
1	MOUNT BRACKET LEFT (LOCATING ARM) (SN)	* CHECK	99.48	-
1	MOUNT BRACKET RIGHT (LOCATING ARM) (SN)	* CHECK	99.48	-
1	MOUNT BRACKET LEFT (SN)	* CHECK	688.08	-

Report Ref No. CS/INC19014779/T1qf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	MOUNT BRACKET RIGHT (SN)	* CHECK	688.08	-
1	LOCATING ARM ASSEMBLY (SN)	BENT	2,977.24	2,977.24
4	SHIM LEFT @\$11.08 (SN)	NECESSARY	44.32	44.32
4	SHIM RIGHT @\$5.48 (SN)	NECESSARY	21.92	21.92
2	BRACKET (FRONT ABSORBER) @\$88.34 (SN)	BENT	176.68	176.68
2	SHOCK ABSORBER FRONT @\$619.44 (SN)	BENT	1,238.88	1,238.88
2	PLATE @\$11.58 (SN)	* CHECK	23.16	-
1	PACKING (SN)	* CHECK	8.00	-
1	BRACKET (CAB SUSPENSION INNER) (SN)	* CHECK	44.50	-
1	PROTECTIVE CAP (SN)	MISSING	48.70	48.70
1	BRACKET (HYDRAULIC CAB) (SN)	* CHECK	11.50	-
1	SENSOR (HYDRAULIC CAB) (SN)	* CHECK	86.54	-
1	CONNECTOR HOUSING A-2-1.5-CODEA/ST-GRBA70 (SN)	* CHECK	13.78	-
1	CURB MIRROR ON DRIVER'S SIDE ELECTRIC WR300 (SN)	MISSING	1,004.30	1,004.30
1	FRONT MIRROR ASSEMBLY EG-DESIGN RIGHT (SN)	CRACKED	497.18	497.18
1	ADAPTER PLATE LEFT FOR R.H. DRIVE (SN)	NECESSARY	75.10	75.10
1	GASKET LEFT FOR RH. DRIVE (SN)	NECESSARY	18.00	18.00
1	HINGE LEFT (FRONT SERVICE DOOR) (SN)	* CHECK	104.48	-
2	HINGE PIN F99 L/R17,34,39,44,45,49 @\$11.58 (SN)	* CHECK	23.16	-
1	HINGE RIGHT (FRONT SERVICE DOOR) (SN)	* CHECK	104.48	-
2	LOCK PIN 8-C60-DELTATONESW @\$6.34 (SN)	* CHECK	12.68	-
1	LOCK (SN)	BENT	49.74	49.74
1	SNAP LOCK ASSEMBLY LEFT (SN)	CRACKED	88.08	88.08
1	SNAP LOCK ASSEMBLY RIGHT (SN)	DISTORTED	88.08	88.08
1	COVERING LEFT, LOWER PRIMED (SN)	CRACKED	44.00	44.00
1	COVERING RIGHT, LOWER PRIMED (SN)	CRACKED	43.80	43.80
1	COVERING LEFT, LOWER (SN)	* CHECK	14.44	-
1	COVERING RIGHT, LOWER (SN)	* CHECK	14.44	-
6	SPEED NUT B4,8-9,7/9,7X18,0-PA-NF @\$3.54 (SN)	NECESSARY	21.24	21.24
2	HOSE CLAMP L/R 17,34,39,44,45,49 @\$25.10 (SN)	DEFORMED	50.20	50.20
1	PILLAR LINING LEFT PRIMED (SN)	CRACKED	233.54	233.54
1	PILLAR LINING RIGHT PRIMED (SN)	CRACKED	233.54	233.54

Report Ref No. CS/INC19014779/T1qf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COVERING LEFT DOOR HINGE (SN)	* CHECK	11.48	-
1	COVERING RIGHT DOOR HINGE (SN)	* CHECK	11.48	-
2	COVERING L/R17,34,39,44,45,49 (81-62410-0109) @\$5.38 (SN)	* CHECK	10.76	-
1	WATER DEFLECTOR LEFT (SN)	* CHECK	11.58	-
1	WATER DEFLECTOR RIGHT (SN)	* CHECK	11.58	-
1	MOULDED FOAM LEFT (SN)	* CHECK	15.74	-
1	SHAPED HOSE RIGHT (SN)	* CHECK	21.48	-
1	MOULDED FOAM LEFT, UPPER (SN)	* CHECK	27.98	-
1	MOULDED FOAM RIGHT, UPPER (SN)	* CHECK	27.98	-
1	SHAPED HOSE (HEATER LINE) (0495) (SN)	* CHECK	70.48	-
1	HEATER LINE 18X1.5 (SN)	* CHECK	130.60	-
1	HOSE BEND 18/18-30/20/30-MAN334-3-BL (SN)	* CHECK	44.14	-
1	SHAPED HOSE (HEATER LINE) (0366) (SN)	* CHECK	44.14	-
1	SHAPED HOSE (HEATER LINE) (0351) (SN)	* CHECK	58.78	-
1	VALVE (SN)	* CHECK	36.78	-
1	MOUNTING CLAMP 2X18-14-PP-SW (SN)	* CHECK	6.18	-
1	TRIM (ROOF FAIRINGS INSIDE) (SN)	* CHECK	33.34	-
1	AIR DUCT LEFT (SN)	* CHECK	324.98	-
1	AIR DUCT RIGHT (SN)	CUT	297.00	297.00
1	WIRING CONDUIT UPPER PART RIGHT SIDE R.H DRIVE VEHICLE (SN)	MISSING	137.80	137.80
1	WIRING CONDUIT LOWER PART RIGHT SIDE R.H DRIVE VEHICLE (SN)	DEFORMED	211.60	211.60
1	WIRING CONDUIT UPPER PART LEFT SIDE (SN)	MISSING	143.18	143.18
1	WIRING CONDUIT LOWER PART IN DRIVER'S SIDE (SN)	DEFORMED	243.94	243.94
1	TRANSFORMER 20A (SN)	* CHECK	471.64	-
2	SOCKET UNION FOR SYSTEM VOSS 232 (NG12-M22XZ.5) (SN)	BROKEN	127.70	127.70
5	W PLUG FOR SYSTEM VOSS 232 (W-SN8-D6/31.5) @\$11.80 (SN)	BROKEN	59.00	59.00
5	RADIATOR COOLANT @\$45.46 (SN)	NECESSARY	227.30	227.30
5	FRONT WINDSCREEN GLASS SEALANT @\$30.00 (SN)	NECESSARY	150.00	150.00
3	REAR CABIN WINDOW GLASS SEALANT @\$30.00 (SN)	NECESSARY	90.00	90.00
4	FRONT CARRIER NARROW SEALANT @\$30.00 (SN)	NECESSARY	120.00	120.00

Report Ref No. CS/INC19014779/T1qf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT ELECTRICAL RETAINING FRAME SEALANT @\$30.00 (SN)	NECESSARY	60.00	60.00
2	FRONT PADEL BRACKET SEALANT @\$30.00 (SN)	NECESSARY	60.00	60.00
			148,746.94	32,975.48
	LABOUR			
	LABOUR TO PANEL BEAT ACCIDENT AREAS & DISMANTLE FRONT CABIN & BOTH FRONT CABIN ABSORBER & BOTH REAR CABIN ABSORBER & BOTH REAR CABIN LOCK & LOCATING ARM & CARRIER NARROW & WIND DEFLECTOR & PILLAR LINING & FRONT SERVICE DOOR & BOTH MUDGUARD GREY & BOTH MUDGUARD BEHIND CAB & FRONT BUMPER STEEL & GAS SPRING & FRONT MIRROR ASSEMBLY & BOTH SIDE CURB MIRROR & CABIN AIR DUCT ASSEMBLY.		21,000.00	10,800.00
	R&R FRONT WINDSCREEN GLASS & SIDE GLASS.		1,040.00	600.00
	R&R REAR WINDSCREEN GLASS & QUOTA GLASS.		550.00	300.00
	R&R FRONT DASH BOARD, DASH BOARD COMPONENTS.		850.00	600.00
	R&R DRIVER SEAT & CARPET & TRIM & INSULATION & FLOOR MAT & ENGINE COWLING.		650.00	300.00
	R&R WIREHARNES & FUSE BOX & FRONT WIRING CONDUIT & WHOLE FRONT RETAINING FRAME & COVERING ELECTRICAL SYSTEM.		730.00	600.00
	R&R AIR COND BLOWER & BRAKE MASTER PUMP CYLINDER & SURGE TANK & WIPER LINKAGE & AIR COND PIPE & PEDAL BRACKET & HEATER LINES & HEATER HOSE & SHAPE HOSE.		1,150.00	600.00
	R&R FRONT DOOR COMPONENTS LH.		390.00	300.00
	R&R FRONT DOOR COMPONENTS RH.		390.00	300.00
	R&R RADIATOR & CONDENSOR & FAN COWLING & VISCO FAN & INTERCOOLER.		1,300.00	900.00
	R&R STEERING, STEERING WHEEL AND COLUMN.	* CHECK	1,300.00	-
	VACUUM AIRCON SYSTEM & TOP UP AIR COND GAS R134A.		350.00	250.00
	R&R ROOF TOP LINING & ROOF COVERING.		390.00	200.00
	ALIGNMENT CHASSIS.	* CHECK	1,560.00	-
	REPAIR FRONT WIRING.		500.00	300.00
	DIAGNOSTIC & DO UP BRAKE SYSTEM.		450.00	300.00

Report Ref No. CS/INC19014779/T1qf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:8 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESpray WHOLE CABIN INSIDE & CABIN FLOOR PANEL & FRONT CABIN & FRONT SERVICE DOOR & PILLAR LINING LEFT AND RIGHT & WIND DEFLECTOR LEFT AND RIGHT.		2,600.00	2,000.00
	TOWING FEES (CHENG HOE MOTOR PTE LTD).		1,340.00	1,340.00
	TOWING FEES (YONG HUA TOWING SERVICE).		1,340.00	1,340.00
	1)REPLACEMENT OF NEW BINLIFTER ASSY FOR RCV XE4126J CAUSED BY ACCIDENT. SUPPLY LABOUR AND MATERIAL FOR THE REPAIR OF RCV XE4126J AS FOLLOWS.		43,950.00	30,000.00
	2)REMOVING OF DAMAGED BINLIFTER ASSY FORMING AND WELDING FABRICATION OF SUB ASSEMBLY, RETROFITTING NEW BIN LIFTER ONTO RCV AND TESTING AND PAINTING OF BINLIFTER ASSEMBLY OF AFFECTED AREA OF REPAIR. }			
	3)TO REMOVING REAR HOPPER COVER DOOR AND REPLACE NEW HOPPER COVER DOOR WITH PAINTWORK.		-	-
	4)TO DISMOUNT ROS ROCA REL BODY AND REMOUNT ONTO NEW CHASSIS, EXISTING LOAD CELL BRACKETS.			
	5)CVP AND LTA INSPECTION. }			
	INCLUSIVE OF THE REPAIR OF BUMPER SIDE PART POWDER-COATED RIGHT (81-41610-6628). }		-	-
			81,830.00	51,030.00
GRAND TOTAL			230,576.94	84,005.48
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$117,358.62 NETT)				84,005.48

Report Ref No. CS/INC19014779/T1qf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.