



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19014790/Ega3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 20-04-2020



ATTN:KHOR SAW THENG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|--------------|-----------------------|------------|
| Insured Veh. | SKJ 3169U | Veh. Inspected | SHB 1382K |
| Policy No. | VPA/P1356030 | Coverage (\$) | 0.00 |
| Claim No. | S9M01XML | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 22/08/2019 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|-------------------|---------------------|------------|
| Make & Model | TOYOTA PRIUS | c.c | 1798 |
| Engine No. | HIDDEN | Year of Reg. | 2013 |
| Chassis No. | JTDKN36U405713654 | Colour | MAROON |
| Odometer | 837173 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | | | |
|-----------------------|-------------|-------------|----------------|
| | Size | Make | Balance |
| R/H Front Tyre | 195/50 R15 | FALKEN | 5 mm |
| L/H Front Tyre | 195/50 R15 | FALKEN | 5 mm |
| R/H Rear Tyre | 195/50 R15 | FALKEN | 5 mm |
| L/H Rear Tyre | 195/50 R15 | FALKEN | 5 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|-----------------------|--|------------------------|------------|
| Accident Date | 17/08/2019 | Inspection Date | 22/08/2019 |
| Survey held at | SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|-----------------------|