

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 5258C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	BENT	534.60	534.60
1	REAR BUMPER RH SIDE RETAINER (CONSISTENT)	CRACKED	58.60	58.60
1	REAR BUMPER RH CORNAL RETAINER (CONSISTENT)	CRACKED	37.80	37.80
1	REAR BUMPER SPONGE (CONSISTENT)	* CHECK	155.70	-
1	REAR BUMPER RH REFLECTOR (CONSISTENT)	CRACKED	42.70	42.70
5	REAR BUMPER CLIP @\$3.89 (CONSISTENT)	NECESSARY	19.45	19.45
1	REAR BOOT (CONSISTENT)	BENT	911.60	911.60
1	REAR BOOT INNER LOCK (CONSISTENT)	* CHECK	126.80	-
1	REAR BOOT LOGO (CONSISTENT)	NECESSARY	55.80	55.80
1	REAR BOOT EMBLEM '1.6' (CONSISTENT)	NECESSARY	32.13	32.13
1	REAR BOOT EMBLEM 'COROLLA' (CONSISTENT)	NECESSARY	51.17	51.17
1	REAR BOOT EMBLEM 'ALTIS' (CONSISTENT)	NECESSARY	50.22	50.22
1	REAR BOOT RH REFLECTOR (CONSISTENT)	CUT	195.70	195.70
1	RH TAILLAMP (CONSISTENT)	BROKEN	424.10	424.10
1	RH TAILLAMP PANEL (CONSISTENT)	BENT	103.40	103.40
1	RH TAILLAMP CLIP (CONSISTENT)	NECESSARY	3.89	3.89
1	REAR RH FENDER (CONSISTENT)	BUCKLED	927.45	927.45
1	REAR RH FENDER INNER TRIM (CONSISTENT)	DEFORMED	388.90	388.90
1	REAR RH FENDER AIR GRILLE (CONSISTENT)	DENTED	155.40	155.40
1	REAR END PANEL (CONSISTENT)	BENT	580.60	580.60
1	REAR END PANEL INNER TOP GARNISH (CONSISTENT)	MTG DISTORTED	227.20	227.20
2	REAR END PANEL INNER TOP GARNISH CLIP @\$3.21 (CONSISTENT)	NECESSARY	6.42	6.42
1	REAR SPARE TYRE PANEL INNER TOP BOARD (CONSISTENT)	CRACKED	369.20	369.20
1	REAR WINDSCREEN GLASS MOULDING (CONSISTENT)	NECESSARY	109.78	109.78
1	REAR MUFFLER (CONSISTENT)	BENT	791.71	791.71
1	REAR MUFFLER RUBBER MOUNTING (CONSISTENT)	TORN	47.80	47.80
	LESS 25% DISCOUNT		-1,602.03	-1,531.41
			4,806.09	4,594.21

Report Ref No. CC4/ASM19014792/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR BOOT INNER RUBBER (50%) (CONSISTENT) (SN)	DISTORTED / CUT	194.70	97.35
	LESS 25% DISCOUNT		-48.68	-
			146.02	97.35
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	200.00	200.00
1	REAR WINDSCREEN GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			280.00	280.00
	<u>LABOUR</u>			
	TOWING.		50.00	50.00
	REMOVE AND REFIX REAR WINDSCREEN GLASS .		120.00	120.00
	REMOVE & REFIX REAR BUMPER ,REAR BOOTLID & ATTACHMENTS ,TAILLAMPS ,TO CUT ,WELD & RENEW REAR END PANEL,REAR RH FENDER ,KNOCKING & REPAIR REAR RH DOOR ,REAR CHASSIS FRAME ,REAR SPARE TYRE PANEL & REALIGN THE SAME.		1,400.00	1,200.00
	PUTTY & RESPRAY REAR BUMPER ,REAR BOOT ,REAR FENDERS ,REAR END PANEL ,REAR SPARE TYRE PANEL ,CHASSIS FRAME ,REAR RH DOOR & ALL AFFECTED AREAS.		1,300.00	1,200.00
	REMOVE & REFIX REAR EXHAUST MUFFLER & REALIGN THE SAME.		60.00	60.00
	REMOVE & REFIX REAR SEAT ,CARPET TO FACILITATE REPAIR.		100.00	100.00
	RUSTPROOFING.		120.00	90.00
	TO MOUNT ON CAR-O-LINER ,JACK & STRAIGHTEN CHASSIS .		250.00	250.00
			3,400.00	3,070.00
	GRAND TOTAL		8,632.11	8,041.56
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$211.88 NETT)			6,400.00

Report Ref No. CC4/ASM19014792/Kpa3q2





Report Ref No. CC4/ASM19014792/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser